



Case Details

Case Reference Number : TAX/12/18/2105
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5448D

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5110-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 26/12/2018 02:00 AM
 Vehicle Age(In Months) : 12

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Repair/ Replace	Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR LH	1	1,249.60	937.20	25.00	937.20	Replace	1	0.00	Replace	DD
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	NEC
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL , LH	1	576.00	576.00	25.00	432.00	Replace	1	0	Repair	
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR , LH	1	1,243.90	1,243.90	25.00	932.93	Replace	1	0	Repair	
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	NEC
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	0	0	Not Give	
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	NEC
									Total Spare Part Cost	2,800.05	Surveyor Total	180.00		
									Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0		
									Final Spare Part Cost	2,800.05	Final Sur Total	180.00		

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR LH PORTION	676.00	400	
Total:		676.00	400.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO RESPRAY FRONT DOOR LH	378.00	200	
2	TO REPSRAY REAR DOOR LH	378.00	200	
3	TO RESPRAY ROCKER PANEL MOULDING	180.00	100	
4	TO RESPRAY REAR FENDER LH	378.00	0	
5	TO REPSRAY REAR BUMPER	378.00	0	
Total:		1,692.00	500.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO TRANSFER DOOR MECHANISM	240.00	50	
2	TO WASH AND VACUUM	60.00	0	
3	TO REPLACE SUNDRY PARTS	100.00	0	
Total:		400.00	50.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,800.05	180.00
Total Labour Cost	676.00	400.00
Total Spray Painting	1,692.00	500.00
Other	400.00	50.00
Overall Total	5,568.05	1,130.00
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	1,130.00
Surveyor Approved Amount		1,130.00
No of Repair Days*	5	3
Remarks	-	P/P repair, photo before paint.
Surveyor Name		Hwee jie

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Signature		
Survey Date	27/12/2018	Save Clear

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: