## COMFORTDELGRO ENGINEERING PTE LTD REPAIR ESTIMATE\*

REPAIR ESTIMATE* VEHICLE NO: SHA 5736C			12/27/2018 10:45	~	m
AKE	: SIA 3730C	Ditte			
ODEL	: HYUNDAI i40		More		
Qty	Parts Description/ Labour	Type	Unit Price	A	mount
	Rear Bumper X Market Rear Bumper Clip 10 pcs X			\$	553.00 22.00
	SUB TOTAL LESS 20%			<b>\$</b>	<b>575.00</b> 115.00
	DISCOUNTED TOTAL			\$	460.00
	Rear Bumper Rubber Mat 🗶			\$	50.00
					50.00
	TOTAL Labour Charge			\$	50.00
	Labour Charge Panel Beating			\$	350.00
	Spray Painting Charge			\$	250.00
	Wiring Charge			\$	30.00
	Remove/Refix Reverse Sensor			\$	80.00
			Consultants hence no	otify	
	Kaki 161614	• To result	rey before/after spray painting of damaged part(s) during of	ing surve	ey * heerig
	Kaki (((C)y  17/n/-8 124 2 Ry.	_/hird ;	erty survey is on a without		Jand
	1 PIP Dair all	Acknot Signal	rledged by Repairer		
	Her TOTAL LABOUR	Date:		\$	710.00
	,				
	ESTIMATE TOTAL		12.71	\$	1,220.00
			7		