

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD18023325/BTD3S2
Date: 12/03/2019

REFERENCE

Insured/Claimant: KHOR KIANG HUNG Policy No: PNCV2018-00000597
Date of Loss: 26/12/2018 Nature of Claim: OD Claim No: 1201800020073

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ6120C**
Make & Model: RENAULT KADJAR, 1.5 DCI EDC 6 S&S EU6 (M) Engine No: K9KF647D035344
Reg. Date: 19/12/2016 (Man. Year: 2016) Chassis No: VF1RFE00255374878
Colour: Brown Odometer: 128724 km
Engine Capacity: 1461 cc
Market Value/New Car Price: S\$91,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40ZR19 Rear Tyre Size: 245/40ZR19
Front Left Side: BLACKLION 7 mm Rear Left Side: BLACKLION 7 mm
Front Right Side: BLACKLION 7 mm Rear Right Side: BLACKLION 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,589.70	11,766.00	3,823.70	24.53
Miscellaneous Items	360.00	320.00	40.00	11.11
Labour	2,050.00	1,740.00	310.00	15.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,999.70	13,826.00	4,173.70	23.19
- Excess (S\$)	0.00	5,000.00	-5,000.00	
(S\$)	17,999.70	8,826.00	9,173.70	50.97
+ GST 7.00/7.00% (S\$)	1,259.98	617.82	642.16	50.97
Nett Amount (S\$)	19,259.68	9,443.82	9,815.86	50.97

INSPECTION

Date of Assignment: 31/12/2018 Present Location: Torque 5 Pte Ltd (Kaki Bukit)
Date Inspected: 31/12/2018 Inspected At: Torque 5 Pte Ltd (Kaki Bukit)
Estimated Period of Repair: 10.0 days No. 8 Kaki Bukit Ave 4., #01-50
Singapore 415875

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Mar 2019)	
Parts:	N/A	RENAULT KADJAR 1.5 DCI EDC 6 S&S EU6 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/SLJ6120C/12/03/2019 10:12	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bumper	Broken	1,055.80 F	*1,055.00 F
2	1		*Front bumper sponge	Not Necessary	188.00 F	*- F
3	1		*Front bumper lower grille	Not Necessary	257.40 F	*- F
4	1		*Front bumper retainer (LH)	Necessary	31.30 F	*33.00 F
5	1		*Front bumper retainer (RH)	Necessary	31.30 F	*33.00 F
6	1		*Radiator grille	Broken	362.00 F	*370.00 F
7	1		*Radiator grille top moulding	Broken	211.00 F	*215.00 F
8	1		*Radiator grille lower chrome moulding	Cracked	281.10 F	*285.00 F
9	1		*Head lamp (LH)	Broken	1,484.50 F	*1,100.00 F
10	1		*Head lamp (RH)	Broken	1,484.50 F	*1,100.00 F
11	1		*Head lamp lower bracket (LH)	Not Necessary	121.90 F	*- F
12	1		*Head lamp bracket (RH)	Not Necessary	121.90 F	*- F
13	1		*Bonnet	Dented	1,051.90 F	*1,050.00 F
14	1		*Bonnet hinge (LH)	Bent	165.80 F	*170.00 F
15	1		*Bonnet hinge (RH)	Bent	165.80 F	*170.00 F
16	1		*Bonnet inner rubber strip	Torn	110.20 F	*160.00 F
17	1		*Front support air guide (LH)	Broken	59.00 F	*60.00 F
18	1		*Front support air guide (RH)	Broken	59.00 F	*60.00 F
19	1		*Radiator upper bracket	Bent	111.80 F	*115.00 F
20	1		*A/C condenser	Bent	1,428.30 F	*1,350.00 F
21	1		*Radiator	Bent	580.80 F	*560.00 F
22	1		*Front support top panel	Bent	1,012.00 F	*1,020.00 F
23	1		*Front support panel top garnish	Not Necessary	480.00 F	*- F
24	1		*Bonnet stand	Broken	280.00 F	*135.00 F
<u>Supplementary #1</u>						
25	1		*Radiator Fan Motor Set	Cracked	776.80 F	*750.00 F
26	1		*Turbo Inter Cooler	Bent	689.80 F	*670.00 F
27	1		*Horn	Cracked	153.20 F	*155.00 F
28	1		*A/C Condenser Pipe Top	Bent	128.80 F	*130.00 F
29	1		*A/C Condenser Pipe Lower	Bent	178.00 F	*150.00 F
30	1		*A/C Suction Pipe	Bent	867.80 F	*870.00 F
31	1		*Electrical Parking Switch	Not Necessary	1,280.00 F	*- F
<u>Supplementary #2</u>						
32	1		*A/C Suction Pipe Lower	Not Necessary	380.00 F	*- F

F=Franchise part.

Total Parts (S\$)	15,589.70	11,766.00
--------------------------	------------------	------------------

LKK Auto Consultants Pte Ltd/SLJ6120C/12/03/2019 10:12. Not valid without Reference section.
--

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	A/C condenser piping oring set (NECESSARY)	50.00	50.00
2	1	Bonnet inner rubber strip clip set (NECESSARY)	30.00	30.00
3	1	Engine coolant (NECESSARY)	120.00	80.00
4	1	Front bumper clip set (NECESSARY)	60.00	60.00
5	1	Front support air guide clip set (NECESSARY)	30.00	30.00
6	1	Front support panel top garnish clip set (NECESSARY)	20.00	20.00
7	1	Radiator grille clip set (NECESSARY)	50.00	50.00
Sub Total (\$\$)			360.00	320.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To check and rectify wiring, socket and focus of head lamp	New	50.00	40.00
2	To R&R a/c condenser, radiator, turbo inter-cooler assy	New	150.00	150.00
3	To perform anti-rust coating pn affected areas	New	50.00	50.00
4	To repair, replace and realign damaged areas	New	900.00	700.00
5	To spray painting on affected areas	New	900.00	800.00
Gross Labour Cost (\$\$)			2,050.00	1,740.00

LKK Auto Consultants Pte Ltd/SLJ6120C/12/03/2019 10:12. Not valid without Reference section.

< END OF ESTIMATES >