Ax course.

(c) Resurvey

(d) Excess

(e) Signature of surveyor



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates	SI	ME 1743 C	1 Month on ha
arts (a) Cost / List Price Items	\$	11,778.75	Resurry Bapains
Plus/Less25%	\$	2,944.69	
Total of Cost / List	\$	8,834.06	LKK Auto Consultants hence notify the Repairer of the following;
(b) Nett Price Items			To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation.
Less		316	Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed
Total of Nett Item			 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
(c) Special Nett Items			Acknowledged by Repairer
otal Parts Cost			Signature: Date:
abour	\$	2,820.00	
otal	\$	11,654.06	
The above total will be subjected to	7% G.S.T.		
Name of Surveyor			Kennerh
Company			Clake
Survey conducted on	:		31/12/18 at
Remarks By Surveyor			
(a) The repair of this vehicle is	authorized	/ is not authorized u	until further notice.
(h) Recommended Days of Re			-6 day(s)

Required / Not Required

31/12/18

Date:



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

S	pa	re	Pa	rts

Vehicle No.	:
Make & Model	:
Chassis No	:

SME 1743 C

TOYOTA NOAH ZWR800334382

Submit By

Year Manufacture Engine No.

Carmen Lim

2018

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate garnish	1			
2	Front number plate garnish chrome LH	1	\$690.40		Pellar-
3	Front number plate garnish chrome RH	1			
4	Headlamp RH Min	1	\$3,001.75		
5	Front support panel (complete)	1	\$1,559.70		?
6	Front grille with chrome	1	\$798.30		?
7	Front grille garnish	1			
8	Front grille logo	1	\$72.70		7
9	Front grille clip	4	\$14.00		7
10	Front bumper &	1	\$1,997.60		
11	Front bumper clip n_{α}	10	\$40.00		
12	Front bumper reinforcement	1	\$322.70		7
13	Front bumper side retainer LH	Ľ 1	\$101.75		4
14	Front bumper side retainer RH	7 1	\$101.75		
15	Front bumper bracket LH	1	\$92.60		7
16	Front bumper bracket RH	1	\$92.60		7
17	Front bumper sponge	1	\$97.80		7
18	Front bumper lower grille	7 1			
19	Front bumper lower grille garnish Bu	- 1	\$198.33		
20	Front bumper lower grille garnish chrome] 1			
21	Fog lamp cover RH	1	\$191.12		
22	Washer tank	U 1	\$122.60		
23	Washer tank pump	~ 1	\$198.90		×

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Pa	irts
----------	------

Vehicle No. :	SME 1743 C	Submit By	:	Carmen Lim
Make & Model :	TOYOTA NOAH	Year Manufacture	:	2018
Chassis No :	ZWR800334382	Engine No.	:	

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	RH front fender Bv	ر 1	\$921.60		
25	RH front fender undershield c N	. 1	\$224.70		
26	RH front fender undershield clip //	. 10	\$35.00		
27	RHF fender wording "hybrid"	1	\$47.90		
28	Bonnet	1	\$793.40		X
29	Bonnet hinge RH	1	\$61.55		X
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Klo, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No.	:	SME 1743 C	Submit By :	Carmen Lim
Make & Model	: _	TOYOTA NOAH	Year of Manufacture:	2018

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (BONNET, SUPPORT PANEL, RHF FENDER,		
	RHF DOOR)	\$1,200.00	6001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (BONNET, SUPPORT PANEL, RHF FENDER,		
	RHF DOOR)	\$1,200.00	
3	To check wiring & focus headlamp	\$50.00	
4	To remove & refit radiator, condenser to assist work load,		
	to top up A/C gas.	\$150.00	
5	To do wheel alignment.	\$120.00	
6	To tuff coat	\$100.00	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.