

ASS REC BY: Menmen REF: CS3/MSG18002299/Gtd3-1 ⁵² Range
 From (Person): Irene Tan ASSIGNMENT (Office): MSIG Date/Time: 2/1/2019
 Estimated Cost: _____ Bill to: _____ Date/Time: 5/2/18 @ 2:24pm
 OD / IP / WS / IP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SKK 5360P Insured: SKC 5832L
 at Workshop no: V.2 Automotive Tel: 91855226
 of 1 Kaki Bkt Ave 6 #02-02
 Policy No: 29004870SMA Claim No: 518524
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A. 02/02/2018
 (Client's Record)
 CA / REV / REP. / REV 24 HRS lwp P.O.D. Endorsement: _____
 Date/Time: 535pm @ 5/2/18 Person Contacted: Ah huet Vehicle: IN/OUT

Date/Time	Action/Instruction (x) Estimate
	SKK 5360 - CC4/A-A13004783 / lwp / up
	SKC 5832L - CC4/A-A13004783 / lwp / up
	Dismantle: 6/2/2018
	After repair: 9/2/2018

Confirm. \$1900, 4 Days, Ured. 6912.64, 78%

4/4 - file pass to typist.

VZ Automotive Pte Ltd

1, Kaki Bukit Ave 6, Autobay @ Kaki Bukit, #02-02, Singapore 417883

Tel: 6555 7272 Fax: 6555 7272 Email: vzauto@iova.com.sg

Vehicle No. : SKK5360P

07/02/2016

Make/Model : Subaru Forester

Chassis No. : JF1SJGK85DG003358

Estimate cost of repairs to SKK5360P.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Nopic

Signature:

\$ 3.80

Date:

\$ 23.00

- 1 1 pc LHF headlamp
- 2 1 pc LHF headlamp lower bracket
- 3 1 pc Frt bumper
- 4 1 pc LHF bumper grille
- 5 1 pc LHF bumper fog lamp
- 6 1 pc LHF bumper fog lamp garnish
- 7 6 pcs Frt bumper clip
- 8 2 pcs Frt bumper retainer
- 9 1 pc Frt bumper reinforcement
- 10 1 pc LHF fender
- 11 1 pc LHF fender cowling
- 12 1 pc LHF shock absorber
- 13 1 pc LHF knuckle arm
- 14 1 pc LHF lower arm
- 15 1 pc LHF wheel hub assy
- 16 1 pc LHF drive shaft
- 17 1 pc LHF stabilizer link
- 18 1 pc LHF stay rod
- 19 1 pc LHF stay rod plate

\$ 1,214.00 BRV
 \$ 132.00 BRV
 \$ 60753.00 CUT
 \$ X 86.00 NN
 \$ X 286.00 NN
 \$ X 162.00 NN
 \$ 22.80
 \$ 46.00 } NECV
 \$ 398.00 NN
 \$ 423.00 X
 \$ 124.00 X
 \$ 389.00 X
 \$ 327.00 X
 \$ 528.00 X
 \$ 351.00 X
 \$ 1,084.00 X
 \$ 119.00 X
 \$ 136.00 X
 \$ 85.00 X
 \$ 6,665.80
 \$ 1,333.16
 \$ 5,332.64

Less Discount : 20%

- 1 1 pc LHF sport rim
- 2 1 pc LHF tyre
- 3 1 bot Brake fluid

S/N \$ 850.00 NN
 S/N \$ 450.00 NN
 S/N \$ 20.00 NN

- 1 To check front electrical system.
- 2 To remove, replace LHF undercarriage parts.
- 3 To conduct wheel alignment.
- 4 To spray anti-rust coating on new and affected panels.
- 5 To straighten, repair, realign LHF affected area and replace damaged parts.
- 6 To spray painting on affected area.

40.00 \$ -80.00
 NN \$ 300.00
 NN \$ 120.00
 NN x \$ 60.00
 400 \$ 800.00
 400.00 \$ 800.00
 Total : \$ 8,812.64

Repair days 4

2425.44

5 Feb 2018

TGrim
 27/12/18

Denise Tay (LKKAuto)

From: VZ auto <vzauto@iova.com.sg>
Sent: Thursday, 4 April 2019 3:46 PM
To: Denise Tay (LKKAuto)
Subject: Re: skk5360p

No choice accept lo..:(

On 1/4/2019 3:28 PM, Denise Tay (LKKAuto) wrote:

> Dear Anna,
>
> I've check with Guo Qiang, final offer is at
>
> Lump sum \$1900, 4days.
>
>
>
> Best Regards,
> Denise Tay | Case Handler
> LKK Auto Consultants Pte Ltd
> Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk
> 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)
>
> -----Original Message-----
> From: Denise Tay (LKKAuto)
> Sent: Thursday, 3 January 2019 4:50 PM
> To: 'VZ AUTO' <vzauto@iova.com.sg>
> Subject: RE: skk5360p
>
> Dear Anna,
>
> Offer lump sum \$3350. 4 working days.
>
> Please check and revert.
>
>
>
> Best Regards,
> Denise Tay | Case Handler
> LKK Auto Consultants Pte Ltd
> Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk
> 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)
>
> -----Original Message-----
> From: VZ AUTO <vzauto@iova.com.sg>
> Sent: Friday, 30 November 2018 11:59 AM
> To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
> Subject: skk5360p
>
> Hi Denise,
>
> Any updates on this?
>

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Feb 2018		05 Feb 2018 14:24 Edit Adj Rpt	S\$1,900.00 Edit Estimates	S\$1,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	WONG SOO HUAT , ID: S1782467H								
Main Claimant:	LEE ENG HONG , ID: S7619870E								
Vehicle Reg. No.:	SKK5360P	Date of Loss:	02/02/2018 00:00 - :59 [54 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 548524	Policy/Cover Note No.:	29004870SMA Coverage: 12/09/2017 - 11/09/2018						
Vehicle Reg. No. (Insured):	SKC5832L	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	V.z Automotive Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #02-02, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/04/2019]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
MSIG_SG (01/04/2019): Report Send Back Alerts - SKK5360P (TP)									
ALL ASSOCIATED TASKS			View All	Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKK5360P (548524)**
[SKC5832L]
TP
LEE ENG HONG
Feb 2 2018 12:00AM
[WONG SOO HUAT]
V.z Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/02/18 10:27	General View	 Load JPG	✓
2	27/02/18 10:27	General View	 Load JPG	✓
3	27/02/18 10:27	General View	 Load JPG	✓
4	27/02/18 10:27	General View	 Load JPG	✓
5	27/02/18 10:27	General View	 Load JPG	✓
6	27/02/18 10:27	General View	 Load JPG	✓
7	27/02/18 10:27	General View	 Load JPG	✓
8	27/02/18 10:27	General View	 Load JPG	✓
9	27/02/18 10:27	General View	 Load JPG	✓
10	27/02/18 10:27	General View	 Load JPG	✓
11	27/02/18 10:27	General View	 Load JPG	✓
12	27/02/18 10:27	General View	 Load JPG	✓
13	27/02/18 10:27	General View	 Load JPG	✓
14	27/02/18 10:27	General View	 Load JPG	✓
15	27/02/18 10:27	Odometer Reading	 Load JPG	✓
16	27/02/18 10:27	Chassis Number	 Load JPG	✓
17	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
18	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
19	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
20	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
21	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
22	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
23	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
24	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
25	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
26	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
27	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
28	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
29	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
30	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
31	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
32	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
33	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
34	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
35	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	☒
37	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	☒
38	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	☒
39	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	☒
40	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	☒
41	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	☒
42	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	☒
43	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	☒
44	27/02/18 10:28	Photo After Spray	 Load JPG	☒
45	27/02/18 10:28	Photo After Spray	 Load JPG	☒
46	27/02/18 10:28	Photo After Spray	 Load JPG	☒
47	27/02/18 10:28	Photo After Spray	 Load JPG	☒
48	27/02/18 10:28	Photo After Spray	 Load JPG	☒
49	27/02/18 10:28	Photo After Spray	 Load JPG	☒
50	27/02/18 10:28	Photo After Spray	 Load JPG	☒
51	27/02/18 10:28	Photo After Spray	 Load JPG	☒
52	27/02/18 10:28	Photo After Spray	 Load JPG	☒
53	27/02/18 10:28	Photo After Spray	 Load JPG	☒
54	27/02/18 10:28	Photo After Spray	 Load JPG	☒
55	27/02/18 10:28	Photo After Spray	 Load JPG	☒
56	27/02/18 10:28	Photo After Spray	 Load JPG	☒
57	27/02/18 10:28	Photo After Spray	 Load JPG	☒
58	27/02/18 10:28	Photo After Spray	 Load JPG	☒
59	27/02/18 10:28	Photo After Spray	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/02/18 14:22	PRI	 Load PDF	
2	05/02/18 14:22	EMAIL to TP reject their list of SJE	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/04/19 11:39	PRS INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18002299/GTD3S2-1
Date: 08/04/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29004870SMA
Claimant Vehicle No: SKK5360P Insured Vehicle No: SKC5832L
Date of Loss: 02/02/2018 Nature of Claim: TP Claim No: 548524

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKK5360P**
Make & Model: SUBARU FORESTER, 2.0 XT AWD CVT (A) Engine No: FA20G904228
Reg. Date: 30/07/2013 (Man. Year: 2012) Chassis No: JF1SJGK85DG003358
Colour: Black Odometer: 115519 km
Engine Capacity: 1998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50R18 Rear Tyre Size: 235/50R18
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,652.64	1,585.44	5,067.20	76.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	840.00	1,320.00	61.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,812.64	2,425.44	6,387.20	72.48
Approved Total (Overridden) (S\$)		1,900.00		
Nett Amount (S\$)	8,812.64	1,900.00	6,912.64	78.44

INSPECTION

Date of Assignment: 05/02/2018
Date Inspected: 05/02/2018 Inspected At: V.Z Automotive Pte Ltd (HQ)
1 Kaki Bukit Avenue 6 #02-02
Singapore 417883
Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 08 Apr 2019)

Parts: M1-SUV SUBARU FORESTER 2.0 XT AWD CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKK5360P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH HEADLAMP	Broken	1,214.00 FL	*1,214.00 FL
2	1		*LH HEADLAMP LOWER BRACKET	Broken	132.00 FL	*62.00 FL
3	1		*FRT BUMPER	Cut	753.00 FL	*660.00 FL
4	1		*LHF BONNET GRILLE	Not Necessary	86.00 FL	*- FL
5	1		*LHF BUMPER FOG LAMP	Not Necessary	286.00 FL	*- FL
6	1		*LHF BUMPER FOG LAMP GARNISH	Not Necessary	162.00 FL	*- FL
7	6		*FRT BUMPER CLIP	Necessary	22.80 FL	*22.80 FL
8	1		*FRT BUMPER RETAINER	N/s Deformed/O/s Not Necessary	46.00 FL	*23.00 FL
9	1		*FRT BUMPER REINFORCEMENT	Not Necessary	398.00 FL	*- FL
10	1		*LHF FENDER	Repair	423.00 FL	*- FL
11	1		*LHF FENDER COWLING	Not Necessary	124.00 FL	*- FL
12	1		*LHF SHOCK ABSORBER	Not Necessary	389.00 FL	*- FL
13	1		*LHF KNUCKLE ARM	Not Necessary	327.00 FL	*- FL
14	1		*LHF LOWER ARM	Not Necessary	528.00 FL	*- FL
15	1		*LHF WHEEL HUB ASSY	Not Necessary	351.00 FL	*- FL
16	1		*LHF DRIVE SHAFT	Not Necessary	1,084.00 FL	*- FL
17	1		*LHF STABILIZER LINK	Not Necessary	119.00 FL	*- FL
18	1		*LHF STAY ROD	Not Necessary	136.00 FL	*- FL
19	1		*LHF STAY ROD PLATE	Not Necessary	85.00 FL	*- FL
20	1		*LHF SPORT RIM	Not Necessary	850.00 FS	*- FS
21	1		*LHF TYRE	Not Necessary	450.00 FS	*- FS
22	1		*BOT BRAKE FLUID	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,985.80	1,981.80
- List Item Discount on L Items 20.00/20.00% (\$)	1,333.16	396.36
Total Parts (\$)	6,652.64	1,585.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT ELECTRICAL SYSTEM.	New	80.00	40.00
2	TO REMOVE, REPLACE LHF UNDERCARRIAGE PARTS.	New	300.00	0.00
3	TO CONDUCT WHEEL ALIGNMENT.	New	120.00	0.00
4	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.	New	60.00	0.00
5	TO STRAIGHTEN, REPAIR, REALIGN LHF AFFECTED AREA AND REPLACE DAMAGED PARTS.	New	800.00	400.00
6	TO SPRAY PAINTING ON AFFECTED AREA.	New	800.00	400.00
Gross Labour Cost (S\$)			2,160.00	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >