

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### **TAX INVOICE**

EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX SINGAPORE 069110 INV No. AC2004001

INV Date 19/05/2020

Reference CC4/EQI19000033/Uea3q2

Code EQI



### **PROFESSIONAL SERVICE FEE**

Vehicle No. GBD 3975Y

Insured Veh. SKD 2112X

Claim No. DM18HO03537/JT

Policy No. DMPPHQ18-004222

Accident Date 22/12/2018

Inspection Date 03/01/2019

Description	Total
Survey Inspection	230.00
Digital Photographs	
Transportation	
Subtotal	230.00
GST (7%)	16.10
Grand Total	246.10

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Affiliated to Federation Internationale Des Experts En Automobile						
EQ INSURANCE COMPANY LTD Ref: CC			CC4/EQI19000033	CC4/EQI19000033/Uea3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date :				
1.		Policy Particulars				
	ed Veh.	SKD 2112X	т —	nspected	GBD 3975Y	
	y No.	DMPPHQ18-004222	+	age (\$)	0.00	
<del></del>	n No.	DM18HO03537/JT	Exces		0.00	
	gn From	JANET	+	n Date	02/01/2019	
2.	<b>5</b>	Vehicle Partic				
	& Model	NISSAN CABSTAR (M)	c.c		2953	
	ne No.	HIDDEN		of Reg.	2014	
	sis No.	JN1SC2F24Z0856544	Colou		SILVER	
Odor	neter	123685	Steeri	 ng	IN ORDER	
Brak	es	IN ORDER	Modifi	cation	NIL	
Gene	ral	GOOD				
3.		Condition	ons of	Tyres		
		Size	Make		Balance	
R/H F	ront Tyre	195 R15	COND	OR	6 mm	
L/H F	ront Tyre	195 R15	COND	OR	6 mm	
	Rear Tyre	155 R13 (D)	COND	OR	6/6 mm	
	Rear Tyre	155 R13 (D)	COND	OR	6/6 mm	
4.		Description				
THE \	/EHICLE SU	STAINED DAMAGES AT THE O/S	REAR	PORTION.		
DAMA	AGES SEE D	ETAILS.				
5.		General	Inform	ation		
	dent Date	22/12/2018	Insped	ction Date	03/01/2019	
Surv	ey held at	ABWIN SERVICE PTE LTD				
	No. 8 KAKI BUKIT AVENUE 4 #07-48 PREMIER@KAKI BUKIT GATE 2 SINGAPORE 415875					
5a.		Re	emarks			
A)THE B)IN A	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					
ESTIN	MATED NORI	MAL PERIOD FOR REPAIR:		3 Working Days		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 3975Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	1,699.70	-
1	TAILGATE HINGE RH	NOT NECESSARY	95.70	-
1	TAILGATE HINGE LH	NOT NECESSARY	95.70	-
1	TAILGATE LOCK CATCH RH	TO REPAIR SEE LABOUR	210.40	-
1	TAILGATE LOCK CATCH LH	NOT NECESSARY	210.40	-
2	TAILGATE STOPPER RH	TORN	30.00	30.00
2	TAILGATE STOPPER LH	NOT NECESSARY	30.00	-
1	RH TAILLAMP	NOT NECESSARY	280.60	-
1	RH TAILLAMP PANEL	TO REPAIR SEE LABOUR	95.60	-
1	RH TAILLAMP BRACKET	NOT NECESSARY	102.60	-
1	RH TAIL DOOR	TO REPAIR SEE LABOUR	3,600.60	-
2	RH TAIL DOOR HINGE BOTTOM	NOT NECESSARY	190.60	-
1	RH REAR FENDER	BUCKLED	185.80	185.80
	LESS 10% DISCOUNT		-682.77	-21.58
			6,144.93	194.22
	SPECIAL NETT ITEMS			
1	RH REAR FENDER MUFLAP (SN)	TORN	150.00	150.00
1	EXHAUST MUFFLER (SN)	NOT NECESSARY	855.60	-
1	RH REAR TYRE (SN)	NOT NECESSARY	350.00	-
1	RH REAR WHEEL RIM (SN)	NOT NECESSARY	450.00	-
			1,805.60	150.00
	LABOUR			
	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS.INCLUSIVE OF THE REPAIR OF TAILGATE LOCK CATCH RH,RH TAILLAMP PANEL AND RH TAIL DOOR .		2,500.00	500.00
	TO SRPAY PAINT ON AFFECTED AREAS.		2,500.00	500.00
	TO CHECK LIGHTING AN FOCUS TAILLAMP .		150.00	20.00
	TO TRANSFER & REFIX LH SLIDING DOOR FIXTURE & FI	NOT NECESSARY	250.00	-

Report Ref No. CC4/EQI19000033/Uea3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

1,100.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO TRANSFER & INSTALL TAILGATE COMPONENTS.	NOT NECESSARY	250.00	-
	TO TRANSFER REAR WINDSCREEN FITTING.	NOT NECESSARY	150.00	-
	TO REFIX RH SLIDING DOOR GLASS .	NOT NECESSARY	150.00	-
	TO APPLY TUFF KOTE.		150.00	30.00
	TO WHEEL ALIGNMENT AND TYRE BALANCING.	NOT NECESSARY	200.00	-
			6,300.00	1,050.00
	GRAND TOTAL		14,250.53	1,394.22

Report Ref No. CC4/EQI19000033/Uea3q2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

CHUA KANG SENG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBD 3975Y



















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315

