

AXA INSURANCE PTE LTD

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

CS3/ASM19000047/Bpa3s2

PRE-REPAIR INSPECTION REPORT

8 SHENTON WAY #24-01 AXA TOWERSINGAPORE Date: 18-03-2020

ATTN: SHARON LIM Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XE 3162K	Veh. Inspected	GBG 3879B	
	Policy No.	GA406054/1	Coverage (\$)	0.00	
	Claim No.	S8M01700	Excess (\$)	0.00	
	Assign From	SHARON LIM	Assign Date	02/01/2019	
2.	2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE DX 3.0 AUTO	c.c	2982	

۷.	venicle Particulars & Condition			
	Make & Model	TOYOTA HIACE DX 3.0 AUTO	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	KDH2015025392	Colour	SILVER
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	POOR		

		,		
3.	Conditions of Tyres			
		Size	Make	Balance
	R/H Front Tyre	195/80 R15	BRIDGESTONE	6 mm
	L/H Front Tyre	195/80 R15	BRIDGESTONE	6 mm
	R/H Rear Tyre	195/80 R15	BRIDGESTONE	6 mm
	L/H Rear Tyre	195/80 R15	BRIDGESTONE	6 mm

4.	Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY



Page No.:1 of 1

5.	General Information			
	Accident Date	17/12/2018	Inspect Date / Time	02/01/2019 (02:40 PM)
	Survey held at	YONG SING MOTOR WORKS		
		10 DEFU LANE 8 DEFU INDUSTRIAL ESTATE SINGAPORE 539315		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B)THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C)ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,000-\$11,000

5b. **Estimate Days of Repair** 7 Working Days ESTIMATED NORMAL PERIOD FOR REPAIR:

Report Ref No. CS3/ASM19000047/Bpa3s2

Inspected By

LIM TEOW GUAN

HO LEONG CHUAN Automotive Assessor

Automotive Assessor