

ASS. REC. BY:

REF: CS/FCL19000101/Drbn2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

WLS Surme Ler.

of

FCL.

Date/Time:

02012019 659pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SH 8159G

Insured:

SHC 8099C

at Workshop m/s

Chunni Motors

Tel:

65425119

of

Blk 10 Amk Ind Amk 2A #01-05

Policy No:

Claim No:

D19000119MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21.12.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

02012019

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SH 8159G - CCS / AT113013429 / Ysb392

DA: 23072013

SHC 8099C - CS / SMO18021291 / Kivd5n2

DA: 2202018

11/1/19

Email preli revised to FCI

REF:

ASSIGNMENT

COR April 2024

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 129 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH 8159 GYr Regn: 2010 AprilType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40C.C. 1685Colour: Blue

A/C Insured / Std / NI / NA

Sp. Reading: 384617

T/Radio: Insured / Std / NI / NA

Eng/No: D4FDFU607402C/No: KMHLEB41UMGU087116Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

205/60 R16

R: _____

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Campion

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 29/12/2018D.O.I. 03/01/2019Survey held at Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

4/3 Front 7 0/3 Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

First Capital SHC 8099C01/03/19 Jumper 2/3 14650/- with 12 days of rev. (Red 12,382.28, 4570)

RECEIVED 07 MAR 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 7/3- typistReport Format: CWSLump Sum / I.B.I: (\$) 14,650/-Days Of Repair: 12Resurvey No. of Trip: 2Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

7/3/19

TOTAL

17x15 = 255170 + 2555050 + 50190765



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19000119MFSH

Our ref: CS/FCI19000101/Dvb

Date: 11/1/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SH 8159G


We thank you for your instruction on 2/1/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 3/1/2019 at the premises of M/s CHUNNI MOTOR WORK PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$27,032.28
Revised Estimate Amount	: S\$18,315.80
"Check" Items Amount	: S\$
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s front and o/s front portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Bryan Ang
Motor Surveyor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	02-01-2019	Our Ref No. D19000119MFSH
Accident Date	29-12-2018	Claim Type. Third Party
Insured Vehicle	SHC8099C	Third Party Vehicle. SH8159G
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 65425119	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE: EST. COR - \$25,921.88	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 11 January 2019 9:54 AM
To: 'CWS Motor Claims'
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000119MFSH/1,SH 8159G
Attachments: SH 8159G PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SH 8159G
Date of survey: 3/1/2019
Number of days : 9 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 2 January 2019 7:08 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000119MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 2 January, 2019 6:59 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000119MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

REPAIR ESTIMATE*

DATE : 31.12.2018

TEL : 6542 5119

FAX : 6542 6039

FCI

QTY	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover New cut			\$ 1,052.20 ✓
	Front Bumper Bracket (RH) NW			\$ 24.60 X
	Headlamp Support Panel Assy broken			\$ 907.40 ✗ ✓
	Front Fender (RH) Dented			\$ 566.30 —
	Front Fender Shield (RH) torn			\$ 174.90 —
	Front Door (RH) Dented			\$ 2,256.40 —
	Front Door Gear / Regulator (RH) NW			\$ 250.60 X
	Front Door Mirror Assy (RH) Crack			\$ 670.00 ✓
	Front Door Power Motor,(RH) NW			\$ 296.40 X
	Rocker Panel Outer Garnish St			\$ 341.40 —
	Front Windscreen Moulding H/LC			\$ 113.30 —
	Front Windscreen Pillar Outer(RH) Dented			\$ 1,745.50 —
	Front Wheel Rim (LH/RH) & distorted St	S	325.30	\$ 650.60 ✗ ✓
	Front Wheel Hub Cap (LH/RH) cut St	S	107.10	\$ 214.20 —
	Front Wheel Bearing & Dam	S	540.50	\$ 1,081.00 ✗ ✓
	Front Shock Absorber (Assy) (LH/RH) & distorted	S	342.20	\$ 684.40 ✗ ✓
	Front Shock Absorber Mounting (LH/RH) NW	S	108.80	\$ 217.60 X
	Front Drive Shaft (LH/RH) & Dam/distorted	S	1,030.80	\$ 2,061.60 ✗ ✓
	Rack & Pinion Assy & Dam			\$ 969.60 ✗ ✓
	STG Tie End & distorted	S	62.60	\$ 125.20 ✗ ✓
	Stabilizer Bar & distorted			\$ 252.30 ✗ ✓
	Stabilizer Bar Bush (LH/RH) NW	S	16.40	\$ 32.80 X
	Stabilizer Bar Link & distorted	S	61.10	\$ 122.20 ✗ ✓
	Stabilizer Bracket & NW	S	24.00	\$ 48.00 ✗ X
	Front Suspension Lower Arm (LH/RH) & distorted	S	529.30	\$ 1,058.60 ✗ ✓
	Knuckle Arm (LH/RH) & distorted	S	552.00	\$ 1,104.00 ✗ ✓
	Engine Under Cover NW			\$ 334.60 X
	Engine Crossmember & distorted			\$ 2,094.40 ✗ ✓
	ABS Sensor NW	S	234.00	\$ 468.00 X
	Electric Power Steering NW photo taken			\$ 4,880.50 X
	SUB TOTAL			\$ 24,798.60
	LESS 20%			\$ 4,959.72
	DISCOUNTED TOTAL			\$ 19,838.88
	Front Fender Advertisement Logo (RH) H/LC			\$ 100.00 Nett ✓
	Front Door Comfort Logo (RH) H/LC			\$ 75.00 Nett ✓
	Front Door Advertisement Logo (RH) H/LC			\$ 100.00 Nett ✓
	Front Windscreen Sealant H/LC			\$ 46.00 Nett ✓
	Front Tyre (LH/RH) W/S cut o/z NW 50% dep	S	216.00	\$ 432.00 Nett ✓ 108.00
				\$ 753.00

Amount

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SH 8159G (Supplementary)

DATE : 3.01.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Headlamp (RH) mounting broken			\$ 1,388.00
	SUB TOTAL			\$ 1,388.00
	LESS 20%		1388.00	\$ 277.60
	DISCOUNTED TOTAL		1110.40	\$ 1,110.40
	 LKK Auto 			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SH 8159 G

Technician:

Mileage: 384617

Time Printed 3.1.19 11:08 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
8°04'		-3°00' 3°00'
3°44'		-0°19' 5°41'
7°12'		-1°30' 1°30'
8°56'		
17°00'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
9°03'		-3°00' 3°00'
3°46'		-0°19' 5°41'
5°50'		-1°30' 1°30'
6°19'		
15°23'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-0°59'		-3°00' 3°00'
-0°02'		-3°00' 3°00'
2°37'		-3°00' 3°00'
13°02'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
0°09'		-3°30' 2°30'
0°12'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
0°06'		-3°30' 2°30'
0°43'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
0°03'		-3°00' 3°00'
0°55'		-3°00' 3°00'
-0°15'		-3°00' 3°00'

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FC119000101/Dvbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 08-03-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8099C	Veh. Inspected	SH 8159G
Policy No.		Coverage (\$)	0.00
Claim No.	D19000119MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	02/01/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU087116	Colour	BLUE
Odometer	384617	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	CAMPEON	5 mm
L/H Front Tyre	205/60 R16	CAMPEON	5 mm
R/H Rear Tyre	205/60 R16	CAMPEON	5 mm
L/H Rear Tyre	205/60 R16	CAMPEON	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT AND O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/12/2018	Inspection Date	03/01/2019
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8159G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER COVER	CUT	1,052.20	1,052.20
1	FRONT BUMPER BRACKET (RH)	NOT NECESSARY	24.60	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	907.40	907.40
1	FRONT FENDER (RH)	DENTED	566.30	566.30
1	FRONT FENDER SHIELD (RH)	TORN	174.90	174.90
1	FRONT DOOR (RH)	DENTED	2,256.40	2,256.40
1	FRONT DOOR GEAR/REGULATOR (RH)	NOT NECESSARY	250.60	-
1	FRONT DOOR MIRROR ASSY (RH)	CRACKED	670.00	670.00
1	FRONT DOOR POWER MOTOR (RH)	NOT NECESSARY	296.40	-
1	ROCKER PANEL OUTER GARNISH	BENT	341.40	341.40
1	FRONT WINDSCREEN MOULDING	NECESSARY	113.30	113.30
1	FRONT WINDSCREEN PILLAR OUTER (RH)	DENTED	1,745.50	1,745.50
2	FRONT WHEEL RIM (LH/RH) @\$325.30	DISTORTED / BENT	650.60	650.60
2	FRONT WHEEL HUB CAP (LH/RH) @\$107.10	CUT / BENT	214.20	214.20
2	FRONT WHEEL BEARING @\$540.50	DAMAGED	1,081.00	1,081.00
2	FRONT SHOCK ABSORBER (ASSY)(LH/RH) @\$342.20	DISTORTED	684.40	684.40
2	FRONT SHOCK ABSORBER MOUNTING (LH/RH) @\$108.80	NOT NECESSARY	217.60	-
2	FRONT DRIVE SHAFT (LH/RH) @\$1030.80	DAMAGED / DISTORTED	2,061.60	2,061.60
1	RACK & PINION ASSY	DAMAGED	969.60	969.60
2	STG TIE END @\$62.60	DISTORTED	125.20	125.20
1	STABILIZER BAR	DISTORTED	252.30	252.30
2	STABILIZER BAR BUSH (LH/RH) @\$16.40	NOT NECESSARY	32.80	-
2	STABILIZER BAR LINK @\$61.10	DISTORTED	122.20	122.20
2	STABILIZER BRACKET @\$24.00	NOT NECESSARY	48.00	-
2	FRONT SUSPENSION LOWER ARM (LH/RH) @\$529.30	DISTORTED	1,058.60	1,058.60
2	KNUCKLE ARM (LH/RH) @\$552.00	DISTORTED	1,104.00	1,104.00
1	ENGINE UNDER COVER	NOT NECESSARY	334.60	-
1	ENGINE CROSSMEMBER	DISTORTED	2,094.40	2,094.40
2	ABS SENSOR @\$234.00	NOT NECESSARY	468.00	-

Report Ref No. CS/FCI19000101/Dvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HEADLAMP (RH)(ADDITIONAL)	MOUNTING BROKEN	1,388.00	1,388.00
1	ELECTRIC POWER STEERING	NOT NECESSARY	4,880.50	-
	LESS 20% DISCOUNT		-5,237.32	-3,926.70
			20,949.28	15,706.80
	SPECIAL NETT ITEMS			
1	FRONT FENDER ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00
1	FRONT DOOR COMFORT LOGO (RH)(SN)	NECESSARY	75.00	75.00
1	FRONT DOOR ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
2	FRONT TYRE (LH/RH) @\$216.00 (50%)(SN)	N/S CUT / O/S NOT NECESSARY	432.00	108.00
			753.00	429.00
	LABOUR			
	PANEL BEATING.		1,600.00	800.00
	SPRAY PAINTING CHARGE.		1,400.00	600.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	TRANSFER OF DOOR.		120.00	60.00
	REMOVE/REFIX UNDERCARRIAGE (FRT).		200.00	180.00
	FRT WHEEL ALIGNMENT.		120.00	60.00
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	150.00	-
	REMOVE/REFIX DASHBOARD.		450.00	150.00
	REMOVE/REFIX FRONT WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX CUSHION & UPHOLSTERY FRONT.	NOT NECESSARY	90.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE. }		480.00	180.00
	RE-SET FRT ABS SYSTEM. }		200.00	-
	RE-SET FRT POWER WINDOW SYSTEM. }		200.00	-
			5,330.00	2,180.00
	GRAND TOTAL		27,032.28	18,315.80



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			14,650.00
---	--	--	-----------

Report Ref No. CS/FCI19000101/Dvbn2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.