
4

# REPUBLIC OF SINGAPORE







LIM KIAN KOK

林建国 Reco CHINESE

Date of Surp. 30 - 11 - 1956 Country of Birth SINGAPORE





COMFORTOELGRO ENGINEERING PIE LTD 45 PANDAN ROAD SINGAPORE 609285







COMFORTDELGRO ENGINEERING PTE LTD 45 PANDAN ROAD SINGAPORE 509285













































Cheong Auto Pte Ltd
262 Queensway (ESSO Petrol Station )
Singapore 149081
Tel: 64720121 Fax: 64723517 GST regn.no.M200500539

Ref:

Jay/CAPL/SBC666P

Date:23.08.2018

Attn:

Chua Chen How

Proforma Invoice no.

CA30166

Re:

SBC666P Mercedes E250

Qty

Amount

Repair costs as per surveyor's report LEE/TP/07/2138/18 dated

08.08.2018

\$10,500.00

\$10,500.00 Subtotal \$735.00 7% Gst \$11,235.00

Total amount due

Thunk you Yours Sincerely

Jason Cheong



CORRESPONDENCE: BUKIT PANJANG POST OFFICE P.O.BOX 244, SINGAPORE 916809 FAX: (65) 6763 3827, HANDPHONE: 8188 2833

BUSINESS REG. NO.: 52891429D

TO:

CHUA CHEN HOW

c/o 262 QUEENSWAY SINGAPORE 149061 INVOICE NO. L18080959

YOUR REF

OUR REF LEE/TP/07/2138/18

DATE 08 AUG 2018

AMOUNTS (S\$) PARTICULARS SBC 666 P VEHICLE REGISTRATION NO. MERCEDES BENZ E250 MAKE/MODEL TO OUR PROFESSIONAL CHARGES FOR X INSPECTION OF VEHICLE X APPRAISAL REPORT x PHOTOGRAPHY \$782.00 \* TRANSPORT CHARGES REINSPECTION OF VEHICLE AUTOMOTIVE CONSULTATION X CORRESPONDENCE, POSTAGE & OTHER DISBURSEMENT OTHERS SEVEN HUNDRED AND EIGHTY TWO ONLY DOLLARS:

(\* CHEQUE SHOULD BE CROSSED AND MAKE PAYABLE TO "LEE AUTOMOBILE APPRAISERS SERVICES")





CORRESPONDENCE: BUKIT PANJANG POST OFFICE P.O.BOX 244, SINGAPORE 916809

FAX: (65) 6763 3827, HANDPHONE: 8188 2833

BUSINESS REG. NO.: 52891429D

TO: CHUA CHEN HOW c/o 262 QUEENSWAY SINGAPORE 149061 OUR REF.LEE/TP/07/2138/18 DATE 08 AUG 2018

# AUTOMOBILE APPRAISAL REPORT

Vehicle Registration No.

: SBC 666 P

Make/Model

: Mercedes Benz E250

Year Manufacture/Register

: 2012

Colour

: Silver

Engine No.

: Obscure

Chassis No.

: WDD2120472A580935

Mileage

: 123624km

Nature Of Inspection

: Third Party

Date Of Accident

: 01 July 2018

Date Of Accident

: 09 July 2018

Name of Workshop

: Cheong Auto Pte Ltd

: 262 Queensway

: Singapore 149061

#### YRE CONDITION ON VEHICLE

Location	Make	Size	Thread Balance
Nearside Front	Michelin	265/35ZR18	8mm
Offside Front	Michelin	265/35ZR18	8mm
Nearside Rear	Michelin	265/35ZR18	8mm
Offside Rear	Michelin	265/35ZR18	8mm

<sup>\*(</sup>The above represent on estimated remaining life of the tyre thread in mm)

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The damages sustained on the vehicle were apparently confined at its rear portion. (Details are describe in the attached schedule).

NOTE: This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items in this survey, kindly notify the company within (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.



CORRESPONDENCE: BUKIT PANJANG POST OFFICE P.O.BOX 244, SINGAPORE 916809 FAX: (65) 6763 3827, HANDPHONE: 8188 2833

BUSINESS REG. NO.: 52891429D

#### APPRAISEMENT SCHEDULE

Vehicle Registration No: SBC 666 P

Our Ref. LEE/TP/07/2138/18

NO.	Qty	Description	Comments/	Repairer's	Assessed	
53066	arati	2500405 TNO 55	Conditions	Estimate	Amount	
		(LIST ITEMS)		£ 1,500,00	\$ 1,580.00	Cu7
1		Rear bumper	distorted/cut	\$ 1,580.00		
2		Rear bumper lower lid	distorted/cut	\$ 500.00	\$ 500.00	
3		Rear bumper inner garnish -centre	torn	\$ 171.00	\$ 171.00	Xº
4		Rear bumper side bracket	essential	\$ 45.00	\$ 45.00	
- 5		Rear bumper reinforcement	bent/oblique	\$ 898.00	\$715 898.00	
6		Boot cover	distorted/cut	\$ 2,100.00	\$ / 2,100.00	DD.
7	1	Boot cover "Mercedes" logo emblem	essential	\$ 45.00	S 45.00	1
8	1	Boot cover E200 emblem	essential	\$ 66.00	\$ < 66.00	YN
9		Boot cover "7G- Tronic"	essential	\$ 98.00	\$ ~98.00	IJ
	1	7   TO STEP BY BY THE STEP STEP STEP STEP	bent/cut	\$ 270.00	\$ 270.00	NN
.0		Boot cover inner lock	broken	\$ 460.00	\$ 460.00	BR
11	1	Boot cover reflector lamp	essential	\$ 170.00	\$ 170.00	Part of the last
12		Boot cover rubber	broken	\$ 640.00	\$53650640.00	BR
13		1 Taillamp		\$ 125.00		
14		Rear end panel garnsh	bent/deformed	\$ 1,326.00	S 125.00 S 1.326.00	RX
15		Rear end panel	distorted/bent		N. 40 Co., 40	NN
16	1	I Rear tow cover	cut	\$ 95.00	5 -95:00	15
17		1 Rear exhaust chrome finisher	cut/bent	\$ 349.00	\$ 349.00	EN
18		t Rear exhaust silencer	bent Four TU	\$ 1,596.00	\$ 1.596.00	17
			5745.50 10%	\$ 10,534.00	\$ 10,534.00	
		Less 10%	1,5		\$ (1,053.40)	
		Sub total parts	1060	\$ 10,534.00	\$ 9,480.60	
			5170.95	A011-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0		
		(SPECIAL NETT ITEMS)	2110.0			
9			shorted/cut	\$ 256.00	\$ 207 -0256:00	cu
	1	Rear bumper reverse sensor	Siturted	, a		
		Total parts	300	\$ 10,790.00	\$ 9,736.60	
		To check rear wiring & function including to remove & refix rear reverse sensor.	1220	\$ 150.00	\$ 60-00 100.00	
		9		1 1 43 C 0 10 10 10 10 10 10 C	S 1,200.00	100
		Labour charge as recommended for repaired & replaced damaged parts.		\$ 1,400.00		
		To putty and spraypainting including touch up all affected areas.		\$ 1,450.00	\$ 1,200.00	
		To apply rustproof treatment to the repaired/replaced panels.		\$ 180.00	S 60:00 120:00	
		To remove & refix rear exhaust silencer.	5170.98	\$ 250.00	\$ 150.00	X
		To mount vehicle onto chassis alignment bench to facilitate repair.	260,00	5 800.00	\$ 600.00	NN
		to mount venuere onto chassis augmnent bench to tachtate tepan.	1270.00			
			7590.95	52727	6 4s-51	5
			GRAND TOTAL	\$ 15,020.00	\$ 13,106.60	1

MV 75K-76K

Repair days 4



CORRESPONDENCE : BUKIT PANJANG POST OFFICE P.O.BOX 244, SINGAPORE 916809 FAX: (65) 6763 3827, HANDPHONE: 8188 2833

BUSINESS REG. NO.: 52891429D

Vehicle Number: -SBC 666 P

Our Ref: LEE/TP/07/2138/18

#### ASSESSMENT SUMMARY

The damages sustained on the vehicle were thoroughly inspected and every item that was mentioned in the repair estimate against the actual damages found on the vehicle. Before we arrived at our recommendation as to whether the parts needed to be replaced or repair.

We have listed the breakdown of our finding and our recommendation as per schedule attached.

Our assessment to reinstate the vehicle is \$13106.60 revised amount of the repairer's estimate of \$15020.00. The aforesaid recommendation, in our opinion, is fair and reasonable for the restoration of the vehicle to its pre-accident condition.

However, after taken into consideration the age and condition of the vehicle and the availability of the recondition components and to economize the repair, we therefore recommend a contract *Lump Sum* at \$10500.00 corresponding to supply of parts, labour and spraypainting charges.

57 photographs were taken at the times of static inspection.

Under normal circumstances, the repairs should be completed within a reasonable period 05 full working day

This inspection was conducted entirely on a 'Without Prejudice' basis and we have not given authorization and instruction to the repairer to proceed with the repair.

We are reverting the matter to you for your discretion.

Very truly yours

大の関係

K. W. LEE DIP Auto. Engrg MIAME, AMIMI, CAE, ENG. TECH, MSAE, AMIRTE, AMSOE AUTOMOTIVE ENGINEER ASSESSOR



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internat	onale Des Experts En Autom	nobile
SON	PO INSURANCE	SINGAPORE PL	Ref : CS3/SMO1801	2149/R1qbs2-1
#05-	AFFLES PLACE 01/06 GAPORE LAND TO	WERSINGAPORE 048623	Date: 08-02-2019	
			Code: SMO	
1.			s :- THIRD PARTY CLA	
	Insured Veh.	SLP 5939H	Veh. Inspected	SBC 666P
	Policy No.	D18MTPV01010339	Coverage (\$)	0.00
	Claim No.	CMTD1802813/AGC	Excess (\$)	0.00
	Assign From	AGNES CHAN	Assign Date	03/01/2019
2.		Vehicle Par	ticulars & Condition	
	Make & Model	MERDECES BENZ E 250	c.c	1796
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	WDD2120472A580935	Colour	GREY
	Odometer	123624	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3.		Condi	tions of Tyres	TELLIN LISTER SERVICE
	ĮL.	Size	Make	Balance
	R/H Front Tyre	265/35Z R18	MICHELIN	6 mm
	L/H Front Tyre	265/35Z R18	MICHELIN	6 mm
	R/H Rear Tyre	265/35Z R18	MICHELIN	6 mm
	L/H Rear Tyre	265/35Z R18	MICHELIN	6 mm
4.		Descrip	tion of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE R	EAR O/S PORTION.	
5.			ral Information	March 1981
	Accident Date	01/07/2018	Inspection Date	09/07/2018
	Survey held at	CHEONG AUTO PTE LTD	Later to the control of the control	
		262 QUEENSWAY SINGAPORE 149061		
5a.			Remarks	
	A)THE INSPECTION B)IN ACCORDANG	ON WAS CONDUCTED ON A"W CE TO YOUR INSTRUCTIONS,	ITHOUT PREJUDICE" BAS WE HAVE NOT AUTHORIS	SIS. SED REPAIRS.
5b.			e Days of Repair	SOUTH COURT IN CLICK
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	4 Working Da	ys



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBC 666P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CUT	1,580.00	1,510.00
1	REAR BUMPER LOWER LID	TO REPAIR SEE LABOUR	500.00	
1	REAR BUMPER INNER GARNISH - CENTRE	SERVICEABLE	171.00	
1	REAR BUMPER SIDE BRACKET	NECESSARY	45.00	45.00
1	REAR BUMPER REINFORCEMENT	BENT	898.00	715.00
1	BOOT COVER	DENTED	2,100.00	2,100.00
1	BOOT COVER "MERCEDES" LOGO EMBLEM	NECESSARY	45.00	45.00
1	BOOT COVER E200 EMBLEM	NECESSARY	66.00	66.00
1	BOOT COVER "7G- TRONIC"	NECESSARY	98.00	98.00
1	BOOT COVER INNER LOCK	NOT NECESSARY	270.00	
1	BOOT COVER REFLECTOR LAMP	BROKEN	460.00	460.00
1	BOOT COVER RUBBER	SERVICEABLE	170.00	
1	TAILLAMP	BROKEN	640.00	536.50
1	REAR END PANEL GARNISH	NOT NECESSARY	125.00	
1	REAR END PANEL	TO REPAIR SEE LABOUR	1,326.00	
1	REAR TOW COVER	NOT NECESSARY	95.00	
1	REAR EXHAUST CHROME FINISHER	NOT NECESSARY	349.00	
1	REAR EXHAUST SILENCER	NOT NECESSARY	1,596.00	
	LESS 10% DISCOUNT		-	-557.55
			10,534.00	5,017.95
	SPECIAL NETT ITEMS			
1	REAR BUMPER REVERSE SENSOR (SN)	CUT	256.00	200.00
3.72	STIDLINAY SCHOOLS FOR TO PROPER AND SERVICE WARRING PROPERTY TO SERVICE PROPERTY AND A SERVICE		256.00	200.00
	LABOUR			
	TO CHECK REAR WIRING & FUNCTION INCLUDING TO REMOVE & REFIX REAR REVERSE SENSOR.		150.00	60.00
	LABOUR CHARGE AS RECOMMENDED FOR REPAIRED & REPLACED DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER LOWER LID AND REAR END PANEL.		1,400.00	500.00
	TO PUTTY AND SPRAY PAINTING INCLUDING TOUCH UP ALL AFFECTED AREAS.		1,450.00	600.00
	TO APPLY RUSTPROOF TREATMENT TO THE REPAIRED / REPLACED PANELS.		180.00	60.00

Report Ref No. CS3/SMO18012149/R1qbs2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIX REAR EXHAUST SILENCER.	NOT NECESSARY	250.00	-
	TO MOUNT VEHICLE ONTO CHASSIS ALIGNMENT BENCH TO FACILITATE REPAIR.	NOT NECESSARY	800.00	8
			4,230.00	1,220.00
	GRAND TOTAL		15,020.00	6,437.95

RECOMMENDED COST OF LUMP SUM REPAIRS	5,150.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS3/SMO18012149/R1qbs2-1

MARKET VALUE: 76,000.00

LTA: 70,762.00

NETT VALUE: 5,238.00

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.