

INS. CASE OWNER:

Chae Henry
NGZ

CC 3, MG 1900

0123

NFA30

LKK:
IDAC:

Surveyor:

DOI:

ASSIGNMENT

21/19

Date / Time:

21/19

Registered in Merimen:

21/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLH 1072B

Claim No.:

Name of Insured:

ONG CHY YOO

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II : S5

D.O.A.:

28/12/2018

Place of Accident:

PIE

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

NFB 1382 → SLH 1072B

→ SHB 18840

→ SKA 8827T

→ SKM 4848 X → SHB 71



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

GMP. m

7p



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

10/1
cpeSHB 18840 - M1001 4012057/1619 bus : 009 : 4/9/14
SLH 1072B - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

21/1/19

OK

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

cy - LOR - should be \$2374.28

7 M1001 4012057/1619 bus : 009 : 4/9/14

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: NRE

Repair Cost:

40

S\$24,550

(

14

days) Reduction:

69

%

Email

Call

FINAL SETTLEMENT

Date/Time: 08.10.19

Confirm with: LEE GAK

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 28

If NO or B 28, Ass. Lia : 0%

Repair Cost:

S\$24,550.00

Loss of Rental (LOR):

S\$ 2,014.28

(

23

days) * 100.26

Loss of Use (LOU):

S\$ -

(\$

x

days)

Loss of Income (LOI):

S\$ 1,150.00

(\$ 50

x

23 days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

S\$ 7.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 28,081.28

Global Sum S\$:

FINAL PAYMENT

Date/Time: 08.10.19

Confirm with: LEE GAK

Email

Call

Payee 1:

S\$ 28,081.28

Name 1:

SMART TANS PTE LTD

Payee 2 (if any):

S\$ -

Name 2:

Payee 3 (if any):

S\$ -

Name 3:

Payee 4 (if any):

S\$ -

Name 4:



Payee 5 (if any):

S\$ -

Name 5:

Section A - Accident Details

Registration Number	SHB1864D
Case Reference Number	TAX/12/18/2120
Registration Date	25/6/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	YEO NGEE BOON
Type of Accident	Head to Rear
Accident Date and Time	28/12/2018 5:10 PM
Accident Reported Date and Time	29/12/2018 11:35 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	28/12/2018 5:45 PM
Replacement Vehicle issued?	No
Job Card Number	24099461
Special Instruction to ARC, if any	TOWED \$90
Prepared Date and Time	31/12/2018 10:59 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates:

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$3,504.00	\$1,400.00
Total Spray Cost	\$6,498.00	\$1,080.00
Total Spare Part Cost	\$64,218.00	\$22,445.45
Total Other Cost	\$4,410.00	\$1,430.00
TOTAL COST	\$78,628.00	\$26,355.45
Lump Sum Total	\$78,650.00	\$26,350.00 (L/S)
Number of Repair Days	18.0	14.0
Prepared / Adjusted By	Zhi Yang Phua	Naz (LKK) / AIG
ARC / Surveyor Sign Off Date	18/01/2019 11:16 AM	17/01/2019 2:20 PM
Signature		
Remarks		LUMP SUM REPAIR 10 DAYS CHECK ITEMS PHOTOS AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Two party survey is on a "Without Prejudice" basis
- No repair modification(s) is allowed
- Supplemental item(s) must be resurveyed and approved from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1902-0063	Invoice Number	
Quotation Date	09.02.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$1,352.00	\$600.00 X \$500 ✓
TO REPAIR REAR PORTION	\$800.00	\$400.00 X \$30 ✓
TO REPAIR REAR PORTION	\$1,352.00	\$400.00 X \$200 ✓
Total Labour	\$3,504.00	\$1,400.00 \$1000

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 \$180
TO REPSRAY FRONT HOOD	\$378.00	\$200.00 \$180
TO REPSRAY REAR BUMPER	\$378.00	\$200.00 \$180
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$0.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$100.00 \$50
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	\$180.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	\$180.00	\$0.00
TO RESPRAY REAR MEMBER LH	\$180.00	\$0.00
TO RESPRAY REAR MEMBER RH	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPOILER	\$180.00	\$80.00 \$50
TO RESPRAY TAIL GATE	\$378.00	\$200.00 \$180
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00 \$50
TO RESPRAY TROUGH BACK DOOR LH	\$180.00	\$0.00
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$0.00
TO RESPRAY REAR DOOR LH	\$378.00	\$0.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$6,456.00	\$1,080.00 870

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO ALIGN CHASSIS	\$350.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$300.00	\$300.00 X \$50
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$100.00 X \$50
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$50.00 X \$20
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$30.00 X \$20
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$950.00	\$950.00 X \$600
TO REMOVE & REFIT EXHAUST	\$120.00	\$0.00
TO REMOVE & REFIT REAR QUARTER GLASS LH	\$120.00	\$0.00
TO REMOVE & REFIT REAR QUARTER GLASS RH	\$120.00	\$0.00
TO REMOVE & REFIT FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	\$120.00	\$0.00
TO REMOVE & REFIT FRONT LHS/RHS QUARTER GLASS	\$240.00	\$0.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO REMOVE / REFIT WINDSCREEN	\$120.00	\$60.00 X \$50
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARNESS	\$300.00	\$0.00
TO REMOVE AND REFIT REAR WINDSCREEN	\$240.00	\$120.00 X \$50
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO TEST AND REFIT REVERSE SENSOR SYSTEM	\$120.00	\$20.00 X \$10
TO TOP UP A/C GAS	\$120.00	\$0.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$4,410.00	\$1,430.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		84778-47050	PROTECTOR, SPARE	0.00	\$143.70	0.00	\$0.00	Replace	Check
		G9040-47090	PUMP ASSY, WATER	0.00	\$454.00	0.00	\$0.00	Replace	Check
		82120-47021	QUARTER GLASS FRT/LH	0.00	\$234.90	0.00	\$0.00	Replace	Check
		82110-47021	QUARTER GLASS FRT/RH	0.00	\$234.90	0.00	\$0.00	Replace	Not Given
		82720-47031	QUARTER GLASS RR/LH	0.00	\$168.10	0.00	\$0.00	Replace	Check
		82710-47130	QUARTER GLASS RR/RH	0.00	\$846.50	0.00	\$0.00	Replace	Check
		G9010-47031	RADIATOR ASSY, UPPER	0.00	\$679.60	0.00	\$0.00	Replace	Check
		16572-37120	RADIATOR HOSE LOWER	0.00	\$42.40	0.00	\$0.00	Replace	Check
		16261-37070	RADIATOR HOSE, BYPASS NO.1	0.00	\$37.20	0.00	\$0.00	Replace	Check
		52611-47080	BUMPER ENERGY ABSORBER FRT	1.00	\$78.60	25.00	\$59.10	Replace	Replace
		52118-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace
		52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check
		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Check

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
30 Woodlands Industrial Park EA, Singapore 117705
FAX Number: 53855562
Estimate Telephone Number: 53855522
Accident Reporting Number: 58823672

Date Generated: 11/02/2019

User ID: PehBuen

	76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Check	X	JVC
	76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Check	X	
	76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Check	X	
	76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Check	X	
	52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace		CRK
	52021-47023	BUMPER REINFORCEMENT FRT	1.00	\$498.40	25.00	\$373.80	Replace	Replace		BT
	52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check	X	JVC
	52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Check	X	
	52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Check	X	
	52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Check	X	
	52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Check	X	JVC
	52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Check	X	
	52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Check	X	
	53630-47050	CABLE ASSY, HOOD	0.00	\$52.20	0.00	\$0.00	Replace	Check	X	
	G2148-47051	CABLE, GENERATOR	0.00	\$169.10	0.00	\$0.00	Replace	Check	X	JVC
	G1148-47051	CABLE, MOTOR INVERTER	0.00	\$199.10	0.00	\$0.00	Replace	Check	X	
	85790-47040	CAMERA ASSY, TELEVISION, RR	0.00	\$1,435.50	0.00	\$0.00	Replace	Check	X	
	51931-47020	CARRIER, SPARE	0.00	\$19.70	0.00	\$0.00	Replace	Check	X	
	53614-47030	CLAMP, HOOD LOCK	0.00	\$5.90	0.00	\$0.00	Replace	Check	X	JVC
		COOLANT	0.00	\$12.32	0.00	\$0.00	Replace	Check	X	
	16480-28080	COOLANT RESERVE TANK	0.00	\$355.30	0.00	\$0.00	Replace	Check	X	
	G9140-47010	COVER ASSY, INVERTER, LH	0.00	\$54.50	0.00	\$0.00	Replace	Check	X	
	52128-47903	COVER, FR BUMPER HOLE LH	1.00	\$18.50	25.00	\$13.88	Replace	Replace		BEF
	52128-47903	COVER, FR BUMPER HOLE LH	0.00	\$18.50	0.00	\$0.00	Replace	Not Given	X	JVC
	53289-47032	COVER, RADIATOR	0.00	\$122.80	0.00	\$0.00	Replace	Check	X	
	16523-21050	CUSHION, RADIATOR	0.00	\$11.30	0.00	\$0.00	Replace	Check	X	
	64777-47090	CUSHION, SPARE WHEEL	0.00	\$230.60	0.00	\$0.00	Replace	Check	X	
	53294-47030	DEFLECTOR, RADIATOR LH	0.00	\$77.00	0.00	\$0.00	Replace	Check	X	JVC
	53293-47040	DEFLECTOR, RADIATOR RH	0.00	\$83.50	0.00	\$0.00	Replace	Check	X	
	67002-47070	DOOR FRT/LH	0.00	\$894.40	0.00	\$0.00	Replace	Not Given	X	
	67001-47070	DOOR FRT/RH	0.00	\$894.40	0.00	\$0.00	Replace	Not Given	X	
	67004-47080	DOOR RR/LH	0.00	\$954.50	0.00	\$0.00	Replace	Check	X	JVC
	75310-47010	EMBLEM FRONT	1.00	\$86.50	25.00	\$64.88	Replace	Replace		
	52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check	X	
	52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check	X	
	58490-47140B0	BOARD ASSY, RR RH	0.00	\$379.20	0.00	\$0.00	Replace	Check	X	JVC
	58415-47030	BOARD, RR FLOOR	0.00	\$392.30	0.00	\$0.00	Replace	Check	X	
	58418-47070B0	BOX, DECK FLOOR, COVER LH	0.00	\$230.10	0.00	\$0.00	Replace	Check	X	
	64997-47020	BOX, DECK FLOOR, LH	0.00	\$196.80	0.00	\$0.00	Replace	Check	X	
	64993-47020	BOX, DECK FLOOR, RR	0.00	\$849.70	0.00	\$0.00	Replace	Check	X	JVC
	58416-47030B3	BOX, RR FLOOR, BOARD	0.00	\$679.60	0.00	\$0.00	Replace	Check	X	
	52114-47140	BRACKET, FR BUMPER	1.00	\$110.40	25.00	\$82.80	Replace	Replace		

SMRT Accident Vehicle Repair Estimates

Date Generated: 11/02/2018

User ID: PehBun

	81529-47080	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Check	X	SUL
	81529-47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Check	X	
	81519-47050	BRACKET, FR TURN LOWER RH	0.00	\$26.00	0.00	\$0.00	Replace	Check	X	
	81529-47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Check	X	
	81519-47080	BRACKET, FR TURN UPPER RH	0.00	\$24.40	0.00	\$0.00	Replace	Check	X	
	G9214-47080	BRACKET, INVERTER, NO.1	0.00	\$31.40	0.00	\$0.00	Replace	Check	X	
		BREAKDOWN SIGN	0.00	\$35.00	0.00	\$0.00	Replace	Check	X	
	52161-18010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.06	Replace	Replace		NEC
	52161-18010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.06	Replace	Replace		NEC
	18400-37230	RADIATOR ASSY	0.00	\$1,496.90	0.00	\$0.00	Replace	Check	X	SUL
	81006-47011	3RD BRAKE LAMP	0.00	\$231.30	0.00	\$0.00	Replace	Not Given	X	
	88460-47150	A/C CONDENSER	0.00	\$1,181.90	0.00	\$0.00	Replace	Check	X	
	17700-38252	AIR CLEANER ASSY	0.00	\$929.90	0.00	\$0.00	Replace	Check	X	
	89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Check	X	BT
	57014-47030	ARM SUB-ASSY, FR BUMPER LH	1.00	\$250.40	25.00	\$187.80	Replace	Replace		
	57013-47030	ARM SUB-ASSY, FR BUMPER RH	1.00	\$250.40	25.00	\$187.80	Replace	Replace		BT
	55083-47011	WIPER GARNISH COVER, RH	0.00	\$23.80	0.00	\$0.00	Replace	Check	X	SUL
	55701-47031	WIPER PANEL SUBASSY, COWL	0.00	\$588.40	0.00	\$0.00	Replace	Check	X	
	82184-47370	WIRE, BACK DOOR, NO.1	0.00	\$582.40	0.00	\$0.00	Replace	Check	X	
	82111-47772	WIRE, ENGINE ROOM	0.00	\$5,567.10	0.00	\$0.00	Replace	Check	X	
	82113-47180	WIRE, ENGINE ROOM, NO.3	0.00	\$242.00	0.00	\$0.00	Replace	Check	X	
	82122-47030	WIRE, ENGINE, NO.2	0.00	\$195.00	0.00	\$0.00	Replace	Check	X	
	82161-47822	WIRE, FLOOR	0.00	\$1,675.00	0.00	\$0.00	Replace	Check	X	
	82162-47820	WIRE, FLOOR, NO.2	0.00	\$1,305.40	0.00	\$0.00	Replace	Check	X	
	82164-47070	WIRE, FRAME	0.00	\$1,680.90	0.00	\$0.00	Replace	Check	X	
	75310-47020	EMBLEM REAR	1.00	\$60.30	25.00	\$45.23	Replace	Replace		
	58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check	X	SUL
	64718-47031B0	END PANEL COVER, DECK TRIM HOLE	0.00	\$48.10	0.00	\$0.00	Replace	Check	X	
	64716-47031B0	END PANEL COVER, DECK TRIM, RR	0.00	\$121.10	0.00	\$0.00	Replace	Check	X	
	58327-47020	EXHAUST HEAT SHIELD, REAR	0.00	\$107.40	0.00	\$0.00	Replace	Check	X	
	17410-37180	EXHAUST PIPE FRT	0.00	\$4,184.70	0.00	\$0.00	Replace	Check	X	
	17430-37380	EXHAUST TAIL PIPE	0.00	\$658.20	0.00	\$0.00	Replace	Check	X	
	16361-37010	FAN BLADE	0.00	\$158.60	0.00	\$0.00	Replace	Check	X	
	16361-28380	FAN BLADE NO.2	0.00	\$204.20	0.00	\$0.00	Replace	Check	X	
	16363-37010	FAN MOTOR NO.1	0.00	\$538.30	0.00	\$0.00	Replace	Check	X	
	16363-37020	FAN MOTOR NO.2	0.00	\$538.30	0.00	\$0.00	Replace	Check	X	
	16711-37040	FAN SHROUD	0.00	\$244.50	0.00	\$0.00	Replace	Check	X	SUL
	16712-37030	FAN SHROUD TOP	0.00	\$99.60	0.00	\$0.00	Replace	Check	X	
	53702-47050	FENDER APRON SUB FRT/LH	0.00	\$637.80	0.00	\$0.00	Replace	Check	X	
	53802-47050	FENDER FRT/LH	0.00	\$723.40	0.00	\$0.00	Replace	Check	X	SUL
	53801-47050	FENDER FRT/RH	0.00	\$723.40	0.00	\$0.00	Replace	Not Given	X	
	53676-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Check	X	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 737702
FAX Number: 63655502
Estimate Telephone Number: 63652623
Accident Reporting Number: 6852672

Date Generated: 11/03/2018

User ID: PakBuan

53875-47030	FENDER LINER FRT/RH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given	✓
53852-47020	FENDER LINER PAD, FR WHEEL LH	0.00	\$49.30	0.00	\$0.00	Replace	Check	X
65638-47021	FENDER LINER RR/LH	0.00	\$141.30	0.00	\$0.00	Replace	Check	X
65637-47021	FENDER LINER RR/RH	0.00	\$141.30	0.00	\$0.00	Replace	Check	X
61802-47091	FENDER RR/LH	0.00	\$766.80	0.00	\$0.00	Replace	Check	X
61804-47090	FENDER RR/RH	0.00	\$766.80	0.00	\$0.00	Replace	Check	X
58303-47301	FLOOR PANEL RR/LH	0.00	\$102.00	0.00	\$0.00	Replace	Check	X
58302-47030	FLOOR PANEL RR/RH	0.00	\$209.90	0.00	\$0.00	Replace	Check	X
81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Check	X
81210-12230	FOG LAMP RH	0.00	\$295.20	0.00	\$0.00	Replace	Check	X
82663-47060	FUSE BLOCK, COVER LOWER	0.00	\$18.50	0.00	\$0.00	Replace	Check	X
82662-47110	FUSE BLOCK, TOP COVER	0.00	\$82.30	0.00	\$0.00	Replace	Check	X
53113-47040	GRILLE RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Check	X
53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Check	X
81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	✓
81130-47500	HEAD LAMP RH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	✓
53395-47020	HOOD END PANEL SEAL	1.00	\$35.50	25.00	\$26.63	Replace	Replace	✓
53420-47070	HOOD HINGE LH	1.00	\$55.90	25.00	\$41.93	Replace	Replace	✓
53410-47070	HOOD HINGE RH	1.00	\$55.90	25.00	\$41.93	Replace	Replace	✓
53510-47102	HOOD LOCK	1.00	\$128.90	25.00	\$96.66	Replace	Replace	✓
53301-47060	HOOD PANEL	1.00	\$748.10	25.00	\$561.08	Replace	Replace	✓
53341-47020	HOOD PANEL INSULATOR	0.00	\$390.50	0.00	\$0.00	Replace	Check	X
86510-28130	HORN ASSY, HIGH	0.00	\$110.40	0.00	\$0.00	Replace	Check	X
86520-28180	HORN ASSY, LOW	0.00	\$110.40	0.00	\$0.00	Replace	Check	X
88703-47040	HOSE SUB-ASSY, DISCHARGE	0.00	\$386.90	0.00	\$0.00	Replace	Check	X
G9226-47020	HOSE, INVERTER COOLING NO.2	0.00	\$90.10	0.00	\$0.00	Replace	Check	X
G9229-47020	HOSE, INVERTER COOLING NO.5	0.00	\$125.30	0.00	\$0.00	Replace	Check	X
G9236-47031	HOSE, INVERTER COOLING NO.6	0.00	\$37.40	0.00	\$0.00	Replace	Check	X
G9225-47021	HOSE, INVERTER NO.1	0.00	\$80.00	0.00	\$0.00	Replace	Check	X
17750-37010	INLET ASSY, AIR	0.00	\$232.50	0.00	\$0.00	Replace	Check	X
G9110-47011	INVERTER BRACKET TRAY	0.00	\$251.60	0.00	\$0.00	Replace	Check	X
9022-47041	INVERTER COVER SUB ASSY	0.00	\$39.60	0.00	\$0.00	Replace	Check	X
G9200-49025	INVERTER W CONVERTER	0.00	\$5,390.20	0.00	\$0.00	Replace	Check	X
81521-47050	LENS & BODY, FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Check	X
81511-47050	LENS & BODY, FR TURN RH	0.00	\$511.80	0.00	\$0.00	Replace	Check	X
81271-53011	LICENSE PLATE LAMP	0.00	\$35.70	0.00	\$0.00	Replace	Not Given	X
57604-47030	MEMBER SUB-ASSY, RR LH	0.00	\$174.10	0.00	\$0.00	Replace	Check	X
57603-47030	MEMBER SUB-ASSY, RR RH	0.00	\$174.10	0.00	\$0.00	Replace	Check	X
75575-47030	MOULDING BACK WINDOW, LOWER NO.1	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	✓
75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Check	X
75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X

SVC

CRK

CRK

NEL

BT

BT

JAM

BT

SVC

NEL

NEL

NN

NN

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
50 Woodlands Industrial Park S4, Singapore 757704
Fax Number : 63686042
Estimator Telephone Number : 63682633
Accident Reporting Number : 68822672

Date Generated : 11/02/2019

User ID : P0000000

	75442-47030	NAME PLATE (PRIUS)	1.00	\$60.80	25.00	\$45.60	Replace	Replace	NEC
	75443-47030	NAME PLATE (TOYOTA)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	NEC
		NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace	DD
		NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given	SUL
		NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace	CRK
		NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given	X
	64740-47031B2	PANEL ASSY, DECK LH	0.00	\$307.00	0.00	\$0.00	Replace	Check	X
	64730-47031B2	PANEL ASSY, DECK RH	0.00	\$307.00	0.00	\$0.00	Replace	Check	X
	69431-47010	STRIKER, BACK DOOR	0.00	\$48.90	0.00	\$0.00	Replace	Check	X
	17565-28010	SUPPORT EXHAUST PIPE, NO 4	0.00	\$40.30	0.00	\$0.00	Replace	Check	X
	53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Check	X
	17565-22030	SUPPORT, EXHAUST REAR	0.00	\$33.60	0.00	\$0.00	Replace	Check	X
	16535-20030	SUPPORT, RADIATOR	0.00	\$18.50	0.00	\$0.00	Replace	Check	X
	16534-37010	SUPPORT, RADIATOR, LH	0.00	\$17.70	0.00	\$0.00	Replace	Check	X
	16533-28051	SUPPORT, RADIATOR, RH	0.00	\$54.50	0.00	\$0.00	Replace	Check	X
	84840-28040	SWITCH ASSY, BACK DOOR OPENER	0.00	\$146.10	0.00	\$0.00	Replace	Check	X
	75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	NEC
	75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	NEC
	81561-47170	TAIL LAMP BRACKET, LH	0.00	\$30.70	0.00	\$0.00	Replace	Check	X
	52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Check	X
	81561-47170	TAIL LAMP LH	0.00	\$548.40	0.00	\$0.00	Replace	Check	X
	81551-47180	TAIL LAMP RH	0.00	\$557.80	0.00	\$0.00	Replace	Check	X
	57005-47241	TAILGATE ASY	1.00	\$1,007.90	25.00	\$755.93	Replace	Replace	DEF
	68810-47010	TAILGATE DOOR HINGE LH/RH	0.00	\$58.30	0.00	\$0.00	Replace	Check	X
	69350-47030	TAILGATE DOOR LOCK	0.00	\$444.10	0.00	\$0.00	Replace	Check	X
	68960-0W532	TAILGATE DOOR STAY LH	0.00	\$241.50	0.00	\$0.00	Replace	Check	X
	68950-0W542	TAILGATE DOOR STAY RH	0.00	\$241.50	0.00	\$0.00	Replace	Check	X
	67881-47022	TAILGATE DOOR WEATHER STRIP	0.00	\$353.40	0.00	\$0.00	Replace	Check	X
	69415-47020	TAILGATE LOCK, COVER	0.00	\$15.70	0.00	\$0.00	Replace	Check	X
	76801-47070-B0	TAILGATE OUTSIDE GARNISH	1.00	\$504.90	25.00	\$378.66	Replace	Replace	DEF
	67751-47040C0	TAILGATE TRIM, LOWER	0.00	\$180.70	0.00	\$0.00	Replace	Check	X
	67750-47071C0	TAILGATE, BOARD ASSY	0.00	\$246.90	0.00	\$0.00	Replace	Check	X
	092A0-47010	TANK ASSY, INVERTER	0.00	\$364.30	0.00	\$0.00	Replace	Check	X
	88790-22131	THERMISTOR ASSY	0.00	\$107.00	0.00	\$0.00	Replace	Check	X
	61621-47030	TROUGH, BACK DOOR	0.00	\$110.90	0.00	\$0.00	Replace	Check	X
	61622-47030	TROUGH, BACK DOOR LH	0.00	\$110.90	0.00	\$0.00	Replace	Check	X
	88710-47150	TUBE & ACCESSORY	0.00	\$631.90	0.00	\$0.00	Replace	Check	X
6503707		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Check	X
6503707		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Check	X
	58308-47011	UNDER COVER SUBASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Check	X
	42611-47140	WHEEL, DISC	0.00	\$1,490.20	0.00	\$0.00	Replace	Check	X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757701
FAX Number: 63655222
Estimate Telephone Number: 63652023
Accident Reporting Number: 69022612

Date Generated: 11/03/2019

User ID: PehBun

561014E 909	WINDSCREEN FRT	1.00	\$1,543.80	25.00	\$1,157.85	Replace	Replace	✓	CEL
75533- 47050	WINDSCREEN MOULDING FRT	1.00	\$57.60	25.00	\$43.20	Replace	Replace	✓	NEL
55708- 47101	WIPER GARNISH	0.00	\$614.00	0.00	\$0.00	Replace	Check	X	
55084- 47011	WIPER GARNISH COVER, LH	0.00	\$23.60	0.00	\$0.00	Replace	Check	X	SUL
	SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Check	X	
	SEALANT W/SCREEN	2.00	\$37.00	0.00	\$74.00	Replace	Replace	✓	NEL
	SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace	✓	NEL
	SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Check	X	
	SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Check	X	NN
	SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Check	X	
	SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check	X	SUL
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓	NEL
	SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Check	Y	NN
	SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Check	X	NN
56427- 47040	SPACER, RR FLOOR	0.00	\$130.60	0.00	\$0.00	Replace	Check	X	SUL
58311- 47071	SPARE TYRE PANEL	0.00	\$667.70	0.00	\$0.00	Replace	Check	X	SUL
76085- 47910	SPOILER REAR	0.00	\$953.70	0.00	\$0.00	Replace	Not Given	✓	SUL
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓	NEL
	STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Check	X	
	STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Check	✓	NN
	STICKER DECAL SMRT (DOOR)	0.00	\$50.00	0.00	\$0.00	Replace	Not Given	X	
	STICKER DECAL SMRT (DOOR)	0.00	\$50.00	0.00	\$0.00	Replace	Not Given	✓	
16264- 37080	RADIATOR HOSE, BYPASS NO.2	0.00	\$29.00	0.00	\$0.00	Replace	Check	X	
16267- 37030	RADIATOR HOSE, BYPASS NO.3	0.00	\$37.20	0.00	\$0.00	Replace	Check	X	
16281- 37030	RADIATOR HOSE, BYPASS NO.4	0.00	\$37.20	0.00	\$0.00	Replace	Check	X	
57104- 47020	RADIATOR LOWER SUPPORT	0.00	\$876.30	0.00	\$0.00	Replace	Check	X	SUL
16571- 37140	RADIATOR TOP HOSE NO 1	0.00	\$42.40	0.00	\$0.00	Replace	Check	X	P. 6239.38
58336- 12090	REINFORCEMENT, RR	0.00	\$34.60	0.00	\$0.00	Replace	Check	X	45-361.40
17894- 37010	RESONATOR, INTAKE	0.00	\$57.20	0.00	\$0.00	Replace	Check	X	541.40
Total			\$72,781.22		\$7,101.18			X	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
16363- 37010			FAN MOTOR NO 1	1.00	\$538.30	25.00	\$403.73	Replace	Replace
76087- 47020			BUMPER LIP COVER RR/RH	1.00	\$116.10	25.00	\$86.57	Replace	Replace
53802- 47050			FENDER FRT/LH	1.00	\$723.40	100.00	\$0.00	Replace	Repair
53630- 47050			CABLE ASSY, HOOD	1.00	\$52.20	25.00	\$39.15	Replace	Replace
82111- 47772			WIRE, ENGINE ROOM	1.00	\$5,567.10	10.00	\$5,010.39	Replace	Replace
64718- 4703180			END PANEL COVER, DECK TRM, RR	1.00	\$121.10	25.00	\$90.83	Replace	Replace
52023- 12240			BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace
16711- 37040			FAN SHROUD	1.00	\$244.50	25.00	\$183.38	Replace	Replace
57603- 47030			MEMBER SUB-ASSY, RR LH	1.00	\$174.10	25.00	\$130.57	Replace	Replace

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 81 Woodlands Industrial Park EA, Singapore 757702
 FAX Number: 63688882
 Estimate Telephone Number: 63682623
 Accident Reporting Number: 6862672

Date Generated: 11/02/2019

User ID: PehDuan

58327-47020	EXHAUST HEAT SHIELD, REAR	1.00	\$107.40	25.00	\$80.55	Replace	Replace	DIS
52016-47030	ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace	BT
67881-47022	TAILGATE DOOR WEATHER STRIP	1.00	\$353.40	25.00	\$265.05	Replace	Replace	DEF
17700-38252	AIR CLEANER ASSY	1.00	\$929.90	25.00	\$697.43	Replace	Replace	BR
16712-37030	FAN SHROUD TOP	1.00	\$99.60	25.00	\$74.70	Replace	Replace	BR
52116-47040	BUMPER SUPPORT F/LH	1.00	\$76.40	25.00	\$57.30	Replace	Replace	CRK
16361-37010	FAN BLADE	1.00	\$158.60	25.00	\$118.95	Replace	Replace	BR
53876-47030	FENDER LINER FRT/LH	1.00	\$171.70	25.00	\$126.78	Replace	Replace	MIS
76891-47020	BUMPER LIP REAR	1.00	\$226.90	25.00	\$171.68	Replace	Replace	CRK
17430-37380	EXHAUST TAIL PIPE	1.00	\$656.20	25.00	\$492.15	Replace	Replace	BT
64718-47031B0	END PANEL COVER, DECK TRIM HOLE	1.00	\$46.10	25.00	\$34.56	Replace	Replace	DIS
75088-47020	BUMPER LIP COVER RR/LH	1.00	\$72.20	25.00	\$54.15	Replace	Replace	CRK
15330-37010	UNDER COVER SUB-ASSY, RR FLOOR	1.00	\$514.50	25.00	\$385.88	Replace	Replace	DEF
17750-37010	INLET ASSY, AIR	1.00	\$232.50	25.00	\$174.38	Replace	Replace	CRK
G9010-47031	RADIATOR ASSY, UPPER	1.00	\$679.60	25.00	\$509.70	Replace	Replace	BT
	SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	CRK
58311-47071	SPARE TYRE PANEL	1.00	\$867.70	25.00	\$500.78	Replace	Replace	DEF
52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace	BT
53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1.00	\$311.10	25.00	\$233.33	Replace	Replace	DIS
53201-47902	SUPPORT SUB-ASSY	1.00	\$1,460.40	25.00	\$1,095.30	Replace	Replace	BT
55708-47101	WIPER GARNISH	1.00	\$614.00	25.00	\$460.50	Replace	Replace	CUT
G92A0-47010	TANK ASSY, INVERTER	1.00	\$364.30	25.00	\$273.23	Replace	Replace	CRK 27,249.35
64778-47050	PROTECTOR, SPARE	1.00	\$143.70	25.00	\$107.77	Replace	Replace	DIS
76851-47020	BUMPER LIP FRT	1.00	\$139.60	25.00	\$104.70	Replace	Replace	MIS 202
53852-47020	FENDER LINER PAD, FR WHEEL, LH	1.00	\$49.30	25.00	\$36.98	Replace	Replace	MIS
55084-47011	WIPER GARNISH COVER, LH	1.00	\$23.60	25.00	\$17.85	Replace	Replace	BR 21,799.48
52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$84.80	25.00	\$71.10	Replace	Replace	BT 1,000.00
88460-47150	A/C CONDENSER	1.00	\$1,181.90	25.00	\$886.43	Replace	Replace	BT + 1,730.00
G9200-49025	INVERTER W CONVERTER	1.00	\$5,390.20	10.00	\$4,851.18	Replace	Replace	BT 24,529.48
52115-47040	BUMPER SUPPORT F/RH	1.00	\$76.40	25.00	\$57.30	Replace	Replace	CRK
55083-47011	WIPER GARNISH COVER, RH	1.00	\$23.60	25.00	\$17.85	Replace	Replace	MIS
16400-37230	RADIATOR ASSY	1.00	\$1,486.90	25.00	\$1,122.68	Replace	Replace	45 \$24,550/-
89997-30070	ANTENNA, ELECTRICAL LOWER REAR	1.00	\$157.40	10.00	\$141.56	Replace	Replace	BT
16363-37020	FAN MOTOR NO 2	1.00	\$538.30	25.00	\$409.73	Replace	Replace	DEF
58307-47060	END PANEL	1.00	\$602.10	25.00	\$451.58	Replace	Replace	X SVC
53111-47040	GRILLE RADIATOR	1.00	\$310.60	25.00	\$232.95	Replace	Replace	BT
16361-28360	FAN BLADE NO 2	1.00	\$204.20	25.00	\$153.15	Replace	Replace	CRK
Total			26,381.20		20,955.63			CRK

FINALIZED LUMP SUM REPAIR \$ 24,550 / 14 DAYS

2620795

NAZUKU

11

21/3/19

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	TAX/12/18/2120	Date of Collection	4/1/19
Vehicle No	SHB 1884D	Date of Request	4/1/19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	5971, 72, 73	Bumper Support Pnt LH		\$ 76.40 / CRK
2	5974, 75, 76, 77	Bumper Support Pnt RH		\$ 76.40 / CRK
3	5978, 79, 80	Bumper Grille Sub Assy Lower		\$ 311.10 / DIS
4	5981, 82, 83	Grille Radiator		\$ 310.60 / CRK
5		Bumper Lip Pnt (Missing)		\$ 139.60 / MIS
6	5987, 88, 89	Wiper Garnish		\$ 614.00 / CUT
7	5990, 91, 92	Wiper Garnish Cover LH		\$ 23.80 / BR
8	5993	Wiper Garnish Cover RH (Missing)		\$ 23.80 / MIS

<<<Please submit photographs for damaged parts>>>

I, (Name) CHIA

(Position) ADVISOR

NAZUKU

Do solemnly and sincerely declare that: Supplementary Parts are raised for replacement for the aforesaid vehicle.

CHIA

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

(1)

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	TAX/12/18/2120	Date of Collection	4/1/19
Vehicle No	SHB 1884 D	Date of Request	11/1/19
Vehicle Model	2010 Toyota Prius	Number of Days to Extend	

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	5994,95	Cable Assy Hood		\$52.20 / BT
2	5996,97,98,99	Support Sub Assy		\$1460.40 / BT
3	6000,01,02,03	Wire Engine Room		\$5567.10 / CUT
4	6004,05,06,07	Inverter With Converter		\$5390.20 / CRK
5	6012,13	Inverter Bracket Tray		\$251.60 / DEF
6	6014,15,16	Tank Assy Inverter		\$364.30 / CRK
7	6017,18	Bumper Side Retainer LH		\$94.80 / CRK
8	6019,20,21	Under Cover Sub Assy RR Floor		\$514.50 / DEF

<<<Please submit photographs for damaged parts>>>

I. (Name) CHIA

(Position) ADVISOR

NAZ LUK

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Chia

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC/ Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

(2)

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	2A/12/18/2120	Date of Collection	4/1/19
Vehicle No	S4B 1884 D	Date of Request	4/1/19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price	
1	6022,23,24	Exhaust Heat Shield Rear		\$107.40	/ DIS
2	6025,26	Exhaust Tail pipe		\$656.20	/ BT
3	6030,31,32	Tail Gate Door weatherstrip		\$353.40	/ DEF
4	6027,28,29	Rnd Panel		\$602.10	/ BT
5	6036,37,38	Rnd Panel Cover Deck Trim Hole		\$46.10	/ DIS
6	6033,34,35	Rnd Panel Cover Deck Trim RR		\$121.10	/ CEC
7	6039,40,41,42	Air Cond Condenser		\$1181.90	/ BT
8	6043,44,45,46	Radiator Assy		\$1496.90	/ BT

<<<Please submit photographs for damaged parts>>>

I. (Name) CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Chia

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

3

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	THX/12/18/2120	Date of Collection	4/1/19
Vehicle No	SHB 1884 D	Date of Request	11/1/19.
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price	
1	6047,48,49	Radiator Assy Upper		\$679.60	✓ BT
2	6050,51	Fan Blade		\$158.60	✓ BR
3	6052,53,54	Fan Blade No 2.		\$204.20	✓ CRK
4	6055,56	Fan Motor No1 (Jum)		\$538.30	X test first
5	6057,58	Fan Motor No2 (Jum)		\$538.30	X test first
6	6054,60,61	Fan Shroud		\$244.50	✓ BR
7	6062,63	Fan Shroud Top		\$99.60	✓ BR
8	6064,65	Air Cleaner Assy		\$929.90	✓ BR

<<<Please submit photographs for damaged parts>>>

I, (Name) CHIA

(Position) ADVISOR

N/A LK

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Chia

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC/ Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

(4)

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	TAY 12/18/2120	Date of Collection	4/1/19
Vehicle No	SHB 1884 D	Date of Request	11/1/19
Vehicle Model	70407B PRIUS	Number of Days to Extend	

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	6066, 67, 68	Inlet Assy Air		\$232.50 / CRK
2	6069, 70, 71	Fender Pnt LH		\$723.40 X R
3	6072	Fender Liner Pnt LH	(Missing)	\$171.70 / MIS
4	6073	Fender Liner Pad Pnt LH	(Missing)	\$49.30 / MIS
5	6074, 75	Bumper Reinforcement Rear		\$205.70 / BT
6	6076, 77	Arm Sub Assy RR Bumper LH		\$139.60 / BT
7	6078, 79	Arm Sub Assy RR Bumper RH		\$139.60 / BT
8	6082, 83, 84	Antenna Electrical Lower Rear		\$157.40 / DEF

<<<Please submit photographs for damaged parts>>>

I, (Name) CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that: Supplementary Parts are raised for replacement for the aforesaid vehicle.

Chia

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

(5)

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	7A7/12/18/2120	Date of Collection	4/1/19
Vehicle No	SHB 1884 D	Date of Request	11/1/19
Vehicle Model	20407B PRIUS	Number of Days to Extend	

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	6080,81	Sensor Reverse.		\$180.00 / CK
2	6085,86,87	Bumper Lip Cover RR LH		\$72.20 / CK
3	6088,89	Bumper Lip Cover RR RH		\$118.10 / CK
4	6091,92,93	Bumper Lip Door		\$228.90 / CK
5	6094,95,96,97	Spare Tyre Panel		\$667.70 / DEF
6	6098,99,70	Member Sub Assy RR LH		\$174.10 / DEF
7	6101,02,03	Protector Spare		\$143.70 / DIS
8				

<<<Please submit photographs for damaged parts>>>

I, (Name) CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that: Supplementary Parts are raised for replacement for the aforesaid vehicle.

Chia

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

(6)

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	TAY 12/18/2120	Date of Collection	4/1/19
Vehicle No	SHB 18840	Date of Request	11/1/19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1		To Request Labour For		
2		Replace Bnd Panel, Rear LH chassis Member And		
3		Spare Tyre Panel.		\$ 800.00
4				
5				
6				
7				
8				

8400

I. (Name)

CHIA

(Position) ADVISOR

<<<Please submit photographs for damaged parts>>>

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Chia

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

(7)



Case Details

Case Reference Number : TAX/12/15/2120
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1884D

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5142-ID
 Assigned By : Tan Lee Ge #

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 28/12/2018 09:10 AM
 Vehicle Age(In Months) : 54

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Parts Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace • /CRV
One Time Key In	Main			BUMPER CLIPS	10	1.81	18.10	25.00	13.08	Replace	10	12.08	Replace • /NEC
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	1	59.10	Replace • /DEF
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	488.40	488.40	25.00	373.80	Replace	1	373.80	Replace • /B1
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	1	187.80	Replace • /B1
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	1	187.80	Replace • /B1
One Time Key In	Main			BRACKET, FR BUMPER	1	110.40	110.40	25.00	82.80	Replace	1	82.80	Replace • /B1
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace • /DD
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	12.00	Replace • /CRV
One Time Key In	Main			COVER, FR BUMPER HOLE LH	1	18.50	18.50	25.00	13.88	Replace	1	13.88	Replace • /DEF
One Time Key In	Main			COVER, FR BUMPER HOLE LH	1	18.50	18.50	25.00	13.88	Replace	0	0	Not Give • KNN
One Time Key In	Main			BUMPER SUPPORT FLH	1	75.40	75.40	25.00	57.30	Replace	0	0	Check • ? XJVL

Total Spare Part Cost: 58,771.89

Surveyor Total: 8,104.34

Lump Sum Discount (%): 20.00

Lump Sum Dis (%): 20

Final Spare Part Cost: 47,017.51

Final Sur Total: 6,483.47

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Check * X50L
One Time Key In	Main			BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0	Check * X50L
One Time Key In	Main			FOG LAMP LH	1	280.10	280.10	10.00	252.09	Replace	0	0	Check * X50L
One Time Key In	Main			FOG LAMP RH	1	295.20	295.20	10.00	265.68	Replace	0	0	Check * ?X50L
One Time Key In	Main			BRACKET, FR TURN LOWER RH	1	26.00	26.00	25.00	19.50	Replace	0	0	Check * X50L
One Time Key In	Main			BRACKET, FR TURN UPPER RH	1	24.40	24.40	25.00	18.30	Replace	0	0	Check * X50L
One Time Key In	Main			LENS & BODY, FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	1	460.62	Replace * ?X50L
One Time Key In	Main			BRACKET, FR TURN CENTER LH	1	58.20	58.20	25.00	43.65	Replace	0	0	Check * }
One Time Key In	Main			BRACKET, FR TURN LOWER LH	1	26.00	26.00	25.00	19.50	Replace	0	0	Check * }
One Time Key In	Main			BRACKET, FR TURN UPPER LH	1	24.40	24.40	25.00	18.30	Replace	0	0	Check * }
One Time Key In	Main			LENS & BODY, FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	0	0	Check * ?X50L
One Time Key In	Main			GRILLE RADIATOR LOWER NO.2	1	94.60	94.60	25.00	70.95	Replace	0	0	Check * }
One Time Key In	Main			GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	Check * }
One Time Key In	Main			EMBLEM FRONT	1	64.80	64.80	25.00	48.60	Replace	1	64.80	Replace * /N/C
One Time Key In	Main			BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	0	0	Check * }
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Check * ?X50L
One Time Key In	Main			WIRE, ENGINE ROOM, NO.3	1	242.00	242.00	10.00	217.80	Replace	0	0	Check * }
One Time Key In	Main			THERMISTOR ASSY	1	107.00	107.00	10.00	96.30	Replace	0	0	Check * }
						Total Spare Part Cost		58,771.89		Surveyor Total		8,104.34	
						Lump Sum Discount (%)		20.00		Lump Sum Dis (%)		20	
						Final Spare Part Cost		47,017.51		Final Sur Total		6,483.47	

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			HOOD PANEL	1	748.10	748.10	25.00	561.08	Replace	1	561.08	Replace • /BT
One Time Key In	Main			HOOD END PANEL SEAL	1	35.50	35.50	25.00	26.63	Replace	1	26.63	Replace • /NFC
One Time Key In	Main			HOOD HINGE LH	1	55.90	55.90	25.00	41.92	Replace	1	41.92	Replace • /BT
One Time Key In	Main			HOOD HINGE RH	1	55.90	55.90	25.00	41.92	Replace	1	41.92	Replace • /BT
One Time Key In	Main			HOOD LOCK	1	128.90	128.90	25.00	96.68	Replace	1	96.68	Replace • /JAM
One Time Key In	Main			HOOD PANEL INSULATOR	1	390.50	390.50	25.00	292.88	Replace	0	0	Check •
One Time Key In	Main			CABLE ASSY, HOOD	1	52.20	52.20	25.00	39.15	Replace	0	0	Check •
One Time Key In	Main			CLAMP, HOOD LOCK	1	5.90	5.90	25.00	4.43	Replace	0	0	Check •
One Time Key In	Main			WIPER GARNISH	1	614.00	614.00	25.00	460.50	Replace	0	0	Check •
One Time Key In	Main			WIPER GARNISH COVER, LH	1	23.80	23.80	25.00	17.85	Replace	0	0	Check •
One Time Key In	Main			WIPER GARNISH COVER, RH	1	23.80	23.80	25.00	17.85	Replace	0	0	Check •
One Time Key In	Main			WIPER PANEL SUBASSY, COWL	1	588.40	588.40	25.00	441.30	Replace	0	0	Check •
One Time Key In	Main			WINDSCREEN MOULDING FRT	1	57.60	57.60	25.00	43.20	Replace	1	43.20	Replace • /NFC
One Time Key In	Main			WINDSCREEN FRT	1	1,543.80	1,543.80	25.00	1,157.85	Replace	1	1,157.85	Replace • /CNC
One Time Key In	Main			SEALANT W/SCREEN	2	37.00	74.00	0.00	74.00	Replace	2	74.00	Replace • /NFC
One Time Key In	Main			SUPPORT SUB-ASSY	1	1,480.40	1,480.40	25.00	1,095.30	Replace	0	0	Check •
One Time Key In	Main			COVER, RADIATOR	1	122.80	122.80	25.00	92.10	Replace	0	0	Check •
One Time Key In	Main			HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	1	850.68	Replace • /CNC
Total Spare Part Cost									58,771.89	Surveyor Total			
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)			
Final Spare Part Cost									47,017.51	Final Sur Total			

SMRT Recommendation												Surveyor Approval	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			HEAD LAMP RH	1	945.20	945.20	10.00	850.68	Replace	1	850.68	Replace *
One Time Key In	Main			WIRE, ENGINE ROOM	1	5,567.10	5,567.10	10.00	5,010.39	Replace	0	0	Check *
One Time Key In	Main			FUSE BLOCK, COVER LOWER	1	18.50	18.50	25.00	13.88	Replace	0	0	Check *
One Time Key In	Main			FUSE BLOCK, TOP COVER	1	82.39	82.39	25.00	61.72	Replace	0	0	Check *
One Time Key In	Main			WIRE, ENGINE, NO.2	1	195.00	195.00	10.00	175.50	Replace	0	0	Check *
One Time Key In	Main			WIRE, FRAME	1	1,680.90	1,680.90	10.00	1,512.81	Replace	0	0	Check *
One Time Key In	Main			CABLE, GENERATOR	1	188.10	188.10	10.00	162.19	Replace	0	0	Check *
One Time Key In	Main			CABLE, MOTOR INVERTER	1	199.10	199.10	10.00	179.19	Replace	0	0	Check *
One Time Key In	Main			INVERTER BRACKET TRAY	1	251.60	251.60	25.00	188.70	Replace	0	0	Check *
One Time Key In	Main			INVERTER COVER SUB ASSY	1	39.60	39.60	25.00	29.70	Replace	0	0	Check *
One Time Key In	Main			INVERTER W CONVERTER	1	5,390.20	5,390.20	10.00	4,851.18	Replace	0	0	Check *
One Time Key In	Main			BRACKET, INVERTER, NO.1	1	31.40	31.40	25.00	23.55	Replace	0	0	Check *
One Time Key In	Main			COVER ASSY, INVERTER, LH	1	54.50	54.50	25.00	40.88	Replace	0	0	Check *
One Time Key In	Main			TANK ASSY, INVERTER	1	364.30	364.30	25.00	273.23	Replace	0	0	Check *
One Time Key In	Main			BUMPER SIDE RETAINER RRLH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check *
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check *
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Check *
One Time Key In	Main			EXHAUST HEAT SHIELD, REAR	1	107.40	107.40	25.00	80.55	Replace	0	0	Check *
						Total Spare Part Cost		58,771.89		Surveyor Total		6,104.34	
						Lump Sum Discount (%)		20.00		Lump Sum Dis (%)		20	
						Final Spare Part Cost		47,017.51		Final Sur Total		6,483.47	

SMRT Recommendation												Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			EXHAUST TAIL PIPE	1	856.20	856.20	25.00	402.15	Replace	0	0	Check	*
One Time Key In	Main			EXHAUST PIPE FRT	1	4,184.70	4,184.70	25.00	3,138.52	Replace	0	0	Check	*
One Time Key In	Main			SUPPORT EXHAUST PIPE, NO.4	3	40.30	80.60	25.00	60.45	Replace	0	0	Check	*
One Time Key In	Main			SUPPORT, EXHAUST REAR	2	33.60	67.20	25.00	50.40	Replace	0	0	Check	*
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.92	Replace	*
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	22.05	22.05	25.00	16.54	Replace	1	16.54	Replace	*
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	22.05	22.05	25.00	16.54	Replace	1	16.54	Replace	*
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	22.05	22.05	25.00	16.54	Replace	1	16.54	Replace	*
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace	*
One Time Key In	Main			TAILGATE DOOR HINGE LHRH	2	58.30	116.60	25.00	87.45	Replace	0	0	Check	*
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0	Check	*
One Time Key In	Main			TAILGATE DOOR STAY LH	1	241.50	241.50	25.00	181.13	Replace	0	0	Check	*
One Time Key In	Main			TAILGATE DOOR STAY RH	1	241.50	241.50	25.00	181.13	Replace	0	0	Check	*
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	263.40	263.40	25.00	197.55	Replace	0	0	Check	*
One Time Key In	Main			TAILGATE LOCK COVER	1	15.70	15.70	25.00	11.77	Replace	0	0	Check	*
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	378.67	378.67	25.00	284.00	Replace	1	284.00	Replace	*
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0	Check	*
One Time Key In	Main			TAILGATE TRIM, LOWER	1	180.70	180.70	25.00	135.52	Replace	0	0	Check	*
Total Spare Part Cost									58,771.89					
										Surveyor Total	8,104.34			
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)	20			
Final Spare Part Cost									47,017.51	Final Sur Total	6,483.47			

SMRT Recommendation											Surveyor Approval		
SOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			TAILGATE, BOARD ASSY	1	246.90	246.90	25.00	185.18	Replace	0	0	Check • X SWL
One Time Key In	Main			WIRE, BACK DOOR, NO.1	1	582.40	582.40	10.00	524.16	Replace	0	0	Check • X SWL
One Time Key In	Main			CAMERA ASSY, TELEVISION, RR	1	1,436.60	1,436.60	10.00	1,292.94	Replace	0	0	Check • X SWL
One Time Key In	Main			SWITCH ASSY, BACK DOOR OPENER	1	148.10	148.10	10.00	131.49	Replace	0	0	Check • X SWL
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	1	45.22	Replace • / NBL
One Time Key In	Main			LICENSE PLATE LAMP	2	35.70	71.40	10.00	64.26	Replace	2	64.26	Replace • X SWL
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	0	0	Not Give • X SWL
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	0	0	Not Give • X SWL
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace • / NBL
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.80	60.80	25.00	45.60	Replace	1	45.60	Replace • / NBL
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace • / NBL
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	0	0	Not Give • X SWL
One Time Key In	Main			3RD BRAKE LAMP	1	231.30	231.30	10.00	208.17	Replace	0	0	Not Give • X SWL
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace • / NBL
One Time Key In	Main			STICKER DECAL 5555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace • / NBL
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check • X SWL
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	Check • X SWL
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0	Check • X SWL
Total Spare Part Cost											Surveyor Total	8,104.34	
Lump Sum Discount (%)										20.00	Lump Sum Dis (%)	20	
Final Spare Part Cost										47,017.61	Final Sur Total	6,483.47	

SMRT Recommendation											Surveyor Approval			
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			REINFORCEMENT, RR	2	34.60	68.20	25.00	51.90	Replace	0	0	Check *	X
One Time Key In	Main			HOSE, INVERTER COOLING NO.2	1	90.10	90.10	25.00	67.57	Replace	0	0	Check *	X
One Time Key In	Main			HOSE, INVERTER COOLING NO.3	1	126.30	126.30	25.00	93.97	Replace	0	0	Check *	X
One Time Key In	Main			HOSE, INVERTER COOLING NO.6	1	37.40	37.40	25.00	28.05	Replace	0	0	Check *	X
One Time Key In	Main			HOSE, INVERTER NO.1	1	80.00	80.00	25.00	60.00	Replace	0	0	Check *	X
One Time Key In	Main			PUMP ASSY, WATER	1	454.00	454.00	25.00	340.50	Replace	0	0	Check *	X
One Time Key In	Main			HORN ASSY, HIGH	1	116.40	116.40	25.00	87.30	Replace	0	0	Check *	X
One Time Key In	Main			HORN ASSY, LOW	1	110.40	110.40	25.00	82.80	Replace	0	0	Check *	X
One Time Key In	Main			DEFLECTOR, RADIATOR LH	1	77.00	77.00	25.00	57.75	Replace	0	0	Check *	X
One Time Key In	Main			DEFLECTOR, RADIATOR RH	1	83.50	83.50	25.00	62.63	Replace	0	0	Check *	X
One Time Key In	Main			A/C CONDENSER	1	1,181.90	1,181.90	25.00	886.43	Replace	0	0	Check *	X
One Time Key In	Main			HOSE SUB-ASSY, DISCHARGE	1	386.90	386.90	25.00	290.17	Replace	0	0	Check *	X
One Time Key In	Main			TUBE & ACCESSORY	1	631.90	631.90	25.00	473.92	Replace	0	0	Check *	X
One Time Key In	Main			COOLANT	1	12.32	12.32	0.00	12.32	Replace	0	0	Check *	X
One Time Key In	Main			RADIATOR ASSY	1	1,496.90	1,496.90	25.00	1,122.68	Replace	0	0	Check *	X
One Time Key In	Main			RADIATOR ASSY, UPPER	1	879.60	879.60	25.00	659.70	Replace	0	0	Check *	X
One Time Key In	Main			RADIATOR LOWER SUPPORT	1	876.30	876.30	25.00	657.22	Replace	0	0	Check *	X
One Time Key In	Main			SUPPORT, RADIATOR	2	18.50	37.00	25.00	27.75	Replace	0	0	Check *	X

Total Spare Part Cost 58,771.89

Surveyor Total 8,104.34

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 47,017.51

Final Sur Total 5,483.47

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			SUPPORT, RADIATOR, LH	1	17.70	17.70	25.00	13.27	Replace	0	0	Check *	X
One Time Key In	Main			SUPPORT, RADIATOR, RH	1	54.50	54.50	25.00	40.88	Replace	0	0	Check *	X
One Time Key In	Main			CUSHION, RADIATOR	2	11.30	22.60	25.00	16.95	Replace	0	0	Check *	X
One Time Key In	Main			RADIATOR TOP HOSE NO 1	1	42.40	42.40	25.00	31.80	Replace	0	0	Check *	X
One Time Key In	Main			RADIATOR HOSE LOWER	1	42.40	42.40	25.00	31.80	Replace	0	0	Check *	X
One Time Key In	Main			RADIATOR HOSE, BYPASS NO.1	1	37.20	37.20	25.00	27.90	Replace	0	0	Check *	X
One Time Key In	Main			RADIATOR HOSE, BYPASS NO.2	1	29.00	29.00	25.00	21.75	Replace	0	0	Check *	X
One Time Key In	Main			RADIATOR HOSE, BYPASS NO.3	1	37.20	37.20	25.00	27.90	Replace	0	0	Check *	X
One Time Key In	Main			RADIATOR HOSE, BYPASS NO.4	1	37.20	37.20	25.00	27.90	Replace	0	0	Check *	X
One Time Key In	Main			COOLANT RESERVE TANK	1	395.20	395.20	25.00	296.40	Replace	0	0	Check *	X
One Time Key In	Main			FAN BLADE	1	158.60	158.60	25.00	118.95	Replace	0	0	Check *	X
One Time Key In	Main			FAN BLADE NO 2	1	204.20	204.20	25.00	153.15	Replace	0	0	Check *	X
One Time Key In	Main			FAN MOTOR NO 1	1	538.30	538.30	25.00	403.72	Replace	0	0	Check *	X
One Time Key In	Main			FAN MOTOR NO 2	1	538.30	538.30	25.00	403.72	Replace	0	0	Check *	X
One Time Key In	Main			FAN SHROUD	1	244.50	244.50	25.00	183.38	Replace	0	0	Check *	X
One Time Key In	Main			FAN SHROUD TOP	1	99.60	99.60	25.00	74.70	Replace	0	0	Check *	X
One Time Key In	Main			AIR CLEANER ASSY	1	829.90	829.90	25.00	622.42	Replace	0	0	Check *	X
One Time Key In	Main			INLET ASSY, AIR	1	232.50	232.50	25.00	174.38	Replace	0	0	Check *	X

Total Spare Part Cost 58,771.89

Surveyor Total 8,104.34

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 47,017.91

Final Sur Total 6,483.47

SMRT Recommendation											Surveyor Approval		
BQM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			RESONATOR, INTAKE	1	57.20	57.20	25.00	42.90	Replace	0	0	Check * XSVL
One Time Key In	Main			FENDER FRTLH	1	723.40	723.40	25.00	542.55	Replace	0	0	Check * XSVL
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	Check * ? NBL
One Time Key In	Main			FENDER LINER FRTLH	1	171.70	171.70	25.00	128.77	Replace	0	0	Check * XSVL
One Time Key In	Main			FENDER LINER PAD. FR WHEEL LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Check * XSVL
One Time Key In	Main			FENDER APRON SUB FRTLH	1	837.80	837.80	25.00	478.35	Replace	1	478.35	Replace * ? X
One Time Key In	Main			QUARTER GLASS FRTLH	1	234.90	234.90	25.00	176.18	Replace	0	0	Check * ? XSVL
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Check * ? XSVL
One Time Key In	Main			DOOR FRTLH	1	894.40	894.40	25.00	670.80	Replace	0	0	Not Give * XSVL
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give * XBNW
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	0	0	Not Give * XSVL
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give * XBNW
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give * XBNW
One Time Key In	Main			QUARTER GLASS FRT/RH	1	234.90	234.90	25.00	176.18	Replace	0	0	Not Give * XBNW
One Time Key In	Main			DOOR FRT/RH	1	894.40	894.40	25.00	670.80	Replace	0	0	Not Give * XSVL
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give * XBNW
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace * /CRK
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace * /NBL
Total Spare Part Cost						58,773.89			Surveyor Total	8,104.34			
Lump Sum Discount (%)						20.00			Lump Sum Dis (%)	20			
Final Spare Part Cost						47,017.51			Final Sur Total	6,483.47			

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation								Surveyor Approval		
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	*
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	138.60	138.60	25.00	104.70	Replace	0	0	Check	*
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	138.60	138.60	25.00	104.70	Replace	0	0	Check	*
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Check	*
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check	*
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	*
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Check	*
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Check	*
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Check	*
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Check	*
One Time Key In	Main			BUMPER SEAL, RR RH	1	85.70	85.70	25.00	64.28	Replace	0	0	Check	*
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check	*
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	0	0	Check	*
One Time Key In	Main			MEMBER SUB-ASSY, RR LH	1	174.10	174.10	25.00	130.57	Replace	0	0	Check	*
One Time Key In	Main			MEMBER SUB-ASSY, RR RH	1	174.10	174.10	25.00	130.57	Replace	0	0	Check	*
One Time Key In	Main			FLOOR PANEL RR/LH	1	102.00	102.00	25.00	76.50	Replace	0	0	Check	*
One Time Key In	Main			FLOOR PANEL RR/RH	1	209.90	209.90	25.00	157.43	Replace	0	0	Check	*
One Time Key In	Main			BOX, DECK FLOOR, RR	1	848.70	848.70	25.00	636.53	Replace	0	0	Check	*
									Total Spare Part Cost	58,771.89	Surveyor Total	8,104.34		
									Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20		
									Final Spare Part Cost	47,017.51	Final Sur Total	6,483.47		

SMRT Recommendation											Surveyor Approval		
SOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	879.60	879.60	25.00	509.70	Replace	0	0	Check *
One Time Key In	Main			BOARD, RR FLOOR	1	392.30	392.30	25.00	294.23	Replace	0	0	Check *
One Time Key In	Main			BOARD ASSY, RR RH	1	379.20	379.20	25.00	284.40	Replace	0	0	Check *
One Time Key In	Main			SPACER, RR FLOOR	1	130.60	130.60	25.00	97.95	Replace	0	0	Check *
One Time Key In	Main			BOX, DECK FLOOR, COVER LH	1	230.10	230.10	25.00	172.57	Replace	0	0	Check *
One Time Key In	Main			BOX, DECK FLOOR, LH	1	196.80	196.80	25.00	147.60	Replace	0	0	Check *
One Time Key In	Main			CUSHION, SPARE WHEEL	1	230.80	230.80	25.00	173.10	Replace	0	0	Check *
One Time Key In	Main			PROTECTOR, SPARE	1	143.70	143.70	25.00	107.77	Replace	0	0	Check *
One Time Key In	Main			CARRIER, SPARE	1	18.70	18.70	25.00	14.77	Replace	0	0	Check *
One Time Key In	Main		8903707	TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Check *
One Time Key In	Main			WHEEL, DISC	1	1,490.20	1,490.20	25.00	1,117.65	Replace	0	0	Check *
One Time Key In	Main			BREAKDOWN SIGN	1	35.00	35.00	0.00	35.00	Replace	0	0	Check *
One Time Key In	Main			PANEL ASSY, DECK LH	1	307.00	307.00	25.00	230.25	Replace	0	0	Check *
One Time Key In	Main			PANEL ASSY, DECK RH	1	307.00	307.00	25.00	230.25	Replace	0	0	Check *
One Time Key In	Main			WIRE, FLOOR	1	1,675.00	1,675.00	10.00	1,507.50	Replace	0	0	Check *
One Time Key In	Main			WIRE, FLOOR, NO.2	1	1,305.40	1,305.40	10.00	1,174.86	Replace	0	0	Check *
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	30.70	30.70	25.00	23.03	Replace	0	0	Check *
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	0	0	Check *

Total Spare Part Cost

58,771.89

Surveyor Total

8,104.34

Lump Sum Discount (%)

20.00

Lump Sum Dis (%)

20

Final Spare Part Cost

47,017.51

Final Sur Total

6,483.47

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation								Surveyor Approval		
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			TROUGH, BACK DOOR LH	1	110.90	110.90	25.00	83.18	Replace	0	0	Check	*
One Time Key In	Main			FENDER RR/LH	1	766.90	766.90	25.00	575.10	Replace	0	0	Check	*
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Check	*
One Time Key In	Main			STICKER DECAL 5555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Check	*
One Time Key In	Main			FENDER LINER RR/LH	1	141.30	141.30	25.00	105.98	Replace	0	0	Check	*
One Time Key In	Main			QUARTER GLASS RR/LH	1	158.10	158.10	25.00	118.67	Replace	0	0	Check	*
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Check	*
One Time Key In	Main		6503707	TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Check	*
One Time Key In	Main			DOOR RR/LH	1	954.50	954.50	25.00	715.88	Replace	0	0	Check	*
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0	Check	*
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	0	0	Check	*
One Time Key In	Main			TROUGH, BACK DOOR	1	110.90	110.90	25.00	83.18	Replace	0	0	Check	*
One Time Key In	Main			FENDER RR/RH	1	766.90	766.90	25.00	575.10	Replace	0	0	Check	*
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Check	*
One Time Key In	Main			STICKER DECAL 5555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Check	*
One Time Key In	Main			FENDER LINER RR/RH	1	141.30	141.30	25.00	105.98	Replace	0	0	Check	*
One Time Key In	Main			QUARTER GLASS RR/RH	1	146.50	146.50	25.00	109.88	Replace	0	0	Check	*
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Check	*
Total Spare Part Cost											Surveyor Total	8,104.34		
Lump Sum Discount (%)										20.00	Lump Sum Dis (%)	20		
Final Spare Part Cost										47,017.51	Final Sur Total	6,483.47		

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR FRONT PORTION	1,352.00	800	
2	TO REPAIR REAR PORTION	1,352.00	400	
Total:		2,704.00	1,000.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY FRONT BUMPER	378.00	200	
2	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0	CHECK
3	TO REPSRAY FRONT HOOD	378.00	200	
4	TO RESPRAY FRONT SUPPORT PANEL	180.00	100	
5	TO RESPRAY FRONT FENDER RH	378.00	0	CHECK
6	TO RESPRAY FRONT FENDER LH	378.00	0	CHECK
7	TO RESPRAY APRON PANEL LH	180.00	0	CHECK
8	TO RESPRAY FRONT DOOR RH	378.00	0	CHECK
9	TO RESPRAY FRONT DOOR LH	378.00	0	CHECK
10	TO REPSRAY REAR BUMPER	378.00	200	
11	TO RESPRAY TAIL GATE	378.00	200	
12	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	
13	TO RESPRAY REAR SPOILER	180.00	80	
14	TO RESPRAY REAR PANEL	180.00	0	CHECK
15	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	CHECK
16	TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0	CHECK
17	TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0	CHECK
18	TO RESPRAY REAR MEMBER,RH	180.00	0	CHECK
19	TO RESPRAY REAR MEMBER,LH	180.00	0	CHECK
20	TO RESPRAY TROUGH BACK DOOR RH	180.00	0	CHECK
21	TO RESPRAY TROUGH BACK DOOR LH	180.00	0	CHECK
22	TO RESPRAY REAR FENDER RH	378.00	0	CHECK
Total:		6,498.00	1,080.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
23	TO RESPRAY REAR FENDER LH	378.00	0	CHECK
24	TO RESPRAY REAR DOOR LH	378.00	0	CHECK
Total:		8,488.00	1,080.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
2	TO APPLY RUST-PROOFING ON AFFECTED AREA	300.00	100	
3	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	NN
4	TO TOP UP A/C GAS	120.00	0	CHECK
5	TO REMOVE / REFIT SEAT	120.00	0	CHECK
6	TO REMOVE / REFIT WINDSCREEN	120.00	60	NEC
7	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120	NEC
8	TO ALIGN CHASSIS	350.00	0	CHECK
9	TO REMOVE & REFIT EXHAUST	120.00	0	CHECK
10	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0	CHECK
11	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
12	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	950.00	950.00	
13	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	120.00	0	CHECK
14	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30	
15	TO CHECK & RESET SYSTEM FUNCTION	350.00	100	
16	TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0	CHECK
17	TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0	CHECK
18	TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	240.00	0	CHECK
19	TO REMOVE AND REFIT WIRE HARNESS	300.00	0	CHECK
20	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	0	CHECK
21	TO REPLACE SUNDRY PARTS	100.00	0	NN
22	TO WASH AND VACUUM	80.00	0	NN
Total:		4,410.00	1,430.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	47,017.51	5,483.47
Total Labour Cost	2,704.00	1,000.00
Total Spray Painting	5,498.00	1,080.00
Other	4,410.00	1,430.00
Overall Total	60,629.51	9,993.47
Lump Sum Repair Option	☐	☒
Lump Sum Total	60,650.00	10,000.00
Surveyor Approved Amount		10,000.00
No of Repair Days*	18	10
Remarks		LUMP SUM REPAIR 10 DAYS CHECK ITEMS PHOTOS AFTER REPAIR PHOTOS
Surveyor Name		NAZ
Signature		
Survey Date	02/01/2019	

NAZ LKK 2/1/19 17:00
L/S

10 DAYS

CHECK ITEMS PHOTOS
AFTER REPAIR PHOTOS

- Request Book Value
- Need to check if economical to repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle No.:	SHB1884D
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Scheme:	Taxi (Company)
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Chassis No.:	JTDKN36U305746581
Propellant:	Petrol-Electric
Engine No.:	22R1385773
Motor No.:	3JM1385773
Engine Capacity:	1798 cc
Power Rating:	60.0 kW
Maximum Power Output:	100.0 kW (134 bhp)
Maximum Laden Weight:	1805 kg
Unladen Weight:	1370 kg
Year Of Manufacture:	2014
Original Registration Date:	25 Jun 2014
Lifespan Expiry Date:	24 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
PQP Paid:	\$57,338.00
COE Expiry Date:	24 Jun 2022
Road Tax Expiry Date:	24 Jun 2019
PARF Eligibility Expiry Date:	24 Jun 2022
Inspection Due Date:	24 Jun 2019
Intended Transfer Date:	03 Jan 2019
CO2 Emission:	92.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$30,000.00
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	5369K

Vehicle Details

Vehicle No.:	SHB1884D
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (5MRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR1385773
Chassis No.:	JTDKN36U305746581
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	25 Jun 2014
First Registration Date:	25 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jun 2022
PARF Rebate Amount:	\$6,066.00

Intended COE Details

COE Expiry Date:	24 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$24,906.00
Total Rebate Amount:	\$30,972.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Jan 2019

OK

$$\begin{aligned}\text{Depreciation per month} &= \text{Purchase price} \div 96 \text{ months (8 yrs COE)} \\ &= \$115,875 \div 96 \\ &= \$1207\end{aligned}$$

$$\begin{aligned}\text{Balance @ 28/12/18} &= 42 \text{ months} \times \$1207 \\ &= \$50,694\end{aligned}$$

$$\begin{aligned}\text{Book Value} &= \text{Balance} + 60\% \text{ of ARF} \\ &= \$50,694 + \$8,088 \times 0.6 \\ &= \$55,546\end{aligned}$$

$$\begin{aligned}\text{Repair Margin} &= \text{Book Value} - \text{COE Rebate} \\ &= \$55,546 - \$30,972 \\ &= \$24,574\end{aligned}$$

Poh Kin (LKKAuto)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>
Sent: Wednesday, 27 March 2019 6:39 PM
To: CS A Team; Admin A
Subject: LOD Re: Accident on 28/12/2018 involving SHB 1884D, SLH 1072B (AIG's insured) etc (Our Ref: TAX/12/18/2120/lg)
Attachments: 12 18 2120 - LOD.pdf

Dear All,

We quantify our claim as follows:-

Cost of Repair	\$24,550.00
Loss of Rental	\$3,614.10 (35 days x \$103.26)
Loss of Income	\$2,100.00 (35 day x \$60.00)
LTA Search Fee	\$7.00
Total	\$30,271.10

We enclose the following documents:

- 1) Repair invoice
- 2) Proof of rental rate
- 3) police/GIA reports
- 4) Accident vehicle laid-up report
- 5) LTA search

Please let us have your offer soon. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)

Claims Department

SMRT Automotive Services Pte Ltd





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG19000123/Nfa3

11 APRIL 2019

ONG CHONG YAO
214 DEPOT ROAD
#06-67 SINGAPORE 109701

Dear Sir/Madam,

**ACCIDENT INVOLVING SLH 1072B(AIG) / SHB 1884D/ OTHERS ALONG/ AT
PIE ON 28/12/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SHB 1884D against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

CHAN JIA LE
Case Handler
DID: 6749 5792
FAX: 6741 4108
Email: chewht@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific - Express Third Party Claim)

I, SMRT TAXIS PTE LTD (the third party claimant") of 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 (address), owner of SHB 1884D (vehicle no.) hereby authorize SMRT AUTOMOTIVE SERVICES PTE LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no SHB 1884D that was damaged pursuant to the accident which occurred on 28/12/2018 (date) along PIE TOWARDS TUAS (location) involving vehicle no/s SLH 1072B ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of SMRT TAXIS PTE LTD.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 8 (day) of October (month) 2019 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, SMRT AUTOMOTIVE SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$24,550.00 (Repair Cost), S\$3,524.98 (Loss of Use/Rental), S\$7.00 (Disbursement) for vehicle no. SHB 1884D that was damaged pursuant to the accident which occurred on 28/12/2018 (date) along PIE TOWARDS TUAS (location) involving vehicle no/s SLH 1072B.

This is pursuant to the inspection conducted on 02/01/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SMRT TAXIS PTE LTD ("the third party claimant") of vehicle no. SHB 1884D make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SHB 1884D (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 8 (day) of October (month) 2019 (year)


NAZ
Signed by appointed surveyor


Signed by "the workshop" (with chop)

*** This Discharge Voucher applies only to the claimant's claim or his property damage and will not affect his personal injuries claim and/or uninsured losses claim in a later date. Further, the settlement terms herein should not be used as an evidence to prejudice to the claimant's personal injuries claim and/or other uninsured losses claim arising of the subject matter in this action.



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705



SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV190300343
Date : 21.03.2019
Vehicle No. : SHB1884D
Your Ref No. : TAX/12/18/2120
Our Ref No. : 24099461
Terms : 30 Days

Description	Qty	Unit Cost	Add / (Discount) Amount	Amount
LUMP SUM AMOUNT FOR REPAIR AS PER SURVEYOR'S RECOMMENDATION	1.00		\$	24,550.00
GRAND TOTAL				\$ 24,550.00

Remark :

Make/Model : TOYOTA PRIUS
Accident Date : 28.12.2018

N.B. Payment by cheque should be crossed and
made payable to 'SMRT Automotive Services Pte Ltd'.
No receipt will be issued unless requested.

Authorised Signature
for SMRT Automotive Services Pte Ltd



SMRT Taxis Pte Ltd

MEMORANDUM

To: Claims Dept

Our Ref: TAX/12/18/2120

From: SMRT Taxis Pte Ltd

Date: 07/01/2019

ACCIDENT INVOLVING SHB 1884D, SLH 1072B ETC ON 28/12/2018 ALONG PIE TOWARDS TUAS

This is to confirm that the daily rental rate for SHB 1884D is \$103.26 per day.

Please proceed to recover any rental loss from the third party as a result of the above accident.

Thank you.

Yours sincerely
SMRT TAXIS PTE LTD



for Manager



Laid Up Report

Accident Start Date : 25/12/2018

Accident End Date : 19/03/2019

Date Generated : 19/03/2019

User Name : LeeGak

Case Reference Number	Vehicle Registration Number	Company Type	Vehicle Make	Vehicle Model	Job Card Number	Date and Time (Accident Repair)	Date and Time (Repair Completed)
TAX/12/16/2120	SH81894D	SMRT Taxi Pte Ltd	TOYOTA	PRIUS	24099461	25/12/2018 5:45 PM	02/02/2019 10:45 AM

Enquire Transaction History

Transaction History Details:

Log Date/Time:	31 Dec 2018 / 09:00:32	Transaction Amount:	\$7.49
Asset Type:	Vehicle		
Asset ID:	SLH1072B		
Transaction Type:	18.32 Insurance Enquiry (GIRO Payment)	Channel:	External Agency
User ID:	ESASBAH0 - BALQISH BINTE ABDUL HALIL	Business Transaction Reference No.:	20181231090032760766

Search Date / Time: 28 Dec 2018 17:10:00
Insurance Company: AIG ASIA PACIFIC INSURANCE PTE. LTD.
Information displayed is correct as at the log date and time.

[Enquire Related Logs](#)[Back to List](#)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jan 2019 Edit Reg		02 Jan 2019 00:00 Edit Adj Rpt	\$24,550.00 Edit Estimates	\$24,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	ONG CHONG YAO (WENG CHONGYAO) , ID: S8306483H								
Main Claimant:	SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHB1884D	Date of Loss:	28/12/2016 17:00 - :59 [54 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6761463391SG	Policy/Cover Note No.:	2100487879 (Comprehensive) Coverage: 25/10/2018 - 24/10/2019						
Vehicle Reg. No. (Insured):	SLH1072B	Policy No. (Claimant):	D-18090213MFSH						
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 14/01/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (25/09/2019): Alert - Adj Mandate Approved (\$28081.98) - SHB1884D - Claim Handler: Loh, Chee-... - AIG_SG_EXPRESS (14/08/2019): Alert - Adj Mandate Approved (\$27775.46) - SHB1884D - Claim Handler: Loh, Chee-... - AIG_SG (04/01/2019): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHB1884D (6761463391SG)
[SLH1072B]
TP
SMRT TAXIS PTE LTD
Dec 28 2018 5:00PM
[ONG CHONG YAO (WENG CHONGYAO)]
SMRT Automotive Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Video															1 per page		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print			
1	24/04/19 15:45	OI ACCIDENT VIDEO											Load MP4				
2	24/04/19 15:45	OI ACCIDENT VIDEO											Load MP4				
Letters/Correspondences															1 per page		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown											Edit				
Photos/Images															3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print			
1	21/03/19 14:58	General View											Load JPG	☒			
2	21/03/19 14:58	General View											Load JPG	☒			
3	21/03/19 14:58	General View											Load JPG	☒			
4	21/03/19 14:58	General View											Load JPG	☒			
5	21/03/19 14:58	General View											Load JPG	☒			
6	21/03/19 14:58	General View											Load JPG	☒			
7	21/03/19 14:58	General View											Load JPG	☒			
8	21/03/19 14:58	General View											Load JPG	☒			
9	21/03/19 14:58	General View											Load JPG	☒			
10	21/03/19 14:58	General View											Load JPG	☒			
11	21/03/19 14:58	General View											Load JPG	☒			
12	21/03/19 14:58	General View											Load JPG	☒			
13	21/03/19 14:58	General View											Load JPG	☒			
14	21/03/19 14:58	General View											Load JPG	☒			
15	21/03/19 14:58	General View											Load JPG	☒			
16	21/03/19 14:58	General View											Load JPG	☒			
17	21/03/19 14:58	General View											Load JPG	☒			
18	21/03/19 14:58	General View											Load JPG	☒			
19	21/03/19 14:58	General View											Load JPG	☒			
20	21/03/19 14:58	General View											Load JPG	☒			
21	21/03/19 14:58	General View											Load JPG	☒			
22	21/03/19 14:58	General View											Load JPG	☒			
23	21/03/19 14:58	General View											Load JPG	☒			
24	21/03/19 14:58	General View											Load JPG	☒			
25	21/03/19 14:58	General View											Load JPG	☒			
26	21/03/19 14:58	General View											Load JPG	☒			
27	21/03/19 14:58	General View											Load JPG	☒			
28	21/03/19 14:58	General View											Load JPG	☒			
29	21/03/19 14:58	General View											Load JPG	☒			
30	21/03/19 14:58	General View											Load JPG	☒			
31	21/03/19 14:58	General View											Load JPG	☒			
32	21/03/19 14:58	General View											Load JPG	☒			
33	21/03/19 14:58	General View											Load JPG	☒			
34	21/03/19 14:59	Dismantled Parts											Load JPG	☒			
35	21/03/19 14:59	Dismantled Parts											Load JPG	☒			

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	21/03/19 14:59	Dismantled Parts		☒
37	21/03/19 14:59	Dismantled Parts		☒
38	21/03/19 14:59	Dismantled Parts		☒
39	21/03/19 14:59	Dismantled Parts		☒
40	21/03/19 14:59	Dismantled Parts		☒
41	21/03/19 14:59	Dismantled Parts		☒
42	21/03/19 14:59	Dismantled Parts		☒
43	21/03/19 14:59	Dismantled Parts		☒
44	21/03/19 14:59	Dismantled Parts		☒
45	21/03/19 14:59	Dismantled Parts		☒
46	21/03/19 14:59	Dismantled Parts		☒
47	21/03/19 14:59	Dismantled Parts		☒
48	21/03/19 14:59	Dismantled Parts		☒
49	21/03/19 14:59	Dismantled Parts		☒
50	21/03/19 14:59	Dismantled Parts		☒
51	21/03/19 14:59	Dismantled Parts		☒
52	21/03/19 14:59	Dismantled Parts		☒
53	21/03/19 14:59	Dismantled Parts		☒
54	21/03/19 14:59	Dismantled Parts		☒
55	21/03/19 14:59	Dismantled Parts		☒
56	21/03/19 14:59	Dismantled Parts		☒
57	21/03/19 14:59	Dismantled Parts		☒
58	21/03/19 14:59	Dismantled Parts		☒
59	21/03/19 14:59	Dismantled Parts		☒
60	21/03/19 14:59	Dismantled Parts		☒
61	21/03/19 14:59	Dismantled Parts		☒
62	21/03/19 14:59	Dismantled Parts		☒
63	21/03/19 14:59	Dismantled Parts		☒
64	21/03/19 14:59	Dismantled Parts		☒
65	21/03/19 14:59	Dismantled Parts		☒
66	21/03/19 14:59	Dismantled Parts		☒
67	21/03/19 14:59	Dismantled Parts		☒
68	21/03/19 14:59	Dismantled Parts		☒
69	21/03/19 14:59	Dismantled Parts		☒
70	21/03/19 14:59	Dismantled Parts		☒
71	21/03/19 14:59	Dismantled Parts		☒
72	21/03/19 14:59	Dismantled Parts		☒
73	21/03/19 14:59	Dismantled Parts		☒
74	21/03/19 14:59	Dismantled Parts		☒
75	21/03/19 14:59	Dismantled Parts		☒
76	21/03/19 14:59	Dismantled Parts		☒
77	21/03/19 14:59	Dismantled Parts		☒
78	21/03/19 14:59	Dismantled Parts		☒
79	21/03/19 14:59	Dismantled Parts		☒
80	21/03/19 14:59	Dismantled Parts		☒
81	21/03/19 14:59	Dismantled Parts		☒
82	21/03/19 14:59	Dismantled Parts		☒
83	21/03/19 14:59	Dismantled Parts		☒
84	21/03/19 14:59	Dismantled Parts		☒
85	21/03/19 14:59	Dismantled Parts		☒
86	21/03/19 14:59	Dismantled Parts		☒
87	21/03/19 14:59	Dismantled Parts		☒
88	21/03/19 14:59	Dismantled Parts		☒
89	21/03/19 14:59	Dismantled Parts		☒
90	21/03/19 14:59	Dismantled Parts		☒
91	21/03/19 14:59	Dismantled Parts		☒

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
92	21/03/19 14:59	Dismantled Parts		☒
93	21/03/19 14:59	Dismantled Parts		☒
94	21/03/19 14:59	Dismantled Parts		☒
95	21/03/19 14:59	Dismantled Parts		☒
96	21/03/19 14:59	Dismantled Parts		☒
97	21/03/19 14:59	Dismantled Parts		☒
98	21/03/19 14:59	Dismantled Parts		☒
99	21/03/19 14:59	Dismantled Parts		☒
100	21/03/19 14:59	Dismantled Parts		☒
101	21/03/19 14:59	Dismantled Parts		☒
102	21/03/19 14:59	Dismantled Parts		☒
103	21/03/19 14:59	Dismantled Parts		☒
104	21/03/19 14:59	Dismantled Parts		☒
105	21/03/19 14:59	Dismantled Parts		☒
106	21/03/19 14:59	Dismantled Parts		☒
107	21/03/19 14:59	Dismantled Parts		☒
108	21/03/19 14:59	Dismantled Parts		☒
109	21/03/19 14:59	Dismantled Parts		☒
110	21/03/19 14:59	Dismantled Parts		☒
111	21/03/19 14:59	Dismantled Parts		☒
112	21/03/19 14:59	Dismantled Parts		☒
113	21/03/19 14:59	Dismantled Parts		☒
114	21/03/19 14:59	Dismantled Parts		☒
115	21/03/19 14:59	Dismantled Parts		☒
116	21/03/19 14:59	Dismantled Parts		☒
117	21/03/19 14:59	Dismantled Parts		☒
118	21/03/19 14:59	Dismantled Parts		☒
119	21/03/19 14:59	Dismantled Parts		☒
120	21/03/19 14:59	Dismantled Parts		☒
121	21/03/19 14:59	Dismantled Parts		☒
122	21/03/19 14:59	Dismantled Parts		☒
123	21/03/19 14:59	Dismantled Parts		☒
124	21/03/19 14:59	Dismantled Parts		☒
125	21/03/19 14:59	Dismantled Parts		☒
126	21/03/19 14:59	Dismantled Parts		☒
127	21/03/19 14:59	Dismantled Parts		☒
128	21/03/19 14:59	Dismantled Parts		☒
129	21/03/19 14:59	Dismantled Parts		☒
130	21/03/19 14:59	Dismantled Parts		☒
131	21/03/19 14:59	Dismantled Parts		☒
132	21/03/19 14:59	Dismantled Parts		☒
133	21/03/19 14:59	Dismantled Parts		☒
134	21/03/19 14:59	Dismantled Parts		☒
135	21/03/19 14:59	Dismantled Parts		☒
136	21/03/19 14:59	Dismantled Parts		☒
137	21/03/19 14:59	Dismantled Parts		☒
138	21/03/19 14:59	Dismantled Parts		☒
139	21/03/19 14:59	Dismantled Parts		☒
140	21/03/19 14:59	Dismantled Parts		☒
141	21/03/19 14:59	Dismantled Parts		☒
142	21/03/19 14:59	Dismantled Parts		☒
143	21/03/19 14:59	Dismantled Parts		☒
144	21/03/19 14:59	Dismantled Parts		☒
145	21/03/19 14:59	Dismantled Parts		☒
146	21/03/19 14:59	Dismantled Parts		☒
147	21/03/19 15:00	Photo After Spray		☒

Video				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
148	21/03/19 15:00	Photo After Spray		Load JPG	☒
149	21/03/19 15:00	Photo After Spray		Load JPG	☒
150	21/03/19 15:00	Photo After Spray		Load JPG	☒
151	21/03/19 15:00	Photo After Spray		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	10/01/19 14:19	TP ESTIMATE - MARKED		Load PDF	
2	14/06/19 12:43	RENTAL RECEIPT		Load PDF	
3	14/06/19 12:43	RENTAL MILEAGE		Load PDF	
4	14/06/19 12:43	LTA SEARCH		Load PDF	
5	14/06/19 12:43	LETTER TO OI		Load PDF	
6	25/09/19 17:00	EMAIL FROM WSP DD 190919		Load PDF	
7	25/09/19 17:06	BREAKDOWN		Load PDF	
8	25/09/19 17:13	Work Chart		Load PDF	
9	17/10/19 12:11	WORKSHOP INVOICE		Load PDF	
10	17/10/19 12:11	AUTHORISATION TO ACT FORM		Load PDF	
11	17/10/19 12:11	Release Voucher		Load PDF	
12	17/10/19 12:11	LOD		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print	
1	04/01/19 10:26	OI GIA REPORT		Load PDF	
2	04/01/19 15:38	TP GIA		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLH1072B (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHB1884D (TP veh)		
Date of Accident:	28/12/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	113,774.40
Final Repair Cost	:	\$	24,550.00
Loss of Use	:	\$	1,150.00 23.00 days at \$50.00 per day
Rental (if any)	:	\$	2,374.98 23 days
LTA / GIA Search Fee	:	\$	7.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	28,081.98

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ 0 _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	SMRT Taxis Pte Ltd	:	\$ 28,081.98
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

17 Oct
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19000123/NEA3Q2

Date: 17/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100487879
 Claimant Vehicle No: SHB1884D Insured Vehicle No: SLH1072B
 Date of Loss: 28/12/2018 Nature of Claim: TP Claim No: 6761463391SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB1884D
 Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Engine No: 2ZR1385773
 Reg. Date: 25/06/2014 (Man. Year: 2014) Chassis No: JTDKN36U305746581
 Colour: Maroon Odometer: 0 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Achilles 5 mm Rear Left Side: Achilles 5 mm
 Front Right Side: Achilles 5 mm Rear Right Side: Achilles 5 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	100,312.40	27,849.35	72,463.05	72.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,462.00	2,120.00	11,342.00	84.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	113,774.40	29,969.35	83,805.05	73.66
Approved Total (Overridden) (S\$)		24,550.00		
Nett Amount (S\$)	113,774.40	24,550.00	89,224.40	78.42
+ Loss of Use (23.0 x S\$50.00/day) (S\$)		1,150.00		
+ Car Rental (23.0 x S\$103.26/day) (S\$)		2,374.98		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		28,081.98		

INSPECTION

Date of Assignment: 02/01/2019

Date Inspected: 02/01/2019 Inspected At:

SMRT Automotive Services Pte Ltd
 (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705

Estimated Period of Repair: 14.0 days

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER ENERGY ABSORBER FRT (DISC 25%)	Deformed	78.80 F	*59.10 F
2	1	*BUMPER FRT (DISC 25%)	Cracked	482.00 F	*361.50 F
3	1	*BUMPER REAR (DISC 25%)	Cracked	458.60 F	*343.95 F
4	1	*BUMPER REINFORCEMENT FRT (DISC 25%)	Bent	498.40 F	*373.80 F
5	1	*COVER ,FR BUMPER HOLE LH (DISC 25%)	Deformed	18.50 F	*13.88 F
6	1	*EMBLEM FRONT (DISC 25%)	Necessary	86.50 F	*64.88 F
7	1	*BRACKET ,FR BUMPER (DISC 25%)	Bent	110.40 F	*82.80 F
8	1	*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	16.10 F	*12.08 F
9	1	*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	16.10 F	*12.08 F
10	1	*ARM SUB-ASSY ,FR BUMPER LH (DISC 25%)	Bent	250.40 F	*187.80 F
11	1	*ARM SUB-ASSY ,FR BUMPER RH (DISC 25%)	Bent	250.40 F	*187.80 F
12	1	*EMBLEM REAR (DISC 25%)	Necessary	60.30 F	*45.23 F
13	1	*HOOD END PANEL SEAL (DISC 25%)	Necessary	35.50 F	*26.63 F
14	1	*HOOD HINGE LH (DISC 25%)	Bent	55.90 F	*41.93 F
15	1	*HOOD HINGE RH (DISC 25%)	Bent	55.90 F	*41.93 F
16	1	*HOOD LOCK (DISC 25%)	Jammed	128.90 F	*96.68 F
17	1	*HOOD PANEL (DISC 25%)	Bent	748.10 F	*561.08 F
18	1	*MOULDING BACK WINDOW ,LOWER NO.1 (DISC 25%)	Necessary	29.40 F	*22.05 F
19	1	*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
20	1	*NAME PLATE (PRIUS) (DISC 25%)	Necessary	60.80 F	*45.60 F
21	1	*NAME PLATE (TOYOTA) (DISC 25%)	Necessary	51.90 F	*38.93 F
22	1	*TAIL GATE DOOR GLASS MOULDING ,LH (DISC 25%)	Necessary	29.40 F	*22.05 F
23	1	*TAIL GATE DOOR GLASS MOULDING ,RH (DISC 25%)	Necessary	29.40 F	*22.05 F
24	1	*TAILGATE ASY (DISC 25%)	Deformed	1,007.90 F	*755.93 F
25	1	*TAILGATE OUTSIDE GARNISH (DISC 25%)	Deformed	504.90 F	*378.68 F
26	1	*WINDSCREEN FRT (DISC 25%)	Cracked	1,543.80 F	*1,157.85 F
27	1	*WINDSCREEN MOULDING FRT (DISC 25%)	Necessary	57.60 F	*43.20 F
28	1	*BUMPER LID COVER RR/RH (DISC 25%)	Cracked	118.10 F	*88.57 F
29	1	*CABLE ASSY ,HOOD (DISC 25%)	Bent	52.20 F	*39.15 F
30	1	*END PANEL COVER ,DECK TRIM RR (DISC 25%)	Cracked	121.10 F	*90.83 F
31	1	*BUMPER REINFORCEMENT REAR (DISC 25%)	Bent	205.70 F	*154.28 F
32	1	*FAN SHROUD (DISC 25%)	Broken	244.50 F	*183.38 F
33	1	*MEMBER SUB-ASSY ,RR LH (DISC 25%)	Deformed	174.10 F	*130.57 F
34	1	*EXHAUST HEAT SHIELD ,REAR (DISC 25%)	Distorted	107.40 F	*80.55 F
35	1	*ARM SUB-ASSY ,RR BUMPER LH (DISC 25%)	Bent	139.60 F	*104.70 F
36	1	*TAILGATE DOOR WEATHERSTRIP (DISC 25%)	Deformed	353.40 F	*265.05 F
37	1	*AIR CLEANER ASSY (DISC 25%)	Broken	929.90 F	*697.43 F
38	1	*FAN SHROUD TOP (DISC 25%)	Broken	99.60 F	*74.70 F
39	1	*BUMPER SUPPORT F/LH (DISC 25%)	Cracked	76.40 F	*57.30 F
40	1	*FAN BLADE (DISC 25%)	Broken	158.60 F	*118.95 F
41	1	*FENDER LINER FRT/LH (DISC 25%)	Missing	171.70 F	*128.78 F
42	1	*BUMPER LIP REAR (DISC 25%)	Cracked	228.90 F	*171.68 F
43	1	*EXHAUST TAIL PIPE (DISC 25%)	Bent	656.20 F	*492.15 F
44	1	*END PANEL COVER ,DECK TRIM HOLE (DISC 25%)	Distorted	46.10 F	*34.58 F
45	1	*BUMPER LIP COVER RR/LH (DISC 25%)	Cracked	72.20 F	*54.15 F
46	1	*UNDER COVER SUB-ASSY ,RR FLOOR (DISC 25%)	Deformed	514.50 F	*385.88 F
47	1	*INLET ASSY ,AIR (DISC 25%)	Cracked	232.50 F	*174.38 F
48	1	*RADIATOR ASSY ,UPPER (DISC 25%)	Bent	679.60 F	*509.70 F
49	1	*SPARE TYRE PANEL (DISC 25%)	Deformed	667.70 F	*500.78 F

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
50	1	*ARM SUB-ASSY ,RR BUMPER RH (DISC 25%)	Bent	139.60 F	*104.70 F
51	1	*BUMPER GRILLE SUB-ASSY ,LOWER (DISC 25%)	Distorted	311.10 F	*233.33 F
52	1	*SUPPORT SUB-ASSY (DISC 25%)	Bent	1,460.40 F	*1,095.30 F
53	1	*WIPER GARNISH (DISC 25%)	Cut	614.00 F	*460.50 F
54	1	*TANK ASSY ,INVERTER (DISC 25%)	Cracked	364.30 F	*273.23 F
55	1	*PROTECTOR ,SPARE (DISC 25%)	Distorted	143.70 F	*107.77 F
56	1	*BUMPER LIP FRT (DISC 25%)	Missing	139.60 F	*104.70 F
57	1	*FENDER LINER PAD ,FR WHEEL ,LH (DISC 25%)	Missing	49.30 F	*36.98 F
58	1	*WIPER GARNISH COVER ,LH (DISC 25%)	Broken	23.80 F	*17.85 F
59	1	*BUMPER SIDE RETAINER RR/LH (DISC 25%)	Cracked	94.80 F	*71.10 F
60	1	*A/C CONDENSER (DISC 25%)	Bent	1,181.90 F	*886.43 F
61	1	*BUMPER SUPPORT F/RH (DISC 25%)	Cracked	76.40 F	*57.30 F
62	1	*WIPER GARNISH COVER ,RH (DISC 25%)	Missing	23.80 F	*17.85 F
63	1	*RADIATOR ASSY (DISC 25%)	Bent	1,496.90 F	*1,122.68 F
64	1	*END PANEL (DISC 25%)	Bent	602.10 F	*451.58 F
65	1	*GRILLE RADIATOR (DISC 25%)	Cracked	310.60 F	*232.95 F
66	1	*FAN BLADE NO 2 (DISC 25%)	Cracked	204.20 F	*153.15 F
67	1	*HEAD LAMP LH (DISC 10%)	Cracked	945.20 F	*850.68 F
68	1	*HEAD LAMP RH (DISC 10%)	Cracked	945.20 F	*850.68 F
69	1	*WIRE, ENGINE ROOM (DISC 10%)	Cut	5,567.10 F	*5,010.39 F
70	1	*INVERTER W CONVERTER (DISC 10%)	Cracked	5,390.20 F	*4,851.18 F
71	1	*ANTENNA,ELECTRICAL LOWER REAR (DISC 10%)	Deformed	157.40 F	*141.66 F
72	1	*FOR SOLAR FILM (SN)	Necessary	950.00 F	*600.00 F
73	2	*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
74	1	*NUMBER PLATE (SN)	Dented	15.00 F	*15.00 F
75	1	*NUMBER PLATE FRAME (SN)	Cracked	12.00 F	*12.00 F
76	2	*SEALANT W/SCREEN (SN)	Necessary	74.00 F	*74.00 F
77	3	*SEALANT W/SCREEN (SN)	Necessary	111.00 F	*111.00 F
78	1	*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
79	1	*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
80	1	*SENSOR REVERSE (SN)	Cracked	180.00 F	*180.00 F
81	1	*PROTECTOR ,SPARE	Serviceable	143.70 F	*- F
82	1	*PUMP ASSY ,WATER	Serviceable	454.00 F	*- F
83	1	*QUARTER GLASS FRT/LH	Serviceable	234.90 F	*- F
84	1	*QUARTER GLASS FRT/RH	Serviceable	234.90 F	*- F
85	1	*QUARTER GLASS RR/LH	Serviceable	168.10 F	*- F
86	1	*QUARTER GLASS RR/RH	Serviceable	846.50 F	*- F
87	1	*RADIATOR ASSY ,UPPER	Serviceable	679.60 F	*- F
88	1	*RADIATOR HOSE LOWER	Serviceable	42.40 F	*- F
89	1	*RADIATOR HOSE ,BYPASS NO.1	Serviceable	37.20 F	*- F
90	1	*BUMPER FRT ABSORBER LOWER	Serviceable	127.70 F	*- F
91	1	*BUMPER GRILLE SUB-ASSY ,LOWER	Serviceable	311.10 F	*- F
92	1	*BUMPER LIP COVER RR/LH	Serviceable	72.20 F	*- F
93	1	*BUMPER LIP COVER RR/RH	Serviceable	118.10 F	*- F
94	1	*BUMPER LIP FRT	Serviceable	139.60 F	*- F
95	1	*BUMPER LIP REAR	Serviceable	228.90 F	*- F
96	1	*BUMPER REINFORCEMENT REAR	Serviceable	205.70 F	*- F
97	1	*BUMPER SEAL ,RR LH	Serviceable	88.90 F	*- F
98	1	*BUMPER SEAL ,RR RH	Serviceable	65.70 F	*- F
99	1	*BUMPER SIDE RETAINER RR/LH	Serviceable	94.80 F	*- F
100	1	*BUMPER SIDE RETAINER RR/RH	Serviceable	94.80 F	*- F
101	1	*BUMPER SUPPORT F/LH	Serviceable	76.40 F	*- F
102	1	*BUMPER SUPPORT F/RH	Serviceable	76.40 F	*- F
103	1	*CABLE ASSY ,HOOD	Serviceable	52.20 F	*- F
104	1	*CABLE ,GENERATOR	Serviceable	169.10 F	*- F
105	1	*CABLE ,MOTOR INVERTER	Serviceable	199.10 F	*- F
106	1	*CAMERA ASSY ,TELEVISION ,RR	Serviceable	1,436.60 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
107	1		*CARRIER ,SPARE	Serviceable	19.70 F	*- F
108	1		*CLAMP ,HOOD LOCK	Serviceable	5.90 F	*- F
109	1		*COOLANT	Serviceable	12.32 F	*- F
110	1		*COOLANT RESERVE TANK	Serviceable	395.30 F	*- F
111	1		*COVER ASSY ,INVERTER,LH	Serviceable	54.50 F	*- F
112	1		*CCOVER ,FR BUMPER HOLE LH	Serviceable	18.50 F	*- F
113	1		*COVER ,RADIATOR	Serviceable	122.80 F	*- F
114	1		*CUSHION ,RADIATOR	Serviceable	11.30 F	*- F
115	1		*CUSHION ,SPARE WHEEL	Serviceable	230.80 F	*- F
116	1		*DEFLECTOR ,RADIATOR LH	Serviceable	77.00 F	*- F
117	1		*DEFLECTOR ,RADIATOR RH	Serviceable	83.50 F	*- F
118	1		*DOOR FRT/LH	Serviceable	894.40 F	*- F
119	1		*DOOR FRT/RH	Serviceable	894.40 F	*- F
120	1		*DOOR RR/LH	Serviceable	954.50 F	*- F
121	1		*ARM SUB-ASSY ,RR BUMPER LH	Serviceable	139.60 F	*- F
122	1		*ARM SUB-ASSY ,RR BUMPER RH	Serviceable	139.60 F	*- F
123	1		*BOARD ASSY ,RR RH	Serviceable	379.20 F	*- F
124	1		*BOARD ,RR FLOOR	Serviceable	392.30 F	*- F
125	1		*BOX ,DECK FLOOR ,COVER LH	Serviceable	230.10 F	*- F
126	1		*BOX ,DECK FLOOR LH	Serviceable	196.80 F	*- F
127	1		*BOX ,DECK FLOOR RR	Serviceable	649.70 F	*- F
128	1		*BOX,RR FLOOR ,BOARD	Serviceable	679.60 F	*- F
129	1		*BRACKET ,FR TURN CENTER LH	Serviceable	58.20 F	*- F
130	1		*BRACKET ,FR TURN LOWER LH	Serviceable	26.00 F	*- F
131	1		*BRACKET ,FR TURN LOWER RH	Serviceable	26.00 F	*- F
132	1		*BRACKET ,FR TURN UPPER LH	Serviceable	24.40 F	*- F
133	1		*BRACKET ,FR TURN UPPER RH	Serviceable	24.40 F	*- F
134	1		*BRACKET ,INVERTER,NO.1	Serviceable	31.40 F	*- F
135	1		*BREAKDOWN SIGN	Serviceable	35.00 F	*- F
136	1		*RADIATOR ASSY	Serviceable	1,496.90 F	*- F
137	1		*3RD BRAKE LAMP	Serviceable	231.30 F	*- F
138	1		*A/C CONDENSER	Serviceable	1,181.90 F	*- F
139	1		*AIR CLEANER ASSY	Serviceable	929.90 F	*- F
140	1		*ANTENNE ,ELECTRICAL LOWER REAR	Serviceable	157.40 F	*- F
141	1		*WIPER GARNISH COVER,RH	Serviceable	23.80 F	*- F
142	1		*WIPER PANEL SUBASSY ,COWL	Serviceable	588.40 F	*- F
143	1		*WIPER ,BACK DOOR ,NO.1	Serviceable	582.40 F	*- F
144	1		*WIRE ,ENGINE ROOM	Serviceable	5,567.10 F	*- F
145	1		*WIRE ,ENGINE ROOM,NO.3	Serviceable	242.00 F	*- F
146	1		*WIRE ,ENGINE ,NO.2	Serviceable	195.00 F	*- F
147	1		*WIRE ,FLOOR	Serviceable	1,675.00 F	*- F
148	1		*WIRE ,FLOOR ,NO.2	Serviceable	1,305.40 F	*- F
149	1		*WIRE ,FRAME	Serviceable	1,680.90 F	*- F
150	1		*END PANEL	Serviceable	602.10 F	*- F
151	1		*END PANEL COVER ,DECK TRIM HOLE	Serviceable	46.10 F	*- F
152	1		*END PANEL COVER ,DECK TRIM ,RR	Serviceable	121.10 F	*- F
153	1		*EXHAUST HEAT SHIELD ,REAR	Serviceable	107.40 F	*- F
154	1		*EXHAUST PIPE FRT	Serviceable	4,184.70 F	*- F
155	1		*EXHAUST TAIL PIPE	Serviceable	656.20 F	*- F
156	1		*FAN BLADE	Serviceable	158.60 F	*- F
157	1		*FAN BLADE NO.2	Serviceable	204.20 F	*- F
158	1		*FAN MOTOR NO 1	Serviceable	538.30 F	*- F
159	1		*FAN MOTOR NO 2	Serviceable	538.30 F	*- F
160	1		*FAN SHROUD	Serviceable	244.50 F	*- F
161	1		*FAN SHROUD TOP	Serviceable	99.60 F	*- F
162	1		*FENDER APRON SUB FRT/LH	Serviceable	637.80 F	*- F
163	1		*FENDER FRT/LH	Serviceable	723.40 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
164	1		*FENDER FRT/RH	Serviceable	723.40 F	*- F
165	1		*FENDER LINER FRT/LH	Serviceable	171.70 F	*- F
166	1		*FENDER LINER FRT/RH	Serviceable	171.70 F	*- F
167	1		*FENDER LINER PAD ,FR WHEEL ,LH	Serviceable	49.30 F	*- F
168	1		*FENDER LINER RR/LH	Serviceable	141.30 F	*- F
169	1		*FENDER LINER RR/RH	Serviceable	141.30 F	*- F
170	1		*FENDER RR/LH	Serviceable	766.80 F	*- F
171	1		*FENDER RR/RH	Serviceable	766.80 F	*- F
172	1		*FLOOR PANEL RR/LH	Serviceable	102.00 F	*- F
173	1		*FLOOR PANEL RR/RH	Serviceable	209.90 F	*- F
174	1		*FOG LAMP LH	Serviceable	280.10 F	*- F
175	1		*FOG LAMP RH	Serviceable	295.20 F	*- F
176	1		*FUSE BLOCK ,COVER LOWER	Serviceable	18.50 F	*- F
177	1		*FUSE BLOCK ,TOP COVER	Serviceable	82.30 F	*- F
178	1		*GRILLE RADIATOR LOWER NO.2	Serviceable	94.60 F	*- F
179	1		*GRILLE ,RADIATOR	Serviceable	310.60 F	*- F
180	1		*HOOD PANEL INSULATOR	Serviceable	390.50 F	*- F
181	1		*HORN ASSY ,HIGH	Serviceable	110.40 F	*- F
182	1		*HORN ASSY ,LOW	Serviceable	110.40 F	*- F
183	1		*HOSE SUB-ASSY ,DISCHARGE	Serviceable	386.90 F	*- F
184	1		*HOSE ,INVERTER COOLING NO.2	Serviceable	90.10 F	*- F
185	1		*HOSE ,INVERTER COOLING NO.5	Serviceable	125.30 F	*- F
186	1		*HOSE ,INVERTER COOLING NO.6	Serviceable	37.40 F	*- F
187	1		*HOSE INVERTER NO.1	Serviceable	80.00 F	*- F
188	1		*INLET ASSY AIR	Serviceable	232.50 F	*- F
189	1		*INVERTER BRACKET TRAY	Serviceable	251.60 F	*- F
190	1		*INVERTER COVER SUB ASSY	Serviceable	39.60 F	*- F
191	1		*INVERTER W CONVERTER	Serviceable	5,390.20 F	*- F
192	1		*LENS & BODY ,FR TURN LH	Serviceable	511.80 F	*- F
193	1		*LENS & BODY ,FR TURN RH	Serviceable	511.80 F	*- F
194	1		*LICENSE PLATE LAMP	Serviceable	35.70 F	*- F
195	1		*MEMBER SUB-ASSY ,RR LH	Serviceable	174.10 F	*- F
196	1		*MEMBER SUB-ASSY ,RR RH	Serviceable	174.10 F	*- F
197	1		*NUMBER PLATE	Serviceable	15.00 F	*- F
198	1		*NUMBER PLATE FRAME	Serviceable	12.00 F	*- F
199	1		*PANEL ASSY ,DECK LH	Serviceable	307.00 F	*- F
200	1		*PANEL ASSY ,DECK RH	Serviceable	307.00 F	*- F
201	1		*STRIKER ,BACK DOOR	Serviceable	48.90 F	*- F
202	1		*SUPPORT EXHAUST PIPE ,NO.4	Serviceable	40.30 F	*- F
203	1		*SUPPORT SUB-ASSY	Serviceable	1,460.40 F	*- F
204	1		*SUPPORT EXHAUST REAR	Serviceable	33.60 F	*- F
205	1		*SUPPORT ,RADIATOR	Serviceable	18.50 F	*- F
206	1		*SUPPORT ,RADIATOR ,LH	Serviceable	17.70 F	*- F
207	1		*SUPPORT ,RADIATOR RH	Serviceable	54.50 F	*- F
208	1		*SWITCH ASSY ,BACK DOOR OPENER	Serviceable	146.10 F	*- F
209	1		*TAIL LAMP BRACKET ,LH	Serviceable	30.70 F	*- F
210	1		*TAIL LAMP BRACKET ,RH	Serviceable	30.70 F	*- F
211	1		*TAIL LAMP LH	Serviceable	548.40 F	*- F
212	1		*TAIL LAMP RH	Serviceable	557.80 F	*- F
213	1		*TAILGATE DOOR LOCK	Serviceable	444.10 F	*- F
214	2		*TAILGATE DOOR HINGE LH/RH	Serviceable	58.30 F	*- F
215	1		*TAILGATE DOOR STAY LH	Serviceable	241.50 F	*- F
216	1		*TAILGATE DOOR STAY RH	Serviceable	241.50 F	*- F
217	1		*TAILGATE DOOR WEATHERSTRIP	Serviceable	353.40 F	*- F
218	1		*TAILGATE LOCK ,COVER	Serviceable	15.70 F	*- F
219	1		*TAILGATE TRIM ,LOWER	Serviceable	180.70 F	*- F
220	1		*TAILGATE ,BOARD ASSY	Serviceable	246.90 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
221	1		*TANK ASSY ,INVERTER	Serviceable	364.30 F	*- F
222	1		*THERMISTOR ASSY	Serviceable	107.00 F	*- F
223	1		*TROUGH ,BACK DOOR	Serviceable	110.90 F	*- F
224	1		*TROUGH ,BACK DOOR LH	Serviceable	110.90 F	*- F
225	1		*TUBE & ACCESSORY	Serviceable	631.90 F	*- F
226	1		*TYRE	Serviceable	126.74 F	*- F
227	1		*TYRE	Serviceable	126.74 F	*- F
228	1		*UNDER COVER SUBASSY ,RR FLOOR	Serviceable	514.50 F	*- F
229	1		*WHEEL ,DISC	Serviceable	1,490.20 F	*- F
230	1		*WIPER GARNISH	Serviceable	614.00 F	*- F
231	1		*WIPER GARNISH COVER ,LH	Serviceable	23.80 F	*- F
232	1		*SEALANT SIKAFLEX	Serviceable	37.00 F	*- F
233	1		*SENSOR REVERSE	Serviceable	180.00 F	*- F
234	1		*SPACER ,RR FLOOR	Serviceable	130.60 F	*- F
235	1		*SPARE TYRE PANEL	Serviceable	667.70 F	*- F
236	1		*SPOILER REAR	Serviceable	953.70 F	*- F
237	1		*RADIATOR HOSE ,BYPASS NO.2	Serviceable	29.00 F	*- F
238	1		*RADIATOR HOSE ,BYPASS NO.3	Serviceable	37.20 F	*- F
239	1		*RADIATOR HOSE ,BYPASS NO.4	Serviceable	37.20 F	*- F
240	1		*RADIATOR LOWER SUPPORT	Serviceable	876.30 F	*- F
241	1		*RADIATOR TOP HOSE NO 1	Serviceable	42.40 F	*- F
242	1		*REINFORCEMENT ,RR	Serviceable	34.60 F	*- F
243	1		*RESONATOR ,INTAKE	Serviceable	57.20 F	*- F
244	1		*FAN MOTOR NO 2	Serviceable	538.30 F	*- F
245	1		*NAME PLATE (HYBRID)	Not Necessary	51.90 F	*- F
246	1		*NAME PLATE (HYBRID)	Not Necessary	51.90 F	*- F
247	1		*SEALANT W/SCREEN	Not Necessary	37.00 F	*- F
248	1		*SEALANT W/SCREEN	Not Necessary	37.00 F	*- F
249	1		*SEALANT W/SCREEN	Not Necessary	37.00 F	*- F
250	1		*SMRT LOGO	Not Necessary	7.80 F	*- F
251	1		*SMRT LOGO	Not Necessary	7.80 F	*- F
252	1		*STICKER DECAL 6555 8888	Not Necessary	21.60 F	*- F
253	1		*STICKER DECAL 6555 8888	Not Necessary	21.60 F	*- F
254	1		*STICKER DECAL SMRT (DOOR)	Not Necessary	60.00 F	*- F
255	1		*STICKER DECAL SMRT (DOOR)	Not Necessary	60.00 F	*- F
256	1		*FAN MOTOR NO1	Serviceable	538.30 F	*- F
257	1		*FENDER FRT/LH	Repair	723.40 F	*- F

F=Franchise part.

Total Parts (\$\$) 100,312.40 27,849.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	3,504.00	1,000.00
2	SPRAY PAINT	New	6,498.00	870.00
3	TO ALIGN CHASSIS	New	350.00	0.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	300.00	50.00
5	TO CHECK & RESET SYSTEM FUNCTION	New	350.00	50.00
6	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
7	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
8	TO INSPECT RR LIGHTING MECHANISM & WATER TEST RR LIGHTING FOR LEAKAGE	New	120.00	20.00
9	TO REMOVE & REFIT EXHAUST	New	120.00	0.00
10	TO REMOVE & REFIT REAR QUARTER GLASS LH	New	120.00	0.00
11	TO REMOVE & REFIT QUARTER GLASS RH	New	120.00	0.00
12	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	New	120.00	0.00
13	TO REMOVE & REFIX FRONT LHS/RHS QUARTER GLASS	New	240.00	0.00
14	TO REMOVE/REFIT SEAT	New	120.00	0.00
15	TO REMOVE/REFIX WINDSCREEN	New	120.00	50.00
16	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	0.00
17	TO REMOVE AND REFIT WIRE HARDNESS	New	300.00	0.00
18	TO REMOVE AND REFIX REAR WINDSCREEN	New	240.00	50.00
19	TO REPLACE SUNDRY PARTS	New	100.00	0.00
20	TO TESTAND REFIX REVERSE SENSOR SYSTEM	New	120.00	10.00
21	TO TOP UP A/C GAS	New	120.00	0.00
22	TO TRANSFER REAR TAILGATE MECHANISM	New	120.00	0.00
23	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			13,462.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >