

ASS. REC. BY:

REF

CS/MSG19000208/USD3n2

Special Instruction

Surveyor

Menmen

Marcus

ASSIGNMENT (Office)

From (Person)

Katherine Wong

of

MSG

Date/Time

4/11/19 @ 10:35am

Estimated Cost

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No:

SKT G985H

Insured:

YL 5963D

at Workshop m/s

Sen Auto

Tel:

9791 1515

of

Blk 18 Jellen Teram

Policy No:

28878178TM

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/12/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

10:53am 4/11/19

Person Contacted:

Mr. Nick

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	Insp: 210 turf club # A-29
	SKT G985H-X
	YL 5963D - CCS/AIG07003008/RDh
	DUA: 21/05/2007

(08/11/13) wef

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SK7698KHat Workshop m/s Sen Ahiof 979/1515

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

G/A / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SK7698KH Yr Regn: 61 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAIMake: Mercedes c.c. 1496Colour: Blue A/C: Insured / Std / Nil / NASp. Reading: 335.9 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: R411020503

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 2 mm R/Bal. 2 mmL/Bal. 2 mm L/Bal. 2 mmD.O.A. 28/12/18 D.O.I. 4/1/19

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No second hand parts. LTA 463017/1/19 confirmed L/S \$2400 with mch.07/01/19 Parts prices checked by marcus.07/01/19 @ 15:40 p.m. revised IA to Katherine Wong Chew Shang via messenger.07/01/19 Confirmed L/S \$2,400/- @ 3 days with marcus(\$ 2,190.40 red 48%)

RECEIVED 00 JAN 2019

Date/Time, File Page to?

☐ : Preli. Report1) Typist☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$1

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$ 2,400/- L/S)

150

10

160

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 07 Jan 2019

Preliminary Advice

Insured Vehicle No	: YL5963D	Accident Date	: 28/12/2018
TP Vehicle No	: SKT6985H	Assignment Date	: 04/01/2019
Make	: HONDA VEZEL	Est. Duration of Repair	: 3 days
Date of Inspection	: 04/01/2019		
Inspection At	: Sen Auto Trading (HQ) 210 TURF CLUB ROAD, THE GRANDSTAND CAR MALL LOT A29 Singapore 287995		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,590.40
Revised Amount	:S\$	3,014.32
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,014.32

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jan 2019 08:38		04 Jan 2019 10:35 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	AQUABLU POOLS PTE LTD, Co. Reg. No.: NA		
Main Claimant:	LIM KOK TIONG (LIN GUZHONG), ID: S7620647C		
Vehicle Reg. No.:	SKT6985H	Date of Loss:	28/12/2018 00:00 - :59 [42 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	28878178TMV (Third Party Only) Coverage: 29/01/2018 - 28/01/2019
Vehicle Reg. No. (Insured):	YL5963D	Policy No. (Claimant):	
		Excess:	
Repairer:	- Not Applicable - (-)		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/01/2019]		
Driver/Custodian (Insured):	SEET YIN HONG CHRISTOPHER (), NRIC: S1740577B		
Adj Asg. Remarks:	Third Party Pre-Repair Survey. TP selected LKK (Mr Marcus Chua) to be SJE, please arrange third party survey at Blk 18 Jalan Tenteram Contact : Mr Nick Lau @ 791 1515 Liability : 100%		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 0647C

Vehicle Details

Vehicle No.: SKT6985H
Vehicle to be Exported: No
Intended Deregistration Date: 07 Jan 2019
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5X CVT
Primary Colour: Blue
Manufacturing Year: 2015
Engine No.: L15B3520519
Chassis No.: RU11020503
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$18,529.00
Original Registration Date: 19 Jun 2015
First Registration Date: 19 Jun 2015
Transfer Count: 1
Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 18 Jun 2025
PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 18 Jun 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$66,000.00
COE Rebate Amount: \$42,551.00
Total Rebate Amount: \$46,301.00

The information contained herein is correct as at 07 Jan 2019

OK

SEN AUTO TRADING

210 Turf Club Road The Grandstand Car Mall Lot A29 SINGAPORE 287995

Mr Nick Lau Hp : 97971515

DATE: 2/1/2019

Name of Insurance Company : MSIG INSURANCE

DATE OF ACCIDEN : 28/12/18

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SKT6985H

TO SUPPLY :

NO	QTY	DESCRIPTION	LIST PRICE
1	1 PC	FRONT BUMPER 762. DO	\$ 817.80
2	10 PCS	FRONT BUMPER CLIPS 2er	\$ 50.00
3	2 PCS	FRONT BUMPER SIDE RETAINER 21.50 1/5 3er	\$ 43.00
4	1 PC	FRONT HEADLAMP 1759.90 cm/sec	\$ 1,820.20
5	1 PC	FRONT LH FENDER 2	\$ 394.90
6	2PCS	FRONT LH FENDER GARNISH 3er	\$ 174.50
7	1PC	FRONT BUMPER SIDE GARNISH 20% 3er	\$ 100.00
8		CHECK HARNESS	\$ 30.00
9		SPRAY PAINTING FOR DAMAGE PORTIONS	\$ 600.00
10		LABOUR CHARGE TO REPLACE /REPAIR DAMAGED PART	\$ 500.00
11		TUFF COAT	\$ 60.00

LKK Auto Consultants hence notify the Repairer of the following:

- To remove all parts for spray painting
- To include all parts in the survey
- Parts prices are subject to confirmation
- Third party liability is a "Without Prejudice" basis
- No claim for depreciation is allowed
- Supplementary amount must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Not Authorised
LKK
MORRIS
Tel: 62863581
3 dy.
4/1/19
Take Mr. Behn pay.

P-2867.90
less 20%
P-2294.32
labour-720.00
3014.32
less 20%
2411.45

\$ 4,590.40

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19000208/USD3N2

Date: 09/01/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28878178TMV
Claimant Vehicle No :	SKT6985H	Insured Vehicle No :	YL5963D
Date of Loss:	28/12/2018	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT6985H	Engine No:	L15B3520519
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11020503
Reg. Date:	19/06/2015 (Man. Year: 2015)	Odometer:	33591 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,400.40	2,294.32	1,106.08	32.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,190.00	720.00	470.00	39.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,590.40	3,014.32	1,576.08	34.33
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	4,590.40	2,400.00	2,190.40	47.72

INSPECTION

Date of Assignment:	04/01/2019	
Date Inspected:	04/01/2019 Inspected At:	Sen Auto Trading (HQ) 210 TURF CLUB ROAD, THE GRANDSTAND CAR MALL LOT A29 Singapore 287995
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Jan 2019)
Parts: M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKT6985H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	817.80 F	*762.00 FL
2	10		*FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
3	1		*FRONT BUMPER SIDE RETAINER	N/s Bent	43.00 F	*21.50 FL
4	1		*FRONT HEADLAMP	Cracked/Scratched	1,820.20 F	*1,759.90 FL
5	1		*FRONT LH FENDER	Repair	394.90 F	*- FL
6	2		*FRONT LH FENDER GARNISH	Grazed	174.50 F	*174.50 FL
7	1		*FRONT BUMPER SIDE GARNISH	Grazed	100.00 F	*100.00 FL
					Sub Total (\$\$)	3,400.40 2,867.90
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 573.58
					Total Parts (\$\$)	3,400.40 2,294.32

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK HARNESS	New	30.00	20.00
2	SPRAY PAINTING FOR DAMAGE PORTIONS	New	600.00	400.00
3	LABOUR CHARGE TO REPLACE/REPAIR DAMAGED PART	New	500.00	300.00
4	TUFF COAT	New	60.00	-
Gross Labour Cost (S\$)			1,190.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >