

ASS. REC. BY:

REF: CS/MSG19000222/Dsd3n2

Special Instruction:

Surveyor  
Menimen

Jynn

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

M&G

Date/Time:

4/1/19 @ 2.48pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SH 9483M

Insured:

SLB 27977

at Workshop m/s

Chunni Motor

Tel:

65425119

of

Blk 10 # 01-05/06 Amk Autopoint

Policy No:

290760740MY

Claim No:

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A.

03/01/2019

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

2.55pm @ 4/1/19

Person Contacted:

Jynn

Vehicle:

IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SH 9483M - NS/INCL 80/1126/K1sbn2 DVA: 17/06/2018
	SLB 27977-X:
15/01/19	@ 10:42 am. revised IA to Christina Wong via messenger

REF:

ASSIGNMENT

COE April 2024

From \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV \_\_\_\_\_  
 To Inspect Vehicle No. \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: **SH 9483 M** Yt Regn: **2016 April**  
 Type: **M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**  
 Truck / Trailer or \_\_\_\_\_  
 Make: **Hyundai I40** CC: **1685**  
 Colour: **Blue** A/C: **Insured / Std / NI / NA**  
 Sp. Reading: **390787** T/Radio: **Insured / Std / NI / NA**  
 Eng/No: **D4FDGU613743**  
 C/No: **KMHLB41UMGU087851**  
 Gen. Cond: **Good** / Fair / Poor / Burnt  
 Steering: **Good** / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: **Good** / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: **NY** / S/Rim / STD A/Rim or \_\_\_\_\_

(Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAG Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: **10** days Res.: Yes or No  
 Lum Sum: **20** % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS \_\_\_\_\_  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Tyre Size: F: **205/60 R16**  
 R: **— " —**  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **Hankook**  

Front	Rear
R/Bal: <b>5</b> mm	R/Bal: <b>5</b> mm
L/Bal: <b>5</b> mm	L/Bal: <b>5</b> mm

D.O.A. **03/01/2019** D.O.I. **07/01/2019**  
 Survey held at **Chunni AMK**  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
**0/8 Front y Front 0/8**  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time \_\_\_\_\_ Action / Instruction \_\_\_\_\_  
**MSIG SLB 27977**  
**after rep photo.**  
**12/02/19 Jinnu 2/5 16000/- with 10 days of rep**  
**(Red. \$ 11,497.88, 42%)**

RECEIVED 14 FEB 2019

Date/Time, File Pass to?  Preli. Report  
 Final Report  
 Date/Time, File Return to? **14/2 - typist**  
 Report Format : \_\_\_\_\_  
 Lump Sum / I.B.F. \$ **16000/-**

Days Of Repair: **10**  
 Resurvey No. of Trip: **2**  
 Add Fee:  Site Insp (\$)  
 Interview (\$)  
 Tech. Invs (\$)  
 Weekend (\$)  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 Photos: \_\_\_\_\_  
 Other: \_\_\_\_\_  
 TOTAL: **210**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Christina Wong

Date: 15 Jan 2019

**Preliminary Advice**

Insured Vehicle No	: SLB2797T	Accident Date	: 03/01/2019
TP Vehicle No	: SH9483M	Assignment Date	: 04/01/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 7 days
Date of Inspection	: 07/01/2019		
Inspection At	: Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint Singapore 568047		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s front & front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,497.88
Revised Amount	:S\$	5,460.88
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,460.88

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rot	Adj Submitted	Ins Auth'd	Status
Main	03 Jan 2019 17:04		04 Jan 2019 14:48 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HOW HEE FATT, ID: S1821447D		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SH9483M	Date of Loss:	03/01/2019 00:00 - :59 [32 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29076074QMY Coverage: 31/03/2018 - 30/03/2019
Vehicle Reg. No. (Insured):	SLB2797T	Policy No. (Claimant):	
		Excess:	
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/01/2019]		
Adj Asg. Remarks:	Liability down. TP agree to use LKK as the SJE. Contact Person: Ms Lynn / 65425119 or Ms Irene / 65427162.		

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MCD61000005 / ConlonDelGro Engineering Pte Ltd - Loyang  
 ENTRY DATE & TIME: 03/01/2019 11:04  
 SUBMITTED BY: Janet Lim Siang Gek

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/01/2019 11:04
Date Of Accident	03/01/2019 06:45
Exact Location Of Accident	ALJUNIED RD > GEYLANG X OF GEYLANG EAST CENTRAL
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH9483M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
<b>Vehicle Particulars</b>	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
<b>Driver</b>	
Name of Driver	NG TECK KEONG
NRIC No	S0074659B
Date Of Birth	24/06/1951
Occupation	OUTDOOR
Date Of Driving Pass	20/01/1971
Driving Experience	47 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92341790
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 74 MARINE DRIVE #10-45
Postcode	440074
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

**General Information of the Accident**

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER ATTACHED \* TYPE OF ACCIDENT :- HEAD TO SIDE

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SLB2797T
Vehicle Make/Model/Colour	MAZDA
<b>Details Of Properties</b>	
Vehicle Category	PRIVATE CAR
Name of Driver	HOW HEE FATT
NRIC/Passport Number	S1821447D
Contact Number	97667620
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT LH
No. Of Passenger (Including Driver)	

**SKETCH PLAN****IMPORTANT NOTICE**


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for Investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)

Date & Time: 03.01.2019@0900HRS

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:

NRIC/FIN No.: June Tan



CHUNNI MOTOR WORK PTE LTD

10 survey by [signature]

REPAIR ESTIMATE\*

VEHICLE NO : SH 9483M

DATE : 3.01.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

M8/G

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bonnet Dent			\$ 2,265.90	✓
	Bonnet Hinge (LH/RH) 5+		\$ 41.00	\$ 82.00	✓
	Bonnet Lock 5+			\$ 36.90	✓
	Bonnet Absorber S/C		\$ 58.10	\$ 116.20	X
	Bonnet Insulator NH			\$ 196.50	X
	Bonnet Insulator Clips NH			\$ 8.40	X
	Radiator Grille broken			\$ 1,110.10	✓
	Radiator Grille H Emblem NH			\$ 39.50	✓
	Front Bumper Cover broken			\$ 1,052.20	✓
	Front Bumper Sponge torn			\$ 99.20	✓
	Front Bumper Reinforcement 5+			\$ 402.10	✓
	Front Bumper Grille (RH) Crack			\$ 93.60	✓
	Front Bumper Grille Airduct (RH) broken			\$ 26.20	✓
	Front Bumper Lip S/C			\$ 54.90	X
	Front Bumper Bracket Top (RH) NH			\$ 22.40	X
	Front Bumper Bracket (RH) broken			\$ 24.60	✓
	Headlamp Support Top Cover NH			\$ 222.60	X
	Headlamp Support Panel Assy broken			\$ 907.40	✓
	Headlamp (LH/RH) O/S broken w/s wandy broken		\$ 1,388.00	\$ 2,776.00	✓
	Headlamp Halogen Bulb (RH) NH			\$ 14.40	X
	Radiator 5+   punctured			\$ 698.30	✓
	Radiator Fan Blade, Cowling, Motor Assy broken			\$ 792.95	✓
	Radiator Bracket (RH) NH			\$ 6.50	X
	Radiator Expansion Tank NH			\$ 28.30	X
	Radiator Guard, RH broken			\$ 20.00	✓
	Front Fender (RH) Dented			\$ 566.30	✓
	Front Fender Apron Panel (RH) Bnc			\$ 637.00	✓
	Front Fender Shield (RH) dislodged			\$ 174.90	✓
	Aircon Condenser 5+   punctured			\$ 927.50	✓
	Aircon Suction & Liquid Hose broken 5+			\$ 624.00	X ✓
	Aircon Discharge Hose broken 5+			\$ 162.60	X ✓
	Wiper Container broken			\$ 61.90	✓
	Wiper Container Motor Dam			\$ 75.00	✓
	Front Wheel Rim (RH) distorted			\$ 325.30	X ✓
	Front Wheel Hub Cap (RH) scratched			\$ 107.10	X ✓
	Front Wheel Bearing broken Dam			\$ 540.50	X ✓
	Front Shock Absorber (Assy) (RH) distorted			\$ 342.20	X ✓
	Front Shock Absorber Mounting (RH) NH			\$ 108.80	X
	Front Drive Shaft (RH) distorted			\$ 1,030.80	X ✓
	Rack & Pinion Assy broken Dam			\$ 969.60	X ✓
	STG Tie End distorted			\$ 62.60	X ✓
	Stabilizer Bar broken distorted			\$ 252.30	X ✓
	Stabilizer Bar Bush (RH) NH			\$ 16.40	X
	Stabilizer Bar Link broken distorted			\$ 61.10	X ✓
	Stabilizer Bracket NH			\$ 24.00	X
	Front Suspension Lower Arm (RH) distorted			\$ 529.30	X ✓
	Knuckle Arm (RH) distorted			\$ 552.00	X ✓

SH 9483M

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Engine Under Cover <del>to r</del>			\$ 334.60 X ✓
	Engine Crossmember <del>to d</del>			\$ 2,094.40 X ✓
	Inter Cooler punctured			\$ 1,032.50 ✓
	Inter Cooler Mounting (2 PCS) <del>to r</del>			\$ 25.90 X
	ABS Sensor, RH <del>to r</del>			\$ 234.00 X
	Actuator - Swirl Control broken			\$ 814.60 ✓
	Electric Power Steering <del>to r</del>			\$ 4,880.50 X
	<b>SUB TOTAL</b>		22705.05 18164.04	\$ 28,664.85
	<b>LESS 20%</b>			\$ 5,732.97
	<b>DISCOUNTED TOTAL</b>			\$ 22,931.88
	Front Fender Advertisement Logo (RH) <del>to r</del>		100.00	\$ 100.00 Nett ✓
	Front Tyre (RH) <del>to r</del>			\$ 216.00 Nett X
				\$ 316.00
	<b>Labour Charge</b>			
	Panel Beating			\$ 1,500.00 800/-
	Spray Painting Charge			\$ 1,000.00 600/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 100.00 40/-
	Towing Charge			\$ 50.00 44
	Front Chassis Alignment Charge			\$ 400.00 44
	Remove/Refix Undercarriage (FRT)			\$ 200.00 150/-
	FRT Wheel Alignment			\$ 120.00 60/-
	Remove/Refix Aircon & Refill Gas		1940.00	\$ 150.00 80/-
	Re-set Frt ABS System			\$ 200.00 44
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 180/-
	<b>TOTAL LABOUR</b>			\$ 4,250.00
	<b>ESTIMATE TOTAL</b>			\$ 27,497.88
	07/01/2019 @ 1300w HA Antm L/Skm 10 days. Ryan LKK Auto		20204.04 1/516000/-	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME  
ADDRESS

Home Tel.:

VIN:

Registration: SH 9483 M

Technician:

Mileage: 390787

Time Printed 7.1.19 1:41 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°22'		-3°00' 3°00'
3°15'		-0°19' 5°41'
0°07'		-1°30' 1°30'
21°39'		
21°18'		

Camber  
Caster  
Toe  
SAI  
Included Angle  
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
4°14'		-3°00' 3°00'
4°02'		-0°19' 5°41'
4°20'		-1°30' 1°30'
15°30'		
19°44'		

Front

Cross Camber  
Cross Caster  
Cross SAI  
Total Toe  
Cross Turn Diff.

Actual	BEFORE	Specified Range
-4°36'		-3°00' 3°00'
-0°47'		-3°00' 3°00'
6°09'		-3°00' 3°00'
4°27'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-0°48'		-3°30' 2°30'
-0°28'		-1°30' 1°30'

Camber  
Toe

Rear : Right

Actual	BEFORE	Specified Range
0°07'		-3°30' 2°30'
0°30'		-1°30' 1°30'

Rear

Cross Camber  
Total Toe  
Thrust Angle

Actual	BEFORE	Specified Range
-0°55'		-3°00' 3°00'
0°02'		-3°00' 3°00'
-0°29'		-3°00' 3°00'

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19000222/DSD3N2

Date: 15/02/2019

**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	D29076074QMY
Claimant Vehicle No :	SH9483M	Insured Vehicle No :	SLB2797T
Date of Loss:	03/01/2019	Nature of Claim:	TP
		Claim No:	581024

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SH9483M	Engine No:	D4FDGU613743
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU087851
Reg. Date:	28/04/2016 (Man. Year: 2016)	Odometer:	390787 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	23,247.88	18,264.04	4,983.84	21.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,250.00	1,940.00	2,310.00	54.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>27,497.88</b>	<b>20,204.04</b>	<b>7,293.84</b>	<b>26.53</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>16,000.00</b>		
	(S\$) 27,497.88	16,000.00	11,497.88	41.81
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,924.85</b>	<b>1,120.00</b>	<b>804.85</b>	<b>41.81</b>
<b>Nett Amount (S\$)</b>	<b>29,422.73</b>	<b>17,120.00</b>	<b>12,302.73</b>	<b>41.81</b>

**INSPECTION**

Date of Assignment:	04/01/2019	
Date Inspected:	07/01/2019 Inspected At:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint Singapore 568047
Estimated Period of Repair:	10.0 days	

Adjuster: BRYAN TANI

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 15 Feb 2019)
<b>Parts:</b> 143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SH9483M)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	2,265.90 FL	*2,265.90 FL
2	2		*BONNET HINGE (LH/RH)	Bent	82.00 FL	*82.00 FL
3	1		*BONNET LOCK	Bent	36.90 FL	*36.90 FL
4	2		*BONNET ABSORBER	Serviceable	116.20 FL	*- FL
5	1		*BONNET INSULATOR	Not Necessary	196.50 FL	*- FL
6	1		*BONNET INSULATOR CLIPS	Not Necessary	8.40 FL	*- FL
7	1		*RADIATOR GRILLE	Broken	1,110.10 FL	*1,110.10 FL
8	1		*RADIATOR GRILLE H EMBLEM	Necessary	39.50 FL	*39.50 FL
9	1		*FRONT BUMPER COVER	Broken	1,052.20 FL	*1,052.20 FL
10	1		*FRONT BUMPER SPONGE	Torn	99.20 FL	*99.20 FL
11	1		*FRONT BUMPER REINFORCEMENT	Bent	402.10 FL	*402.10 FL
12	1		*FRONT BUMPER GRILLE (RH)	Cracked	93.60 FL	*93.60 FL
13	1		*FRONT BUMPER GRILLE AIRDUCT (RH)	Broken	26.20 FL	*26.20 FL
14	1		*FRONT BUMPER LIP	Serviceable	54.90 FL	*- FL
15	1		*FRONT BUMPER BRACKET TOP (RH)	Not Necessary	22.40 FL	*- FL
16	1		*FRONT BUMPER BRACKET (RH)	Broken	24.60 FL	*24.60 FL
17	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
18	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
19	2		*HEADLAMP (LH/RH)	O/s Broken/N/s Mounting Broken	2,776.00 FL	*2,776.00 FL
20	1		*HEADLAMP HALOGEN BULB (RH)	Not Necessary	14.40 FL	*- FL
21	1		*RADIATOR	Bent/Punctured	698.30 FL	*698.30 FL
22	1		*RADIATOR FAN BLADE,COWLING,MOTOR ASSY	Broken	792.95 FL	*792.95 FL
23	1		*RADIATOR BRACKET (RH)	Not Necessary	6.50 FL	*- FL
24	1		*RADIATOR EXPANSION TANK	Not Necessary	28.30 FL	*- FL
25	1		*RADIATOR GUARD,RH	Broken	20.00 FL	*20.00 FL
26	1		*FRONT FENDER (RH)	Dented	566.30 FL	*566.30 FL
27	1		*FRONT FENDER APRON PANEL (RH)	Buckled	637.00 FL	*637.00 FL
28	1		*FRONT FENDER SHIELD (RH)	Dislodged	174.90 FL	*174.90 FL
29	1		*AIRCON CONDENSER	Bent/Punctured	927.50 FL	*927.50 FL
30	1		*AIRCON SUCTION & LIQUID HOSE	Bent	624.00 FL	*624.00 FL
31	1		*AIRCON DISCHARGE HOSE	Bent	162.60 FL	*162.60 FL
32	1		*WIPER CONTAINER	Broken	61.90 FL	*61.90 FL
33	1		*WIPER CONTAINER MOTOR	Damaged	75.00 FL	*75.00 FL
34	1		*FRONT WHEEL RIM (RH)	Distorted	325.30 FL	*325.30 FL
35	1		*FRONT WHEEL HUB CAP (RH)	Scratched	107.10 FL	*107.10 FL
36	1		*FRONT WHEEL BEARING	Damaged	540.50 FL	*540.50 FL
37	1		*FRONT SHOCK ABSORBER (ASSY)(RH)	Distorted	342.20 FL	*342.20 FL
38	1		*FRONT SHOCK ABSORBER MOUNTING (RH)	Not Necessary	108.80 FL	*- FL
39	1		*FRONT DRIVE SHAFT (RH)	Distorted	1,030.80 FL	*1,030.80 FL
40	1		*RACK & PINION ASSY	Damaged	969.60 FL	*969.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*STG TIE END	Distorted	62.60 FL	*62.60 FL
42	1		*STABILIZER BAR	Distorted	252.30 FL	*252.30 FL
43	1		*STABILIZER BAR BUSH (RH)	Not Necessary	16.40 FL	*- FL
44	1		*STABILIZER BAR LINK	Distorted	61.10 FL	*61.10 FL
45	1		*STABILIZER BRACKET	Not Necessary	24.00 FL	*- FL
46	1		*FRONT SUSPENSION LOWER ARM (RH)	Distorted	529.30 FL	*529.30 FL
47	1		*KNUCKLE ARM (RH)	Distorted	552.00 FL	*552.00 FL
48	1		*ENGINE UNDER COVER	Torn	334.60 FL	*334.60 FL
49	1		*ENGINE CROSSMEMBER	Distorted	2,094.40 FL	*2,094.40 FL
50	1		*INTER COOLER	Punctured	1,032.50 FL	*1,032.50 FL
51	1		*INTER COOLER MOUNTING (2 PCS)	Not Necessary	25.90 FL	*- FL
52	1		*ABS SENSOR,RH	Not Necessary	234.00 FL	*- FL
53	1		*ACTUATOR,SWIRL CONTROL	Broken	814.60 FL	*814.60 FL
54	1		*ELECTRIC POWER STEERING	Not Necessary	4,880.50 FL	*- FL
55	1		*FRONT FENDER ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
56	1		*FRONT TYRE (RH)	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>28,980.85</b>	<b>22,805.05</b>
- List Item Discount on L Items 20.00/20.00% (S\$)	5,732.97	4,541.01
<b>Total Parts (S\$)</b>	<b>23,247.88</b>	<b>18,264.04</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,500.00	800.00
2	SPRAY PAINTING CHARGE	New	1,000.00	600.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	FRONT CHASSIS ALIGNMENT CHARGE	New	400.00	0.00
7	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	200.00	150.00
8	FRT WHEEL ALIGNMENT	New	120.00	60.00
9	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	80.00
10	RE-SET FRT ABS SYTEM }	New	200.00	180.00
11	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	480.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>4,250.00</b>	<b>1,940.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;