

Case Details

Case Reference Number : BUS/12/18/5059
Type of Repair : Accident Repair
Vehicle Registration Number : SG1703L

Company Type : SMRT Buses Ltd
Estimation ID : EST-5160-ID
Assigned By : Eileen Bay Yee Ling

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
Accident Date and Time : 30/12/2018 01:35 AM
Vehicle Age(In Months) : 34

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
Standard	Main	Body	6011408	BUMPER:REAR,CENTRE,MAN A22 'C' SERIES	1	1,625.00	1,625.00	10.00	1,462.50	Replace	1	1,462.50	Replace <i>an</i>
Standard	Main	Body	6010062	COVER:REAR TAIL LAMP,RH,FOR MAN A22 BUS	1	974.70	974.70	10.00	877.23	Replace	1	877.23	Replace <i>an</i>
Standard	Main	Body	6010463	FRAME,REAR BUMPER:FOR MAN A22 BUS	1	1,423.20	1,423.20	10.00	1,280.88	Replace	1	1,280.88	Replace <i>bt</i>
Standard	Main	VE	6010298	LAMP,STOP:LED (MAN BUS)	2	1,141.70	2,283.40	0.00	2,283.40	Replace	2	2,283.40	Replace <i>an</i>
Standard	Main	VE	6010299	LAMP,INDICATOR:LED (MAN BUS)	1	1,274.10	1,274.10	0.00	1,274.10	Replace	1	1,274.10	Replace <i>an</i>
Standard	Main	BODY RH	6009991	PANEL,SIDE:R10,FOR MAN A22 BUS	1	192.70	192.70	10.00	173.43	Replace	1	173.43	Replace <i>bt</i>
Standard	Main	BODY RH	6009992	PANEL,SIDE:R11,FOR MAN A22 BUS	1	1,782.50	1,782.50	10.00	1,604.25	Replace	1	1,604.25	Replace <i>bt</i>
Standard	Main	BODY RH	6009990	PANEL,SIDE:R9 WITH FRAME,FOR MAN A22 BUS	1	710.70	710.70	100.00	0.00	Repair	1	0.00	Repair
One Time Key In	Main			COOLING AIR DUCT	1	1,856.23	1,856.23	10.00	1,670.61	Replace	1	1,670.61	<i>an</i>
Total Spare Part Cost									10,626.40		Surveyor Total	10,626.40	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost									10,626.40		Final Sur Total	10,626.40	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR RH REAR PORTION	1,590.00	1,060	
Total:		1,590.00	1,060.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO PUTTY & RESPRAY	1,514.00	1,400	
Total:		1,514.00	1,400.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TOWING CHARGE	200.00	200.00	request for towing receipt
2	REMOVE AND REFIT INNER COOLER AND FAN SHROUD ASSY	530.00	265	
Total:		730.00	465.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	10,626.40	10,626.40
Total Labour Cost	1,590.00	1,060.00
Total Spray Painting	1,514.00	1,400.00
Other	730.00	465.00
Overall Total	14,460.40	13,551.40
Lump Sum Repair Option		
Lump Sum Total	0.00	13,551.40
Surveyor Approved Amount		13,551.40
No of Repair Days*	5	4
Remarks	-	Resurvey before paint
Surveyor Name		Taufikh

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taylor 97495749
wp'
3/1/19
Rising before part
sur @ 11:40 a.m.
4 days