

ASS. REC. BY:

REF:

es/FCI19000241/Bg d3n2

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Officer)

From (Person):

Joanne Yong

of

FCI

Date/Time:

3:21pm @ 4/1/2019

Estimated Cost:

Bill to:

OD/TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 6386A

Insured:

SHD 7067X

at Workshop m/s

Torque 5

Tel:

9147 8841

of

8 kaki Bukit Ave 4 #01-49 Premier

Policy No:

Claim No:

DL9000774MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 31/12/18

7/1/19 @ after 10am

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Cup

Date/Time:

3:25pm @ 4/1/19

Person Contacted:

Stephanie

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLA 6386A - NA/AIG/19000056/r3
	SHD 7067X - NA/AIG/19000056/r3
11/1/19 @ 5:24pm	revised to Joanne Yong by email.
18/1/19	our claim finalised with wksp LS to 7300, 4 days.
	CPed \$6893.12, 75%.

ASSIGNMENT

From: Date: 7/01/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLA 6386A

at Workshop m/s

of 8 Kelai Bkt Ave 4 # 01-49/50 premier

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 10 am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLA 6386A Yr Regn: 16/4/2009

Type: (M.Car) M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HYUNDAI AVANTE C.C. 1591

Colour: BLUE A/C: Insured / Std / NI / NA

Sp Reading: 257602 T/Radio: Insured / Std / NI / NA

Eng/No: GAFC94630901

C/No: KMHDU41BR94728667

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65/15

R: 195/65/15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or GRENLANDER Comfort

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 31/12/18 D.O.I. 7/1/19 1030

Survey held at TORQUES

Des. of Damages: Frt / Rear L/R / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV 9,000/2

PV 6180/2

NV 2,820/2

2,300/2 offer accept by m/s

RECEIVED 21 JAN 2019

(Est)

MV: \$9K - LTA = \$6180 = net value: \$2820.00

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 4

1) 21/1 TORQUES

☐ : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:

Transportation

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

) 3 + RS \$1

) Photos

) Others

Report Format: TP

Lump Sum / I.B.I. (\$) 2300

TOTAL

391

170

50

50+50

71

TORQUES

blue

7/1/18



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SHD7067X

Date: 11 January 2019

Our Ref: CS/FCI19000241/Bqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLA 6386A


Please be informed that we had conducted the inspection of the abovementioned vehicle on 07/01/2019 at the premises of M/s TORQUE 5 and have the following to report:-

Workshop Estimate Amount	: S\$ 4,030.00 (SN+LABOUR)
Revised Estimate Amount	: S\$ 1,230.00
"Check" Items Amount	: S\$ -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Pending for parts prices.

Description of Damage:

The vehicle sustained damages
at the front o/s portion.



Yours faithfully

Lim T.G.
Automotive Assessor

CTPL

MOTOR SURVEY ASSIGNMENT

Date

3/1/19

Our Ref No. SHD 7067X

Accident Date

31/12/18

Claim Type.

TP

Insured Vehicle

SHD 7067X

Third Party Vehicle.

SLA 6386A

Survey Location

8 Kaki Bukit Ave 4

Contact Person.

#01-49 Premier @ KB S'pore

Contact No.

9147 8841 / 6452 4457 458 75

Fax No.

64524584

Survey Type

Without prejudice.

Appointed

Surveyor

Lkh

Contact Person

Contact Number.

6256 3561

Fax No.

68416315

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Cc : Workshop

TORQUE 5

Cc : TP Solicitor

-Nil-

Attention.

Stephanie Teo

TP Solicitor Fax No.

-Nil-

Officer Incharge

Joanne Yong

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 11 January 2019 5:24 PM
To: 'Teo Swee Keong'; assignments
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: NEW SURVEY ASSIGNMENT - SLA6386A OUR SHD7067X DOA 31/12/2018
Attachments: CSFCI19000241Bqd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SLA 6386A.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 4 January 2019 3:31 PM
To: 'Teo Swee Keong' <TeoSweeKeong@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: NEW SURVEY ASSIGNMENT - SLA6386A OUR SHD7067X DOA 31/12/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer arrange on 07/01/2019.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo Swee Keong [<mailto:TeoSweeKeong@msfirstcapital.com.sg>]
Sent: Friday, 4 January 2019 3:22 PM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: NEW SURVEY ASSIGNMENT - SLA6386A OUR SHD7067X DOA 31/12/2018

Dear Sirs

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 0701N

Vehicle Details

Vehicle No.: SLA6386A
Vehicle to be Exported: No
Intended Deregistration Date: 07 Jan 2019
Vehicle Make: HYUNDAI
Vehicle Model: HD AVANTE 1.6 A
Primary Colour: Blue
Manufacturing Year: 2009
Engine No.: G4FC9U630901
Chassis No.: KMH DU41BR9U728667
Maximum Power Output: 89.7 kW (120 bhp)
Open Market Value: \$11,974.00
Original Registration Date: 16 Apr 2009
First Registration Date: 16 Apr 2009
Transfer Count: 3
Actual ARF Paid: \$11,974.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 15 Apr 2019
PARF Rebate Amount: \$5,987.00

Intended COE Rebate Details

COE Expiry Date: 15 Apr 2019
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$7,090.00
COE Rebate Amount: \$193.00
Total Rebate Amount: \$6,180.00

The information contained herein is correct as at 07 Jan 2019

OK

Dep 6760/yr
563/mth

coe left 4 mth

MV 8K - 3K
PV 6180/-
NV 2820/-
Vat

7/1/18



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLA6386A
Make & Model : HYUNDAI ,HD AVANTE 1.6
A,KMH DU41BR9U728667
Year of Manufacture : 2009

Estimation No. : E19010005
DOA : 03/01/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Front bumper	1.00	0.00	0.00 ^{CUT} DD ✓
2	Front bumper retainer (LH)	1.00	0.00	0.00 } NECV
3	Rear bumper retainer (RH)	1.00	0.00	0.00 }
4	Fog lamp garnish (RH)	1.00	0.00	0.00 } NNX
5	Front bumper lower grille	1.00	0.00	0.00 }
6	Radiator grille	1.00	0.00	0.00 ?
7	Head lamp (RH)	1.00	0.00	0.00 ^{CUT} ✓
8	Front fender (RH)	1.00	0.00	0.00 ^{DD} ✓
9	Front fender inner shield (RH)	1.00	0.00	0.00 ?
10	Front bumper sponge	1.00	0.00	0.00 ?
11	Front bumper reinforcement	1.00	0.00	0.00 ?
12	Front bumper bracket (LH)	1.00	0.00	0.00 NNX
13	Front bumper bracket (RH)	1.00	0.00	0.00 BRV
14	Front support panel	1.00	0.00	0.00 ?
15	Front absorber (RH)	1.00	0.00	0.00 }
16	Front absorber top mounting (RH)	1.00	0.00	0.00 }
17	Front knuckle arm (RH)	1.00	0.00	0.00 } ?
18	Front knuckle bearing (RH)	1.00	0.00	0.00 }
19	Front lower arm (RH)	1.00	0.00	0.00 }

Amt S\$ 0.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 0.00

Section: Special Nett Items

20	Front bumper clip set	1.00	45.00	45.00 ^{NECV}
----	-----------------------	------	-------	-----------------------

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLA6386A
Make & Model : HYUNDAI ,HD AVANTE 1.6
A,KMHU41BR9U728667
Year of Manufacture : 2009

Estimation No. : E19010005
DOA : 03/01/2019

No	Description	Qty	U/P	Amt
21	Front fender inner shield clip set	1.00	45.00	45.00 <i>NECV</i>
22	Front wheel rim (RH)	1.00	600.00	600.00 } <i>NNX</i>
23	Front tyre (RH)	1.00	200.00	200.00 }
24	Front tyre valve (RH)	1.00	10.00	10.00 <i>NNX</i>
25	Engine coolant	1.00	80.00	80.00 }
26	Auto transmission fluid 1 liter	1.00	60.00	60.00 } <i>NNX</i>
27	A/C condenser o'ring set	1.00	20.00	20.00 }

Amt S\$ 1,060.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 1,060.00

Section: Labour Items

28	To check wiring and lighting systems	1.00	80.00 <i>Ho</i>	80.00
29	To focus head lamp assy	1.00	80.00 <i>Ho</i>	80.00
30	To R&R a/c condenser, radiator assy	1.00	350.00	350.00 <i>NNX</i>
31	To conduct wheel alignment before and after	1.00	160.00 <i>60</i>	160.00
32	To R&R front wheel rim & tyre, balancing	1.00	50.00	50.00 <i>NNX</i>
33	To R&R front RH undercarriage damaged parts	1.00	350.00	350.00 <i>NNX</i>
34	To press RH knuckle bearing assy	1.00	100.00	100.00 <i>NNX</i>
35	To repair, replace and realign damaged areas	1.00	1,000.00 <i>600.00</i>	1,000.00
36	To spray painting on affected areas	1.00	800.00 <i>400.00</i>	800.00

Amt S\$ 2,970.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 2,970.00

? Photo T&C in 7/1/19
1128

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

List Items Subtotal S\$ 0.00
Special Nett Items S\$
Subtotal 1,060.00
Labour Items Subtotal S\$
2,970.00
Total S\$
4,030.00



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLA6386A
Make & Model : HYUNDAI ,HD AVANTE 1.6
A,KMH DU41BR9U728667
Year of Manufacture : 2009

Estimation No. : E19010005
DOA : 03/01/2019

*record purpose,
just for reference.*

No	Description	Qty	U/P	Amt
Section: List Items				
1	Front bumper	452 1.00	0.00 918.00	0.00 DDV ^{CUT}
2	Front bumper retainer (LH)	1.00	0.00 126.00	0.00 } ^{NECV}
3	Rear bumper retainer (RH)	1.00	0.00 126.00	0.00 }
4	Fog lamp garnish (RH)	1.00	0.00 128.50	0.00 } ^{NNX}
5	Front bumper lower grille	105.20 1.00	0.00 128.50	0.00 }
6	Radiator grille	298 1.00	0.00 329.60	0.00 ? CRV
7	Head lamp (RH)	480 1.00	0.00 670.00	0.00 CUTV
8	Front fender (RH)	478.62 1.00	0.00 585.90	0.00 DDV
9	Front fender inner shield (RH)	90.10 1.00	0.00 154.00	0.00 ? TNV
10	Front bumper sponge	124 1.00	0.00 216.00	0.00 ? TNV
11	Front bumper reinforcement	279 1.00	0.00 539.00	0.00 ? NNX
12	Front bumper bracket (LH)	63 1.00	0.00 142.00	0.00 NNX
13	Front bumper bracket (RH)	63 1.00	0.00 142.00	0.00 BRV
14	Front support panel	1.00	0.00 735.00	0.00 ? EB CR
15	Front absorber (RH)	194.60 1.00	0.00 328.20	0.00 } BTV
16	Front absorber top mounting (RH)	86.40 1.00	0.00 102.50	0.00 } JMV
17	Front knuckle arm (RH)	396.69 1.00	0.00 467.20	0.00 } ? DDV
18	Front knuckle bearing (RH)	1.00	0.00 198.30	0.00 } JMV
19	Front lower arm (RH)	1.00	0.00 417.20	0.00 } DDV

Parts : 5515.70 - 20% AAA
= 4412.70

Amt S\$ 0.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 0.00

Section: Special Nett Items s/n = 180

20 Front bumper clip set 1.00 45.00 45.00 ^{NECV}

labour = 1440

*P+STL = 6032.70 - 20% L/s
= \$ 4800.*

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLA6386A
Make & Model : HYUNDAI ,HD AVANTE 1.6
A,KMH DU41BR9U728667
Year of Manufacture : 2009

Estimation No. : E19010005
DOA : 03/01/2019

No	Description	Qty	U/P	Amt	
21	Front fender inner shield clip set	1.00	45.00	45.00	NECV
22	Front wheel rim (RH)	1.00	600.00	600.00	RX
23	Front tyre (RH)	1.00	200.00	200.00	NNX
24	Front tyre valve (RH)	1.00	10.00	10.00	NNX
25	Engine coolant	1.00	80.00	80.00	NEC
26	Auto transmission fluid 1 liter	1.00	60.00	60.00	NECV
27	A/C condenser o'ring set	1.00	20.00	20.00	NECV

Amt S\$ 1,060.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 1,060.00

Section: Labour Items

28	To check wiring and lighting systems	1.00	80.00	80.00	
29	To focus head lamp assy	1.00	80.00	80.00	
30	To R&R a/c condenser, radiator assy	1.00	350.00	350.00	NNX
31	To conduct wheel alignment before and after	1.00	160.00	160.00	
32	To R&R front wheel rim & tyre, balancing	1.00	50.00	50.00	NNX
33	To R&R front RH undercarriage damaged parts	1.00	350.00	350.00	NNX
34	To press RH knuckle bearing assy	1.00	100.00	100.00	NNX
35	To repair, replace and realign damaged areas	1.00	1,000.00	1,000.00	
36	To spray painting on affected areas	1.00	800.00	800.00	

Amt S\$ 2,970.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 2,970.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Days of repair 5

List Items Subtotal	S\$ 0.00
Special Nett Items	S\$
Subtotal	1,060.00
Labour Items Subtotal	S\$
	2,970.00
Total	S\$
	4,030.00

9193.12

MOTOR STOP PTE LTD
NO 8 KAKI BUKIT AVENUE 4
PREMIER@KAKI BUKIT
#01-07 SINGAPORE 415875
TEL: 93261342
FAX: 64524584

EMAIL: motorstopoffice@gmail.com

Work Order: R003519
 License: SLA6386A
 Date: 7.1.19 14:20

Hyundai : Avante/Elantra/Lantra : 2006-11 (-HD-)
 4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-0°56'	-0°56'	-1°00' 0°00'
3°53'	3°53'	3°49' 4°49'
0°06'	0°06'	-0°05' 0°05'
32°24'	32°24'	12°52' 13°52'
31°28'	31°28'	11°52' 13°52'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-1°32'	-1°32'	-1°00' 0°00'
4°44'	4°44'	3°49' 4°49'
-0°18'	-0°18'	-0°05' 0°05'
14°48'	14°48'	12°52' 13°52'
13°16'	13°16'	11°52' 13°52'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°36'	0°36'	
-0°51'	-0°51'	
17°36'	17°36'	
-0°12'	-0°12'	-0°09' 0°09'

Rear : Left

Actual	Before	Specified Range
-2°17'	-2°17'	-1°30' -0°30'
0°01'	0°01'	0°00' 0°10'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°05'	-1°05'	-1°30' -0°30'
0°05'	0°05'	0°00' 0°10'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
-1°12'	-1°12'	
0°06'	0°06'	0°01' 0°20'
-0°02'	-0°02'	

MOTOR STOP PTE LTD
NO 8 KAKI BUKIT AVENUE 4
PREMIER@KAKI BUKIT
#01-07 SINGAPORE 415875

TEL: 93261342

FAX: 64524584

EMAIL: motorstopoffice@gmail.com

Work Order: R003524
 License: SLA6386A
 Date: 8.1.19 18:45

Hyundai : Avante/Elantra/Lantra : 2006-11 (-HD-)
4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-0°50'	-0°51'	-1°00' 0°00'
4°39'	4°39'	3°49' 4°49'
0°00'	0°02'	-0°05' 0°05'
14°18'	14°19'	12°52' 13°52'
13°28'	13°28'	11°52' 13°52'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°46'	-0°45'	-1°00' 0°00'
4°27'	4°27'	3°49' 4°49'
0°01'	-0°14'	-0°05' 0°05'
13°39'	13°37'	12°52' 13°52'
12°53'	12°53'	11°52' 13°52'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°04'	-0°06'	
0°12'	0°12'	
0°39'	0°42'	
0°01'	-0°13'	-0°09' 0°09'

Rear : Left

Actual	Before	Specified Range
-2°19'	-2°19'	-1°30' -0°30'
0°02'	0°02'	0°00' 0°10'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°07'	-1°07'	-1°30' -0°30'
0°05'	0°05'	0°00' 0°10'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-1°12'	-1°12'	
0°07'	0°07'	0°01' 0°20'
-0°01'	-0°01'	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19000241/Bqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 22-01-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 7067X	Veh. Inspected	SLA 6386A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000224MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	04/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI AVANTE	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	KMH DU41BR9U728667	Colour	BLUE	
Odometer	257602	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65/15	GREN LANDER COMFORT	6 mm	
L/H Front Tyre	195/65/15	GREN LANDER COMFORT	6 mm	
R/H Rear Tyre	195/65/15	GREN LANDER COMFORT	6 mm	
L/H Rear Tyre	195/65/15	GREN LANDER COMFORT	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/12/2018	Inspection Date	07/01/2019	
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 6386A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	CUT	918.00	918.00
1	FRONT BUMPER RETAINER (LH)	NECESSARY	126.00	126.00
1	FRONT BUMPER RETAINER (RH)	NECESSARY	126.00	126.00
1	FOG LAMP GARNISH (RH)	NOT NECESSARY	128.50	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	128.50	-
1	RADIATOR GRILLE	CRUMPLED	329.60	329.60
1	HEAD LAMP (RH)	CUT	670.00	670.00
1	FRONT FENDER (RH)	DENTED	585.90	585.90
1	FRONT FENDER INNER SHIELD (RH)	TORN	154.00	154.00
1	FRONT BUMPER SPONGE	TORN	216.00	216.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	539.00	-
1	FRONT BUMPER BRACKET (LH)	NOT NECESSARY	142.00	-
1	FRONT BUMPER BRACKET (RH)	BROKEN	142.00	142.00
1	FRONT SUPPORT PANEL	CRUMPLED	735.00	735.00
1	FRONT ABSORBER (RH)	BENT	328.20	328.20
1	FRONT ABSORBER TOP MOUNTING (RH)	JAMMED	102.50	102.50
1	FRONT KNUCKLE ARM (RH)	DENTED	467.20	467.20
1	FRONT KNUCKLE BEARING (RH)	JAMMED	198.30	198.30
1	FRONT LOWER ARM (RH)	DENTED	417.20	417.20
	LESS 20% DISCOUNT		-1,290.78	-1,103.18
			5,163.12	4,412.72
SPECIAL NETT ITEMS				
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	45.00	45.00
1	FRONT WHEEL RIM (RH)(SN)	TO REPAIR SEE LABOUR	600.00	-
1	FRONT TYRE (RH)(SN)	NOT NECESSARY	200.00	-
1	FRONT TYRE VALVE (RH)(SN)	NOT NECESSARY	10.00	-
1	ENGINE COOLANT (SN)	NECESSARY	80.00	50.00
1	LITER AUTO TRANSMISSION FLUID (SN)	NECESSARY	60.00	20.00
1	SET A/C CONDENSER O'RING (SN)	NECESSARY	20.00	20.00

Report Ref No. CS/FCI19000241/Bqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	45.00	45.00
			1,060.00	180.00
	LABOUR			
	TO CHECK WIRING AND LIGHTING SYSTEMS.		80.00	40.00
	TO FOCUS HEAD LAMP ASSY.		80.00	40.00
	TO R&R A/C CONDENSER,RADIATOR ASSY.		350.00	150.00
	TO CONDUCT WHEEL ALIGNMENT BEFORE AND AFTER.		160.00	60.00
	TO R&R FRONT WHEEL RIM & TYRE,BALANCING.	NOT NECESSARY	50.00	-
	TO R&R FRONT RH UNDERCARRIAGE DAMAGED PARTS.	NOT NECESSARY	350.00	-
	TO PRESS RH KNUCKLE BEARING ASSY.	NOT NECESSARY	100.00	-
	TO REPAIR,REPLACE AND REALIGN DAMAGED AREAS.INCLUSIVE OF THE REPAIR OF FRONT WHEEL RIM (RH).		1,000.00	600.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		800.00	400.00
			2,970.00	1,290.00
GRAND TOTAL			9,193.12	5,882.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CS/FCI19000241/Bqd3n2

MARKET VALUE: \$9,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$6,180.00=NETT VALUE: \$2,820.00

LIM TEOW GUAN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.