

Surveyor:

REF: CSA/LAW19000268/Arbez

Special Instruction:

P/P: \$ 27967.00

ASSIGNMENT (Office)

From (Person): Jolene Quah of Tunkok Quan Date/Time: 19/12/18

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: PAL's Appraiser

Workshop: Hua Meng

OD TP Re-inspection Evaluation

To Inspect Vehicle No: SKC 5808H Insured: AGY 6881

at Workshop m/s Hua Meng Tel: of Bik 1 Kaki Bukit Ave 6 # 01-61

Policy No: MKR/106/6173/2015/jk Claim No: CF-LHP.2012.17-bai

Sum Insured: Excess:

Make of Veh: D.O.A. 27032015

(Client's Record)

SJR

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: 18/04/19 Confirmed with Hua Final Fig LS 161c, 18 days (Red \$ 11,967 43%; Original 24 days)

Date/Time: Submit Final Fig, days (Red \$ / %; Original days)

Date/Time	Action/Instruction
	SKC 5808H - NA/DNC15005836/d2 AGY 6881 - X DIA: 27032015
	23/02/19 Sat 10am Bik 360A Admiralty Drive Zul 96260057.
	URGENT
	URGENT
	URGENT

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 10 APR 2019

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

1000

1000

1) Date/Time 18/4 - typist File Pass to

3) Date/Time File Pass to

5) Date/Time File Pass to

2) Date/Time

4) Date/Time

6) Date/Time

File Return to

File Return to

File Return to

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKCS808H

Yr Regn:

2006 / DecType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit Colt Plus

c.c.

1499

Colour:

Blue

A/C:

Insured / Std / Nil / NA

Sp. Reading

172836

T/Radio:

Insured / Std / Nil / NA

Eng/No:

C/No:

JMYL7223W62000357Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

195/50R16

R:

Continental 195/50R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

23/02/19

Survey held at

Admiralty PoliceDes. of Damages FR / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Reinspection Hua MengCOE Expiry : 30/11/21MV :PV :Nett :

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Catherine Chong (LKK Auto)

From: Jolene Quah on behalf of Low Huai Pin <jolenequah@tkqp.com.sg>
Sent: Wednesday, 19 December, 2018 5:15 PM
To: Catherine Chong (LKK Auto)
Cc: Low Huai Pin; roynpartners@roynpartners.com.sg
Subject: MC/MC 12524/2017 | ACCIDENT INVOLVING SKC 5808H, WSR 3661, JCJ 77, AGY 6881 & WNE 7661 ON 27.03.2015 | TKQP REF: CF.LHP.2012.17-bst | ROY & PARTNERS REF: MKR/106/6173/2015/jk

Dear Sirs

We act for Berjaya Sompo Insurance Berhad, the insurers of motor vehicle no. AGY 6881.

M/s Roy & Partners who are carbon copied in this email, act for the Plaintiff (claimant) who is the owner of motor vehicle no. SKC 5808H.

Parties have agreed to appoint Mr Adrian Ling from your firm, LKK Auto Consultants Pte Ltd as the single joint expert (SJE) in this matter for purposes of preparing an SJE report on the Plaintiff's motor vehicle.

Please let us know if you would require to conduct a physical re-inspection of the motor vehicle or alternatively, a paper re-survey.

We attach herein a copy of the following documents for your perusal: -

- a) Accident Statement of vehicle no. SKC 5808H;
- b) Police report of vehicle no. SKC 5808H;
- c) Police report of AGY 6881;
- d) Police report of JCJ 77;
- e) Police report of WNE 7661;
- f) Police report of WSR 3661
- g) The Plaintiff's repair bill;
- h) The Plaintiff's survey report (Pal's Appraiser Pte Ltd) dated 27 May 2015; and
- i) Scene photographs

You may access the documents via this link

<https://tkqp.sharepoint.com/:u:/g/insurancelitigation/ERXeODqplBZOqjeodQNXWMEBz24LaO5CDWZQF09V8Mx04w?e=woV7yD>.

Kindly acknowledge the assignment and let us have your report in due course.

Best Regards

Jolene Quah
For and on behalf of Low Huai Pin
Associate

TKQP

Tan Kok Quan Partnership
Advocates & Solicitors, Singapore
1 Wallich Street #07-02 Guoco Tower Singapore 078881

T (65) 6225 9333

D (65) 6496 9543

F (65) 6225 0111

E jolenequah@tkqp.com.sg

W www.tkqp.com.sg

This email is intended solely for the abovenamed addressee(s). It may contain confidential and/or legally privileged information. If this email has reached you in error, please delete it immediately and inform us of the error. Thank you for your co-operation.

Internet communications cannot be guaranteed to be secured or error-free as information can be intercepted, corrupted, lost, or it may arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message which arise as a result of Internet transmission.



華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1 Kaki Bukit Avenue 6, Blk C, #01-61/01-34, Singapore 417883

Tel: 6747 8064, 6746 5519 Fax: 6743 4896

Reg. No.: 254678/00M

Your Ref:

Our Ref:

Date: 27/05/2015

VEHICLE NO : SKC 5808 H
MAKE / MODEL : MITSUBISHI COLT
NAME : MOHAMAD ZULKAFLI BIN ZAKARIA
ADDRESS : BLK 360A ADMIRALTY DRIVE
#14-76
S 751360

FINAL REPAIR BILL FOR VEHICLE NO. SKC 5808 H

<u>NETT ITEMS</u>	<u>QTY</u>	<u>COST (\$\$)</u>
Bonnet	1	514
Bonnet hinges	2	86
Bonnet lock	1	48
Bonnet rear ruber	1	24
Bonnet rubber	1	22
Front headlamps	2	1092
Front grille	1	238
Front grille clip (1set)	1	34
Front grille logo	1	32
Front bumper	1	627
Front bumper reinforcement	1	214
Front bumper side retainers	2	24
Front bumper undercover	1	156
Front support panel	1	219
Front brace panel	1	40
Air con condenser	1	874
Radiator	1	726
Radiator fan blade	1	46
Radiator fan cowling	1	95
Radiator fan motor	1	311
Front drive seat	1	850
Rear windscreen glass	1	630
Rear windscreen inner side garnish	1	64
Rear windscreen moulding	1	118



華明噴漆廠 HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1 Kaki Bukit Avenue 6, Blk C, #01-61/01-34, Singapore 417883

Tel: 6747 8064, 6746 5519 Fax: 6743 4896

Reg. No.: 254678/00M

Your Ref:

Our Ref:

Date: 27/05/2015

VEHICLE NO : SKC 5808 H
MAKE / MODEL : MITSUBISHI COLT
NAME : MOHAMAD ZULKAFI BIN ZAKARIA
ADDRESS : BLK 360A ADMIRALTY DRIVE
#14-76
S 751360

FINAL REPAIR BILL FOR VEHICLE NO. SKC 5808 H

<u>Nett Items</u>	QTY	COST (\$)
Rear tailgate	1	855
Rear tailgate dampers	2	292
Rear tailgate inner trim board	1	245
Rear tailgate lamps	2	378
Rear tailgate lock	1	339
Rear tailgate logo	1	40
Rear tailgate outer handle	1	129
Rear tailgate rubber	1	145
Rear tailgate 'COLT' emblem	1	28
Rear tailgate 'PLUS' emblem	1	26
Rear tailgate 'C&C' emblem	1	40
Rear tailgate third brake light	1	102
Rear wiper motor	1	264
Rear taillamps	2	554
Rear taillamp panel	1	58
Rear end panel	1	327
Rear end panel inner garnish	1	179
Rear end panel inner member	1	245
Rear bumper	1	586
Rear bumper reflector	1	38
Rear bumper side retainers	2	72
Rear number plate lamp (1set)	1	62
Rear spare tyre panel	1	856
Rear spare tyre panel tray	1	182



華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1 Kaki Bukit Avenue 6, Blk C, #01-61/01-34, Singapore 417883

Tel: 6747 8064, 6746 5519 Fax: 6743 4896

Reg. No.: 254678/00M

Your Ref:

27/05/2015

Our Ref:

Date: _____

VEHICLE NO : SKC 5808 H
MAKE / MODEL : MITSUBISHI COLT
NAME : MOHAMAD ZULKAFLI BIN ZAKARIA
ADDRESS : BLK 360A ADMIRALTY DRIVE
#14-76
S 751360

FINAL REPAIR BILL FOR VEHICLE NO. SKC 5808 H

Nett Items

	QTY	COST (\$\$)
Rear chassis member	1	468
Rear fender	1	764
Rear fender air gate	1	32
Rear fender inner top garnish	1	228
Rear fender inner panel	1	387
Rear fender inner trim boards	2	828
Rear fender quarter glass moulding	1	310
Rear fender lower extension panel	1	68
Rear n/s door	1	960
Rear n/s door outer moulding	1	84
Rear n/s door inner board	1	362
Rear n/s door lock	1	216
Rear seat	1	960
Total		18793



華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1 Kaki Bukit Avenue 6, Blk C, #01-61/01-34, Singapore 417883

Tel: 6747 8064, 6746 5519 Fax: 6743 4896

Reg. No.: 254678/00M

Your Ref:

Our Ref:

Date: 27/05/2015

VEHICLE NO : SKC 5808 H
MAKE / MODEL : MITSUBISHI COLT
NAME : MOHAMAD ZULKAFI BIN ZAKARIA
ADDRESS : BLK 360A ADMIRALTY DRIVE
#14-76
S 751360

FINAL REPAIR BILL FOR VEHICLE NO. SKC 5808 H

Special Nett Items

	QTY	COST (S\$)
Rear bumper clip (1set)	1	30
Rear tailgate sticker	1	75
Rear tailgate 'LED' light	1	80
Rear tailgate inner board clips (1set)	1	36
Rear end panel inner garnish clips (1set)	1	25
Rear fender inner trim board clips (2set)	2	70
Rear n/s door inner board clip (1set)	1	45
Rear bumper clip (1set)	1	28
Rear number plate	1	45
Rear reverse sensor (1set)	1	280
Total		714



華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1 Kaki Bukit Avenue 6, Blk C, #01-61/01-34, Singapore 417883

Tel: 6747 8064, 6746 5519 Fax: 6743 4896

Reg. No.: 254678/00M

Your Ref:

Our Ref:

27/05/2015

Date: _____

VEHICLE NO : SKC 5808 H
MAKE / MODEL : MITSUBISHI COLT
NAME : MOHAMAD ZULKAFLI BIN ZAKARIA
ADDRESS : BLK 360A ADMIRALTY DRIVE
#14-76
S 751360

FINAL REPAIR BILL FOR VEHICLE NO. SKC 5808 H

Labour Cost

To provide towing service charge.

QTY COST (S\$)
80

To remove and refit damage parts, test for proper functioning
and focus of headlamps.

40

To remove and refit rear electrical wiring, replaced damaged
lamps and test for proper functioning.

40

To remove and refit rear cushion seats, radio speaker board,
interior upholstery to facilitate the repairs.

240

To remove and refit fuel tank system.

80

To remove and refit rear bumper sensor.

80

To remove and refit air-con system, refill gas and test for leakages.

120

To remove and refit rear windscreen glass.

150

To remove and refit the door lock mechanism, regulator gear,
window glass, handle, inner board, hinges, channel to facilitate
the repairs.

80



華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1 Kaki Bukit Avenue 6, Blk C, #01-61/01-34, Singapore 417883

Tel: 6747 8064, 6746 5519 Fax: 6743 4896

Reg. No.: 254678/00M

Your Ref:

Our Ref:

Date: 27/05/2015

VEHICLE NO : SKC 5808 H
MAKE / MODEL : MITSUBISHI COLT
NAME : MOHAMAD ZULKAFI BIN ZAKARIA
ADDRESS : BLK 360A ADMIRALTY DRIVE
#14-76
S 751360

FINAL REPAIR BILL FOR VEHICLE NO. SKC 5808 H

Labour Cost

To remove and replace the above damaged parts, straighten, knock out
realign and repair including cut and weld body panels. To re-adjust
to the original position using power tools.

QTY COST (\$\$)
3750

To spray paint on the replaced and repaired parts, prepare spray
such as masking tape the unaffected areas with paper, cleaning
and sanding of surfaces, final polishing and waxing are also available.

3500

To apply undercoating on the repaired and replaced panels for
rust protection.

300

Total 8460

Grand Total 27967

SINGAPORE DOLLARS: TWENTY SEVEN THOUSAND NINE HUNDRED SIXTY SEVEN ONLY

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/04/2015 15:43
Date Of Accident	27/03/2015 14:30
Exact Location Of Accident	ALONG JLN LINGKARAN TENGAH 2 PANDAN INDAH TWDS KL
Country/State of Loss	Malaysia/Selangor Darul Ehsan

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC5808H
Insured/Policyholder	
Name Of Registered Owner	MOHAMAD ZULKAFI BIN ZAKARIA
NRIC No	S1525810A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96260057
Alternative Phone No	Others-96260057

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	COLTPLUSPRT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle?

No

If No, Please state action to be taken

Third Party

Vehicle Category

Private Car

Insurance Company

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5053630180-02

Cover Note Number

Driver

Name of Driver	MOHAMAD ZULKAFI BIN ZAKARIA
NRIC No	S1525810A
Date Of Birth	01/02/1962
Occupation	Outdoor
Date Of Driving Pass	15/11/2010
Driving Experience	4 Years And 4 Months
Gender	Male
Mobile Number	(Local) +65-96260057
Fax Number	
Contact Number	Others-96260057
Email Address	NOEMAIL

Address BLK 360A ADMIRALTY DRIVE #14-76
Postcode 751360
Was driver an employee of the Insured's Company No
If No, Relationship of the Driver with the Insured Owner
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident Collision- Chain Collision
Weather Conditions Clear
Road Surface Dry

Other Information

Was any foreign vehicle involved in this accident? Yes
Foreign Vehicle Registration Number WSR3661 (Commercial Vehicle)
Was any body injured in the Accident? No
Was any other material or property damaged? Yes
Was there any video captured by Car Camera? No
Number of Passengers (Including Driver) 4

Details of Police Action

Was the accident reported to the police? Yes
If Yes, Please state which Police Station
Police Station Name [Other] TRAFIK AMPANG JAYA
Was notice of Intended Prosecution given? No
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT AND POLICE REPORT.

Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number WSR3661
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number JCJ77
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time
06/04/15
13:57hrs

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel
06/04/15 13:57hrs

Sketch Plan



Sketch Plan #2

Describe Circumstances of the Accident

On 27/03/2015 at about 1430hrs, I was driving my vehicle no. SKCTP08H Model make Mitsubishi from Singapore towards Cyberjaya Tropical Hotel (KL) When driving along Jln Lingkaran Tengah 2 Pandan Indah, I was driving on the right lane due to slow traffic. Suddenly a van no. WSE3661 model make Nissan hit me from behind with strong impact caused my vehicle pushed forward and hit onto the front vehicle no. WNE3661 model make Toyota Vios. Due to this accident, my vehicle - front portion (Bumper, bumper light, radiator) and rear portion (bumper, bumper, reverse sensor, exhaust, rear windscreen, auto sensor) and others part was damaged. That's all.

After the accident, I failed to get the plate number of vehicle in front of me because the front vehicle didn't stop and just drove off. I get the plate number of front vehicle from the Malaysia's towing man and the towing man told me the front vehicle wanted claim my insurance.

The owner, WNE3661 make a report to traffic police in KL, after the accident on the date of 27/03/2015 on Friday, the owner make a report at the traffic police same location on the date 20/03/2015 On Sunday.

Declaration

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature / Date & Time
 06-04-15
 13:57hrs

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

 06-04-15 13:57hrs

**POLIS DIRAJA MALAYSIA**
REPOT POLIS

Balai : TRAFIK AMPANG JAYA
Daerah : AMPANG JAYA
Kontinjen : SELANGOR
No Repot : TRAFIK AMPANG JAYA/003716/15
Tarikh : 27/03/2015
Waktu : 1635 PM
Bahasa Diterima : B. Malaysia

Pegawal Penyiasat : G21920
No Repot Bersangkut : TRAFIK AMPANG JAYA/003714/15

Butir-butir Penerima Repot

Nama : MOHD REDZUAN BIN SURATMIN
Butir-butir Jurubahasa (Jika Ada)
Nama : ---
No Pasport : ---
Alamat : ---

No Personal : R152956
Pangkat : KPL
No K/P (Baru) : ---
Bahasa Asal : ---
No Polis/Tentera : ---

Butir-butir Pengadu

Nama : WOO KA LOON
No K/P (Baru) : 860116086011
No Sijil Beranak : ---
Jantina : Lelaki
Keturunan : Cina
Pekerjaan : -

No Polis/Tentera : ---
Tarikh Lahir : 16/01/1986
Warganegara : Malaysia
No Pasport : ---
Umur : 29 tahun 2 bulan

Alamat Tempat Tinggal : NO 42 PERSIRAAN BERCHAM TIMUR 5, TAMAN BERCHAM BARU, IPOH, 31400, PERAK
Alamat Ibu/Bapa : ---
Alamat Pejabat : ---
No Tel (Rumah) : ---
No Tel (Pejabat) : ---
No Tel (HP) : 0164402973

Pengadu Menyatakan:-

PADA 27/3/2015 JAM LEBIH KURANG 1430 HRS SEMASA SAYA MEMANDU M/KAE NO: AGY 6881 JENIS HONDA CITY DARI ARAH CHERAS MENUJU KE WANGSA MAJU. APABILA SAMPAI DI MJRR2 PANDAN INDAH KETIKA ITU SAYA MEMANDU DI LORONG KANAN SEBUAH M/KAR NO: JCJ 77 JENIS TOYOTA HILUX YANG BERADA DI HADAPAN TELAH BREK DAN SAYA JUGA BREK TIBA-TIBA SEBUAH M/KAR NO SERTA JENIS TIDAK PASTI TELAH MELANGGAR BAHAGIAN BELAKANG SEBELAH KIRI M/KAR SAYA MENYEBABKAN M/KAR SAYA TERLAJAK KE HADAPAN DAN MELANGGAR BAHAGIAN BELAKANG M/KAR YANG BERADA DI HADAPAN TADI. KEROSAKAN M/KAR SAYA DI BAHAGIAN HADAPAN BUMPER, BONET, LAMPU, FENDER, MUDGUARD, PINTU KIRI DEPAN/BELAKANG, TANGKI AIR, AIRCOND MANAKALA BAHAGIAN BELAKANG FENDER DAN LAIN-LAIN KEROSAKAN BELUM PASTI LAGI. SEKIAN LAPORAN SAYA.

Tandatangan Pengadu: _____ Tandatangan Jurubahasa (Jika ada): _____ Tandatangan Penerima Repot: _____

ID Pencetak | Tarikh @ Masa Cetak

: R7141786 | 16/02/2016 03:53:04 PM

PEJ. SALINAN REPORT
TRAFIK JOHOR BAHRU (S)
SALINAN YANG DISAHKAN BENAR
(HANYA UNTUK TUNTUTAN SIVIL)

.....
KETUA TRAFIK DAERAH JOHOR BAHRU (S) JOHOR
TIDAK BOLEH DIGUNAKAN UNTUK TUJUAN PERBICARAAN

**POLIS DIRAJA MALAYSIA**
REPOT POLIS

Balai : TRAFIK AMPANG JAYA
Daerah : AMPANG JAYA
Kontinjen : SELANGOR
No Repot : TRAFIK AMPANG JAYA/003734/15
Tarikh : 27/03/2015
Waktu : 2046 PM
Bahasa Diterima : B. Malaysia

Pegawai Penyiasat : G21920
No Repot Bersangkut : TRAFIK AMPANG
JAYA/003714/15

Butir-butir Penerima Repot

Nama : ROSLINDA BT ABDULLAH
Butir-butir Jurubahasa (Jika Ada)

No Personel : R134648

Pangkat : KPL

Nama : ---

No K/P (Baru) : ---

No Polis/Tentera : ---

No Pasport : ---

Bahasa Asal : ---

Alamat : ---

Butir-butir Pengadu

Nama : AARON CHIN SHI MIN

No K/P (Baru) : 640101715159

No Polis/Tentera : ---

No Pasport : ---

No Sijil Beranak : ---

Jantina : Lelaki

Tarikh Lahir : 01/01/1964

Umur : 51 tahun 2 bulan

Keturunan : Cina

Warganegara : Malaysia

Pekerjaan : BERNIAGA

Alamat Tempat Tinggal : TAMAN BUKIT JOBINA JALAN ULU KALNG AMPANG, 68000, SELANGOR

Alamat Ibu/Bapa : ---

Alamat Pejabat : ---

No Tel (Rumah) : -

No Tel (Pejabat) : ---

No Tel (HP) : 012-3246677

Pengadu Menyatakan:-

PADA 27/03/2015 JAM LEBIH KURANG 1430HRS. SEMASA SAYA MEMANDU M/JIP NO. JCJ77 JENIS MITSUBISHI TRITON DARI CHERAS MENGHALA KE AMPANG. APABILA SAMPAI DI LINGKARAN TENGAH PANDAN INDAH TIBA-TIBA M/KAR NO. AGY6881 JENIS HONDA CITY MELANGGAR M/JIP SAYA DIBAHGIAN BELAKANG DAN MENYEBABKAN M/JIP SAYA TERLAJAK KEHADAPAN LALU MELANGGAR M/VAN NO. WSR3661 JENIS URBAN. SAYA TIDAK MENGALAMI SEBARANG KECEDERAAN. KEROSAKAN M/JIP SAYA BAHAGIAN HADAPAN BONET, LAMPU DAN BUMPER BAHAGIAN BELAKANG BONET, LAMPU DAN LAIN-LAIN KEROSAKAN BELUM PASTI. SEKIAN LAPORAN SAYA.

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada):

Tandatangan Penerima Repot:

ID Pencetak | Tarikh @ Masa Cetak

: R7141786 | 16/02/2016 03:53:31 PM

PEJ. SALINAN REPORT
TRAFIK JOHOR BAHRU (S)
SALINAN YANG DISAHKAN BENAR
(BANYA UNTUK TUNTUTAN SIVIL)

.....
SALINAN TRAFIK DAERAH JOHOR BAHRU (S) JOHOR
BAHRU DICUNAKAN UNTUK TUJUAN PERSICAPAN

**POLIS DIRAJA MALAYSIA**
REPOT POLIS

Balai : TRAFIK AMPANG JAYA
Daerah : AMPANG JAYA
Kontinjen : SELANGOR
No Repot : TRAFIK AMPANG JAYA/003715/15
Tarikh : 27/03/2015
Waktu : 1612 PM
Bahasa Diterima : B. Malaysia

Pegawai Penyiasat : G21920
No Repot Bersangkut : TRAFIK AMPANG JAYA/003714/15

Butir-butir Penerima Repot

Nama : HAFIZULL BIN ABU HANIFAH
Butir-butir Jurubahasa (Jika Ada)
Nama : ---
No Paspot : ---
Alamat : ---

No Personel : R148467
Pangkat : KPL
No K/P (Baru) : ---
Bahasa Asal : ---
No Polis/Tentera : ---

Butir-butir Pengadu

Nama : MOHAMAD ZULKAFLI BIN ZAKARIA
No K/P (Baru) : ---
No Sijil Beranak : ---
Jantina : Lelaki
Keturunan : Melayu
Pekerjaan : CRANE OPERATOR
Alamat Tempat Tinggal : BLOK 360A, ADMIRALTY DRIVE #14-76 SINGAPORE, 751360
Alamat Ibu/Bapa : ---
Alamat Pejabat : ---
No Tel (Rumah) : ---

No Polis/Tentera : ---
No Paspot : E1982711K
Tarikh Lahir : 01/02/1962
Warganegara : Singapore
Umur : 53 tahun 1 bulan
No Tel (Pejabat) : ---
No Tel (HP) : 96260057

Pengadu Menyatakan:-

PADA 27/03/2015 JAM LEBIH KURANG 1430HRS SAYA MEMANDU M/KAR NO.SKC5808H JENIS MITSUBISHI DARI SINGAPURA MENGHALA KE COLMAR TROPICAL HOTEL. SEMASA MELALUI JLN LINGKARAN TENGAH 2 PANDAN INDAH SAYA MEMANDU DI LORANG PALING KANAN DALAM KEADAAN TRAFIK BERGERAK PERLAHAN TIBA-TIBA SEBUAH M/VAN NO. WSR3661 JENIS NISSAN MELANGGAR M/KAR SAYA DARI BELAKANG DENGAN KUAT MENYEBABKAN M/KAR SAYA TERLAJAK KEDEPAN DAN MELANGGAR SEBUAH M/KAR NO.WNE7661 JENIS TOYOTA VIOS YANG BERADA DIHADAPAN SAYA. AKIBAT DARI ITU M/KAR SAYA MENGALAMI KEROSAKAN PADA BAHAGIAN DEPAN (BONET, BUMPER, LAMPU, RADIATOR) BAHAGIAN BELAKANG (BUMPER, BONET, REVERS SENSOR, EKZOS, CERMIN BESAR, OUTO SERSOR) DAN JUGA LAIN-LAIN KEROSAKAN YANG SAYA MASIH BELUM PASTI. SEKIAN LAPORAN SAYA.

Tandatangan Pengadu: _____ Tandatangan Jurubahasa(Jika ada) : _____ Tandatangan Penerima Repot: _____

ID Pencetak | Tarikh @ Masa Cetak : R7141786 | 16/02/2016 03:52:27 PM

REPOT SALINAN REPOT
TRAFIK JOHOR BAHRU (S)
SALINAN YANG DISAHKAN BENAR
(HANYA UNTUK TUNTUTAN SIVIL)

KEPADA TRAFIK DAERAH JOHOR BAHRU (S) JOHOR
TIDAK BOLEH DIGUNAKAN UNTUK TUJUAN PERSEKUTUAN

**POLIS DIRAJA MALAYSIA**
REPOT POLIS

Balai : TRAFIK AMPANG JAYA
Daerah : AMPANG JAYA
Kontinjen : SELANGOR
No Repot : TRAFIK AMPANG JAYA/003763/15
Tarikh : 28/03/2015
Waktu : 1313 PM
Bahasa Diterima : B. Malaysia

Pegawal Penyiasat : G21920
No Repot Bersangkut : TRAFIK AMPANG
JAYA/003714/15

Butir-butir Penerima Repot
Nama : MAZLAN B MOHAMAD
Butir-butir Jurubahasa (Jika Ada)
Nama : —
No Paspot : —
Alamat : —

No Personel : R124103 Pangkat : KPL
No K/P (Baru) : — No Polis/Tentera : —
Bahasa Asal : —

Butir-butir Pengadu
Nama : DENNY LOW SEE LEONG
No K/P (Baru) : 790916105435
No Sijil Beranak : —
Jantina : Lelaki
Keturunan : Cina
Pekerjaan : -

No Polis/Tentera : — No Paspot : —
Tarikh Lahir : 16/09/1979 Umur : 35 tahun 6 bulan
Warganegara : Malaysia

Alamat Tempat Tinggal : 150 LORONG 10-SUBANG NEW VELLAGED, SHAH ALAM, 40150, SELANGOR
Alamat Ibu/Bapa : —
Alamat Pejabat : —
No Tel (Rumah) : — No Tel (Pejabat) : — No Tel (HP) : 0122328933

Pengadu Menyatakan:-

PADA 17/03/2015 JAM LEBIH KURANG 1430HRS SAYA MEMANDU M/KAR NO WNE 7661 JENIS TOYOTA VIOS WARNA HITAM DARI SUNWAY MENUJU AMPANG. APABILA SAMPAI DI LINGKARAN TENGAH PANDAN INDAH SEBUAH M/KAR NO SKC 5808 H JENIS MITSUBISHI WARNA PUTIH TELAH MELANGGAR BELAKANG M/KAR SAYA. AKIBAT DARI PELANGGARAN TERSEBUT M/KAR SAYA TERLAJAK KEHADAPAN DAN TERLANGGAR BELAKANG M/KAR NO TIDAK PASTI. KEROSAKAN M/KAR SAYA BAHAGIAN BELAKANG BUMPER, BONET, LAMPU, MUDGUARD, EKZOS DAN BAHAGIAN HADAPAN BUMPER, LAMPU DAN LAIN-LAIN KEROSAKAN BELUM PASTI.

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada):

Tandatangan Penerima Repot:

ID Pencetak | Tarikh @ Masa Cetak : R7141786 | 16/02/2016 03:53:56 PM

PEJ. SALINAN REPORT
TRAFIK JOHOR BAHRU (S)
SALINAN YANG DISAHKAN BENAR
(HANYA UNTUK TUNTUTAN SIVIL)

TRAFIK DAERAH JOHOR BAHRU (S) JOHOR
JELAH DIGUNAKAN UNTUK TUJUAN PERBICARAAN

**POLIS DIRAJA MALAYSIA**
REPOT POLIS

Balai : TRAFIK AMPANG JAYA
Daerah : AMPANG JAYA
Kontinjen : SELANGOR
No Repot : TRAFIK AMPANG JAYA/003714/15
Tarikh : 27/03/2015
Waktu : 1616 PM
Bahasa Diterima : B. Malaysia

Pegawai Penyiasat : G21920

Butir-butir Penerima Repot

Nama : MOHD REDZUAN BIN SURATMIN
Butir-butir Jurubahasa (Jika Ada)

No Personel : R152956

Pangkat : KPL

Nama : ---

No K/P (Baru) : ---

No Polis/Tentera : ---

No Paspot : ---

Bahasa Asal : ---

Alamat : ---

Butir-butir Pengadu

Nama : VASUKI AMMAL A/P K.SHANMUGAM

No K/P (Baru) : 801005145592

No Polis/Tentera : ---

No Paspot : ---

No Sijil Beranak : ---

Jantina : Perempuan

Tarikh Lahir : 05/10/1980

Umur : 34 tahun 5 bulan

Keturunan : India

Warganegara : Malaysia

Pekerjaan : -

Alamat Tempat Tinggal : NO 202 BLOCK L19,PANDAN JAYA, 55100, KUALA LUMPUR

Alamat Ibu/Bapa : ---

Alamat Pejabat : ---

No Tel (Rumah) : ---

No Tel (Pejabat) : ---

No Tel (HP) : 0162245203

Pengadu Menyatakan:-

PADA 27/3/2015 JAM LEBIH KURANG 1430 HRS SEMASA SAYA MEMANDU M/VAN NO: WSR 3661 JENIS NISSAN URBAN DARI ARAH CHERAS BARU MENUJU KE KG PANDAN. APABILA SAMPAI DI MRR2 PANDAN INDAH KETIKA ITU SAYA MEMANDU DI LORONG KANAN DAN SAYA MELIHAT KENDERAAN DI HADAPAN BERHENTI DAN SAYA JUGA MEMPERLAHANKAN M/VAN SAYA TIBA-TIBA SEBUAH M/HILUX NO: JCJ 77 JENIS TOYOTA HILUX TELAH MELANGGAR BAHAGIAN BELAKANG M/VAN SAYA MENYEBABKAN M/VAN SAYA TERLAJAK KE HADAPAN DAN MELANGGAR SEBUAH M/KAR NO: SKC 5808H JENIS MITSUBISHI. KEROSAKAN M/VAN SAYA DI BAHAGIAN HADAPAN BUMPER, BONET, FRAME GRILL, TANGKI AIR, GEARBOX, MUDGUARD, LAMPU MANAKALA BAHAGIAN BELAKANG BUMPER, BONET, LAMPU, MUDGUARD DAN LAIN-LAIN KEROSAKAN BELUM PASTI LAGI. SEKIAN LAPORAN SAYA. DALAM KEJADIAN ITU SAYA MENGALAMI KECEDERAAN LUKA DI BAWAH BIBIR DAN SAKIT DI BAHAGIAN BELAKANG KEPALA. SEKIAN LAPORAN SAYA.

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada):

Tandatangan Penerima Repot:

ID Pencetak | Tarikh @ Masa Cetak

: R7141786 | 16/02/2016 03:52

PEJ. SALINAN REPORT
TAMBAH JOHOR BAHRU (S)
SALINAN YANG DISAHKAN BENAR
(HANYA UNTUK TUNTUTAN SIVIL)

.....
KETUA TRAFIK DAERAH JOHOR BAHRU (S) JOHOR
TIDAK BOLEH DIGUNAKAN UNTUK TUJUAN PERKARAAN

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Avenue 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 8181 8802 Fax: 6747 1017
Registration No.: 201000268D

Report Reference : TP / 04-15011/DY / 2015

Date of Report : 27 May 2015

Mohamad Zulkafli Bin Zakaria

Blk 360A Admiralty Drive

#14-76

Singapore 751360

THIRD PARTY SURVEY

ACCIDENT HAPPENED ON 27 Mar 2015

As per your instruction dated 7 Apr 2015
carried out a physical inspection on the said vehicle
our report and findings as follows:

with regard to the above matter. We have
SKC 5808 H . We enclosed herewith

1. VEHICLE PARTICULARS

Registration No : SKC 5808 H
Model : Mitsubishi Colt
Year / Capacity : 2006/1499
Chassis No : JMYLTZ23W6Z000357
Engine No : 4A910022181
Mileage : 122281
Colour : White

2. TYRES CONDITION

		<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	: 195/50 R16	Continental	7.00	mm	Sport
REAR	O/S	: 195/50 R16	Continental	7.00	mm	Sport
FRONT	N/S	: 195/50 R16	Continental	7.00	mm	Sport
REAR	N/S	: 195/50 R16	Continental	7.00	mm	Sport

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Avenue 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 8181 8802 Fax: 6747 1017
Registration No.: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear n/s and front portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Hua Meng Spray Painting Workshop
No. 1 Kaki Bukit Avenue 6
#01-61/34 AutoBay @ Kaki Bukit
Singapore 417883

5. Estimated normal period of repair : 24 working days to complete.
6. Enclosed number of photograph : 297 copies.
7. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
8. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SKC 5808 H
Report No: TP/ 04-15011/DY / 2015

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>Nett Items</u>				
1	Bonnet	Damage	\$ 514.00	\$ 514.00 ✓
2	Bonnet hinges <i>not Repld</i>	Damage	\$ 86.00	\$ 86.00 ✗
1	Bonnet lock	Damage	\$ 48.00	\$ 48.00 ✓
1	Bonnet rear rubber	Necessary	\$ 24.00	\$ 24.00 ✗
1	Bonnet rubber <i>not Repld</i>	Necessary	\$ 22.00	\$ 22.00 ✗
2	Front headlamps	Damage	\$ 1092.00	\$ 1092.00 ✓
1	Front grille	Damage	\$ 238.00	\$ 238.00 ✓
1	Front grille clip (1 set)	Necessary	\$ 34.00	\$ 34.00 ✓
1	Front grille logo	Necessary	\$ 32.00	\$ 32.00 ✓
1	Front bumper	Damage	\$ 627.00	\$ 627.00 ✓
1	Front bumper reinforcement	Damage	\$ 214.00	\$ 214.00 ✓
2	Front bumper side retainers	Necessary	\$ 24.00	\$ 24.00 ✓
1	Front bumper undercover <i>not Repld</i>	Damage	\$ 156.00	\$ 156.00 ✗
1	Front support panel	Damage	\$ 219.00	\$ 219.00 ✓
1	Front brace panel	Damage	\$ 40.00	\$ 40.00 ✓
1	Air con condenser	Damage	\$ 874.00	\$ 874.00 ✓
1	Radiator	Damage	\$ 726.00	\$ 726.00 ✓
1	Radiator fan blade	Damage	\$ 46.00	\$ 46.00 ✗
1	Radiator fan cowling	Damage	\$ 95.00	\$ 95.00 ✗
1	Radiator fan motor <i>not Repld.</i>	Damage	\$ 311.00	\$ 311.00 ✗
1	Front drive seat	Damage	\$ 850.00	\$ 850.00 ✗
1	Rear windscreen glass	Necessary	\$ 630.00	\$ 630.00 ✓
1	Rear windscreen inner side garnish	Damage	\$ 64.00	\$ 64.00 ✓
1	Rear windscreen moulding	Necessary	\$ 118.00	\$ 118.00 ✓
1	Rear tailgate	Damage	\$ 855.00	\$ 855.00 ✓
2	Rear tailgate dampers	Damage	\$ 292.00	\$ 292.00 ✓
2	Rear tailgate hinges <i>NH</i>	Intact	\$ 76.00	\$ 76.00 ✗
1	Rear tailgate inner trim board	Damage	\$ 245.00	\$ 245.00 ✓
2	Rear tailgate lamps	Damage	\$ 378.00	\$ 378.00 ✓
1	Rear tailgate lock	Damage	\$ 339.00	\$ 339.00 ✓
1	Rear tailgate logo	Necessary	\$ 40.00	\$ 40.00 ✓
1	Rear tailgate outer handle	Damage	\$ 129.00	\$ 129.00 ✓
1	Rear tailgate rubber	Necessary	\$ 145.00	\$ 145.00 ✓
1	Rear tailgate 'COLT' emblem	Necessary	\$ 28.00	\$ 28.00 ✓
1	Rear tailgate 'PLUS' emblem	Necessary	\$ 26.00	\$ 26.00 ✓
1	Rear tailgate 'C & C' emblem	Necessary	\$ 40.00	\$ 40.00 ✓
1	Rear tailgate third brake light <i>not Repld</i>	Damage	\$ 102.00	\$ 102.00 ✗

Nett Items Sub Total \$ 9779.00 \$ 9703.00

Vehicle No: SKC 5808 H
Report No: TP/ 04-15011/DY / 2015

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
-----	-------------------	-----------	-----------------------	------------------------

Nett Items Total c/f \$ 9779.00 \$ 9703.00

Nett Items

1	Rear wiper motor	Damage	\$ 264.00	\$ 264.00 ✓
2	Rear taillamps	Damage	\$ 554.00	\$ 554.00 ✓
1	Rear taillamp panel	Damage	\$ 58.00	\$ 58.00 ✓
1	Rear end panel	Damage	\$ 327.00	\$ 327.00 ✓
1	Rear end panel inner garnish	Damage	\$ 179.00	\$ 179.00 ✓
1	Rear end panel inner member	Damage	\$ 245.00	\$ 245.00 ✓
1	Rear bumper	Damage	\$ 586.00	\$ 586.00 ✓
1	Rear bumper reflector	Damage	\$ 38.00	\$ 38.00 ✓
2	Rear bumper side retainers	Necessary	\$ 72.00	\$ 72.00 ✓
1	Rear number plate lamp (1 set)	Damage	\$ 62.00	\$ 62.00 ✓
1	Rear spare tyre panel	Damage	\$ 856.00	\$ 856.00 ✓
1	Rear spare tyre panel tray	Damage	\$ 182.00	\$ 182.00 ✓
1	Rear chassis member	Damage	\$ 468.00	\$ 468.00 ✓
1	Rear fender	Damage	\$ 764.00	\$ 764.00 ✓
1	Rear fender air gate	Damage	\$ 32.00	\$ 32.00 ✓
1	Rear fender inner top garnish	Damage	\$ 228.00	\$ 228.00 ✓
1	Rear fender inner panel <i>Rp15</i>	Damage	\$ 387.00	\$ 387.00 X
2	Rear fender inner trim boards	Damage	\$ 828.00	\$ 828.00 424 ✓
1	Rear fender quarter glass moulding	Necessary	\$ 310.00	\$ 310.00 ✓
1	Rear fender lower extension panel	Damage	\$ 68.00	\$ 68.00 ✓
1	Rear n/s door <i>Rp15 DD</i>	Damage	\$ 960.00	\$ 960.00 ✓
1	Rear n/s door outer moulding <i>DD</i>	Necessary	\$ 84.00	\$ 84.00 +
1	Rear n/s door inner board <i>15585</i>	Damage	\$ 362.00	\$ 362.00 +
1	Rear n/s door lock <i>Rp15</i>	Damage	\$ 216.00	\$ 216.00 +
1	Rear seat <i>1402650</i>	Damage	\$ 960.00	\$ 960.00 +
			\$ 18869.00	\$ 18793.00

Special Nett Items

1	Rear bumper clip (1 set)	Necessary	\$ 30.00	\$ 30.00 ✓
1	Rear tailgate sticker	Necessary	\$ 75.00	\$ 75.00 ✓
1	Rear tailgate 'LED' light	Damage	\$ 80.00	\$ 80.00 ✓
1	Rear tailgate inner board clip (1 set)	Necessary	\$ 36.00	\$ 36.00 ✓
1	Rear end panel inner garnish clip (1 set)	Necessary	\$ 25.00	\$ 25.00 10 ✓
2	Rear fender inner trim board clips (2 set)	Necessary	\$ 70.00	\$ 70.00 ✓
1	Rear n/s door inner board clip (1 set) <i>Rp15</i>	Necessary	\$ 45.00	\$ 45.00 X
1	Rear bumper clip (1 set)	Necessary	\$ 28.00	\$ 28.00 ✓
1	Rear number plate	Damage	\$ 60.00	\$ 45.00 ✓
1	Rear reverse sensor (1 set) <i>574</i>	Damage	\$ 280.00	\$ 280.00 200 ✓
			\$ 729.00	\$ 714.00

Spare Parts Total \$ 19598.00 \$ 19507.00

Vehicle No: **SKC 5808 H**
 Report No: **TP/ 04-15011/DY / 2015**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 19598.00	\$ 19507.00
1	To provide towing service charge.	\$ 80.00	80.00 50
2	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 40.00	40.00 30
3	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 40.00	40.00 30
4	To remove and refit rear cushion seats, radio speaker board, interior upholstery to facilitate the repairs.	\$ 350.00	240.00 200
5	To remove and refit fuel tank system.	\$ 120.00	\$ 80.00 ✓
6	To remove and refit rear bumper sensor.	\$ 120.00	80.00 50
7	To remove and refit air-con system, refill gas and test for leakages.	\$ 200.00	\$ 120.00 ✓
8	To remove and refit rear windscreen glass.	\$ 200.00	150.00 120
9	To remove and refit the door lock mechanism, regulator gear, window glass, handle, inner board, hinges, channel to facilitate the repairs.	\$ 150.00	80.00 ✓
10	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 4200.00	3750.00 2500
11	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 4000.00	3500.00 2000
12	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 300.00	300.00 160
Total		\$ 29398.00	\$ 27967.00

Vehicle No: SKC 5808 H
Report No: TP/ 04-15011/DY / 2015


LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
------	------------------	-----------------------	------------------------

Total c/f \$ 29398.00 \$ 27967.00

Recommended PART BY PART Repair Amount of: \$ 27967.00

SDLS: TWENTY SEVEN THOUSAND NINE HUNDRED SIXTY SEVEN ONLY


Qualified Appraiser

total 20020.500
N/S : 16K.
18 days.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TAN KOK QUAN PARTNERSHIP		Ref : CS/LAW19000268/Avd3e2		
1 WALLICH STREET #07-02 GUOCO TOWERSINGAPORE 078881		Date : 23-04-2019		
		Code : L021		
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	AGY 6881	Veh. Inspected	SKC 5808H	
Policy No.	MKR/106/6173/2015/jk	Coverage (\$)	0.00	
Claim No.	CF.LHP.2012.17-bsi	Excess (\$)	0.00	
Assign From	JOLENE QUAH	Assign Date	19/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI COLTPLUSSPRT	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JMYLTZ23W6Z000357	Colour	BLUE	
Odometer	172836	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R16	CONTINENTAL	6 mm	
L/H Front Tyre	195/50 R16	CONTINENTAL	6 mm	
R/H Rear Tyre	195/50 R16	CONTINENTAL	6 mm	
L/H Rear Tyre	195/50 R16	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	27/03/2015	Inspection Date	23/02/2019	
Survey held at	BLK 360A ADMIRALTY DRIVE			
Repairer	HUA MENG SPRAY PAINTING WKSP			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		18 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 5808H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET (N)	REPLACED	514.00	514.00
2	BONNET HINGES (N)	NOT CHANGED	86.00	-
1	BONNET LOCK (N)	REPLACED	48.00	48.00
1	BONNET REAR RUBBER (N)	NOT CHANGED	24.00	-
1	BONNET RUBBER (N)	NOT CHANGED	22.00	-
2	FRONT HEADLAMPS (N)	REPLACED	1,092.00	1,092.00
1	FRONT GRILLE (N)	REPLACED	238.00	238.00
1	SET FRONT GRILLE CLIP (N)	REPLACED	34.00	34.00
1	FRONT GRILLE LOGO (N)	REPLACED	32.00	32.00
1	FRONT BUMPER (N)	REPLACED	627.00	627.00
1	FRONT BUMPER REINFORCEMENT (N)	REPLACED	214.00	214.00
2	FRONT BUMPER SIDE RETAINERS (N)	REPLACED	24.00	24.00
1	FRONT BUMPER UNDERCOVER (N)	NOT CHANGED	156.00	-
1	FRONT SUPPORT PANEL (N)	REPLACED	219.00	219.00
1	FRONT BRACE PANEL (N)	REPLACED	40.00	40.00
1	AIR CON CONDENSER (N)	REPLACED	874.00	874.00
1	RADIATOR (N)	REPLACED	726.00	726.00
1	RADIATOR FAN BLADE (N)	NOT CHANGED	46.00	-
1	RADIATOR FAN COWLING (N)	REPLACED	95.00	95.00
1	RADIATOR FAN MOTOR (N)	NOT CHANGED	311.00	-
1	FRONT DRIVE SEAT (N)	REPLACED	850.00	850.00
1	REAR WINDSCREEN GLASS (N)	REPLACED	630.00	630.00
1	REAR WINDSCREEN INNER SIDE GARNISH (N)	REPLACED	64.00	64.00
1	REAR WINDSCREEN MOULDING (N)	REPLACED	118.00	118.00
1	REAR TAILGATE (N)	REPLACED	855.00	855.00
2	REAR TAILGATE DAMPERS (N)	REPLACED	292.00	292.00
2	REAR TAILGATE HINGES (N)	NOT CHANGED	76.00	-
1	REAR TAILGATE INNER TRIM BOARD (N)	REPLACED	245.00	245.00
2	REAR TAILGATE LAMPS (N)	REPLACED	378.00	378.00
1	REAR TAILGATE LOCK (N)	REPLACED	339.00	339.00
1	REAR TAILGATE LOGO (N)	REPLACED	40.00	40.00

Report Ref No. CS/LAW19000268/Avd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILGATE OUTER HANDLE (N)	REPLACED	129.00	129.00
1	REAR TAILGATE RUBBER (N)	REPLACED	145.00	145.00
1	REAR TAILGATE "COLT" EMBLEM (N)	REPLACED	28.00	28.00
1	REAR TAILGATE "PLUS" EMBLEM (N)	REPLACED	26.00	26.00
1	REAR TAILGATE "C&C" EMBLEM (N)	REPLACED	40.00	40.00
1	REAR TAILGATE THIRD BRAKE LIGHT (N)	NOT CHANGED	102.00	-
1	REAR WIPER MOTOR (N)	REPLACED	264.00	264.00
2	REAR TAILLAMPS (N)	REPLACED	554.00	554.00
1	REAR TAILLAMP PANEL (N)	REPLACED	58.00	58.00
1	REAR END PANEL (N)	REPLACED	327.00	327.00
1	REAR END PANEL INNER GARNISH (N)	REPLACED	179.00	179.00
1	REAR END PANEL INNER MEMBER (N)	REPLACED	245.00	245.00
1	REAR BUMPER (N)	REPLACED	586.00	586.00
1	REAR BUMPER REFLECTOR (N)	REPLACED	38.00	38.00
2	REAR BUMPER SIDE RETAINERS (N)	REPLACED	72.00	72.00
1	SET REAR NUMBER PLATE LAMP (N)	REPLACED	62.00	62.00
1	REAR SPARE TYRE PANEL (N)	REPLACED	856.00	856.00
1	REAR SPARE TYRE PANEL TRAY (N)	REPLACED	182.00	182.00
1	REAR CHASSIS MEMBER (N)	REPLACED	468.00	468.00
1	REAR FENDER (N)	REPLACED	764.00	764.00
1	REAR FENDER AIR GATE (N)	REPLACED	32.00	32.00
1	REAR FENDER INNER TOP GARNISH (N)	REPLACED	228.00	228.00
1	REAR FENDER INNER PANEL (N)	REPAIRED SEE LABOUR	387.00	-
2	REAR FENDER INNER TRIM BOARDS (N)	REPLACED	828.00	424.00
1	REAR FENDER QUARTER GLASS MOULDING (N)	REPLACED	310.00	310.00
1	REAR FENDER LOWER EXTENSION PANEL (N)	REPLACED	68.00	68.00
1	REAR N/S DOOR (N)	REPLACED	960.00	960.00
1	REAR N/S DOOR OUTER MOULDING (N)	NOT CHANGED	84.00	-
1	REAR N/S DOOR INNER BOARD (N)	NOT CHANGED	362.00	-
1	REAR N/S DOOR LOCK (N)	NOT CHANGED	216.00	-
1	REAR SEAT (N)	NOT CHANGED	960.00	-

Report Ref No. CS/LAW19000268/Avd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-	-1,563.30
			18,869.00	14,069.70
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIP (SN)	REPLACED	30.00	30.00
1	REAR TAILGATE STICKER (SN)	REPLACED	75.00	75.00
1	REAR TAILGATE "LED" LIGHT (SN)	REPLACED	80.00	80.00
1	SET REAR TAILGATE INNER BOARD CLIP (SN)	REPLACED	36.00	36.00
1	SET REAR END PANEL INNER GARNISH CLIP (SN)	REPLACED	25.00	10.00
2	SET REAR FENDER INNER TRIM BOARD CLIPS (SN)	REPLACED	70.00	70.00
1	SET REAR N/S DOOR INNER BOARD CLIP (SN)	NOT CHANGED	45.00	-
1	SET REAR BUMPER CLIP (SN)	REPLACED	28.00	28.00
1	REAR NUMBER PLATE (SN)	REPLACED	60.00	45.00
1	SET REAR REVERSE SENSOR (SN)	REPLACED	280.00	200.00
			729.00	574.00
	<u>LABOUR</u>			
	TO PROVIDE TOWING SERVICE CHARGE.		80.00	50.00
	TO REMOVE AND REFIT DAMAGE PARTS,TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.		40.00	30.00
	TO REMOVE AND REFIT REAR ELECTRICAL WIRING,REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING.		40.00	30.00
	TO REMOVE AND REFIT REAR CUSHION SEATS,RADIO SPEAKER BOARD,INTERIOR UPHOLSTERY TO FACILITATE THE REPAIRS.		350.00	200.00
	TO REMOVE AND REFIT FUEL TANK SYSTEM.		120.00	80.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		120.00	50.00
	TO REMOVE AND REFIT AIR-CON SYSTEM,REFILL GAS AND TEST FOR LEAKAGES.		200.00	120.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		200.00	120.00
	TO REMOVE AND REFIT THE DOOR LOCK MECHANISM,REGULATOR GEAR,WINDOW GLASS,HANDLE,INNER BOARD,HINGES,CHANNEL TO FACILITATE THE REPAIRS.		150.00	80.00

Report Ref No. CS/LAW19000268/Avd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.INCLUSIVE OF THE REPAIR OF REAR FENDER INNER PANEL.		4,200.00	2,500.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		4,000.00	2,000.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		300.00	160.00
			9,800.00	5,420.00
GRAND TOTAL			29,398.00	20,063.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				16,000.00

Report Ref No. CS/LAW19000268/Avd3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.