

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: YP6237P18

Estimate

Customer

Name: AIG Asia Pacific Insurance Pte Ltd

Date: 03-01-19

Address Motor Claims Department

Vehicle No: YP6237P

78 Shenton Way #07-16

Model/Make: Mitsubishi Fuso

AIG Building

Singapore 079120

FM65FM2RDEB


Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Bumper	\$ 1,830.00	
2	Bumper Lamp o/s	\$ 293.30	
3	Head Lamp o/s	\$ 1,302.40	
4	Head Lamp Outer Garnish o/s	\$ 497.40	X
5	Signal Lamp o/s	\$ 230.70	X
6	Reflector o/s	\$ 138.00	
7	Door Signal Lamp o/s	\$ 230.70	
8	Corner Panel garnish o/s	\$ 1,183.70	
9	Step Garnish o/s	\$ 613.20	
10	Step Aluminium Top o/s	\$ 876.70	
11	Step Aluminium Lower o/s	\$ 425.00	
	To check all wiring & electrical component for proper function	\$ 80.00	20
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 600.00	400
	To putty & spray painting & including touch up paint on accident affected area	\$ 800.00	550
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 60.00	X

Total Parts & Labour of estimate for damaged vehicle

\$ 9,161.10

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

P- 6893
 252
 5169.75
 6139.75

Not Authorized
 4/1/19
 L/S # 4900/
 3 day

LKK Auto Consultants hence notify the Repairer of the following:

- * Insurance policyholder spray painting
- * 2nd party (any other parts) during resurvey
- * Each party is subject to confirmation
- * This party survey is on a "Without Prejudice" basis
- * Knowledge of insurance is allowed
- * Supplementary damage must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: