



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 14U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER FASCIA	DENTED / DEFORMED	2,450.00	2,450.00
1	REAR BUMPER EXHAUST CHROME PIPE LH	SERVICEABLE	580.00	-
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	361.00	-
10	REAR BUMPER CLIPS @\$10.00	NECESSARY	100.00	100.00
2	REAR BUMPER PARKING SENSOR @\$313.60	SERVICEABLE	617.20	-
2	REAR BUMPER PARKING SENSOR HOLDER @\$110.00	NOT NECESSARY	220.00	-
1	REAR BUMPER PARKING SENSOR WIRING	NOT NECESSARY	461.00	-
1	TAIL GATE EMBLUM 'RANGE ROVER'	NOT NECESSARY	89.00	-
1	TAIL GATE EMBLUM 'EVOQUE'	NECESSARY	81.00	81.00
1	TAIL GATE EMBLUM 'S14'	NECESSARY	78.00	78.00
1	TAIL GATE BADGE	NECESSARY	88.00	88.00
	LESS 10% DISCOUNT		-512.52	-279.70
			4,612.68	2,517.30
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING SYSTEM.		80.00	30.00
	TO RESPRAY AFFECTED AREAS (2 TONE).		1,050.00	600.00
	TO RESET ELECTRICAL MODULE SYSTEM.	NOT NECESSARY	280.00	-
	TO RENEW DAMAGED PARTS ,STRAIGHTEN &REPAIR TAILGATE ,REAR END PANEL AND ALIGNED ALL PARTS.		850.00	300.00
			2,260.00	930.00
<b>GRAND TOTAL</b>			<b>6,872.68</b>	<b>3,447.30</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,750.00</b>

Report Ref No. CC4/ASM19000293/Upa3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.