

Accident Photo



Accident Photo



Accident Photo



PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883

Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 12-18001/DY / 2018

Date of Report : 12 Dec 2018

Teng Kah Seng (Ding Jiasheng)

Blk 120 Bukit Batok Central

#08-351

Singapore 650120

THIRD PARTY SURVEY

ACCIDENT HAPPENED ON 29 Nov 2018

As per your instruction dated 1 Dec 2018 with regard to the above matter. We have carried out a physical inspection on the said vehicle SLW 5707 Z. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SLW 5707 Z
Model : Kia Cerato
Year / Capacity : 2010/1591
Chassis No : KNAFW611MA5204108
Engine No : G4FCAH366727
Mileage : 98723
Colour : White

2. TYRES CONDITION

		<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	: 225/45 ZR17	CST	6.00	mm	Sport
REAR	O/S	: 225/45 ZR17	CST	6.00	mm	Sport
FRONT	N/S	: 225/45 ZR17	CST	6.00	mm	Sport
REAR	N/S	: 225/45 ZR17	CST	6.00	mm	Sport

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the front n/s portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Derrick Motor Works
Blk 9002 Tampines Street 93
#01-72 Tampines Ind Park A
Singapore 528836

5. Estimated normal period of repair : 6 working days to complete.

6. Enclosed number of photograph : 102 copies.

7. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.

8. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SLW 5707 Z
Report No: TP/ 12-18001/DY / 2018

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Front headlamp	Damage	\$ 586.00	\$ 586.00
1	Front headlamp lower bracket	Damage	\$ 36.00	\$ 36.00
1	Front bumper	Damage	\$ 545.00	\$ 545.00
1	Front bumper fog lamp	Damage	\$ 380.00	\$ 380.00
1	Front bumper fog lamp cover	Damage	\$ 45.80	\$ 45.80
1	Front bumper inner sponge	Damage	\$ 83.60	\$ 83.60
2	Front bumper side retainers	Necessary	\$ 56.00	\$ 56.00
1	Front fender	Damage	\$ 385.00	\$ 385.00
1	Front fender inner shield	Damage	\$ 86.00	\$ 86.00
1	Front support panel	Damage	\$ 485.00	\$ 485.00
1	Front wheel hub	Damage	\$ 185.00	\$ 185.00
1	Front wheel bearing	Necessary	\$ 112.50	\$ 112.50
1	Front shock absorber	Damage	\$ 281.50	\$ 281.50
1	Front ABS sensor	Damage	\$ 260.00	\$ 260.00
1	Front knuckle arm	Damage	\$ 297.00	\$ 297.00
1	Front lower arm	Damage	\$ 273.00	\$ 273.00
1	Front lower arm ball joint	Damage	\$ 69.50	\$ 69.50
1	Front stabilizer bar link	Damage	\$ 85.00	\$ 85.00
1	Front door side mirror	Damage	\$ 881.00	\$ 881.00
			\$ 5132.90	\$ 5132.90
	Discount	10.0%	\$ 513.29	\$ 513.29
			\$ 4619.61	\$ 4619.61
<u>Special Nett Items</u>				
1	Front bumper clip (1 set)	Necessary	\$ 35.00	\$ 35.00
1	Front fender inner shield clip (1 set)	Necessary	\$ 35.00	\$ 35.00
1	Front tyre (Depreciation)	Damage	\$ 380.00	\$ 228.00
1	Front sport rim	Damage	\$ 650.00	\$ 650.00
			\$ 1100.00	\$ 948.00

Spare Parts Total \$ 5719.61 \$ 5567.61

Vehicle No: SLW 5707 Z
Report No: TP/ 12-18001/DY / 2018


LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 5719.61	\$ 5567.61
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 60.00	\$ 40.00 30
2	To remove and refit front undercarriage.	\$ 400.00	\$ 200.00 80
3	To check and re-adjust (Computerized) all wheel alignment.	\$ 180.00	\$ 120.00 60
4	To remove and refit air-con system, refill gas and test for leakages.	\$ 200.00	\$ 120.00 60
5	To remove and refit radiator system.	\$ 150.00	\$ 60.00 40
6	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1000.00	\$ 660.00 600
7	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 700.00	\$ 440.00 400
8	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 100.00	\$ 30.00 /
Total		\$ 8509.61	\$ 7237.61

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 5800.00

SDLS: FIVE THOUSAND EIGHT HUNDRED ONLY


Qualified Appraiser

5200.21
20% 4150
(6 days)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Dec 2018		04 Dec 2018 09:05 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LOI KOK KHEONG, ID: S0124213Z		
Main Claimant:	TENG KAH SENG		
Vehicle Reg. No.:	SLW5707Z	Date of Loss:	29/11/2018 00:00 - :59 [105 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 577704	Policy/Cover Note No.:	290697256DMA (Comprehensive) Coverage: 20/01/2018 - 19/01/2019
Vehicle Reg. No. (Insured):	SGT979M	Policy No. (Claimant):	
		Excess:	
Repairer:	Derrick Motor Works (HQ) 9002 Tampines St. 93, #01-72 Tampines Industrial Park A, 528836 Tampines - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 08/01/2019]		
Adj Asg. Remarks:	OI not reported, SJE disagree - assign LKK, Contact : Mr Jeromy at HP 9633 3593		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (04/01/2019): Report Send Back Alerts - SLW5707Z (TP)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLW5707Z (577704)**

[SGT979M]

TP

TENG KAH SENG

Nov 29 2018 12:00AM

[LOI KOK KHEONG]

Derrick Motor Works

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View
[View in Browser](#)

Assessment Reports

1 per page



No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/12/18 11:13	Accident Statement From:SC - Reg. No: SGT979M, Claimant: LOI KOK KHEONG	Load HTM	

Photos/Images

3 per page



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/12/18 09:58	General View	Load JPG	
2	07/12/18 09:58	General View	Load JPG	
3	07/12/18 09:58	General View	Load JPG	
4	07/12/18 09:58	General View	Load JPG	
5	07/12/18 09:58	General View	Load JPG	
6	07/12/18 09:58	General View	Load JPG	
7	07/12/18 09:58	General View	Load JPG	
8	07/12/18 09:58	General View	Load JPG	
9	07/12/18 09:58	General View	Load JPG	
10	07/12/18 09:58	General View	Load JPG	
11	07/12/18 09:58	General View	Load JPG	
12	07/12/18 09:58	General View	Load JPG	
13	07/12/18 09:58	General View	Load JPG	
14	07/12/18 09:58	General View	Load JPG	
15	07/12/18 09:58	General View	Load JPG	
16	07/12/18 09:58	General View	Load JPG	
17	07/12/18 09:58	General View	Load JPG	
18	07/12/18 09:58	General View	Load JPG	
19	07/12/18 09:58	General View	Load JPG	
20	07/12/18 09:58	General View	Load JPG	
21	07/12/18 09:58	General View	Load JPG	
22	07/12/18 09:58	General View	Load JPG	
23	07/12/18 09:58	General View	Load JPG	
24	07/12/18 09:58	General View	Load JPG	
25	07/12/18 09:58	General View	Load JPG	
26	07/12/18 09:58	General View	Load JPG	
27	07/12/18 09:58	General View	Load JPG	
28	07/12/18 09:58	General View	Load JPG	
29	07/12/18 09:58	General View	Load JPG	
30	07/12/18 09:58	General View	Load JPG	
31	07/12/18 09:58	General View	Load JPG	

Assessment Reports			1 per page	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	07/12/18 09:58	General View	 Load JPG	✓
33	07/12/18 09:58	General View	 Load JPG	✓
34	07/12/18 09:58	General View	 Load JPG	✓
35	07/12/18 09:58	General View	 Load JPG	✓
36	07/12/18 09:58	General View	 Load JPG	✓
37	07/12/18 09:58	General View	 Load JPG	✓
38	07/12/18 09:58	General View	 Load JPG	✓
Documentation			1 per page	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/12/18 13:38	Pri from Vision Law LLC	 Load PDF	
2	03/12/18 16:35	Survey Disagree on SJE - assign LKK	 Load PDF	
3	03/12/18 18:19	Workshop & Location to Survey	 Load PDF	
4	07/12/18 11:13	SLW5707Z E-FILE & POLICE REPORT From:SC - Reg. No: SGT979M, Claimant: LOI KOK KHEONG	 Load PDF	
5	04/01/19 14:00	Survey Report	 Load PDF	
6	04/01/19 14:06	Survey Photos	 Load PDF	
7	04/01/19 14:08	Survey Photos	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/01/19 13:17	PRS INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18021767/GTD3S2-1

Date: 23/01/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 290697256DMA

Claimant Vehicle No: SLW5707Z

Insured Vehicle No: SGT979M

Date of Loss: 29/11/2018

Nature of Claim: TP

Claim No: 577704

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLW5707Z

Make & Model: KIA CERATO FORTE Koup, 1.6 SX ABS D/AB SR (A)

Engine No: G4FCAH366727

Reg. Date: 24/02/2010 (Man. Year: 2009)

Chassis No: KNAFW611MA5204108

Colour: White

Odometer: 98728 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 225/45ZR17

Rear Tyre Size: 225/45ZR17

Front Left Side: CST 6 mm

Rear Left Side: CST 6 mm

Front Right Side: CST 6 mm

Rear Right Side: CST 6 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,719.61	3,733.71	1,985.90	34.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,790.00	1,300.00	1,490.00	53.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,509.61	5,033.71	3,475.90	40.85
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	8,509.61	4,000.00	4,509.61	52.99

INSPECTION

Date of Assignment: 04/12/2018

Date Inspected: 04/12/2018 Inspected At:

Derrick Motor Works (HQ)
9002 Tampines St. 93, #01-72 Tampines Industrial Park A
Singapore 528836

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 23 Jan 2019)

Parts: 143 KIA CERATO FORTE KOUP 1.6 SX ABS D/AB SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLW5707Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP	Damaged	586.00 FL	*586.00 FL
2	1		*FRONT HEADLAMP LOWER BRACKET	Damaged	36.00 FL	*36.00 FL
3	1		*FRONT BUMPER	Damaged	545.00 FL	*545.00 FL
4	1		*FRONT BUMPER FOG LAMP	Damaged	380.00 FL	*380.00 FL
5	1		*FRONT BUMPER FOG LAMP COVER	Damaged	45.80 FL	*45.80 FL
6	1		*FRONT BUMPER INNER SPONGE	Damaged	83.60 FL	*83.60 FL
7	2		*FRONT BUMPER SIDE RETAINERS	Necessary	56.00 FL	*56.00 FL
8	1		*FRONT FENDER	Damaged	385.00 FL	*385.00 FL
9	1		*FRONT FENDER INNER SHIELD	Damaged	86.00 FL	*86.00 FL
10	1		*FRONT SUPPORT PANEL	Damaged	485.00 FL	*485.00 FL
11	1		*FRONT WHEEL HUB	Not Necessary	185.00 FL	*- FL
12	1		*FRONT WHEEL BEARING	Bent	112.50 FL	*112.50 FL
13	1		*FRONT SHOCK ABSORBER	Not Necessary	281.50 FL	*- FL
14	1		*FRONT ABS SENSOR	Not Necessary	260.00 FL	*- FL
15	1		*FRONT KNUCKLE ARM	Not Necessary	297.00 FL	*- FL
16	1		*FRONT LOWER ARM	Not Necessary	273.00 FL	*- FL
17	1		*FRONT LOWER ARM BALL JOINT	Not Necessary	69.50 FL	*- FL
18	1		*FRONT STABILIZER BAR LINK	Not Necessary	85.00 FL	*- FL
19	1		*FRONT DOOR SIDE MIRROR	Damaged	881.00 FL	*881.00 FL
20	1		*SET FRONT BUMPER CLIP	Necessary	35.00 FS	*35.00 FS
21	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	35.00 FS	*35.00 FS
22	1		*FRONT TYRE	Not Necessary	380.00 FS	*- FS
23	1		*FRONT SPORT RIM	Damaged	650.00 FS	*350.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc,

Sub Total (\$\$)	6,232.90	4,101.90
- List Item Discount on L Items 10.00/10.00% (\$\$)	513.29	368.19
Total Parts (\$\$)	5,719.61	3,733.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.	New	60.00	30.00
2	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.	New	400.00	80.00
3	TO CHECK AND RE-ADJUST (COMPUTERIZED) ALL WHEEL ALIGNMENT.	New	180.00	60.00
4	TO REMOVE AND REFIT AIR-CON SYSTEM, REFILL GAS AND TEST FOR LEAKAGE.	New	200.00	60.00
5	TO REMOVE AND REFIT RADIATOR SYSTEM.	New	150.00	40.00
6	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.	New	1,000.00	600.00
7	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.	New	700.00	400.00
8	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.	New	100.00	30.00
Gross Labour Cost (S\$)			2,790.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >