Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19000353/APA3Q2

Date: 29/09/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00010341

Claimant CL 7366ELL Inquired Vehicle No.

Vehicle No: SLZ3665H Insured Vehicle No: SGY3268K

Date of Loss: 02/01/2019 Nature of Claim: TP Claim No: 1201900001283

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLZ3665H

Make & Model: HONDA ODYSSEY, 2.3 (A) Engine No: K24W72400372

Reg. Date: 30/04/2018 (Man. Year: 2017) Chassis No: JHMRC1880JC200855

Colour: Silver Odometer: 16167 km

Engine Capacity: 2356 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm
Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,268.56	795.76	1,472.80	64.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	650.00	250.00	27.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,168.56	1,445.76	1,722.80	54.37
Approved Total (Overridden) (S\$)		1,150.00		
Nett Amount (S\$)	3,168.56	1,150.00	2,018.56	63.71
Global Sum S	Global Sum Settlement (S\$)			,

INSPECTION

Date of Assignment: 04/01/2019

Date Inspected: 04/01/2019 Inspected At: Jcn Autolution Pte Ltd - Kaki Bukit

(HQ)

NO.1 KAKI BUKIT AVENUE 6, BLK D #01-85, AUTOBAY @ KAKI BUKIT

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: CHEW HSIAO TONG

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference			
Part Source	: MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2019)	
Parts:	M1-MPV	HONDA ODYSSEY 2.3 (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	: (Unsubmitted, no print-code for SLZ3665H)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.			

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	568.30 FL	*568.30 FL
2	1		*REAR BUMPER REFLECTOR CHROM GARNISH L/R	Not Necessary	114.10 FL	*-FL
3	1		*REAR BUMPER REFLECTOR L/R	Not Necessary	45.40 FL	*-FL
4	1		*REAR BUMPER SIDE RETAINER L/R	Necessary	19.10 FL	*19.10 FL
5	1		*REAR TAILGATE	Repair	1,216.80 FL	*- FL
6	1		*REAR TAILGATE ODYSEY EMBLEM	Necessary	31.00 FL	*31.00 FL
7	1		*REAR TAILGATE HONDA EMBLEM	Necessary	26.30 FL	*26.30 FL
8	1		*REAR TAILGATE LOWER NO.PLATE CHROM GARNISH	Not Necessary	175.50 FL	*-FL
9	1		*REAR TAILGATE UPPER NO PLATE CHROM GARNISH	Not Necessary	164.20 FL	*-FL
10	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
11 F=Fra	1 inchise	part. S=S	*REAR BUMPER REVERSE SENSOR SpcNett. L=ListItemDisc.	Damaged	350.00 FS	*250.00 FS
				Sub Total (S\$)	2,740.70	924.70
			- List Item Discount on L Items 2	20.00/20.00% (S\$)	472.14	128.94
				Total Parts (S\$)	2,268.56	795.76
			Report was unsubmitted during this pri	nt-out.		

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	<u>Labour Items</u>					
1	TO REMOVE, REFIX / RENEW REVERSE CAMERA ASSY	New	100.00	50.00		
2	TO RESPRAY PAINTING ON THE CHANGE BODYPARTS ,REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	New	500.00	400.00		
3	TO PROVIDE LABOUR WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-ALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	300.00	200.00		
	Gross Labour Cost (S\$)		900.00	650.00		
	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >