

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1490B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	СИТ	459.40	459.40
1	REAR BUMPER SIDE BRACKET (RH)	NOT NECESSARY	33.10	-
1	REAR BUMPER COVER CLIPS	NECESSARY	22.00	22.00
1	REAR FENDER (RH)	TORN	1,768.30	1,768.30
1	REAR FENDER INNER LINING (RH)	NOT NECESSARY	73.60	-
1	REAR DOOR	BENT	1,789.90	1,789.90
1	REAR WHEEL HUP - CAP (RH)	GRAZED	346.40	346.40
	LESS 20% DISCOUNT		-898.54	-877.20
			3,594.16	3,508.80
	SPECIAL NETT ITEMS			
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (RH) (SN)	NECESSARY	80.00	80.00
1	FRONT DOOR COLOURED COMFORT LOGO (RH) (SN)	NECESSARY	75.00	75.00
1	REAR WHEEL TYRE (RH) (SN)	CUT	216.00	216.00
			421.00	421.00
	<u>LABOUR</u>			
İ	PANEL BEATING.		1,000.00	600.00
	SPRAY PAINTING CHARGE.		1,000.00	600.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.		100.00	50.00
	TOWING CHARGE.	NOT NECESSARY	60.00	-
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.		150.00	60.00
	REMOVE / REFIX REVERSE SENSOR.		120.00	40.00
	TRANSFER OF DOOR.		120.00	60.00
	REAR WHEEL ALIGNMENT.	NOT NECESSARY	120.00	
			2,720.00	1,430.00
	GRAND TOTAL		6,735.16	5,359.80

RECOMMENDED COST OF REPAIRS		5,359.80

Report Ref No. CS1/SPF19000362/Dtbs2



Page No.:2 of 2

Report Ref No. CS1/SPF19000362/Dtbs2

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$5,763.08

ANG BRYAN TANI

Automotive Assessor / Investigator

h

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser