

ASS. REC. BY:

REF

es/CT119000363/D9d3n2

Special Instruction:

Surveyor:

Bryen

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time:

7/1/19 @ 3:14pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 324E

Insured:

GU 4145X

at Workshop m/s

Chunni Motor

Tel:

6542 5119

of

BLK 10 AMK Autopoint # 01-05/06

Policy No:

DYM CVS N306 2301801

Claim No:

SMM 19D 200053 C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/01/2019

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

3:22pm @ 7/1/19

Person Contacted:

Jupin

Vehicle

IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 324E-03/CTI18000700/K1Y5392 DOA: 9/1/2018
	GU 4145X-CC6/ALG12016683/Kr43w2 DOA: 7/8/2012

REF:


ASSIGNMENT

COE 2020 April

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s: _____
 of _____
 Insured _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12/2 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 324E Yt Regn: April 2012
 Type: M.Car / M.Cycle / Bus / Van / Lorry (X) Prime Mover /

Truck / Trailer or

Make: Hyundai Sonata C.C. 1991
 Colour: Yellow A/C: Insured / Std / NI / NA
 Sp Reading: 375641 T/Radio: Insured / Std / NI / NA
 Eng/No: D4EAC086292
 C/No: KMHET41VMCA824558

Gen. Cond: (X) Good / Fair / Poor / BurntSteering: (X) In order / Jammed / Leaked / Burnt orBrake: (X) In order / Jammed / Leaked / Burnt orModi: (X) S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16
 R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake

Front	Rear
R/Bal. <u>S</u> mm	R/Bal. <u>S</u> mm
L/Bal. <u>S</u> mm	L/Bal. <u>S</u> mm

D.O.A. 01/01/2019 D.O.I. 07/01/2019Survey held at: Chunni TMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front y H/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Chun Taping GU 4145XVehicle balance 14 months at time of loss

12/02/19 Juniper L/S 140001- 5th 13 days 8 hr
(Red 5 18770.57, 53%)

RECEIVED 12 APR 2019

Date/Time: File Pass to?

☐

Preli. Report

☐

Final Report

Date/Time: File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Days Of Repair: 13Resurvey No. of Trip: 2

Survey Fee:

Transportation

) 5 x RS. 54

1. Photos

2. Other

3. 10

TOTAL

Report Format:

MEP-TP

Lump Sum / L.R. (\$

14000

220

Nivitha (LKK Auto)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Monday, 7 January 2019 3:14 PM
To: 'assignments'; Chunni Motor
Subject: FW: Accident involving veh no: SHC 324E & GU 4145X on 01.01.19
Attachments: TP REPAIR ESTIMATE & SAS REPORT- SHC324E.pdf

WITHOUT PREJUDICE

Dear Sir,

We refer to your email of 04.01.19.

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle and propose direct settlement with quantum to be agreed.

Aside to LKK,

Please refer to the email below with attachment and proceed to survey the third party vehicle.

Kindly acknowledge receipt. Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com



From: Chunni Motor [mailto:chunnimotor@gmail.com]
Sent: Friday, 4 January, 2019 5:11 PM
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Subject: Re: Accident involving veh no: SHC 324E & GU 4145X on 01.01.19

Dear Sir,

We appoint Henry Ng

Thank you

Regards,
Chunni Motor Work P/L

On Fri, Jan 4, 2019 at 5:03 PM Elaine Cheong <elaine.cheong@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear All,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE
DERECK OH SIONG WEE
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Elaine Cheong

Executive (Motor Claims)

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6530

Fax: 6224 7478 / 6224 7175

Email: elaine.cheong@sg.cntaiping.com

Website: www.sg.cntaiping.com



From: Chunni Motor [mailto:chunnimotor@gmail.com]

Sent: Friday, 4 January, 2019 4:25 PM

To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>

Subject: Fwd: Accident involving veh no: SHC 324E & GU 4145X on 01.01.19

----- Forwarded message -----

From: **Chunni Motor** <chunnimotor@gmail.com>

Date: Fri, Jan 4, 2019 at 11:14 AM

Subject: Fwd: Accident involving veh no: SHC 324E & GU 4145X on 01.01.19

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

----- Forwarded message -----

From: **Chunni Motor** <chunnimotor@gmail.com>

Date: Thu, Jan 3, 2019 at 9:09 AM

Subject: Accident involving veh no: SHC 324E & GU 4145X on 01.01.19

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly arrange to survey in AMK Autopoint, Soon Hock Motor, #01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

MCD619000797 / ComfortDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 03/01/2019 07:31
 SUBMITTED BY: Catherine Per May Juan

Your NCD will be affected due to late reporting
 Actual e-Filing Submission Date & Time: 03/01/2019 07:37

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 03/01/2019 07:31
 Date Of Accident 01/01/2019 10:50
 Exact Location Of Accident JOO CHIAT RD TWDS KOON SENG RD .
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC324E
 Insured/Policyholder
 Name Of Registered Owner CITYCAB PTE LTD
 Co Reg No 199502839G
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768
 Vehicle Particulars
 Manufacturer HYUNDAI
 Model SONATA
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
 Insurance Company
 Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number D-18088937MFSH
 Cover Note Number
 Driver
 Name of Driver CHONG NAM
 NRIC No S2598074C
 Date Of Birth 02/10/1961
 Occupation OUTDOOR
 Date Of Driving Pass 13/01/1983
 Driving Experience 35 YEARS AND 11 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-90308074
 Fax Number
 Contact Number
 Email Address ZHENG8074NAM@YAHOO.COM

Address 108 #07-26 ALJUNIED CRESCENT
 Postcode 380108
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 1
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GU4145X
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver GOVINDARAJAN VIMAL RAJU
 NRIC/Passport Number G6847610R
 Contact Number 94479837
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage FRT RHT
 No. Of Passenger (Including Driver)

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CITYCAB PTE LTD
CO. REG. NO. 199502839G

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 02 JAN 2019
@ 12:10 hrs

Reporting Centre Personnel's Signature
Name: Len Chan
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 1/1/2019 @ 10:50hrs. My taxi (A) was travelling along Joo Chuan Rd towards Koon Peng Road with no passenger on board.

I was travelling straight on the driveway, while travelling straight. Suddenly, veh (B) Gu 4145X came out from carpark lot, cut into my lane and hit onto my taxi (A) left portion. My taxi (A) whole left portion was damaged.

Veh (B) Gu 4145X was driven by Mr. Gouindarajan Vimal Raju. Fin no: 66847610 R. HP no: 9447 9837.

No injury in this accident.


DECLARATION

I/We declare the foregoing particulars are true in every respect.

CITYCAB PTE LTD
CO. REG. NO. 189502839G

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 02 JAN 2019

Reporting Centre Personnel's Signature
Name: 
NRIC/FIN No.:

LKK

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 324E

DATE : 2.01.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI SONATA

FAX : 6542 6039

ChinaTaiping

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bonnet Dented			\$ 2,265.90	✓
	Bonnet Hinge (LH/RH) 44		\$ 87.50	\$ 175.00	X
	Front Bumper Cover distorted			\$ 544.50	✓
	Front Bumper Sponge 44			\$ 136.30	X
	Front Bumper Reinforcement 44			\$ 504.10	X
	Front Bumper Bracket Top (LH) 44			\$ 22.40	X
	Front Bumper Protector (LH) cut			\$ 29.20	✓
	Front Bumper Bracket (LH) 44			\$ 24.60	X
	Headlamp Support Panel Assy Dented			\$ 1,023.00	✓
	Headlamp (LH) broken			\$ 1,388.00	✓
	Front Fender (LH) Bnc			\$ 593.00	✓
	Front Fender Shield (LH) deformed			\$ 174.90	✓
	Battery Tray 44			\$ 52.00	X
	Front Door (LH) Bnc			\$ 2,256.40	✓
	Front Door Gear / Regulator (LH) 2 1st			\$ 625.00	2 ✓
	Front Door Key Lock Set (LH) 44			\$ 186.50	X
	Front Door Outer Handle (LH) cut			\$ 37.00	✓
	Front Door Mirror (LH) repair			\$ 670.00	X
	Front Door Power Motor 44			\$ 425.00	X
	Front Door Protector (LH) broken			\$ 78.25	✓
	Door Centre Pillar Outer (LH) Dented			\$ 2,527.80	✓
	Rear Door (LH) Dented			\$ 2,201.10	✓
	Rear Door Protector (LH) 44			\$ 56.90	X
	Front Wheel Rim (LH) 2 distorted			\$ 325.30	2 ✓
	Front Wheel Hub Cap (LH) cut			\$ 145.00	2 ✓
	Front Wheel Bearing 2 Down			\$ 540.50	2 ✓
	Front Shock Absorber (Assy) (LH) 2 distorted			\$ 342.20	2 ✓
	Front Shock Absorber Mounting (LH) 44			\$ 108.80	X
	Front Shock Absorber Fork (LH) 2 distorted			\$ 203.30	2 ✓
	Front Suspension Upper Arm (LH) 2 distorted			\$ 240.00	2 ✓
	Front Drive Shaft (LH) 44 2 distorted			\$ 1,030.80	2 ✓
	Rack & Pinion Assy 44 Down			\$ 2,093.00	2 ✓
	STG Tie End 2 distorted			\$ 66.50	2 ✓
	Stabilizer Bar 2 distorted			\$ 252.30	2 ✓
	Stabilizer Bar Bush (LH) 44			\$ 16.40	X
	Stabilizer Bar Link 2 distorted			\$ 78.30	2 ✓
	Stabilizer Bracket 2 44			\$ 24.00	X
	Front Suspension Lower Arm (LH) 2 distorted			\$ 685.20	2 ✓
	Knuckle Arm (LH) 2 distorted			\$ 558.60	2 ✓
	Engine Under Cover 44			\$ 334.60	X
	Engine Crossmember 2 44 distorted			\$ 2,143.70	2 ✓
	ABS Sensor 44			\$ 250.50	X
	Wiring-Engine 44 housing broken			\$ 3,326.00	2 ✓
	Wiring-Front 2 housing broken			\$ 1,960.80	2 ✓
	Wiring-ECM 44 housing broken			\$ 3,243.00	2 ✓

SHC 324E

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	SUB TOTAL			\$ 33,965.65
	LESS 20%			\$ 6,793.13
	DISCOUNTED TOTAL			\$ 27,172.52
			30978.55 24782.84	
	Front Door City Cab Logo (LH) H/c			\$ 75.00 Net ✓
	Rear Door Tel No. Sticker (LH) H/c			\$ 10.00 Net ✓
	Front Tyre (LH) S/c			\$ 216.00 Net X
	New Battery L/H		85.00	\$ 207.00 Net X
				\$ 508.00
	Labour Charge			
	Panel Beating			\$ 1,800.00 900/-
	Spray Painting Charge			\$ 1,600.00 800/-
	Wiring Charge			\$ 100.00 30/-
	Tuff Kote			\$ 150.00 40/-
	Towing Charge			\$ 50.00 H/W
	Transfer of Door		\$ 120.00	\$ 240.00 120/-
	Remove/Refix Undercarriage (FRT)			\$ 200.00 150/-
	FRT Wheel Alignment			\$ 120.00 60/-
	Remove/Refix Aircon & Refill Gas		2300.00	\$ 150.00 H/W
	Remove/Refix Dashboard			\$ 450.00 150/-
	Remove/Refix Fuse Box			\$ 180.00 50/-
	TOTAL LABOUR			\$ 5,040.00
	ESTIMATE TOTAL			\$ 32,720.52
	07/01/2019 @ 1345h H/A Andrew 2/5mm g'ds. LKK Auto 		27167.84 R/S 14000/- Vehicle upr 14 months.	
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHC 324 E

Technician:

Mileage: 375641

Time Printed 7.1.19 2:02 PM

Hyundai 05- Sonata (NF)

Front : Left

Actual	BEFORE	Specified Range
1°58'		-0°30' 0°30'
3°11'		3°50' 5°50'
5°01'		-0°05' 0°05'
20°56'		
22°54'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
0°59'		-0°30' 0°30'
4°01'		3°50' 5°50'
0°03'		-0°05' 0°05'
18°37'		
19°36'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
0°59'		
-0°51'		
2°19'		
5°04'		-0°09' 0°09'

Rear : Left

Actual	BEFORE	Specified Range
-0°47'		-1°00' 0°00'
0°03'		0°00' 0°09'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
0°06'		-1°00' 0°00'
-0°04'		0°00' 0°09'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°53'		
-0°02'		0°00' 0°19'
0°03'		

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119000363/DQD3N2

Date: 18/04/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3062301801	
Claimant Vehicle No :	SHC324E	Insured Vehicle No :	GU4145X	
Date of Loss:	01/01/2019	Nature of Claim:	TP	Claim No: SNM19D200053C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC324E	Engine No:	D4EAC086292
Make & Model:	HYUNDAI SONATA, 2.0 (A)	Chassis No:	KMHET41VMCA824558
Reg. Date:	30/04/2012 (Man. Year: 2012)	Odometer:	375641 km
Colour:	Yellow		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	27,680.52	24,867.84	2,812.68	10.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,040.00	2,300.00	2,740.00	54.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,720.52	27,167.84	5,552.68	16.97
Approved Total (Overridden) (S\$)		14,000.00		
(S\$)	32,720.52	14,000.00	18,720.52	57.21
+ GST 7.00/7.00% (S\$)	2,290.44	980.00	1,310.44	57.21
Nett Amount (S\$)	35,010.96	14,980.00	20,030.96	57.21

INSPECTION

Date of Assignment:	11/04/2019	
Date Inspected:	07/01/2019 Inspected At:	Chunni Motor Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint Singapore 568047

Estimated Period of Repair: 13.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Apr 2019)
Parts: 143	HYUNDAI SONATA 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC324E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	2,265.90 FL	*2,265.90 FL
2	2		*BONNET HINGE (LH/RH)	Not Necessary	175.00 FL	*- FL
3	1		*FRONT BUMPER COVER	Distorted	544.50 FL	*544.50 FL
4	1		*FRONT BUMPER SPONGE	Not Necessary	136.30 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	504.10 FL	*- FL
6	1		*FRONT BUMPER BRACKET TOP (LH)	Not Necessary	22.40 FL	*- FL
7	1		*FRONT BUMPER PROTECTOR (LH)	Cut	29.20 FL	*29.20 FL
8	1		*FRONT BUMPER BRACKET (LH)	Not Necessary	24.60 FL	*- FL
9	1		*HEADLAMP SUPPORT PANEL ASSY	Dented	1,023.00 FL	*1,023.00 FL
10	1		*HEADLAMP (LH)	Broken	1,388.00 FL	*1,388.00 FL
11	1		*FRONT FENDER (LH)	Buckled	593.00 FL	*593.00 FL
12	1		*FRONT FENDER SHIELD (LH)	Deformed	174.90 FL	*174.90 FL
13	1		*BATTERY TRAY	Not Necessary	52.00 FL	*- FL
14	1		*FRONT DOOR (LH)	Buckled	2,256.40 FL	*2,256.40 FL
15	1		*FRONT DOOR GEAR/REGULATOR (LH)	Bent	625.00 FL	*625.00 FL
16	1		*FRONT DOOR KEY LOCK SET (LH)	Not Necessary	186.50 FL	*- FL
17	1		*FRONT DOOR OUTER HANDLE (LH)	Cut	37.00 FL	*37.00 FL
18	1		*FRONT DOOR MIRROR (LH)	Repair	670.00 FL	*- FL
19	1		*FRONT DOOR POWER MOTOR	Not Necessary	425.00 FL	*- FL
20	1		*FRONT DOOR PROTECTOR (LH)	Broken	78.25 FL	*78.25 FL
21	1		*DOOR CENTRE PILLAR OUTER (LH)	Dented	2,527.80 FL	*2,527.80 FL
22	1		*REAR DOOR (LH)	Dented	2,201.10 FL	*2,201.10 FL
23	1		*REAR DOOR PROTECTOR (LH)	Not Necessary	56.90 FL	*- FL
24	1		*FRONT WHEEL RIM (LH)	Distorted	325.30 FL	*325.30 FL
25	1		*FRONT WHEEL HUB CAP (LH)	Cut	145.00 FL	*145.00 FL
26	1		*FRONT WHEEL BEARING	Damaged	540.50 FL	*540.50 FL
27	1		*FRONT SHOCK ABSORBER (ASSY)(LH)	Distorted	342.20 FL	*342.20 FL
28	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	108.80 FL	*- FL
29	1		*FRONT SHOCK ABSORBER FORK (LH)	Distorted	203.30 FL	*203.30 FL
30	1		*FRONT SUSPENSION UPPER ARM (LH)	Distorted	240.00 FL	*240.00 FL
31	1		*FRONT DRIVE SHAFT (LH)	Distorted	1,030.80 FL	*1,030.80 FL
32	1		*RACK & PINION ASSY	Damaged	2,093.00 FL	*2,093.00 FL
33	1		*STG TIE END	Distorted	66.50 FL	*66.50 FL
34	1		*STABILIZER BAR	Distorted	252.30 FL	*252.30 FL
35	1		*STABILIZER BAR BUSH (LH)	Not Necessary	16.40 FL	*- FL
36	1		*STABILIZER BAR LINK	Distorted	78.30 FL	*78.30 FL
37	1		*STABILIZER BRACKET	Not Necessary	24.00 FL	*- FL
38	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	685.20 FL	*685.20 FL
39	1		*KNUCKLE ARM (LH)	Distorted	558.60 FL	*558.60 FL
40	1		*ENGINE UNDER COVER	Not Necessary	334.60 FL	*- FL
41	1		*ENGINE CROSSMEMBER	Distorted	2,143.70 FL	*2,143.70 FL
42	1		*ABS SENSOR	Not Necessary	250.50 FL	*- FL
43	1		*WIRING-ENGINE	Housing Broken	3,326.00 FL	*3,326.00 FL
44	1		*WIRING-FRONT	Broken	1,960.80 FL	*1,960.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*WIRING-ECM	Housing Broken	3,243.00 FL	*3,243.00 FL
46	1		*FRONT DOOR CITY CAB LOGO (LH)	Necessary	75.00 FS	*75.00 FS
47	1		*REAR DOOR TEL NO STICKER (LH)	Necessary	10.00 FS	*10.00 FS
48	1		*FRONT TYRE (LH)	Serviceable	216.00 FS	*- FS
49	1		*NEW BATTERY	Not Necessary	207.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	34,473.65	31,063.55
				- List Item Discount on L Items 20.00/20.00% (S\$)	6,793.13	6,195.71
				Total Parts (S\$)	27,680.52	24,867.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	900.00
2	SPRAY PAINTING CHARGE	New	1,600.00	800.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	150.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	TRANSFER OF DOOR	New	240.00	120.00
7	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	200.00	150.00
8	FRT WHEEL ALIGNMENT	New	120.00	60.00
9	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	0.00
10	REMOVE/REFIX DASHBOARD	New	450.00	150.00
11	REMOVE/REFIX FUSE BOX	New	180.00	50.00
Gross Labour Cost (S\$)			5,040.00	2,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >