

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/III19000370/BCD3E2

**Date:** 28/02/2019

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant Vehicle No :</b> SJF5181C	<b>Insured Vehicle No :</b>	SH8872E
Date of Loss: 22/12/2018	Nature of Claim:	TP Claim No: MCT18120643

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJF5181C</b>	Engine No:	2AZC366527
Make & Model:	TOYOTA 86, 2.0 (A)	Chassis No:	ACR500066441
Reg. Date:	30/05/2008 (Man. Year: 2008)	Odometer:	292869 km
Colour:	Black		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Pirelli 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	04/01/2019	Inspected At:	Blk 3006 UBI RD 1 #01-346
Date Inspected:	22/01/2019	Repairer :	JL AUTO SERVICE
Estimated Period of Repair:	0.0 days		

**Adjuster:** XING GUO QIANG

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG                      Version: 1.0 (Last Synchronised: 27 Feb 2019)

**Parts:**                      M1-COUPE                      TOYOTA 86 2.0 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:**                      Repairer's                      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJF5181C)

**Validity:**                      These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**