

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19000377/ABA3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994638

Claimant
Vehicle No : SJW7922D **Insured Vehicle No :** SJV4187J

Date of Loss: 21/12/2018 Nature of Claim: TP Claim No: 7107528828SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW7922D		
Make & Model:	NISSAN LATIO, 1.5 L (A)	Engine No:	HR15358555B
Reg. Date:	20/04/2010 (Man. Year: 2010)	Chassis No:	JN1BAAC11Z0025132
Colour:	Silver	Odometer:	100728 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,718.30	5,179.28	4,539.02	46.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,380.00	2,990.00	2,390.00	44.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,098.30	8,169.28	6,929.02	45.89
Approved Total (Overridden) (\$\$)		6,500.00		
Nett Amount (\$\$)	15,098.30	6,500.00	8,598.30	56.95
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 04/01/2019

Date Inspected: 04/01/2019 Inspected At:

TEK SOON MOTOR REPAIR &
SPRAY PAINTING (HQ)
1 KAKI BUKIT AVE 6, BLK D #01-93,,
AUTOBAY@KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
2	1		*FRONT NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
3	1		*FRONT BUMPER	Deformed	436.00 FL	*436.00 FL
4	1		*FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
5	2		*FRONT BUMPER SIDE HOLDER	Necessary	46.20 FL	*46.20 FL
6	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	186.20 FL	*- FL
7	2		*FRONT BUMPER FOG LAMP	Not Necessary	520.40 FL	*- FL
8	1		*FRONT BUMPER SPONGE	Cracked	207.20 FL	*207.20 FL
9	1		*FRONT BUMPER REINFORCEMENT	Bent	444.90 FL	*444.90 FL
10	2		*FRONT BUMPER REINFORCEMENT BRACKET	Not Necessary	504.40 FL	*- FL
11	1		*FRONT GRILLE	Cracked	273.60 FL	*273.60 FL
12	1		*FRONT GRILLE LOGO	Necessary	35.50 FL	*35.50 FL
13	2		*HEADLAMP	Cracked	599.20 FL	*599.20 FL
14	1		*REAR BUMPER	Deformed	551.00 FL	*551.00 FL
15	1		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
16	2		*REAR BUMPER SIDE HOLDER	Necessary	70.40 FL	*70.40 FL
17	1		*REAR BUMPER SPONGE	Cracked	35.60 FL	*35.60 FL
18	2		*REAR BUMPER IMPACT BRACKET	Not Necessary	183.40 FL	*- FL
19	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
20	1		*REAR END PANEL	Dented	442.60 FL	*442.60 FL
21	1		*REAR END PANEL TOP GARNISH	Deformed	80.40 FL	*80.40 FL
22	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
23	2		*TAILLAMP	Cracked	597.60 FL	*597.60 FL
24	2		*TAILLAMP PANEL	Repair	362.40 FL	*- FL
25	1		*BOOTLID	Buckled	764.60 FL	*764.60 FL
26	1		*BOOTLID LOCK	Damaged	97.90 FL	*97.90 FL
27	1		*BOOTLID LOCK SENSOR	Not Necessary	57.50 FL	*- FL
28	1		*BOOTLID WEATHERSTRIPE	Cut	59.90 FL	*59.90 FL
29	2		*BOOTLID HINGE	Not Necessary	102.20 FL	*- FL
30	1		*BOOTLID INNER TRIM BOARD	Not Necessary	199.80 FL	*- FL
31	1		*BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	30.00 FL	*- FL
32	1		*NISSAN LOGO	Necessary	35.20 FL	*35.20 FL
33	1		*LATI O EMBLEM	Necessary	66.40 FL	*66.40 FL
34	2		*REAR FENDER	Repair	2,105.40 FL	*- FL
35	1		*SPARE TYRE PANEL TOP COVER	Deformed	495.00 FL	*495.00 FL
36	1		*REAR WINDSCREEN MOULDING	Not Necessary	130.10 FL	*- FL
37	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
38	1		*REAR EXHAUST PIPE	Not Necessary	468.60 FL	*- FL
39	1		*REAR EXHAUST MOUNTING	Not Necessary	37.40 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,747.00	5,719.20
- List Item Discount on L Items 10.00/10.00% (\$)	1,028.70	539.92
Total Parts (\$)	9,718.30	5,179.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	2,400.00	1,300.00
2	SPRAY PAINTING	New	2,000.00	1,400.00
3	WIRING	New	100.00	60.00
4	TO UNDERSEAL	New	150.00	60.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE UPHOLSTERY	New	150.00	60.00
7	TO TRANSFER BOOTLID FITTINGS	New	150.00	60.00
8	TO REMOVE EXHAUST PIPE	New	150.00	0.00
9	TO REMOVE REAR WINDSCREEN	New	180.00	0.00
Gross Labour Cost (\$)			5,380.00	2,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >