

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

CANA

VEHICLE NO : SHB 6280M

DATE 7/1/2019 11:25

MAKE :

MODEL : HYUNDAI SONATA

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Qty	Parts Description/ Labour	Unit Price	Amount
	Boot Lid	bt	\$ 1,349.50
	Boot Lid Lock Upper	bt	\$ 132.10
	Boot Lid Lock Lower	bt	\$ 30.30
	Boot Lid Sonata Plate	ne	\$ 43.60
	Boot Lid Hyundai Plate	ne	\$ 24.20
	Boot Lid 'H' Emblem	ne	\$ 26.10
	Boot Lid CRDI Plate	ne	\$ 22.70
	Boot Lid Lamp (LH/RH)	\$ cur 230.20	\$ 460.40
	Boot Lid Trimboard	sd	\$ 165.40
	Boot Lid Trimboard Clips (10pcs)	ne	\$ 10.00
	Rear Bumper	dl	\$ 578.40
	Rear Bumper Reinforcement	photo ?	\$ 483.30
	Rear Bumper Clip	ne	\$ 22.00
	Rear Bumper Sponge	photo ?	\$ 137.40
	Rear Bumper Under Cover	dl	\$ 185.80
	Rear Bumper Protector (LH/RH)	\$ 38.00	\$ Rx 76.00
	Tail Lamp (LH/RH)	\$ cur 344.00	\$ 688.00
	Rear Panel	bt	\$ 391.80
	Rear Panel Garnish	dl	\$ 95.80
	SUB TOTAL		\$ 4,922.80
	LESS 20%		\$ 984.56
	DISCOUNTED TOTAL		\$ 3,938.24
	Boot Lid Comfort Logo & Tel No. Sticker	ne	\$ 30.00
	Boot Lid Advertisement Logo	ne	\$ 100.00
	Rear No. Plate	ne	\$ 25.00
	Rear Bumper Reverse Sensor	ne	\$ 135.70
	Rear Fender Advertisement Logo (LH/RH)	\$ ne 100.00	\$ 200.00
			\$ 490.70
	Labour Charge		
	Panel Beating	700	\$ 800.00
	Spray Painting Charge	800	\$ 900.00
	Wiring Charge	30	\$ 30.00
	Tuff Kote	30	\$ 80.00
	Remove/Refix Reverse Sensor		
	TOTAL LABOUR		\$ 1,860.00
	ESTIMATE TOTAL		\$ 6,288.94

Nett
 Nett
 Nett
 Nett
 Nett

Tanfikh 97495749
 'up'
 7/1/19 @ 1720
 Lumpsum
 Resurvey after repair
 tanfikh@lkkauto.com
 6 days

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.