

ASS. REC. BY:

REF:

CS/SMD190001156/U6072

Special Instruction:

Surveyor:

Maiman

ASSIGNMENT (Office)

From (Person):

Shawn Ngo

of

SMD

Date/Time:

08/01/2019 4:26pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 3522K

Insured:

SLD 9438Z

at Workshop m/s

Liu's Brother

Tel:

of

Blok 1 Kaki Bukit Ave 6 #01-01

Policy No:

D17MTRENT000064

Claim No:

CMTD1900108

Sum Insured:

Excess:

Make of Veh:

D.O.A.

31-12-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

09-01-2019

H.O.D. Endorsement:

Date/Time:

08/01/2019 4:32pm

Person Contacted:

Susan

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBF 3522K - X

SLD 9438Z - X

10/1/19 @ 12pm informed Shawn Ngo, we are pending estimate from repairer.
 16/1/19 @ 2pm advised to Shawn Ngo via Maiman.

Surrogate Marcus

REF: SMO

ASSIGNMENT

From: Date: 09/01/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: CBF 3522K
at Workshop n/s: Liu's Brother
of Blk 1, Kaki Bkt Ave 6 # 01-01

Insured

Policy No.

Claims No.

Sum Insured.

Excess:

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days Res: Yes or No

Lum Sum:

20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

27/1/19

7 yrs 9 m.

10/1/19

confirmed L/S & 4400 with Susan.
(Red to 490700, 53%)

RECEIVED 16 JAN 2019

Veh No: CBF 3522K Yr Regn: 9 16
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace DX cc 2.982

Colour: Blue A/C Insured / Std / NI / NA

Sp Reading: 64002 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KDH.2010194056

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

195-R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fronts

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

3/1/18

D.O.I.

9/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Prel. Report

1) 16/1/19

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

S + RS \$

Photos

Others

Report Format: MER-TP

Lump Sum / I.B.T. (\$

4400

TOTAL

250
10

260

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: NGO SAU WEI SHAWN

Date: 16 Jan 2019

Preliminary Advice

Insured Vehicle No	: SLD9438Z		
TP Vehicle No	: GBF3522K	Accident Date	: 31/12/2018
Make	: TOYOTA HIACE	Assignment Date	: 08/01/2019
Date of Inspection	: 09/01/2019	Est. Duration of Repair	: 5.00
Inspection At	: LIU'S BROTHER AUTO WORKSHOP (HQ) 1 KAKI BUKIT AVE 6 #01-01, AUTO BAY@KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,307.20
Revised Amount	:S\$	5,550.33
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,550.33
 Lump Sum Repair	 :S\$	 4,400.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Dec 2018		08 Jan 2019 16:26 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H		
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N		
Vehicle Reg. No.:	GBF3522K	Date of Loss:	31/12/2018 15:00 - :59
Claim Type:	TP / CMTD1900108	Policy/Cover Note No.:	D17MTRENT000064 (Third Party Only)
Vehicle Reg. No. (Insured):	SLD9438Z	Policy No. (Claimant):	
		Excess:	
Repairer:	LIU'S BROTHER AUTO WORKSHOP (HQ) 1 Kaki Bukit Ave 6 #01-01, Auto Bay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6741-1730/1731		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5202]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/01/2019]		
Driver/Custodian (Insured):	KAMARUZAMAN BIN HANAFI (), NRIC: S7235617I, Tel: +6597424451		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Thursday, 10 January 2019 12:00 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE GBF 3522K (YOUR REF: CMTD1900108)

This mail is associated with :
***GBF3522K (CMTD1900108)**
[SLD9438Z]
TP
GOLDBELL LEASING PTE LTD
Dec 31 2018 3:00PM
[ETHOZ GROUP LTD]
LIU'S BROTHER AUTO WORKSHOP

Dear Shawn,

Please be informed that we have inspected the vehicle GBF 3522K on 09/01/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Toyota Hiace High Roof Euro 5 Keyless.



Comes With Some Cosmetic Accessories And Extra Auto Step Board.

Direct Owner StarAd



Browse by Category ▼

Sort by Date Posted

20 vehicles

Hiace

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	Hiace		Any	Any	2016	Any	Any	
	Toyota	Hiace Commuter	\$83,000	\$10,570 /yr	14-Nov-2016	2,982 cc	128,645 km	
Fuel Type: Diesel Single Owner Used Fuel Stations Diesel, (Non Industrial), Accident Free Regular Service At 10,000km Set Of New Tyres. Comes With Some Cosmetic Accessories And Extra Auto Step Board. Posted: 09-Jan-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Toyota	Hiace	\$52,800	\$7,550 /yr	07-Jan-2016	2,982 cc	-	
Fuel Type: Diesel Vehicle Is In Good Condition. Feel Free To Contact For More Details Or Arrange For Viewing. Doorstep Viewing Can Be Arrange. ABWIN (1994) Pte Ltd Posted: 09-Jan-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Toyota	Hiace	\$60,800	\$8,400 /yr	06-Apr-2016	2,982 cc	-	
Fuel Type: Diesel In-house Loan Available. Call To View Now. Please Note, This Is Van.not Bus. Prime Motor & Leasing Posted: 08-Jan-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Toyota	Hiace	\$53,800	\$7,680 /yr	11-Jan-2016	2,982 cc	87,000 km	
Fuel Type: Diesel High Loan Available! Accident Free Unit, And Well Maintained Interior Too. All Working Mechanism Is Working As How It Should Be. Reli For Your Business Needs. Popular Van That Needs No Intr... Tan Wei Auto Pte Ltd Posted: 08-Jan-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Modellista	Front Grill						
Toyota Hiace Modellista Front Grill More info about this product								
Compare	ta Hiace		\$57,500	\$7,740 /yr	15-Jun-2016	2,982 cc	-	
	e: Diesel							

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 1196N

Vehicle Details

Vehicle No.: GBF3522K

Vehicle to be Exported: No

Intended Deregistration Date: 08 Jan 2019

Vehicle Make: TOYOTA

Vehicle Model: HIACE DX 3.0 MANUAL

Primary Colour: Blue

Manufacturing Year: 2016

Engine No.: 1KD2604361

Chassis No.: KDH2010194056

Maximum Power Output: -

Open Market Value: \$30,644.00

Original Registration Date: 16 Sep 2016

First Registration Date: 16 Sep 2016

Transfer Count: 1

Actual ARF Paid: \$1,533.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 15 Sep 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$22,731.00

COE Rebate Amount: \$17,471.00

Total Rebate Amount: \$17,471.00

The information contained herein is correct as at 08 Jan 2019

OK



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liusbros@gmail.com

Invoice/Ref No: GBF3522K181231

Estimate

Customer

Name: Sompo Insurance Singapore Private Limited

Address Motor Claims Department

50 Raffles Place #05-01 / 06

Singapore Land Tower

Singapore 048623

Date:

08-01-19

Vehicle No: GBF3522K

Model/Make: Toyota Hiace

DX 3.0 Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate		
2	Tailgate "Toyota Logo" Motif	\$ 2,051.60	
3	Tailgate Inner Lock	\$ 72.20	
4	Tailgate Lock Cover	\$ 359.00	
5	Tailgate Weatherstrip	\$ 137.60	
6	Tail Lamp 02 pcs (@ S\$365.60)	\$ 391.20	
7	Bumper	\$ 731.20	
8	Bumper Step Panel	\$ 428.10	
9	Bumper Lower Brackets 04 pcs (@ S\$45.50)	\$ 262.30	
10	Bumper Side Holders 02 pcs (@ S\$65.10)	\$ 182.00	
11	End Panel Outer	\$ 130.20	X
12	End Panel Top Steel Plate	\$ 566.10	
13	End Panel Inner	\$ 299.50	X
13	End Panel Sealant	\$ 936.20	X
14	Windscreen Sealant	\$ 50.00	SN
15	Windscreen Inner Seal	\$ 50.00	SN
16	Tailgate "70 KM/H" Sticker	\$ 50.00	SN 405.N
17	Tailgate "8 PAX" Sticker	\$ 20.00	SN 405.N
18	Tailgate "Corporate" Advertisement & Artwork	\$ 20.00	SN 105.N
19	Bumper Reverse Sensor 1 set	\$ 200.00	SN 105.N
20	Bumper Clips 1 set	\$ 250.00	SN 1005.N
		\$ 50.00	SN
	To check all wiring & electrical component for proper function	\$ 50.00	20
	Remove & reinstall Tailgate Glass to facilitate repairs	\$ 120.00	
	Remove and refix rear bumper reverse sensor	\$ 60.00	50
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	60
	Remove and replace rear exhaust pipe system to facilitate repairs	\$ 80.00	X 11
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc.	\$ 800.00	680
	To putty & spray painting & including touch up paint on accident affected	\$ 800.00	500
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 80.00	60

Total Parts & Labour of estimate for damaged vehicle

\$ 9,307.20

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

P-4747-1

25%

3560.32

S.N 500.00

labor 1490.00

5500.32

4440.28

not Authorized
LWH
9/1/19
L/S 4400/-
Whph. Atk. repair

Scary

Liu's Brother Auto Engineering Workshop hereby notify the Customer of the following:

- To receive balance after repair
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No financial and liability is allowed
- Supplementary parts must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19000456/UQBN2

Date: 17/01/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D17MTRENT000064
Claimant Vehicle No :	GBF3522K	Insured Vehicle No :	SLD9438Z
Date of Loss:	31/12/2018	Nature of Claim:	TP
		Claim No:	CMTD1900108

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF3522K	Engine No:	1KD2604361
Make & Model:	TOYOTA HIACE, 3.0 D DX (M)	Chassis No:	KDH2010194056
Reg. Date:	16/09/2016 (Man. Year: 2016)	Odometer:	64002 km
Colour:	Blue		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,237.20	4,060.32	3,176.88	43.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,070.00	1,490.00	580.00	28.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,307.20	5,550.32	3,756.88	40.37
Approved Total (Overridden) (S\$)		4,400.00		
Nett Amount (S\$)	9,307.20	4,400.00	4,907.20	52.72

INSPECTION

Date of Assignment:	08/01/2019	
Date Inspected:	09/01/2019 Inspected At:	LIU'S BROTHER AUTO WORKSHOP (HQ) 1 Kaki Bukit Ave 6 #01-01, Auto Bay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Jan 2019)
Parts: 213	TOYOTA HIACE 3.0 D DX (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBF3522K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	2,051.60 F	*2,051.60 FL
2	1		*REAR TAILGATE TOYOTA LOGO MOTIF	Necessary	72.20 F	*68.10 FL
3	1		*REAR TAILGATE INNER LOCK	Dented/Jammed	359.00 F	*359.00 FL
4	1		*REAR TAILGATE LOCK COVER	Cut	137.60 F	*137.60 FL
5	1		*REAR TAILGATE WEATHERSTRIP	Twisted	391.20 F	*391.20 FL
6	1		*REAR TAIL LAMP	N/s Cracked	731.20 F	*301.10 FL
7	1		*REAR BUMPER	Bent	428.10 F	*428.10 FL
8	1		*REAR BUMPER STEP PANEL	Bent	262.30 F	*262.30 FL
9	4		*REAR BUMPER LOWER BRACKETS	Bent	182.00 F	*182.00 FL
10	2		*REAR BUMPER SIDE HOLDERS	Not Necessary	130.20 F	*- FL
11	1		*REAR END PANEL OUTER	Badly Dented	566.10 F	*566.10 FL
12	1		*REAR END PANEL TOP STEEL PLATE	Not Necessary	299.50 F	*- FL
13	1		*REAR END PANEL INNER	Repair	936.20 F	*- FL
14	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
15	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
16	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
17	1		*REAR TAILGATE 70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
18	1		*REAR TAILGATE 8 PAX STICKER	Necessary	20.00 FS	*10.00 FS
19	1		*REAR TAILGATE CORPORATE ADVERTISEMENT & ARTWORK	Necessary	200.00 FS	*100.00 FS
20	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
21	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 7,237.20 5,247.10
 - List Item Discount on L Items 0.00/25.00% (S\$) 0.00 1,186.78

Total Parts (S\$) 7,237.20 4,060.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00
2	REMOVE & REINSTALL TAILGATE GLASS TO FACILITATE REPAIRS	New	120.00	120.00
3	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	60.00	50.00
4	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM	New	80.00	60.00
5	REMOVE AND REPLACE REAR EXHAUST PIPE SYSTEM TO FACILITATE REPAIRS	New	80.00	-
6	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS	New	800.00	680.00
7	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	800.00	500.00
8	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	60.00
Gross Labour Cost (\$\$)			2,070.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >