

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120**Our File No:** CC3/AIG19000538/AVBE2
Date: 02/05/2019REFERENCE**Insured/Claimant:** NG ING-YONG BRIAN (HUANG YINGRONG BRIAN)
Date of Loss: 22/12/2018**Policy No:**
Nature of Claim: OD **Claim No:** 2366897869SGDESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ1749M	Engine No:	CVK057562
Make & Model:	AUDI A4, 2.0 (A)	Chassis No:	WAUZZZF43JA137437
Reg. Date:	25/04/2018 (Man. Year: 2018)	Odometer:	10136 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$160,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,298.00	8,199.76	5,098.24	38.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,552.00	3,022.00	1,530.00	33.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,850.00	11,221.76	6,628.24	37.13
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	17,250.00	10,621.76	6,628.24	38.42
+ GST 7.00/7.00% (S\$)	1,207.50	743.52	463.98	38.42
Nett Amount (S\$)	18,457.50	11,365.28	7,092.22	38.42

INSPECTION

Date of Assignment:	09/01/2019		
Date Inspected:	09/01/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,999.00 FS	*1,599.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	258.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Necessary	32.00 FS	*25.44 FS
4	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	191.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE -RH	Deformed	56.00 FS	*44.40 FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE -RH	Not Necessary	123.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION -RH	Damaged	34.00 FS	*27.12 FS
8	1		*FRONT BUMPER FOAM FILLIER PIECE	Not Necessary	113.00 FS	*- FS
9	1		*FRONT BUMPER CARRIER	Not Necessary	733.00 FS	*- FS
10	1		*FRONT BUMPER SUPPORT-RH	Not Necessary	26.00 FS	*- FS
11	2		*FRONT SENSOR	Not Necessary	462.00 FS	*- FS
12	4		*FRONT SENSOR SEAL RING	Not Necessary	123.00 FS	*- FS
13	1		*FRONT FENDER -RH	Dented	700.00 FS	*559.60 FS
14	1		*FRONT FENDER ATTACHMENT PARTS-RH	Not Necessary	48.00 FS	*- FS
15	1		*FRONT FENDER CLOSING ELEMENT -RH	Necessary	45.00 FS	*36.00 FS
16	1		*FRONT FENDER BRACKET -RH	Not Necessary	32.00 FS	*- FS
17	1		*FRONT FENDER BRACE -RH	Bent	107.00 FS	*85.60 FS
18	1		*FRONT FENDER COVER-RH	Necessary	28.00 FS	*22.24 FS
19	1		*FRONT FENDER TOP COVER-RH	Necessary	21.00 FS	*16.16 FS
20	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	220.00 FS	*- FS
21	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-RH	Not Necessary	82.00 FS	*- FS
22	1		*FRONT WHEEL SPOILER-RH	Torn	66.00 FS	*52.32 FS
23	1		*FRONT FENDER LEDGE -RH	Not Necessary	33.00 FS	*- FS
24	1		*FRONT STONE CHIP GUARD-RH	Necessary	46.00 FS	*36.64 FS
25	1		*LED HEADLIGHT-RH	Cut	7,087.00 FS	*5,669.60 FS
26	1		*HEADLIGHT LIFT CYLINDER -RH	Not Necessary	120.00 FS	*- FS
27	4		*RUBBER VALVE	Not Necessary	13.00 FS	*- FS
28	1		*FRONT RIM -RH (NPA)	Not Necessary	0.00 FS	*- FS
29	1		*SUNDRIES	Necessary	500.00 FS	*25.44 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					13,298.00	8,199.76

LKK Auto Consultants Pte Ltd/SLZ1749M/02/05/2019 08:34

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,100.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	1,500.00	1,100.00
4	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,552.00	3,022.00

LKK Auto Consultants Pte Ltd/SLZ1749M/02/05/2019 08:34

< END OF ESTIMATES >