

ASS. REC. BY:

REF: es/FCI19000531/DSd3n2 Special Instruction:

Surveyor:

aus

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time:

11:40am @ 9/1/19

Estimated Cost:

Bill to:

OD (P) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 4065X

Insured:

SHC 0788A

at Workshop n/z:

Chunni Motor

Tel:

65425119

of

AMK Autopoint # 01-05 / 06

Policy No:

Claim No:

D19000247MF84

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/01/2019

CA / REV / REP. / REV 24 HRS

(up)

10/1/19

H.O.D. Endorsement:

Date/Time:

11:40am @ 9/1/19

Person Contacted:

Irene

Vehicle

IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SHD 4065X - X</u>
	<u>SHC 0788A - X</u>
<u>23/1/19</u>	<u>Email preti. revised to FCI</u>

REF:

CBE Feb 2020

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 8 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No


CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 4065 X Yt Regn: 2012 Feb
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Hyundai Sonata C.C. 1991
 Colour: Blue A/C Insured / Std / NI / NA
 Sp. Reading: 131791 T/Radio: Insured / Std / NI / NA
 Eng/No: D4EA9806395
 C/No: KMHET41VMCA821213
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16
 R: — 11 —



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake

Front Rear
 R/Bal. S mm R/Bal. S mm
 L/Bal. S mm L/Bal. S mm
 D.O.A. 04/01/2019 D.O.I. 10/01/2019
 Survey held at Chunni AMC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 O/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

First Capital SHC 788A

vehicle belongs about 13 months at time of accident.

12/02/19 Jharkhand 2/5 10,100/- with 10 days of repair
 (Red. 4327.04, 30%)

RECEIVED 14 FEB 2019

Date/Time, File Pass to?



Preli. Report

Days Of Repair: 10

1)



Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2) 14/2 - typist

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$) 10,000/-

Survey Fee:

Transportation

S + RS \$

Photos 057

Office 14/2/19

TOTAL

4x15= 60

170+60

50

50+50

106

486



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19000247MFSH

Our ref: CS/FCI19000539/Dsd3

Date: 23/1/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 4065X


We thank you for your instruction on 9/1/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 10/1/2019 at the premises of M/s CHUNNI MOTOR WORKS PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$14,327.04
Revised Estimate Amount	: S\$12,677.60
"Check" Items Amount	: S\$200.00
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s front portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Bryan Ang
Automotive Assessor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	08-01-2019	Our Ref No. D19000247MFSH
Accident Date	05-01-2019	Claim Type. Third Party
Insured Vehicle	SHC0788A	Third Party Vehicle. SHD4065X
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 65425119	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 23 January 2019 12:02 PM
To: 'CWS Motor Claims'
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000247MFSH/1, SHD 4065X
Attachments: SHD 4065X PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHD 4065X
Date of survey: 10/1/2019
Number of days : 8 days

Best Regards,

Veron Chen | Case Handler **on behalf of Shirley**

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 9 January 2019 11:54 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000247MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 9 January 2019 11:40 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000247MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHD 4065X

DATE : 7.01.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI SONATA

FAX : 6542 6039

FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bonnet is Dented			\$ 2,265.90	✓
	Front Bumper Cover distorted / mainly broken			\$ 544.50	✓
	Front Bumper Sponge NH			\$ 136.30	X
	Front Bumper Protector (RH) cut			\$ 29.20	✓
	Front Bumper Bracket (RH) NH			\$ 24.60	X
	Headlamp Support Panel Assy is deformed / distorted / broken			\$ 1,023.00	2-1
	Headlamp (RH) Scratched / cut			\$ 1,388.00	✓
	Front Fender (RH) Dented			\$ 593.00	✓
	Front Fender Shield (RH) deformed			\$ 174.90	✓
	Wiper Container is Cracks			\$ 61.90	X ✓
	Wiper Container Motor is Dam			\$ 75.00	X ✓
	Front Wheel Rim (RH) is			\$ 325.30	✓
	Front Wheel Bearing is Dam			\$ 540.50	2-1
	Front Shock Absorber (Assy) RH is distorted			\$ 342.20	2-1
	Front Shock Absorber Mounting (RH) NH			\$ 108.80	X
	Front Shock Absorber Fork (RH) is distorted			\$ 203.30	2-1
	Front Suspension Upper Arm (RH) is distorted			\$ 240.00	2-1
	Front Drive Shaft (RH) is Dam			\$ 1,030.80	2-1
	Rack & Pinion Assy is deformed			\$ 2,093.00	2-1
	STG Tie End is distorted			\$ 66.50	2-1
	Front Suspension Lower Arm (RH) is distorted			\$ 685.20	2-1
	Knuckle Arm (RH) is distorted			\$ 558.60	2-1
	Engine Under Cover NH			\$ 334.60	X
	Engine Crossmember is distorted			\$ 2,143.70	2-1
			14384.50		
			11507.60		
	SUB TOTAL			\$ 14,988.80	
	LESS 20%			\$ 2,997.76	
	DISCOUNTED TOTAL			\$ 11,991.04	
	Front Tyre (RH) Svc			\$ 216.00	Nett X
	Labour Charge				
	Panel Beating			\$ 1,000.00	600/-
	Spray Painting Charge			\$ 500.00	450/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 50.00	30/-
	Towing Charge			\$ 50.00	NH
	Remove/Refix Undercarriage (FRT)			\$ 200.00	150/-
	FRT Wheel Alignment			\$ 120.00	60/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00	NH
	10/01/2019 @ 1115hrs				
	with Antenna				
	2/15hrs 10 days.				
	TOTAL LABOUR			\$ 2,120.00	
	ESTIMATE TOTAL			\$ 14,327.04	
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by Page 1 of 1 Surveyor appointed by the insurance company.				

10/01/2019 @ 1115hrs
with Antenna
2/15hrs 10 days.

NAME
ADDRESS

Home Tel.:
VIN:
Registration: SHD 4065 X
Technician:
Mileage: 131791
Time Printed 10.1.19 1:06 PM

Hyundai : Sonata : 2005-

Front : Left

Actual	BEFORE	Specified Range
2°02'		-0°30' 0°30'
4°40'		3°50' 5°50'
0°01'		-0°05' 0°05'
18°56'		
20°59'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
1°31'		-0°30' 0°30'
4°24'		3°50' 5°50'
6°23'		-0°05' 0°05'
9°29'		
11°01'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
0°31'		
0°15'		
9°27'		
6°24'		-0°09' 0°09'

Rear : Left

Actual	BEFORE	Specified Range
-0°41'		-1°00' 0°00'
-0°04'		0°00' 0°09'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°38'		-1°00' 0°00'
0°15'		0°00' 0°09'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
0°57'		
0°11'		0°00' 0°19'
-0°09'		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19000539/Dsd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 15-02-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 788A	Veh. Inspected	SHD 4065X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000247MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	09/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI SONATA	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	KMHET41VMCA821213	Colour	BLUE	
Odometer	131791	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	WEST LAKE	5 mm	
L/H Front Tyre	215/60 R16	WEST LAKE	5 mm	
R/H Rear Tyre	215/60 R16	WEST LAKE	5 mm	
L/H Rear Tyre	215/60 R16	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/01/2019	Inspection Date	10/01/2019	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4065X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	BENT / DENTED	2,265.90	2,265.90
1	FRONT BUMPER COVER	DISTORTED / MOUNTING BROKEN	544.50	544.50
1	FRONT BUMPER SPONGE	NOT NECESSARY	136.30	-
1	FRONT BUMPER PROTECTOR (RH)	CUT	29.20	29.20
1	FRONT BUMPER BRACKET (RH)	NOT NECESSARY	24.60	-
1	HEADLAMP SUPPORT PANEL ASSY	DEFORMED / DISTORTED / BROKEN	1,023.00	1,023.00
1	HEADLAMP (RH)	SCRATCHED / CUT	1,388.00	1,388.00
1	FRONT FENDER (RH)	DENTED	593.00	593.00
1	FRONT FENDER SHIELD (RH)	DEFORMED	174.90	174.90
1	WIPER CONTAINER	CRACKED	61.90	61.90
1	WIPER CONTAINER MOTOR	DAMAGED	75.00	75.00
1	FRONT WHEEL RIM (RH)	BENT	325.30	325.30
1	FRONT WHEEL BEARING	DAMAGED	540.50	540.50
1	FRONT SHOCK ABSORBER (ASSY)(RH)	DISTORTED	342.20	342.20
1	FRONT SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	108.80	-
1	FRONT SHOCK ABSORBER FORK (RH)	DISTORTED	203.30	203.30
1	FRONT SUSPENSION UPPER ARM (RH)	DISTORTED	240.00	240.00
1	FRONT DRIVE SHAFT (RH)	DAMAGED	1,030.80	1,030.80
1	RACK & PINION ASSY	DAMAGED	2,093.00	2,093.00
1	STG TIE END	DISTORTED	66.50	66.50
1	FRONT SUSPENSION LOWER ARM (RH)	DISTORTED	685.20	685.20
1	KNUCKLE ARM (RH)	DISTORTED	558.60	558.60
1	ENGINE UNDER COVER	NOT NECESSARY	334.60	-
1	ENGINE CROSSMEMBER	DISTORTED	2,143.70	2,143.70
	LESS 20% DISCOUNT		-2,997.76	-2,876.90
			11,991.04	11,507.60
SPECIAL NETT ITEMS				
1	FRONT TYRE (RH)(SN)	SERVICEABLE	216.00	-

Report Ref No. CS/FCI19000539/Dsd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
			216.00	-
	LABOUR			
	PANEL BEATING.		1,000.00	600.00
	SPRAY PAINTING CHARGE.		500.00	450.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		50.00	30.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX UNDERCARRIAGE (FRT).		200.00	150.00
	FRT WHEEL ALIGNMENT.		120.00	60.00
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	150.00	-
			2,120.00	1,320.00
	GRAND TOTAL		14,327.04	12,827.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,000.00

Report Ref No. CS/FCI19000539/Dsd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.