6			Etill to	Date/Tu	9/11/08/11-2101
OD (IP) W	STTP RESTOD RE	ES / EVA / INV / M	V7CS	11	
	ehicle No:			Insured: SL	7 8131E
at Workshop	m/s	Chunni Mo.	tor	Tel: 6	5425119
of	BIK 10	AMK Ind. Purl	CDA #03-1	9	
Policy No:_	2906976	56	Claim No:		9
Sum Insured			Excess:		1
and a second					
Make of Vel (Client's Reco				D.O.A.	01/01/2019
(Client's Recor	/ REP. / REV 24 F	IRS (W)		rollo	019
(Client's Recor	(d)	IRS (47) Person Contacte	ed: Irene	(oli)a	
(Client's Recor	(d) REP. REV 24 F 11-31 am@ 9/1/19	Person Contact		(oli)a	ol9 Endorsement:
(Client's Recon	/ REP. / REV 24 F	Person Contact	ate	Vehicl I	Endorsement
(Client's Recon	Action/Instruction	Person Contacte () Estima D-CCA / III 6	ate	Vehicl I	ol9 Endorsement
(Client's Recon	Action/Instruction SHA26441 SLT 81316	Person Contacte () Estima D-CC4 / III 6	ate	Vehicle 1	Endorsement

Weekend (\$

310

Lump Sum / I.P 1: 15

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHA 2644D

MAKE :

DATE : 8.01.2019

TEL : 6542 5119

MODEL : HYUNDAI i40 FAX : 6542 6039 MSIG

MODEL	: HYUNDAI i40	10.0	: 6542		_	MŞIG	Í
Qty	Parts Description/ Labour	Type	Ur	it Price	_	Amount	
	Bonnet bro			4	S	2,265.90	
	Bonnet Hinge (LH/RH) \$4		S	41.00	S	82.00	
	Bonnet Lock 14			***	S	36.90	
	Bonnet Absorber 4-4		\$	58.10	\$	116.20	7.00
	Bonnet Insulator → →				\$	196.50	×
	Bonnet Insulator Clips NH				S	8.40	X
	Radiator Grille brike				S	1,110.10	_
	Radiator Grille H Emblem Hu				S	39.50	
	Front Bumper Cover				S	1,052.20	
	Front Bumper Sponge down				S	99.20	
	Front Bumper Reinforcement Dath				S	402.10	_
	Front Bumper Grille (LH/RH) C		S	93.60	\$	187.20	—
	Front Bumper Grille Airduct (LH/RH)		S	26.20	S	52.40	×
	Front Bumper Lip الما				S	54.90	×
	Front Bumper Bracket Top (LH/RH)	HH	S	22.40	S	44.80	×
	Front Bumper Bracket (LH/RH) 0 S booken HIS HA		S	(24.60)	\$	49.20	سلسا
	Headlamp Support Top Cover end broken			$\overline{}$	\$	222.60	
	Headlamp Support Panel Assy broken Dandon				S	907.40	_
	Headlamp (LH/RH) broken distribut		S	1,388.00	S	2,776.00	_
	Radiator Pundwal 14+				\$	698.30	- photo
Ø	Radiator Fan Blade, Cowling, Motor Assy & broken				\$	792,95	RL
	Radiator Bracket (RH/LH) >14		S	6.50	\$	13.00	×
	Radiator Hose Upper 2 MJ				5	36.50	2×
	Radiator Hose Lower > ~~				\$	36.50	XX
	Radiator Expansion Tank & CARK wornting				S	28.30	×-
	Radiator Guard Some		S	20.00	\$	40.00	1
	Horn Unit (LH/RH) of s broken M/s 2 LIN		S	73.80	\$	147.60	RLL
	Horn Wire Nu			\sim	\$	156.50	1
	Front Fender (LH/RH) 0 3 3 NC MISA NIL		S	(566.30)	\$	1,132.60	
	Front Fender Apron Panel (LH/RH) 0/5 5- 1/5	12.4.1		637.00	1	1,274.00	1 5
	Front Fender Shield (LH/RH) torn distaly	1 120121	S	174.90	1	349.80	
	Air Cleaner Assy tooku monity		1		\$	118.60	Tours of the second
	Air Duct				\$	134.60	1
	Aircon Condenser Prnd 1 194		120	121.45	\$	927.50	1
	Aircon Suction & Liquid Hose > Ur		97	12110	5	624.00	RU
	Aircon Discharge Hose ≥ K†				\$	162.60	7-
	Aircon Compressor de distrit				S	2,578.00	XU
	Front Pillar Upper Cover/Garnish		S	83.50		167.00	
	Front Windscreen Glass CNLAC			(ಎಡೆಚಿಕೆ)	S	1,017.80	
	Front Windscreen Moulding - Le		1		\$	113.30	
	Front Windscreen Pillar Outer(LH/RH) Reveal		s	1,745.50	S		
	Wiper Panel Top Garnish Cat boku			100	\$	3,491.00 222.60	
	Wiper Container by Ku				\$	61.90	
	Wiper Container Motor D-w				S	75.00	-
			1			, 5.00	

SHA 2644D

					A 2644D	
Qty	Parts Description/ Labour	Type	Unit Price	A	mount	
	Front Wheel Rim (RH) Z Al Sto And			S	325.30	2 _
	Front Wheel Hub Cap (RH) 15th cut			S	107.10	
	Front Wheel Bearing 2 2			\$	540.50	2:-
	Front Shock Absorber (Assy) (RH) 2 disturbed			\$	342.20	DI
	Front Shock Absorber Mounting (RH)			S	108.80	×
	Front Drive Shaft (RH) & Dom			S	1,030.80	
	Rack & Pinion Assy Z D.			S	969.60	2 L
	STG Tie End 2 distrated			\$	62.60	
	Stabilizer Bar Austratu			\$	252.30	
	Stabilizer Bar Bush (RH) -IH			S	16.40	X
	Stabilizer Bar Link Australia			\$	61.10	4-
	Stabilizer Bracket HA			\$	24.00	×
	Front Suspension Lower Arm (RH) A 184 .			S	529.30	4-
	Front Chasis Member Dedo A 013			\$	1,060.70	_
	Knuckle Arm (RH) ≥ distwt>		5	\$	552.00	2 -
	Timing Cover Assy ⋈н			\$	535.80	×
	Timing Tensioner Assy & distuted			S	260.80	2-
	Fan Belt 7 toru 50% deprivation		SH 58.10	S	146.20	2,-
	Engine Mounting 2. Dom		J	\$	456.30	2-
	Engine Under Cover 2. broke		\	S	334.60	2 ,
	Engine Crossmember Z. dishaha			S	2,094.40	2 -
	Engine Mtg (Rear) by Drug			\$	279.60	
	Engine Support Bracket Assy			\$	546.60	X
	Gearbox - Li			S	14,808.00	×
	Gearbox Mounting 7 7			S	215.40	Z.L
	Starter Motor Assy of disturbed Dan			S	790.60	*-
	Inter Cooler 25 154			S	1,032.50	
	Inter Cooler Mounting (2 PCS) Ha			S	25.90	
	Hose B To Inter Cooler NA			S	229.70	
	Hose C To Inter Cooler Inlet HILL			S	294.50	X
	Pipe To Inter Cooler HA			S	167,05	1000
	Pipe To Inter Cooler Outlet + + + 1 deformed		1712695	S	244.55	AL
	ABS Sensor, RH WH			S	234.00	×
	Wiring-ECM Had booker monty comments			5	3,243.00	93
	Wiring-FEM, RH MA			S	168.00	1.00
	Actuator - Swirl Control & boke		1	S	814.60	
	Auto Gear Oil Has heaking fother Had			S	110.40	
	Engine Top Cover by Ku			S	386.00	
	Throule Body Assy his			S	1,096.60	100
	Intake Manifold Assy			S	1,141.10	
	Electric Power Steering			S	4,880.50	
	Zitting Like		20548.40	1.5		_
	SUB TOTAL		39548.40	S	64,592.85	1
	LESS 20%		. 112	S	12,918.57	
	DISCOUNTED TOTAL		31638.10	S	51,674.28	1
						1

SHA 2644D

					SE	IA 2044D	
Qty	Parts Description/ Labour	Type		Unit Price	1	Amount	
	Front Number Plate broken distaged		Г		\$	25.00	Nett _
	Front No Plate Trim Cover Data				S	30.00	Nett _
	Front Fender Advertisement Logo (LH/RH)		S	100.00	S	200.00	Nett -
	Front Door Comfort Logo (RH) المرا				S	75.00	Nett -
	Front Windscreen Sealant H.				S	46.00	Nett -
1	Front ERP Sticker her				S	26.00	Nett -
1	Front Tyre (RH) SVC			7	S	216.00	Nett X
				402.00			
				58.10	S	618.00	
				10			
				460.10			
	Labour Charge			25			
	Panel Beating				\$	2,400.00	14001-
	Spray Painting Charge				S	1,750.00	10001-
	Wiring Charge				\$	100.00	30 -
	Tuff Kote				S	150.00	401-
	Towing Charge				S	50.00	HT
	Front Chassis Alignment Charge				S	400.00	150/-
	Remove/Refix Undercarriage (FRT)				S	200.00	7 150
	FRT Wheel Alignment				S	120.00	601-
	Remove/Refix Aircon & Refill Gas				S	150.00	801-
	Remove/Refix Engine/Gearbox				\$	650:00°	100 C.P
	Remove/Refix Dashboard			355°°-00	\$	450.00	1801-
1	Remove/Refix Fuse Box			2200	\$	180.00	MM
	Remove/Refix Front Windscreen Glass		1		S	120.00	801-
	Remove/Refix Cushion & Upholstery Front				S	90.00	MH
	Re-set Frt ABS System				\$	200.00	31801-
	Diagnostic & Resetting To Erase Fault Code				\$	480.00	7,801-
	TOTAL LABOUR		١,	<i>((111)</i> • •	\$	7,490.00	
			1	5648.82]
	ESTIMATE TOTAL	gapp		740.08	\$	59,782.28	
	10/01/2019 0 11115		3	6388.90			
	11451						
	10/01/2019 C 1145h		L	1290001			
	4 Sny Hodge	LKK Au	o C	onsultants hence	otify		
	2	the Rep	aire	r of the following:			
	Man			before/after spray pain			
				amaged part(s) during are subject to confirma		oy .	
	LKK Ando	Third pa	rty:	survey is on a "Without	Prejud	dice" basis	
				odification(s) is allowed lary item(s) must be res		ed and	
	7 mae 3V	is subje	ct to	final approval from Ins	urano	e Company	
		Acknowle	dae	d by Repairer		- 1	
		Signature					J
	· 1	Date:					l
							1
	This is an initial estimate based on a visual inspection of the						
	be prepared after the vehicle is surveyed by a motor Survey	yor appoint	ed	by the insurance c	omp	any.	J
						d - m	

60577.36

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHA 2644D (Supplementary)

DATE : 22.01.2019

MAKE

TEL: 6542 5119

ODEL	: HYUNDAI i40	FAX	: 6542 6039	
Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Oil Sump broken			\$ 435.60
	Engine Oil 6 Litres when I head			\$ 300.00
	Fan Idle Pulley bokn			\$ 189.50
	LATIOT WILL		915.10	\$ 925.10
	SUB TOTAL LESS 20%		120	\$ 925.10 \$ 185.02
	DISCOUNTED TOTAL		95.10	\$ 740.08
	DISCOUNTED TOTAL			3 740.00
	22/01/2019 @ 16com		MI	
	2)01/219 @ 1600m MA Admy 1/5mm			
	2/5mm			
	Man			
	yan)			
	1)-1 / 1-	1		
	2 kk Anto			
		{	1	
		1	3	
	This is an initial estimate based on a visual inspection of the	he above ve	hicle. The final repa	ir quantum will

NAME ADDRESS

Home Tel.:

VIN:

Registration: SHC 2644 D

Technician: Mileage:

Time Printed 10.1.19 1:00 PM

HYUNDAI 140

Front: Left

Actual	BEFORE	Specified Range
1°27'		-3°00' 3°00'
4°37'		-0°19' 5°41'
0°08'		-1°30' 1°30'
18°47'		
20°14'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Actual	BEFORE	Specified Range
3°56'		-3°00' 3°00'
4°26'		-0°19' 5°41'
5°38'		-1°30' 1°30'
7°36'		400000000000000000000000000000000000000
11°32'		

Front : Right

Front

Cross Camber Cross Caster Cross SAI Total Toe Cross Turn Diff.

Actual	BEFORE	Specified Range
-2°29'		-3°00' 3°00'
0°11'		-3°00' 3°00'
11°11'		-3°00' 3°00'
5°47'		-3°00' 3°00'

Rear: Left

Actual BEFORE Specified Range
-1°11' -3°30' 2°30'
-0°01' -1°30' 1°30'

Camber Toe

Actual	BEFORE	Specified Range
-1°05'		-3°30' 2°30'
0°14'		-1°30' 1°30'

Rear: Right

Rear

Cross Camber Total Toe Thrust Angle

	rtour							
Actual	BEFORE	Specified Range						
-0°06'		-3°00' 3°00'						
0°12'		-3°00' 3°00'						
-0°08'		-3°00' 3°00'						

...CLAIM SUBFOLDER...(New Assignment)

		CKING							
	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adic	ubmitted	1.		
Main	08 Jan 2019		09 Jan 2019		[80]	FURTHING	Ins Auth'ed	Status	
Main	2013		11:21 Assign					New Assig	
1	1ain	Re	eference		laim Detail:	,)(Docume	ents	Show Al
CLAIM SU	BFOLDER DE	TAILS							_ SHOW AI
Insured:	GRAB REN	TALS PTE LTD,	Co. Reg. No : 20	116172000		[Create	d by insurer]		
Main Claimant:	COMFORT	TRANSPORTATI	ON PTE LTD,	Co. Reg. No.	: 199303821	R			
Vehicle Reg. No.:	SHA2644				Date of Los	. 01/01/20	19 14:00 - :59	Townson Co.	
Claim Type:	TP / 5809	129			Policy/Cove	29069768	(Comprehensiv	From LTA Reg Da	te (Man Yr)]
Vehicle Reg. No. (Insured):	SLT8131E				Note No.: Policy No. (Claimant):	Coverage	: 01/02/2018 - :	31/01/2019	
No. of the last of	Chunni Mot	to- Wt Di					00		
Repairer:	7162	tor Work Pte Ltd	(HQ) Blk 10 An	g Mo Kio Ind	ustrial Park 2	A, #03-19 A	MK Autopoint, 5	68047 Ang Mo K	Cio - Toly 654
landling	MSTG TROUG	rance (Singapor	e) Pte. Ltd. (HQ)) - Tel: +65	6827 7888	flanded b		OUGH AND NO	10 - Tel: 654
nsurer:	11510 Ilisui				0027 7000	. Inangled b	y NG CHEN HO	W - 6643 1391]	
djuster:	LKK Auto C	onsultants Pte I	td (HO) - Tole 6	356 3564	r				
Adjuster: Driver/Custo		consultants Pte I	ta (HQ) - Tel: 6	256-3561	[Imm.Adv +659828268		0/01/2019]		
djuster: Priver/Custo lan (Insured): dj Asg.	CHNG KOK S	SEONG (63 / Male), NRIC: S1172	256-3561 425F, Tel:	[Imm.Adv +659828268	2		dly contact MS L	
djuster: Priver/Custo lan Insured): dj Asg, emarks:	CHNG KOK S	SEONG (63 / Male NCERTAIN Worksh 42 5119 or 6542), NRIC: S1172	256-3561 425F, Tel:	[Imm.Adv +659828268	2		dly contact MS L	
djuster: Priver/Custo Jan (Insured): dj Asg. emarks: SSOCIATE	CHNG KOK S LIABILITY UN IRENE @ 654	SEONG (63 / Male NCERTAIN Worksh 42 5119 or 6542 7), NRIC: S1172	256-3561 425F, Tel:	[Imm.Adv +659828268	2	UTOPOINT . Kin		
here are no	CHNG KOK S LIABILITY UN IRENE @ 654	SEONG (63 / Male NCERTAIN Worksh 42 5119 or 6542 7 EIVED ise.), NRIC: S1172	256-3561 425F, Tel:	[Imm.Adv +659828268	2	UTOPOINT . Kin		YNN OR MS
Adjuster: Driver/Custo dian Insured): Adj Asg. demarks: ASSOCIATE	CHNG KOK S LIABILITY UN IRENE @ 654 D MAIL RECE mail for this ca	SEONG (63 / Male NCERTAIN Worksh 42 5119 or 6542 7 EIVED ise.	op location : SOC	256-3561 2425F, Tel: DN HOCK MO or survey .	[Imm.Ad v +659828268 TOR @ #01-I	2 05/06 AMK A	UTOPOINT . Kin		YNN OR MS pose Case Ma

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co,Reg,No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn:

NG CHEN HOW

Date:

24 Jan 2019

Preliminary Advice

Insured Vehicle No : SLT8131E

TP Vehicle No

: SHA2644D

Accident Date

: 01/01/2019

Make

: HYUNDAI 140

Assignment Date

: 09/01/2019

Date of Inspection

: 10/01/2019

Est. Duration of Repair

: 16.00

Inspection At

: CHUNNI MOTOR WORK PTE LTD (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #03-19 AMK AUTOPOINT

SINGAPORE 568047

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	59,782.38
Revised Amount	:S\$	36,165.22
Check Items (Estimated)	:S\$	0.00
Total	:S\$	36,165.22

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	·S\$

Remarks

() The vehicle	e is	economical/no	t economical	for	repair.
---	---------------	------	---------------	--------------	-----	---------

(X) The above survey was conducted on a 'without prejudice' basis.

MCD619000796-01 / ComfortDolOro Engineering Pto Ltd - Loyang ENTRY DATE & TIME; 02/01/2019 07:17 SUBMITTED BY: Catherine Par May Juan

Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 08/01/2019 11:57

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy fiability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- G. This report will be forwarded by the insurers of the GIA Records Management Centre established by the Ceneral Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	03/01/2019 07:17
Date Of Accident	01/01/2019 14:00
Exact Location Of Accident	BOON TAT STREET X JUNCTION OF CECIL STREET.
Country/State of Loss	SINGAPORE

	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHA2644D	

Insured/Policyholder

Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD

Co Reg No 199303821R

Email Address FLEETSAFETY@CDGTAXI.COM.SG

Mobile Phone No

Alternative Phone No OFFICE-65508768

Vehicle Particulars

Manufacturer HYUNDAI

Model 140

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD

Type Of Coverage THIRD PARTY FIRE AND/OR THEFT

Fleet Policy YES

Policy Number MCOM0015

Cover Note Number

Driver

Name of Driver CHUA THIAM POH

 NRIC No
 \$0330447G

 Date Of Birth
 07/06/1950

 Occupation
 OUTDOOR

 Date Of Driving Pass
 20/02/1980

Driving Experience 38 YEARS AND 10 MONTHS

Gender MALE

Mobile Number +65-96202338

Fax Number Contact Number

EMail Address NOEMAIL

Address

112A 08-121 DEPOT ROAD

Postcode

101112

Was driver an employee of the insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CROSS JUNCTION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vahicles (including own vehicle)

involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by ambulance?

YES

Was any other material or property damaged?

YES

I have been approached by unknown person(s) sollciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Polico Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

SEE POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLT8131E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

LEFT CENTRE

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

CHUA THIAM POH

; -

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

69

GIDDY, CHEST

SHA2644D

YES

NO

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesald.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Jackson Heng

COMFORT TRANSPORTATION PTE LIL Policyholder's Signature. 199303821R Driver's Signature

Date & Time:

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No .:

GIARMC ShetchPlanForm_V3

1





1 of 3

Report No. T/20190102/2054

Police Station Of Origin: Pasir Ris N.P.C 1 Pasir Ris Drive 4 #01-01 SINGAPORE 519457

Tel No: 1800-5852999

REPORT OF A TRAFFIC ACCIDENT

Date/Time 02/01/201		fade:	Vide Report No.: A/20190101/0186	Station Diary No.: 57
Informan	t's Partici	ulars	DECEMBER OF THE SAME	The state of the s
Name of I CHUA TH			Address: APT BLK 112A DEPOT	ROAD #08-121 SINGAPORE 101112
ID Type / NRIC NO		47G	Contact No.: Home/Office:	Mobile: 96202338
Nationality SINGAPO	THE PARTY OF THE P	EN	Email:	
Sex: Male	Age: 68	Date of Birth: 07/06/1950	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation COMFOR		O TAXI DRIVER	Driving Licence Informati Class:	tion: Date of Expiry:

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 01/01/2019 14:00	Type X-Jun	of Location:
Location: Along Road 1 BOON TAT S CECIL STREI CROSS JUNG		ND CECIL STREET			
Weather: Clear		Road Surface: Dry		Road Spee	d Limit:
Traffic Flow:		Traffic Control:		Traffic Volu Light	me:
Type of Collis Between Mov	ion: ing Vehicles - Head On			Anyone cor ambulance: Yes	

Vehicle No.	Type	Make	Model	Color:	Condition	No of Passenger
SHA2644D	COMFROT DELGRO TAXI				Seriously Damaged	0
SLT8131E	Car					0



Police Station Of Origin: 1 Pasir Ris Drive 4 #01-01 SINGAPORE

2 of 3 Report No. T/20190102/2054

Pasir Ris N.P.C 519457 Tel No: 1800-5852999

CONTINUATION OF REPORT

Brief Details.

On the 1st January 2019 at about 2.01pm, I was driving along Boon Tat Street towards Robinson Road. As the traffic light was green and there was not much traffic, my taxi was driving straight.

Suddenly a vehicle was driving along Cecil Street and came out from my right side.

I tried to brake my vehicle however both our vehicles could not brake in time thus the opposite vehicle front portion collided onto my taxi front portion.

My taxi then swerved and stopped after the collision.

After the accident, I was still semi-conscious and I could only remember there I was conveyed to hospital.

I have a video recording device installed inside my vehicle aiming at the front direction.

I would wish to state that my vehicle was driving straight as the traffic light was green.





Police Station Of Origin: Pasir Ris N.P.C 1 Pasir Ris Drive 4 #01-01 SINGAPORE 519457 Tel No: 1800-5852999

3 of 3 Ж Report No. Т/20190102/2054

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Red G /	ording The Report:	Signature Of Informant:	
Sr Staff Sgt CHUA WAN	GLONG	ph	Ŋ.
Signature Of Interpreter: Not applicable		Date/Time: 02/01/2019 13:18	
Officer In Charge Of Cas	SE SINGAPORE POLICE FORCE	Classification Of Case:	
Contact No.:	POLICE PORCE	1/2	
Authentication Stamp NP168	SIGNAT	LYRE	

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRA	CKING									
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Submit	ted	Ins Auth'ed		Status	
Main	08 Jan 2019		09 Jan 2019 11:21 Edit Adj Rpt	S\$29,000 Edit Estin	Second III	S\$29,000. View Rpt	00]			Pending for Survey Report Cancel Case	
	Main	R	eference	CI	aim Deta	ils		Docume	ents	\supset	Show All
CLAIM SU	BFOLDER DE	TAILS			The Lines	[Crea	ted by	insurer]		and the latest test	
Insured:	GRAB RE	NTALS PTE LTD,	Co. Reg. No.: 2016	517200G			•				
Main Claimant:	COMFORT	TRANSPORTAT	ION PTE LTD, Co	. Reg. No.:	19930382	1R					
Vehicle Reg No.:	SHA264	4D			Date of L			4:00 - :59 nd 3 Days F	rom LT	A Reg Date	(Man Yr)]
Claim Type:	TP / 580	TP / 580929						(Comprehensive) : 01/02/2018 - 31/01/2019			
Vehicle Reg No. (Insured):		SLT8131E				t):	5				
					Excess:	S\$2,0	00.00				
Repairer:	Chunni M 7162	otor Work Pte L	td (HQ) Blk 10 Ang	Mo Kio Indu	strial Pari	k 2A, #03-1	9 AMK	Autopoint, 5	68047	Ang Mo Kio	Tel: 6542
Handling Insurer:	MSIG Ins	urance (Singapo	ore) Pte. Ltd. (HQ)	- Tel: +65 6	827 788	8 [Handle	ed by N	G CHEN HO	W - 66	43 1391]	
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561	Handled	by BRYAN	TANI]	[Final F	Ppt du	e 08/02/2	019]
Driver/Cust dian (Insured):		SEONG (63 / Ma	le), NRIC: S11724	25F, Tel:	+659828	2682					
Adj Asg. Remarks:			shop location : SOO 2 7162 to arrange fo		TOR @ #0	01-05/06 AN	MK AUT	OPOINT , Kir	ndly con	tact MS LYN	IN OR MS
ASSOCIAT	TED MAIL RE	CEIVED							View Al	Compo	se Case Ma
There are n	o mail for this	case.									
ALL ASSO	CIATED TAS	ks⊡				View All	Sea	arch Tasks	Creat	e New Task	Complet
Due Date	e Priority	Type Task	Group Subjec	t Handle	er As	signed By		ompleted (Created C	

Claim Documents

*SHA2644D (580929)

[SLT8131E]

TP

COMFORT TRANSPORTATION PTE LTD

Jan 1 2019 2:00PM

[GRAB RENTALS PTE LTD]

Chunni Motor Work Pte Ltd

Ass	essment Reports		1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbna	ail Prin
1	09/01/19 09:08	Accident Statement From:SC - Reg. No: SLT8131E, Claimant: GRAB RENTALS PTE LTD	1 Load HT	ч
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	ail Prin
1	24/01/19 16:48	Adjuster Immediate Advice	1 Load HT	4
Pho	otos/Images		3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	ail Prin
1	16/02/19 14:22	Front View Right	Load JPC	V
2	16/02/19 14:22	Front View Left	1 Load JPC	i 🗸
3	16/02/19 14:22	Front View	1 Load JPC	· 🗸
4	16/02/19 14:24	General View	1 Load JPC	· 🗸
5	16/02/19 14:24	General View	1 Load JPC	V
6	16/02/19 14:24	General View	1 Load JPC	· 🗸
7	16/02/19 14:24	General View	1 Load JPC	
8	16/02/19 14:24	General View	1 Load JPC	5 V
9	16/02/19 14:24	General View	1 Load JPC	· •
10	16/02/19 14:24	General View	1 Load JPC	· •
11	16/02/19 14:24	General View	■ Load JPC	
12	16/02/19 14:24	General View	1 Load JPC	
13	16/02/19 14:24	General View	1 Load JPC	· 🗸
14	16/02/19 14:24	General View	1 Load JPC	· •
15	16/02/19 14:24	General View	1 Load JPG	
16	16/02/19 14:24	General View	1 Load JPC	· •
17	16/02/19 14:24	General View	1 Load JPC	-
18	16/02/19 14:24	General View	■ Load JPC	· 7
19	16/02/19 14:24	General View	■ Load JPC	· •
20	16/02/19 14:24	General View	1 Load JPC	
21	16/02/19 14:24	General View	1 Load JPC	-
22	16/02/19 14:24	General View	1 Load JPC	-
23	16/02/19 14:24	General View	1 Load JPC	
24	16/02/19 14:24	General View	1 Load JPC	
25	16/02/19 14:24	General View	1 Load JPC	
26	16/02/19 14:24	General View	1 Load JPC	
27	16/02/19 14:24	General View	1 Load JPC	
28	16/02/19 14:24	General View	1 Load JPC	person
29	16/02/19 14:24	General View	1 Load JPC	
30	16/02/19 14:24	General View	1 Load JPC	
-	16/02/19 14:24	General View	1 Load JPC	-

Ass	essment Reports			
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbna	
82		S. S. WAR		<u> </u>
33	16/02/19 14:24	General View	1 Load JPC	-
34	16/02/19 14:24	General View	1 Load JPC	
35	16/02/19 14:24	General View	Load JPC	-
36	16/02/19 14:24	General View	1 Load JPC	_
37	16/02/19 14:24	General View	① Load JPC	-
38	16/02/19 14:24	General View	1 Load JPC	-
39	16/02/19 14:24	General View	1 Load JPC	-
40	16/02/19 14:24	General View	1 Load JPC	
11	16/02/19 14:24	General View	1 Load JPC	_
42	16/02/19 14:24	General View	1 Load JPC	
43	16/02/19 14:24	General View	1 Load JPC	_
14	16/02/19 14:24	General View	1 Load JPC	- Head
45	16/02/19 14:24	General View	1 Load JPC	3 V
46	16/02/19 14:24	General View	1 Load JPG	-
47	16/02/19 14:24	General View	1 Load JPG	_
48	16/02/19 14:24	General View	1 Load JPC	3 🗸
19	16/02/19 14:24	General View	1 Load JPC	3 V
50	16/02/19 14:24	General View	1 Load JPC	3 🗸
51	16/02/19 14:24	General View	■ Load JPC	3 Z
52	16/02/19 14:24	General View	■ Load JPG	3 4
53	16/02/19 14:24	General View	Load JPG	G 🗸
54	16/02/19 14:24	General View	1 Load JPG	3 V
55	16/02/19 14:24	General View	■ Load JPC	G 🗸
56	16/02/19 14:24	General View	■ Load JPG	3 4
57	16/02/19 14:24	General View	■ Load JPG	3 V
58	16/02/19 14:24	General View	1 Load JPG	3 •
59	16/02/19 14:24	General View	■ Load JPG	3 V
50	16/02/19 14:24	General View	1 Load JPG	3 2
51	16/02/19 14:24	General View	1 Load JPG	3 V
52	16/02/19 14:24	General View	1 Load JPG	3 •
63	16/02/19 14:24	General View	1 Load JPG	3 2
64	16/02/19 14:24	General View	1 Load JPG	3 4
65	16/02/19 14:24	General View	1 Load JPG	3 •
66	16/02/19 14:24	General View	1 Load JPG	3 V
57	16/02/19 14:24	General View	1 Load JPG	G 🗸
58	16/02/19 14:24	General View	1 Load JPG	5 V
59	16/02/19 14:24	General View	1 Load JPG	3 🗸
70	16/02/19 14:24	General View	1 Load JPG	3 •
7.1	16/02/19 14:24	General View	1 Load JPC	3 V
72	16/02/19 14:24	General View	1 Load JPG	G 🗸
73	16/02/19 14:24	General View	1 Load JPG	3 V
74	16/02/19 14:24	General View	1 Load JPC	
75	16/02/19 14:24	General View	1 Load JP	-
76	16/02/19 14:24	General View	1 Load JPG	-
77	16/02/19 14:24	General View	1 Load JP	
78	16/02/19 14:24	General View	1 Load JPG	-
79	16/02/19 14:24	General View	1 Load JPG	
80	16/02/19 14:24	General View	1 Load JP	-
81	16/02/19 14:24	General View	1 Load JPG	

Ass	essment Reports		1 per page 🔻	▼
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail Load JPG	
82	16/02/19 14:24	General View		V
83	16/02/19 14:24	General View	1 Load JPG	<u>~</u>
84	16/02/19 14:24	General View	1 Load JPG	✓
85	16/02/19 14:24	General View	1 Load JPG	✓
86	16/02/19 14:24	General View	1 Load JPG	V
87	16/02/19 14:24	General View	Load JPG	✓
88	16/02/19 14:24	General View	1 Load JPG	V
89	16/02/19 14:24	General View	1 Load JPG	V
90	16/02/19 14:24	General View	1 Load JPG	V
91	16/02/19 14:24	General View	1 Load JPG	V
92	16/02/19 14:24	General View	1 Load JPG	V
93	16/02/19 14:24	General View	1 Load JPG	V
94	16/02/19 14:24	General View	Load JPG	V
95	16/02/19 14:24	General View	■ Load JPG	V
96	16/02/19 14:24	General View	1 Load JPG	V
97	16/02/19 14:24	General View	■ Load JPG	₹
98		General View	■ Load JPG	V
98	16/02/19 14:24	General View	1 Load JPG	₹
	16/02/19 14:24	GII PROG		
100	16/02/19 14:24	General View	Load JPG	V
101	16/02/19 14:24	General View	Load JPG	V
102	16/02/19 14:24	Chassis Number	1 Load JPG	V
103	16/02/19 14:25	Reinspection Photo	1 Load JPG	V
104	16/02/19 14:25	Reinspection Photo	1 Load JPG	~
105	16/02/19 14:25	Reinspection Photo	1 Load JPG	V
106	16/02/19 14:25	Reinspection Photo	1 Load JPG	✓
107	16/02/19 14:26	Reinspection Photo	1 Load JPG	✓
108	16/02/19 14:26	Reinspection Photo	1 Load JPG	₹
109	16/02/19 14:26	Reinspection Photo	■ Load JPG	✓
110	16/02/19 14:26	Reinspection Photo	■ Load JPG	V
111	16/02/19 14:26	Reinspection Photo	■ Load JPG	✓
112	16/02/19 14:26	Reinspection Photo	■ Load JPG	Y
113	16/02/19 14:26	Reinspection Photo	■ Load JPG	~
114	16/02/19 14:26	Reinspection Photo	1 Load JPG	V
115	16/02/19 14:26	Reinspection Photo	■ Load JPG	V
116	16/02/19 14:26	Reinspection Photo	■ Load JPG	~
117	16/02/19 14:26	Reinspection Photo	■ Load JPG	-
118	Venezum of da	Reinspection Photo	Load JPG	V
119	16/02/19 14:26	Reinspection Photo	1 Load JPG	V
120	16/02/19 14:26	Reinspection Photo	1 Load JPG	V
121	16/02/19 14:26	Reinspection Photo	■ Load JPG	V
	NY ANY CANADA AND ANY CONTROL	Reinspection Photo	■ Load JPG	+=
122	16/02/19 14:26	STOR 426 (989 M	1 Load JPG	▼
123		Reinspection Photo	1 Load JPG	1 =
124		Reinspection Photo		_
125	16/02/19 14:26	Reinspection Photo	Load JPG	_
126	16/02/19 14:26	Reinspection Photo	Load JPG	V
127	16/02/19 14:26	Reinspection Photo	Load JPG	_
128	16/02/19 14:26	Reinspection Photo	1 Load JPG	+=
129	16/02/19 14:26	Reinspection Photo	1 Load JPG	V
130	16/02/19 14:26	Reinspection Photo	1 Load JPG	_
131	16/02/19 14:26	Reinspection Photo	1 Load JPG	V

ASSE	essment Reports			
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbna Load IPC	
132	16/02/19 14:26	Reinspection Photo	1 Load JPC	14
133	16/02/19 14:26	Reinspection Photo	1 Load JPC	_
134	16/02/19 14:26	Reinspection Photo	1 Load JPC	-
35	16/02/19 14:27	Reinspection Photo	1 Load JPC	_
36	16/02/19 14:27	Reinspection Photo	1 Load JPC	_
137	16/02/19 14:27	Reinspection Photo	1 Load JPC	_
138	16/02/19 14:27	Reinspection Photo	1 Load JPC	3 4
139	16/02/19 14:27	Reinspection Photo	1 Load JPC	3 V
140	16/02/19 14:27	Reinspection Photo	1 Load JPC	5 😾
141	16/02/19 14:27	Reinspection Photo	1 Load JPC	3 2
142	16/02/19 14:27	Reinspection Photo	1 Load JPC	5 🗸
143	16/02/19 14:27	Reinspection Photo	1 Load JPC	3 🗸
144	16/02/19 14:27	Reinspection Photo	1 Load JPC	5 2
145	16/02/19 14:27	Reinspection Photo	1 Load JPG	3 👿
146	16/02/19 14:27	Reinspection Photo	1 Load JPC	3 2
147	16/02/19 14:27	Reinspection Photo	1 Load JPC	5 •
148	16/02/19 14:27	Reinspection Photo	1 Load JPG	3 2
149	16/02/19 14:27	Reinspection Photo	1 Load JPC	3 🗸
150	16/02/19 14:27	Reinspection Photo	■ Load JPG	_
151	16/02/19 14:27	Reinspection Photo	■ Load JPG	3 2
152	16/02/19 14:27	Reinspection Photo	■ Load JPG	-
153	16/02/19 14:27	Reinspection Photo	■ Load JPG	
154	16/02/19 14:27	Reinspection Photo	1 Load JPG	-
155	16/02/19 14:27	Reinspection Photo	1 Load JPG	
	CONTROL CONTROL OF THE CONTROL OF TH		1 Load JPC	
156	16/02/19 14:27	Reinspection Photo	1 Load JPC	
157	16/02/19 14:27	Reinspection Photo	1 Load JPC	
158	16/02/19 14:27	Reinspection Photo	D Load JPC	-
159	16/02/19 14:27	Reinspection Photo	1 Load JPC	-
160	16/02/19 14:27	Reinspection Photo		-
161	16/02/19 14:27	Reinspection Photo	Load JPC	_
162	16/02/19 14:27	Reinspection Photo	1 Load JPC	_
163	16/02/19 14:27	Reinspection Photo	1 Load JPC	-
164	16/02/19 14:27	Reinspection Photo	1 Load JPC	_
165	16/02/19 14:27	Reinspection Photo	1 Load JPG	
166	16/02/19 14:27	Reinspection Photo	1 Load JPC	_
167	16/02/19 14:27	Reinspection Photo	1 Load JP6	_
168	16/02/19 14:27	Reinspection Photo	1 Load JPC	
169	16/02/19 14:27	Reinspection Photo	1 Load JPG	_
170	16/02/19 14:27	Reinspection Photo	1 Load JPC	-
171	16/02/19 14:27	Reinspection Photo	1 Load JPC	3 🔽
172	16/02/19 14:27	Reinspection Photo	■ Load JP6	3 5
173	16/02/19 14:27	Reinspection Photo	1 Load JPC	3
174	16/02/19 14:27	Reinspection Photo	1 Load JPC	3 👿
175	16/02/19 14:27	Reinspection Photo	1 Load JPG	3 🖳
176	16/02/19 14:27	Reinspection Photo	1 Load JPG	3 5
177	16/02/19 14:27	Reinspection Photo	1 Load JP6	3 5
178	16/02/19 14:27	Reinspection Photo	1 Load JPG	3 -
179	16/02/19 14:27	Reinspection Photo	1 Load JPG	3 🖳
180	16/02/19 14:27	Reinspection Photo	1 Load JPG	3 E
181	16/02/19 14:27	Reinspection Photo	€ Load JP	3 👿

Assessment Report	S	1 per page 🗸	\checkmark
No Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Prin
182 16/02/19 14:27	Reinspection Photo	1 Load JPG	✓
183 16/02/19 14:27	Reinspection Photo	1 Load JPG	<u>~</u>
184 16/02/19 14:27	Reinspection Photo	1 Load JPG	✓
185 16/02/19 14:27	Reinspection Photo	1 Load JPG	✓
186 16/02/19 14:27	Reinspection Photo	1 Load JPG	V
187 16/02/19 14:27	Reinspection Photo	1 Load JPG	V
188 16/02/19 14:27	Reinspection Photo	1 Load JPG	4
189 16/02/19 14:27	Reinspection Photo	1 Load JPG	✓
190 16/02/19 14:27	Reinspection Photo	1 Load JPG	4
191 16/02/19 14:27	Reinspection Photo	1 Load JPG	~
192 16/02/19 14:27	Reinspection Photo	1 Load JPG	V
193 16/02/19 14:27	Reinspection Photo	1 Load JPG	V
194 16/02/19 14:27	Reinspection Photo	1 Load JPG	V
195 16/02/19 14:27	Reinspection Photo	■ Load JPG	V
196 16/02/19 14:27	Reinspection Photo	Load JPG	V
197 16/02/19 14:27	Reinspection Photo	Load JPG	~
198 16/02/19 14:27	Reinspection Photo	Load JPG	V
199 16/02/19 14:27	Reinspection Photo	1 Load JPG	√
	Reinspection Photo	1 Load JPG	∀
200 16/02/19 14:27		Load JPG Load JPG	▼
201 16/02/19 14:27	Reinspection Photo		
202 16/02/19 14:27	Reinspection Photo	Load JPG	4
203 16/02/19 14:27	Reinspection Photo	1 Load JPG	∀
204 16/02/19 14:27	Reinspection Photo	1 Load JPG	✓
205 16/02/19 14:27	Reinspection Photo	1 Load JPG	✓
206 16/02/19 14:27	Reinspection Photo	1 Load JPG	✓
207 16/02/19 14:27	Reinspection Photo	1 Load JPG	4
208 16/02/19 14:27	Reinspection Photo	1 Load JPG	~
209 16/02/19 14:27	Reinspection Photo	1 Load JPG	V
210 16/02/19 14:27	Reinspection Photo	1 Load JPG	V
211 16/02/19 14:27	Reinspection Photo	■ Load JPG	V
212 16/02/19 14:27	Reinspection Photo	■ Load JPG	V
213 16/02/19 14:27	Reinspection Photo	Load JPG	~
214 16/02/19 14:27	Reinspection Photo	1 Load JPG	V
215 16/02/19 14:27	Reinspection Photo	1 Load JPG	V
216 16/02/19 14:27	Reinspection Photo	■ Load JPG	~
217 16/02/19 14:27	Reinspection Photo	■ Load JPG	V
218 16/02/19 14:27	Reinspection Photo	Load JPG	~
219 16/02/19 14:27	Reinspection Photo	■ Load JPG	V
220 16/02/19 14:27	Reinspection Photo	■ Load JPG	V
221 16/02/19 14:27	Reinspection Photo	1 Load JPG	✓
		1 Load JPG	V
222 16/02/19 14:27	Reinspection Photo		V
223 16/02/19 14:27	Reinspection Photo	Load JPG	
224 16/02/19 14:27	Reinspection Photo	Load JPG	∀
225 16/02/19 14:27	Reinspection Photo	1 Load JPG	Y
226 16/02/19 14:27	Reinspection Photo	1 Load JPG	V
227 16/02/19 14:27	Reinspection Photo	1 Load JPG	V
228 16/02/19 14:27	Reinspection Photo	1 Load JPG	~
229 16/02/19 14:27	Reinspection Photo	1 Load JPG	4
230 16/02/19 14:27	Reinspection Photo	1 Load JPG	✓
231 16/02/19 14:27	Reinspection Photo	1 Load JPG	¥

Assessment Reports		1 per pag	e 🗸	✓
No Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		humbnail	_
232 16/02/19 14:27	Reinspection Photo	0	Load JPG	✓
233 16/02/19 14:27	Reinspection Photo	0	Load JPG	~
234 16/02/19 14:27	Reinspection Photo	0	Load JPG	V
235 16/02/19 14:27	Reinspection Photo	0	Load JPG	~
236 16/02/19 14:27	Reinspection Photo	0	Load JPG	V
237 16/02/19 14:27	Reinspection Photo	0	Load JPG	~
238 16/02/19 14:27	Reinspection Photo	0	Load JPG	V
239 16/02/19 14:27	Reinspection Photo	0	Load JPG	V
240 16/02/19 14:27	Reinspection Photo	0	Load JPG	V
241 16/02/19 14:27	Reinspection Photo	0	Load JPG	V
242 16/02/19 14:27	Reinspection Photo		Load JPG	V
243 16/02/19 14:27	Reinspection Photo		Load JPG	V
244 16/02/19 14:27	Reinspection Photo		Load JPG	V
245 16/02/19 14:27	Reinspection Photo		Load JPG	V
246 16/02/19 14:27	Reinspection Photo		Load JPG	V
			Load JPG	V
247 16/02/19 14:27	Reinspection Photo		Load JPG	V
248 16/02/19 14:27	Reinspection Photo			-
249 16/02/19 14:27	Reinspection Photo		Load JPG	<u>~</u>
250 16/02/19 14:27	Reinspection Photo		Load JPG	V
251 16/02/19 14:27	Reinspection Photo		Load JPG	V
252 16/02/19 14:27	Reinspection Photo		Load JPG	<u>~</u>
253 16/02/19 14:27	Reinspection Photo		Load JPG	✓
254 16/02/19 14:27	Reinspection Photo		Load JPG	✓
255 16/02/19 14:27	Reinspection Photo	0	Load JPG	V
256 16/02/19 14:27	Reinspection Photo	0	Load JPG	~
257 16/02/19 14:27	Reinspection Photo	0	Load JPG	V
258 16/02/19 14:27	Reinspection Photo	0	Load JPG	V
259 16/02/19 14:27	Reinspection Photo	0	Load JPG	~
260 16/02/19 14:27	Reinspection Photo	0	Load JPG	V
261 16/02/19 14:27	Reinspection Photo	0	Load JPG	~
262 16/02/19 14:27	Reinspection Photo	0	Load JPG	V
263 16/02/19 14:27	Reinspection Photo	0	Load JPG	V
264 16/02/19 14:27	Reinspection Photo	0	Load JPG	V
265 16/02/19 14:27	Reinspection Photo	0	Load JPG	V
266 16/02/19 14:27	Reinspection Photo	0	Load JPG	~
267 16/02/19 14:27	Reinspection Photo	0	Load JPG	V
268 16/02/19 14:27	Reinspection Photo	0	Load JPG	~
269 16/02/19 14:27	Reinspection Photo		Load JPG	V
270 16/02/19 14:27	Reinspection Photo		Load JPG	V
271 16/02/19 14:27	Reinspection Photo	-	Load JPG	V
272 16/02/19 14:27	Reinspection Photo		Load JPG	V
273 16/02/19 14:27	Reinspection Photo		Load JPG	₹
	Reinspection Photo		Load JPG	₹ V
	To an order of the control of the co		Load JPG	₹
275 16/02/19 14:27	Reinspection Photo		Load JPG	<u>A</u>
276 16/02/19 14:27	Reinspection Photo			₹
277 16/02/19 14:27	Reinspection Photo		Load JPG	
278 16/02/19 14:27	Reinspection Photo		Load JPG	✓
279 16/02/19 14:27	Reinspection Photo		Load JPG	V
280 16/02/19 14:27	Reinspection Photo		Load JPG	V
281 16/02/19 14:27	Reinspection Photo	0	Load JPG	V

Assessment Reports		1 per p		✓
No Finalized On 282 16/02/19 14:27	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Reinspection Photo	0	Thumbnail Load JPG	Prin
		0		
283 16/02/19 14:27	Reinspection Photo		Load JPG	V
284 16/02/19 14:27	Reinspection Photo	0	Load JPG	V
285 16/02/19 14:27	Reinspection Photo	0	Load JPG	V
286 16/02/19 14:27	Reinspection Photo	0	Load JPG	Y
287 16/02/19 14:28	Finishing Photo	0	Load JPG	V
288 16/02/19 14:28	Finishing Photo	0	Load JPG	V
289 16/02/19 14:28	Finishing Photo	0	Load JPG	V
290 16/02/19 14:28	Finishing Photo	0	Load JPG	V
291 16/02/19 14:28	Finishing Photo	0	Load JPG	V
292 16/02/19 14:28	Finishing Photo	0	Load JPG	~
293 16/02/19 14:28	Finishing Photo	0	Load JPG	V
294 16/02/19 14:28	Finishing Photo	0	Load JPG	V
295 16/02/19 14:28	Finishing Photo	0	Load JPG	V
296 16/02/19 14:28	Finishing Photo	0	Load JPG	V
297 16/02/19 14:28	Finishing Photo	0	Load JPG	V
298 16/02/19 14:28	Finishing Photo	0	Load JPG	V
299 16/02/19 14:28	Finishing Photo	0	Load JPG	V
300 16/02/19 14:28	Finishing Photo	0	Load JPG	V
	British Sec. 1917	0	Load JPG	▼
301 16/02/19 14:28	Finishing Photo	0		V
302 16/02/19 14:28	Finishing Photo		Load JPG	_
303 16/02/19 14:28	Finishing Photo	0	Load JPG	~
304 16/02/19 14:28	Finishing Photo	0	Load JPG	~
305 16/02/19 14:28	Finishing Photo	0	Load JPG	¥
306 16/02/19 14:28	Finishing Photo	0	Load JPG	✓
307 16/02/19 14:28	Finishing Photo	0	Load JPG	4
308 16/02/19 14:28	Finishing Photo	0	Load JPG	V
309 16/02/19 14:28	Finishing Photo	0	Load JPG	~
310 16/02/19 14:28	Finishing Photo	0	Load JPG	~
311 16/02/19 14:28	Finishing Photo	0	Load JPG	~
312 16/02/19 14:28	Finishing Photo	0	Load JPG	~
313 16/02/19 14:28	Finishing Photo	0	Load JPG	~
314 16/02/19 14:28	Finishing Photo	0	Load JPG	V
315 16/02/19 14:28	Finishing Photo	0	Load JPG	~
316 16/02/19 14:28	Finishing Photo	0	Load JPG	V
317 16/02/19 14:28	Finishing Photo	0	Load JPG	V
318 16/02/19 14:28	Finishing Photo	0	Load JPG	~
319 16/02/19 14:28	Finishing Photo	0	Load JPG	V
320 16/02/19 14:28	Finishing Photo	0	Load JPG	V
321 16/02/19 14:28	Finishing Photo	0	Load JPG	~
322 16/02/19 14:28	Finishing Photo	0	Load JPG	V
		0	Load JPG	V
323 16/02/19 14:28	Finishing Photo	0	V 1000000000000000000000000000000000000	∀
324 16/02/19 14:28	Finishing Photo		Load JPG	_
325 16/02/19 14:28	Finishing Photo	0	Load JPG	~
326 16/02/19 14:28	Finishing Photo	0	Load JPG	×
327 16/02/19 14:28	Finishing Photo	0	Load JPG	V
328 16/02/19 14:28	Finishing Photo	0	Load JPG	~
329 16/02/19 14:28	Finishing Photo	0	Load JPG	¥
330 16/02/19 14:28	Finishing Photo	0	Load JPG	~
331 16/02/19 14:28	Finishing Photo	O	Load JPG	4

Ass	essment Reports		1 per p	age 🗸	~
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
332	16/02/19 14:28	Finishing Photo	Ð	Load JPG	V
333	16/02/19 14:28	Finishing Photo	0	Load JPG	√
334	16/02/19 14:28	Finishing Photo	0	Load JPG	✓
335	16/02/19 14:28	Finishing Photo	0	Load JPG	V
336	16/02/19 14:28	Finishing Photo	0	Load JPG	V
337	16/02/19 14:28	Finishing Photo	0	Load JPG	✓
338	16/02/19 14:28	Finishing Photo	0	Load JPG	✓
Doc	umentation		1 per p	page 🔻	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	09/01/19 09:08	TPD SHA2644D GIA REPORT From:SC - Reg. No: SLT8131E, Claimant: GRAB RENTALS PTE LTD	0	Load PDF	
2	09/01/19 09:08	TPD SHA2644D - ESTIMATE REPAIR	0	Load PDF	
3	09/01/19 11:00	Reply email from TP Workshop & appoint In-house	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/02/19 10:47	Supplementary	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG19000542/DQD3E2

Date:

19/02/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

29069766

Claimant Vehicle

Date of Loss:

SHA2644D

Insured Vehicle No:

SLT8131E

01/01/2019

Nature of Claim:

TP

Claim No: 580929

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHA2644D

Make & Model:

HYUNDAI 140, 1.7 D CRDI F/L ABS AIRBAG 4DR

Engine No:

D4FDGU672458

Reg. Date:

(A) 29/09/2016 (Man. Year: 2016)

Chassis No: Odometer:

KMHLB41UMGU093612

Colour:

Blue

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES Front Tyre Size:

205/60 R16

Yes Engine Modification:

205/60 R16

Front Left Side:

Campeon 5 mm

Rear Tyre Size: Rear Left Side:

Campeon 5 mm

0 km

Front Right Side:

Campeon 5 mm

Rear Right Side:

Campeon 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	53,032.36	32,838.90	20,193.46	38.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,490.00	3,550.00	3,940.00	52.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	60,522.36	36,388.90	24,133.46	39.88
Approved Total (Overridden) (S\$)		29,000.00		
(S\$)	60,522.36	29,000.00	31,522.36	52.08
+ GST 7.00/7.00% (S\$)	4,236.57	2,030.00	2,206.57	52.08
Nett Amount (S\$)	64,758.93	31,030.00	33,728.93	52.08

INSPECTION

Date of Assignment:

09/01/2019

Date Inspected:

10/01/2019 Inspected At:

Chunni Motor Work Pte Ltd (HQ)

Blk 10 Ang Mo Kio Industrial Park 2A, #03-

19 AMK Autopoint Singapore 568047

Estimated Period of Repair:

23.0 days

Adjuster: BRYAN TANI Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen		Version: 1.0 (Last Synchronised: 19 Feb 2019)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted	d, no print-code for SHA2644D)
Validity:		ates are valid only if they contain the print code (above) on all estimate pages, running page in the END OF ESTIMATES marker on the last estimate page
Further Info	Items/values	not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	2,265.90 FL	*2,265.90 FL
2	2		*BONNET HINGE (LH/RH)	Bent	82.00 FL	*82.00 FL
3	1		*BONNET LOCK	Bent	36.90 FL	*36.90 FL
4	2		*BONNET ABSORBER	Not Necessary	116.20 FL	*-FL
5	1		*BONNET INSULATOR	Not Necessary	196.50 FL	*-FL
6	1		*BONNET INSULATOR CLIPS	Not Necessary	8.40 FL	*-FL
7	1		*RADIATOR GRILLE	Broken	1,110.10 FL	*1,110.10 FL
8	1		*RADIATOR GRILLE H EMBLEM	Necessary	39.50 FL	*39.50 FL
9	1		*FRONT BUMPER COVER	Torn	1,052.20 FL	*1,052.20 FL
10	1		*FRONT BUMPER SPONGE	Torn	99.20 FL	*99.20 FL
11	1		*FRONT BUMPER REINFORCEMENT	Dented	402.10 FL	*402.10 FL
12	2		*FRONT BUMPER GRILLE (LH/RH)	Cut	187.20 FL	*187.20 FL
13	2		*FRONT BUMPER GRILLE AIRDUCT (LH/RH)	Not Necessary	52.40 FL	*-FL
14	1		*FRONT BUMPER LIP	Not Necessary	54.90 FL	*-FL
15	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	44.80 FL	*-FL
16	1		*FRONT BUMPER BRACKET (LH/RH)	O/S Broken / N/S Not Necessary	49.20 FL	*24.60 FL
17	1		*HEADLAMP SUPPORT TOP COVER	Cut / Broken	222.60 FL	*222.60 FL
18	1		*HEADLAMP SUPPORT PANEL ASSY	Broken / Dented	907.40 FL	*907.40 FL
19	2		*HEADLAMP (LH/RH)	Broken / Dislodged	2,776.00 FL	*2,776.00 FL
20	1		*RADIATOR	Punctured / Bent	698.30 FL	*698.30 FL
21	2		*RADIATOR BRACKET (RH/LH)	Not Necessary	13.00 FL	*- FL
22	1		*RADIATOR HOSE UPPER	Not Necessary	36.50 FL	*-FL
23	1		*RADIATOR HOSE LOWER	Not Necessary	36.50 FL	*- FL
24	1		*RADIATOR EXPANSION TANK	Mtg Cracked	28.30 FL	*28.30 FL
25	2		*RADIATOR GUARD	Broken	40.00 FL	*40.00 FL
26	1		*HORN UNIT (LH/RH)	O/S Broken / N/S Not Necessary	147.60 FL	*73.80 FL
27	1		*HORN WIRE	Not Necessary	156.50 FL	*-FL
28	1		*FRONT FENDER (LH/RH)	O/S Buckled / N/S NotNecessary	1,132.60 FL	*566.30 FL
29	2		*FRONT FENDER APRON PANEL (LH/RH)	O/S Buckled / N/S Dented	1,274.00 FL	*1,274.00 FL
30	2		*FRONT FENDER SHIELD (LH/RH)	Torn / Dislodged	349.80 FL	*349.80 FL
31	1		*AIR CLEANER ASSY	Mtg Broken	118.60 FL	*118.60 FL
32	1		*AIR DUCT	Not Necessary	134.60 FL	*-FL
33	1		*AIRCON CONDENSER	Punctured / Bent	927.50 FL	*927.50 FL
34	1		*AIRCON SUCTION & LIQUID HOSE	Bent	624.00 FL	
35	1		*AIRCON DISCHARGE HOSE	Bent	162.60 FL	
36	1		*AIRCON COMPRESSOR	Distorted		*2,578.00 FL
22.0			Report was unsubmitted du	1 41 1		10

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	2	m(Hoda)	*FRONT PILLAR UPPER COVER / GARNISH	Not Necessary	167.00 FL	*- FL
38	1		*FRONT WINDSCREEN GLASS	Cracked	1,017.80 FL	
39	1		*FRONT WINDSCREEN MOULDING	Necessary		*113.30 FL
40	2		*FRONT WINDSCREEN PILLAR OUTER (LH/RH)	Dented	3,491.00 FL	*3,491.00 FL
41	1		*WIPER PANEL TOP GARNISH	Cut / Broken	222.60 FL	*222.60 FL
42	1		*WIPER CONTAINER	Broken	61.90 FL	*61.90 FL
43	1		*WIPER CONTAINER MOTOR	Damaged	75.00 FL	*75.00 FL
44	1		*FRONT WHEEL RIM (RH)	Distorted	325.30 FL	*325.30 FL
45	1		*FRONT WHEEL HUB CAP (RH)	Bent / Cut	107.10 FL	*107.10 FL
46	1		*FRONT WHEEL BEARING	Damaged	540.50 FL	*540.50 FL
47	1		*FRONT SHOCK ABSORBER (ASSY) (RH)	Distorted	342.20 FL	*342.20 FL
48	1		*FRONT SHOCK ABSORBER MOUNTING (RH)	Not Necessary	108.80 FL	*-FL
49	1		*FRONT DRIVE SHAFT (RH)	Damaged	1,030.80 FL	
50	1		*RACK & PINION ASSY	Damaged	969.60 FL	*969.60 FL
51	1		*STG TIE END	Distorted	62.60 FL	*62.60 FL
52	1		*STABILIZER BAR	Distorted	252.30 FL	*252.30 FL
53	1		*STABILIZER BAR BUSH (RH)	Not Necessary	16.40 FL	*-FL
54	1		*STABILIZER BAR LINK	Distorted	61.10 FL	*61.10 FL
55	1		*STABILIZER BRACKET	Not Necessary	24.00 FL	*-FL
56	1		*FRONT SUSPENSION LOWER ARM (RH)	Bent	529.30 FL	*529.30 FL
57	1		*FRONT CHASSIS MEMBER O/S	Dented	1,060.70 FL	
58	1		*KNUCKLE ARM (RH)	Distorted	552.00 FL	*552.00 FL
59	1		*TIMING COVER ASSY	Not Necessary	535.80 FL	*-FL
60	1		*TIMING TENSIONER ASSY	Distorted	260.80 FL	*260.80 FL
61	1		*FAN BELT (\$116.20) (50%)	Torn	92.96 FS	*58.10 FS
62	1		*ENGINE MOUNTING	Damaged	456.30 FL	*456.30 FL
63	1		*ENGINE UNDER COVER	Broken	334.60 FL	*334.60 FL
64	1		*ENGINE CROSSMEMBER	Distorted	2,094.40 FL	
65	1		*ENGINE MTG (REAR)	Damaged	279.60 FL	*279.60 FL
66	1		*ENGINE SUPPORT BRACKET ASSY	Not Necessary	546.60 FL	*-FL
67	1		*GEARBOX	Not Necessary	14,808.00 FL	*-FL
68	1		*GEARBOX MOUNTING	Damaged	215.40 FL	*215.40 FL
69	1		*STARTER MOTOR ASSY	Distorted / Damaged	790.60 FL	*790.60 FL
70	1		*INTER COOLER	Bent	1,032.50 FL	
71	2		*INTER COOLER MOUNTING	Not Necessary	25.90 FL	*-FL
72	1		*HOSE B TO INTER COOLER	Not Necessary	229.70 FL	*-FL
73	1		*HOSE C TO INTER COOLER INLET	Not Necessary	294.50 FL	*-FL
74	1		*PIPE TO INTER COOLER	Not Necessary	167.05 FL	*-FL
75	1		*PIPE TO INTER COOLER OUTLET	Bent / Deformed	244.55 FL	
76	1		*ABS SENSOR, RH	Not Necessary	234.00 FL	*-FL
77	1		*WIRING-ECM	Mtg Broken	3,243.00 FL	
78	1		*WIRING-FEM, RH	Not Necessary	168.00 FL	*-FL
79	1		*ACTUATOR - SWIRL CONTROL	Broken	814.60 FL	
80	1		*AUTO GEAR OIL	Not Necessary	110.40 FL	*-FL
81	1		*ENGINE TOP COVER	Broken	386.00 FL	
82	1		*THROTTLE BODY ASSY	Not Necessary	1,096.60 FL	*-FL
83	1		*INTAKE MANIFOLD ASSY	Broken	1,141.10 FL	
84	1		*ELECTRIC POWER STEERING	Not Necessary	4,880.50 FL	*-FL
85	1		*FRONT NUMBER PLATE	Broken / Dislodged	25.00 FS	
86	1		*FRONT NO PLATE TRIM COVER	Dented	30.00 FS	*30.00 FS
87	2			Necessary	200.00 FS	*200.00 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*FRONT FENDER ADVERTISEMENT LOGO (LH/RH)			
88	1		*FRONT DOOR COMFORT LOGO (RH)	Necessary	75.00 FS	*75.00 FS
89	1		*FRONT WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
90	1		*FRONT ERP STICKER	Necessary	26.00 FS	*26.00 FS
91	1		*FRONT TYRE (RH)	Serviceable	216.00 FS	*-FS
92	1		*OIL SUMP	Broken	435.60 FL	*435.60 FL
93	1		*ENGINE OIL 6 LITRES	Necessary / Leak	300.00 FL	*300.00 FL
94	1		*FAN IDLE PULLEY	Broken	189.50 FL	*189.50 FL
95	1		*RADIATOR FAN BLADE, COWLING, MOTO ASSY	R Broken	792.95 FL	*792.95 FL
F=Fra	nchise	part. S=	SpcNett. L=ListItemDisc.	Sub Total (S\$)	66,112.71	40,933.60
			- List Item Discount	on L Items 20.00/20.00% (S\$)	13,080.35	8,094.70
				Total Parts (S\$)	53,032.36	32,838.90
			Report was unsubmitted of	during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	2,400.00	1,400.00
2	SPRAY PAINTING CHARGE	New	1,750.00	1,000.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	150.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	FRONT CHASSIS ALIGNMENT CHARGE	New	400.00	150.00
7	REMOVE / REFIX UNDERCARRIAGE (FRT)	New	200.00	150.00
8	FRT WHEEL ALIGNMENT	New	120.00	60.00
9	REMOVE / REFIX AIRCON & REFILL GAS	New	150.00	80.00
10	REMOVE / REFIX ENGINE / GEARBOX	New	650.00	200.00
11	REMOVE / REFIX DASHBOARD	New	450.00	180.00
12	REMOVE / REFIX FUSE BOX	New	180.00	0.00
13	REMOVE / REFIX FRONT WINDSCREEN GLASS	New	120.00	80.00
14	REMOVE / REFIX CUSHION & UPHOLSTERY FRONT	New	90.00	0.00
15	RE-SET FRT ABS SYSTEM }	New	200.00	180.00
16	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	480.00	0.00
	Gross La	bour Cost (S\$)	7,490.00	3,550.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.