

ASS. REC. BY:

REF:

CS/FCI19000579/Dsd3⁷²

Special Instruction:

Surveyor:

Bryun

ASSIGNMENT (Office)

From (Person):

CWS

Serene for

of

FCI

Date/Time:

9:28pm@9/11/19

Estimated Cost

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 783M

Insured:

SH 6259P

at Workshop n/s

Chunni Motor

Tel:

65425119

of

Amk Autopoint #01-05

Policy No:

Claim No:

D19000301MP8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A:

08/01/2019

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

9:11am@10/11/19

Person Contacted:

Irene

Vehicle:

IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 783M-cc3 / AIG18011040 / Klpb3g2 DUA: 16/06/2018
	SH 6259P-CS / FCI10009948 / Kfn DUA: 11/05/2010
13/01/19	@ 17:27 p.m. revised PA to have via email.

Surveyor

REF:

ASSIGNMENT

COB Sept 2023

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 129 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC 783M Yr Regn: 2015 Sept

Type: M.Car / M.Cycle / Bus / Van / Lorry / Trax / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 c.c. 1685

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 679032 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDBU484750

C/No: KMHLB41UMGU079283

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modl: Oil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: - - -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 08/01/2019 D.O.I. 10/01/2019

Survey held at Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Body y o/s Res

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

First Capital SH6259P

12/12/19 Jinapu 2/5 140211- with 12 days of work
(Red. \$8938.72, 39%)

RECEIVED 14 FEB 2019

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) 14-2 - typrst

Report Format:

Lump Sum / I.B.I: (\$) 14000/=

Days Of Repair: 12

Resurvey No. of Trip: 2

Add Fee: Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

Survey Fee:

Transportation

S + RT (\$)

Photos 580

Others 050

12x15 = 180

170 + 180

30

50 + 50

158

658

14/12/19



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000301MFSH

Date: 18 January 2019

Our Ref: CS/FCI19000579/Dsd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 783M .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 10/01/2019 at the premises of M/s Chunni Motor Work Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>22,938.72</u> .
Revised Estimate Amount	: S\$ <u>16,610.48</u> .
"Check" Items Amount	: S\$ _____ .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the o/s body & o/s rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 9 Days

Yours faithfully,
Bryan Ang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date 09-01-2019 **Our Ref No.** D19000301MFSH

Accident Date 08-01-2019 **Claim Type.** Third Party

Insured Vehicle SH6259P **Third Party Vehicle.** SHC783M

Survey Location AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06

Contact Person. LYNN OR IRENE - 65421726

Contact No. 65427162/ 65425119 **Fax No.** 65426039

Survey Type WITHOUT PREJUDICE: EST. COR - \$22,938.72

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA **Fax No.** 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop CHUNNI MOTOR WORK **Attention.** NIL
PTE LTD

Cc : TP Solicitor NA **TP Solicitor Fax No.** NA

Officer Incharge SERENE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 18 January 2019 5:27 PM
To: 'Serene Ler'; 'CWS Motor Claims'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D19000301MFSH/1
Attachments: SHC 783M - Preli Advise.pdf

Dear Serene,

Enclosed preliminary revised of vehicle SHC 783M.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 10 January 2019 9:11 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000301MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 9 January 2019 9:27 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000301MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 783M

DATE : 8.01.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Fender With Housing (RH) <i>hnc</i>			\$ 4,736.80	✓
	Rear Fender Inner Lining (RH) <i>hnc</i>			\$ 169.30	X
	Rear Windscreen Moulding <i>hnc</i>			\$ 28.30	✓
	Rear Door (RH) <i>Dental</i>			\$ 2,201.10	✓
	Rear Door Rubber (RH) <i>hnc</i>			\$ 280.50	✓
	Rear Door Gear/Regulator (RH) <i>mounty broken</i>			\$ 242.80	✓
	Rear Door Power Motor (RH) <i>hnc</i>			\$ 158.60	X
	Rear Door Trim Board (RH) <i>mounty broken</i>			\$ 808.70	✓
	Front Door (RH) <i>Dental</i>			\$ 2,256.40	✓
	Front Door Gear / Regulator (RH) <i>mounty broken</i>			\$ 250.60	✓
	Front Door Power Motor, RH <i>hnc</i>			\$ 296.40	X
	Front Door Trim Board (RH) <i>mounty broken</i>			\$ 973.50	✓
	Door Centre Pillar Outer (RH) <i>Dental</i>			\$ 2,527.80	✓
	Rocker Panel Outer Garnish (RH) <i>cut / mounty broken</i>			\$ 341.40	✓
	Rocker Panel Outer <i>hnc</i>			\$ 1,310.60	X
	Rear Tyre Rim (RH) <i>distorted</i>			\$ 325.30	✓
	Rear Wheel Hup-Cap (RH) <i>cut</i>			\$ 107.10	✓
	Rear Wheelbearing ING & Hub <i>Don</i>			\$ 362.00	✓
	Rear Trailing Arm (RH) <i>distorted</i>			\$ 192.00	✓
	Rear Assist (RH) <i>distorted</i>			\$ 145.70	✓
	Rear Shock Absorber (RH) <i>distorted</i>			\$ 276.30	✓
	Rear Shock Absorber Mounting (RH) <i>hnc</i>			\$ 81.30	X
	Rear Crossmember <i>distorted</i>			\$ 1,021.50	✓
	Stabilizer Bar <i>distorted</i>			\$ 199.60	✓
	Stabilizer Link <i>distorted</i>			\$ 85.90	✓
	Rear Upper Arm (RH) <i>distorted</i>			\$ 335.75	✓
	Rear Lower Arm (RH) <i>distorted</i>			\$ 353.80	✓
	Rear Knuckle Arm (RH) <i>distorted</i>			\$ 545.60	✓
			18598.45	\$ 20,614.65	
			14878.76	\$ 4,122.93	
				\$ 16,491.72	
	Rear Windscreen Sealant <i>hnc</i>			\$ 46.00	Nett ✓
	Rear Door Advertisement Logo (RH) <i>hnc</i>			\$ 100.00	Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>hnc</i>			\$ 80.00	Nett ✓
	Front Door Coloured Comfort Logo (RH) <i>hnc</i>			\$ 75.00	Nett ✓
	Front Door Advertisement Logo (RH) <i>hnc</i>			\$ 100.00	Nett ✓
	Rear Tyre (RH) <i>hnc</i>		401.00	\$ 216.00	Nett X
				\$ 617.00	

SHC 783M

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 2,000.00 800/-
	Spray Painting Charge			\$ 1,500.00 800/-
	Wiring Charge			\$ 100.00 111
	Tuff Kote			\$ 150.00 40/-
	Towing Charge			\$ 50.00 111
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 111
	Transfer of Door	S	120.00	\$ 240.00 120/-
	Remove/Refix Undercarriage (RR)			\$ 200.00 150/-
	Rear Wheel Alignment			\$ 120.00 60/-
	Re-set Rear ABS System			\$ 200.00 111
	Re-set Frt & Rear Power Window System	S	200.00	\$ 400.00 111 } 180/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 111
	TOTAL LABOUR		2310.00	\$ 5,830.00
	ESTIMATE TOTAL			\$ 22,938.72

10/01/2019 @ 1100am
 H/A Actual
 1/5mm 12 days.
 ngn
 LKK Auto

17589.76
 4/5 14000/-



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME
ADDRESS

Home Tel.:
VIN:
Registration: SHC 783 M
Technician:
Mileage: 679032
Time Printed 10.1.19 12:53 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°11'		-3°00' 3°00'
4°41'		-0°19' 5°41'
-0°02'		-1°30' 1°30'
21°25'		
21°14'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°36'		-3°00' 3°00'
4°24'		-0°19' 5°41'
0°21'		-1°30' 1°30'
11°35'		
10°59'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
0°25'		-3°00' 3°00'
0°17'		-3°00' 3°00'
9°50'		-3°00' 3°00'
0°19'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
1°53'		-3°30' 2°30'
0°17'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
3°18'		-3°30' 2°30'
6°06'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-1°26'		-3°00' 3°00'
6°24'		-3°00' 3°00'
-2°55'		-3°00' 3°00'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19000579/Dsd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-02-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 6259P	Veh. Inspected	SHC 783M
Policy No.		Coverage (\$)	0.00
Claim No.	D19000301MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	09/01/2019
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KMHLB41UMGU079283	Colour	YELLOW
Odometer	679032	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	5 mm
L/H Front Tyre	205/60 R16	HANKOOK	5 mm
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/01/2019	Inspection Date	10/01/2019
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 783M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR FENDER WITH HOUSING (RH)	BUCKLED	4,736.80	4,736.80
1	REAR FENDER INNER LINING (RH)	NOT NECESSARY	169.30	-
1	REAR WINDSCREEN MOULDING	NECESSARY	28.30	28.30
1	REAR DOOR (RH)	DENTED	2,201.10	2,201.10
1	REAR DOOR RUBBER (RH)	NECESSARY	280.50	280.50
1	REAR DOOR GEAR/REGULATOR (RH)	MOUNTING BROKEN	242.80	242.80
1	REAR DOOR POWER MOTOR (RH)	NOT NECESSARY	158.60	-
1	REAR DOOR TRIM BOARD (RH)	MOUNTING BROKEN	808.70	808.70
1	FRONT DOOR (RH)	DENTED	2,256.40	2,256.40
1	FRONT DOOR GEAR/REGULATOR (RH)	MOUNTING BROKEN	250.60	250.60
1	FRONT DOOR POWER MOTOR,RH	NOT NECESSARY	296.40	-
1	FRONT DOOR TRIM BOARD (RH)	MOUNTING BROKEN	973.50	973.50
1	DOOR CENTRE PILLAR OUTER (RH)	DENTED	2,527.80	2,527.80
1	ROCKER PANEL OUTER GARNISH (RH)	CUT / MOUNTING BROKEN	341.40	341.40
1	ROCKER PANEL OUTER	NOT NECESSARY	1,310.60	-
1	REAR TYRE RIM (RH)	DISTORTED	325.30	325.30
1	REAR WHEEL HUP-CAP (RH)	CUT	107.10	107.10
1	REAR WHEELBEARING ING & HUB	DAMAGED	362.00	362.00
1	REAR TRAILING ARM (RH)	DISTORTED	192.00	192.00
1	REAR ASSIST (RH)	DISTORTED	145.70	145.70
1	REAR SHOCK ABSORBER (RH)	DISTORTED	276.30	276.30
1	REAR SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	81.30	-
1	REAR CROSSMEMBER	DISTORTED	1,021.50	1,021.50
1	STABILIZER BAR	DISTORTED	199.60	199.60
1	STABILIZER LINK	DISTORTED	85.90	85.90
1	REAR UPPER ARM (RH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (RH)	DISTORTED	353.80	353.80



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR KNUCKLE ARM (RH) LESS 20% DISCOUNT	DISTORTED	545.60 -4,122.93	545.60 -3,719.69
			16,491.72	14,878.76
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (RH)(SN)	NECESSARY	80.00	80.00
1	FRONT DOOR COLOURED COMFORT LOGO (RH)(SN)	NECESSARY	75.00	75.00
1	FRONT DOOR ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00
1	REAR TYRE (RH)(SN)	NOT NECESSARY	216.00	-
			617.00	401.00
	<u>LABOUR</u>			
	PANEL BEATING.		2,000.00	800.00
	SPRAY PAINTING CHARGE.		1,500.00	800.00
	WIRING CHARGE.	NOT NECESSARY	100.00	-
	TUFF KOTE.		150.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
	TRANSFER OF DOOR.		240.00	120.00
	REMOVE/REFIX UNDERCARRIAGE (RR).		200.00	150.00
	REAR WHEEL ALIGNMENT.		120.00	60.00
	RE-SET REAR ABS SYSTEM. }		200.00	180.00
	RE-SET FRT & REAR POWER WINDOW SYSTEM. }		400.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE. }		480.00	-
	-		-	-
	-		-	-
	-		-	-
			5,830.00	2,310.00
GRAND TOTAL			22,938.72	17,589.76



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			14,000.00
---	--	--	-----------

Report Ref No. CS/FCI19000579/Dsd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.