

ASS. REC. BY:

REF: CS/SPF19000591/Gibbs

Special Instruction:

Surveor:

GZ

ASSIGNMENT (Office)

From (Person):

Perry He

of

SPF

Date/Time:

10012019 1123am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No.:

GZ 3130M

Insured:

at Workshop m/s

Indeco Engineers

Tel:

of

39 Defu Lane 12

Policy No.:

Claim No.:

HOMSPFETQ17300218

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GZ 3130M - (33/SPF180119896/Gibbs)

Ref: 2510.2018

1111-

Email to Perry photograph

Part by Part \$4824

man hour - 30.

Surveyor: XRL

REF: SPF

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Indeco

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**



Bal. or Market Value: _____

IDAC Accident Rpt.: _____ Consistent? : **Yes** or No

GIA / PR Seen: _____ Consistent? : **Yes** or No

Est. Repairs: _____ days Res.: **Yes** or No

Lum Sum: _____ % 3 Val.: **Yes** or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 68223 OM Yr Regn: - /

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Pick up

Make: Toyota Hilux Cab.c 2982

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 205831 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MROE8126104002295

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/70R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. _____ D.O.I. 10-01-19

Survey held at w/s 3:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
10/1	Finalised \$ 30 Hrs with Asa Anson.

RECEIVED 24 JAN 2019

Date/Time, File Pass to? : Preli. Report
1) 23/1 Typist : Final Report

Date/Time, File Return to? _____
2) _____

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	<u>280</u>
Transportation:	
\$ + RS. (\$)	
Photos	
Others	
TOTAL	<u>280</u>

Report Format : _____
Lump Sum / I.B.I: (\$ _____)

Catherine Chong (LKK Auto)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Thursday, 10 January, 2019 11:23 AM
To: assignments
Cc: Wei Yea LIM (SPF); Kwee Huat TAN (SPF); Kim Pang CHAY (SPF); Ai Phing (LKKAuto); Shiau Chan (LKKAuto); Veron Chen (LKKAuto); Janice Lee (LKKAuto)
Subject: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - GZ3230M

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at INDECO.

Vehicle No: GZ3230M

Parts:

CADDY BOY TAIL DOOR GLASS
SEALANT
TAILGATE
REAR BUMPER
REVERSE SENSOR
CADDY BOY TAIL DOOR
TAILLAMP RH

Labour:

LABOUR DESCRIPTION	Man-Hour Qty
TO REPLACE CADDY BOY TAIL DOOR GLASS	4
TO REPLACE AND RESPRAY REAR BUMPER	5
TO INSTALL SENSOR AND DRILL SENSOR HOLE ON NEW BUMPER	1
TO REPAIR AND RESPRAY RHR BODY PANEL	8
TO REPLACE AND RESPRAY TAILGATE	6
TO REPLACE AND RESPRAY CADDY BOY TAIL DOOR	6

Thank you.

Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 11 January 2019 2:11 PM
To: 'Perry HE (SPF)'; assignments
Cc: Wei Yea LIM (SPF); Kwee Huat TAN (SPF); Kim Pang CHAY (SPF); Shiau Chan (LKKAuto); Veron Chen (LKKAuto)
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - GZ3230M
Attachments: GZ 3230M.xls; Full page photo.pdf

Dear Perry,

Please refer to the attachment above.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Thursday, 10 January 2019 11:23 AM
To: assignments <assignments@lkkauto.com>
Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Ai Phing (LKKAuto) <aiphing@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>
Subject: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ17300218 - GZ3230M

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF vehicle at INDECO.

Vehicle No: GZ3230M

Parts:

CADDY BOY TAIL DOOR GLASS
SEALANT
TAILGATE
REAR BUMPER
REVERSE SENSOR
CADDY BOY TAIL DOOR
TAILLAMP RH

Labour:

LABOUR DESCRIPTION	Man-Hour Qty
--------------------	--------------

SPF/2019/01-0006



ACCIDENT/DAMAGE REPAIR AND AD HOC WORKS REQUEST FORM

ILMS Notification No	1100016902		
Vehicle No	GZ 3230M	Division/Unit	Tanglin/KJ NPC
Vehicle Type (e.g. FRC, minibus)	Police Marked Car	Date	02/01/2019
Vehicle Make & Model	Toyota Hilux	Mileage (km)	-

Description	Pls tick	Police Report No & Date of Accident (if applicable)
NP168 (Accident involve 3 rd Party)	✓	T/20190101/2051 on 01/01/2019
NP168 (Accident do not involve 3 rd Party)		
NP299 Discovered Damage		
NP299 Vandalism		
Ad hoc, pls specify		

Description of affected area/required works (e.g. dented, cracked, grazed etc)

- Rear windscreen shattered
- Rear bumper damaged

Pls mark affected area with



Rank/Name
SSgt Mohamad Rashydi

Signature



**Scope Of Work
Home Team Agency**

SCOPE OF WORK

To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	Indeco Engineers Pte Ltd	VEH TYPE :		UNIT :	E DIV
VEH NO :	GZ3230M	FRV		REPAIR TYPE:	ACCIDENT
VEH MAKE/MODEL	TOYOTA HILUX		Mileage: 205831		

Reference No.
MHA/SPF/2019/01-0006 1100016902

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	CADDY BOY TAIL DOOR GLASS / SM	1350.00	1	20%	1620.00	1620.00
1.2	SEALANT / MEL	20.00	2	20%	24.00	48.00
1.3	TAILGATE / IT	680.00	1	20%	816.00	816.00
1.4	REAR BUMPER / AS	220.00	1	20%	264.00	264.00
1.5	REVERSE SENSOR / OM	100.00	1	20%	120.00	120.00
1.6	CADDY BOY TAIL DOOR / BUC	1550.00	1	20%	1860.00	1860.00
1.7	TAILLAMP RH / CRA	80.00	1	20%	96.00	96.00
2	Additional Services					
Remarks:					Parts Total:	\$ 4,824.00

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	TO REPLACE CADDY BOY TAIL DOOR GLASS	61.80	4	247.20
1.2	TO REPLACE AND RESPRAY REAR BUMPER	61.80	5	309.00
1.3	TO INSTALL SENSOR AND DRILL SENSOR HOLE ON NEW BUMPER	61.80	1	61.80
1.4	TO REPAIR AND RESPRAY RHR BODY PANEL	61.80	8	494.40
1.5	TO REPLACE AND RESPRAY TAILGATE	61.80	6	370.80
1.6	TO REPLACE AND RESPRAY CADDY BOY TAIL DOOR	61.80	6	370.80
			30	
2	Additional Services			
Guo Qiang - 8288082				
Not Authorised before & after photo				
			Labour Total:	\$ 1,854.00
			GRAND TOTAL :	\$ 6,678.00

Contractor shall complete the entire repair within 60 working days upon quotation approved date.

10/1/2019			Verification of Scope of Work		
Contractor QC		Vetted By:		Approved By:	
Name:	Gan Hup Tiong	Name:		Name:	
Date:	3/1/19	Date:		Date:	
Sign:		Sign:		Sign:	
Contractor QC			Home Team QC / Fleet Manager / Appointed Surveyor		
Name:		Name:		Name:	
Date:		Date:		Date:	
Sign:		Sign:		Sign:	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Pages prices are subject to Home Team Contract / Fleet Manager
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19000591/Gtbe2	
CONTRACT MANAGEMENT SECTION(SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 24-01-2019	
ATTN : PERRY HE		Code : SPF3	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	GZ 3230M
Policy No.		Coverage (\$)	0.00
Claim No.	HOMSPFETQ17300218	Excess (\$)	0.00
Assign From	PERRY HE	Assign Date	10/01/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HILUX D CAB	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	MR0EZ12G104002295	Colour	WHITE
Odometer	205831	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/70 R15	FALKEN	5 mm
L/H Front Tyre	205/70 R15	FALKEN	5 mm
R/H Rear Tyre	205/70 R15	FALKEN	5 mm
L/H Rear Tyre	205/70 R15	FALKEN	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date		Inspection Date	10/01/2019
Survey held at	INDECO ENGINEERS PTE LTD 39 DEFU LANE 12 . SINGAPORE 539139		
5a. Remarks			



Registration No. GZ3230M

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	CADDY BOY TAIL DOOR GLASS	1	SMASHED	\$1,620.00	\$1,620.00	
1.2	SEALANT	1	NECESSARY	\$24.00	\$48.00	
1.3	TAIL GATE	1	BENT	\$816.00	\$816.00	
1.4	REAR BUMPER	1	DISTORTED	\$264.00	\$264.00	
1.5	REVERSE SENSOR	1	DAMAGED	\$120.00	\$120.00	
1.6	CADDY BOY TAIL DOOR	1	BUCKLED	\$1,860.00	\$1,860.00	
1.7	TAIL LAMP	1	CRACKED	\$96.00	\$96.00	
1	SCOPE OF REPAIRS					
1.1	TO REPLACE CADDY BOY TAIL DOOR GLASS					4
1.2	TO REPLACE AND RESPARAY REAR BUMPER					5
1.3	TO INSTALL SENSOR AND DRILL SENSOR HOLE ON NEW BUMPER					1
1.4	TO REPAIR AND RESPRAY TAILGATE					8
1.5	TO REPLACE AND RESPARAY TAILGATE					6
1.6	TO REPLACE AND RESPRAY CADDY BOY TAIL DOOR					6
COSTING		TOTAL PARTS COST			\$4,824.00	
		TOTAL MAN-HOUR				30

Registration No. GZ3230M

Vehicle Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.