

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19000597/ABA3Q2

**Date:** 16/10/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100440551  
**Claimant**  
**Vehicle No :** PA2341H **Insured Vehicle No :** SKW4953Y  
Date of Loss: 05/01/2019 Nature of Claim: TP Claim No: 7071699046SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PA2341H**  
Make & Model: MITSUBISHI ROSA, 4.2 D BE637 (M) Engine No: 4D33H53129  
Reg. Date: 21/12/2000 (Man. Year: 2000) Chassis No: BE637GB00639  
Colour: White Odometer: 0 km  
Engine Capacity: 4214 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

#### CONDITION OF TYRES

Front Tyre Size: 215/75 R17.5 Rear Tyre Size: 215/75 R17.5  
Front Left Side: Sumitomo 6 mm Rear Left Side: Triangle 6 mm  
Front Right Side: Sumitomo 6 mm Rear Right Side: Triangle 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>	
Parts	28,213.00	18,848.25	9,364.75	33.19	
Miscellaneous Items	0.00	0.00	0.00		
Labour	17,570.00	10,310.00	7,260.00	41.32	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>45,783.00</b>	<b>29,158.25</b>	<b>16,624.75</b>	<b>36.31</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>8,400.00</b>			
	<b>(S\$)</b>	45,783.00	8,400.00	37,383.00	81.65
	<b>+ GST 7.00/7.00% (S\$)</b>	3,204.81	588.00	2,616.81	81.65
	<b>Nett Amount (S\$)</b>	<b>48,987.81</b>	<b>8,988.00</b>	<b>39,999.81</b>	<b>81.65</b>
	<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

#### INSPECTION

Date of Assignment: 09/01/2019  
Date Inspected: 09/01/2019 Inspected At: Chew Motor Pte Ltd (HQ)  
No 1 Kaki Bukit Ave 6, #01-11/41,  
Autobay@Kaki Bukit  
Singapore 417883  
Estimated Period of Repair: 28.0 days

**Adjuster:** ADRIAN LING

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR R/H FENDER	Distorted	3,783.00 FL	*3,783.00 FL
2	1		*REAR R/H FENDER EXCURSION BUS STICKER	Necessary	50.00 FL	*50.00 FL
3	1		*REAR R/H FENDER GLASS	Shattered	895.00 FL	*895.00 FL
4	1		*REAR R/H FENDER GLASS FRAME	Distorted	298.00 FL	*298.00 FL
5	4		*REAR R/H FENDER GLASS FRAME INNER SEAL	Necessary	160.00 FL	*160.00 FL
6	1		*REAR R/H FENDER GLASS FRAME MOULDING RUBBER	Necessary	245.00 FL	*245.00 FL
7	1		*REAR R/H FENDER GLASS SUPPORT BRACKET	Necessary	85.00 FL	*85.00 FL
8	1		*REAR R/H FENDER INNER TRIM BOARD	Distorted	880.00 FL	*880.00 FL
9	1		*REAR R/H FENDER AIR-CON OUTER COVER	Not Necessary	355.00 FL	*- FL
10	1		*REAR R/H FENDER AIR-CON CONDENSER	Not Necessary	1,280.00 FL	*- FL
11	1		*REAR R/H FENDER AIR-CON CONDENSER FAN MOTOR ASSY	Not Necessary	390.00 FL	*- FL
12	1		*REAR R/H FENDER AIR-CON CONDENSER BRACKET	Not Necessary	120.00 FL	*- FL
13	1		*REAR ROOF TOP	Distorted	5,500.00 FL	*5,500.00 FL
14	1		*REAR ROOF TOP LINNING	Crumpled	3,590.00 FL	*3,590.00 FL
15	1		*REAR ROOF TOP LINNING AIR COVER	Not Necessary	130.00 FL	*- FL
16	1		*REAR ROOF TOP LINNING AIR COVER LOWER LINNING COVER	Not Necessary	85.00 FL	*- FL
17	2		*REAR R/H SEAT CUSHION	Not Necessary	300.00 FL	*- FL
18	1		*REAR FLOOR PANEL CARPET ASSY	Not Necessary	2,500.00 FL	*- FL
19	1		*REAR L/H FENDER	Distorted	2,450.00 FL	*2,450.00 FL
20	1		*REAR L/H FENDER INNER PANEL	Distorted	1,850.00 FL	*1,850.00 FL
21	1		*REAR L/H FENDER EXCURSION BUS STICKER	Necessary	100.00 FL	*100.00 FL
22	2		*REAR L/H FENDER GLASS FRAME	Not Necessary	298.00 FL	*- FL
23	3		*REAR L/H FENDER GLASS FRAME INNER SEAL	Not Necessary	160.00 FL	*- FL
24	1		*REAR L/H FENDER LOWER SUPPORT BRACKET	Not Necessary	85.00 FL	*- FL
25	1		*REAR L/H FENDER MUD FLAP	Distorted	225.00 FL	*225.00 FL
26	2		*REAR L/H RIM	Bent (1 PCS ONLY)	400.00 FS	*200.00 FS
27	2		*REAR L/H TYRE	Punctured (1 PCS ONLY)	600.00 FS	*250.00 FS
28	1		*REAR L/H AXLE BEARING	Damaged	580.00 FL	*580.00 FL
29	1		*REAR L/H AXLE SHOCK ABSORBER	Bent	390.00 FL	*390.00 FL
30	1		*REAR L/H AXLE LONG SHAFT	Damaged	950.00 FL	*950.00 FL
31	1		*REAR L/H AXLE SPRING ASSY	Bent	1,800.00 FL	*1,800.00 FL
32	2		*REAR AXLE SPRING BRACKET	Bent	700.00 FL	*700.00 FL
33	1		*REAR AXLE	Not Necessary	3,200.00 FL	*- FL
34	1		*REAR CENTER LONG SHAFT ASSY	Not Necessary	2,850.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>37,284.00</b>	<b>24,981.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	9,071.00	6,132.75
<b>Total Parts (\$\$)</b>	<b>28,213.00</b>	<b>18,848.25</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIT SEAT CUSHION & CARPET	New	2,000.00	0.00
2	TO REMOVE & REFIT ROOF TOP LINNING ,AIR-CON AIR COVER ,AIR-CON PIPE	New	2,200.00	1,000.00
3	TO REMOVE & REFIT AIRCON CONDENSER & TOP UP GAS	New	480.00	0.00
4	TO REMOVE & REFIT REAR L/H & R/H FENDER GLASS	New	1,050.00	1,050.00
5	GUM	New	560.00	560.00
6	TO REMOVE & REFIT REAR AXLE ,LONG SHAFT & SPRING ASSY	New	1,200.00	800.00
7	TO CHECK WHEEL ALIGNMENT	New	200.00	120.00
8	TO CHECK WIRING	New	200.00	100.00
9	TUFF KOTE	New	180.00	180.00
10	TOWING FEE	New	200.00	200.00
11	PANEL BEATING	New	5,500.00	3,500.00
12	SPRAY PAINTING	New	3,800.00	2,800.00
<b>Gross Labour Cost (\$\$)</b>			<b>17,570.00</b>	<b>10,310.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >