



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk C #01-41 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

05/01/2019

Registration No.: 201718369R

GST Reg No.: 201718369R

01-43

Singapore 417883

TPALG.
Jasper.

Accident date: 05/01/2019

Estimated repair cost for vehicle no: PA2341H MITSUBISHI ROSA BE637 4.2 M '00

CHASSIS: BE637GB00639

S/n	Qty	Items	U/price	Amount	
1	1	Rear R/H Fender Distorted		3783	✓
2	1	Rear R/H Fender Excursion Bus Sticker New		50	✓
3	1	Rear R/H Fender Glass Shattered		895	✓
4	1	Rear R/H Fender Glass Frame Distorted		298	✓
5	4	Rear R/H Fender Glass Frame Inner Seal 3/4 40		160	✓
6	1	Rear R/H Fender Glass Frame Moulding Rubber 3/4 40		245	✓
7	1	Rear R/H Fender Glass Support Bracket New		85	✓
8	1	Rear R/H Fender Inner Trim Board Distorted		880	✓
9	1	Rear R/H Fender Air-Con Outer Cover 3/4 New		355	X
10	2	Rear R/H Fender Air-Con Condenser 3/4 New		1280	X
11	2	Rear R/H Fender Air-Con Condenser Fan Motor Assy 3/4 New		390	X
12	1	Rear R/H Fender Air-Con Condenser Bracket 3/4 New		120	X
13	1	Rear Roof Top Distorted		5500	✓
14	1	Rear Roof Top Lining completed		3590	✓
15	1	Rear Roof Top Lining Air Cover New		130	X
16	1	Rear Roof Top Lining Air Cover Lower Lining Cover New		85	X
17	2	Rear R/H Seat Cushion 3/4 1500		300	X
18	1	Rear Floor Panel Carpet Assy 3/4 New		2500	X
19	1	Rear L/H Fender Distorted		2450	✓
20	1	Rear L/H Fender Inner Panel Distorted		1850	✓
21	1	Rear L/H Fender Excursion Bus Sticker New		100	✓
22	2	Rear L/H Fender Glass Frame 2		298	X
23	3	Rear L/H Fender Glass Frame Inner Seal 3/4 40		160	X
24	1	Rear L/H Fender Lower Support Bracket 3/4 New		85	X
25	1	Rear L/H Fender Mud Flap Distorted		225	✓
26	2	Rear L/H Rim 1 piece bent 200		400 (SW)	200 (SW)
27	2	Rear L/H Tyre 1 piece punched 300		600 (SW)	200 (SW)
28	1	Rear L/H Axle Bearing Damaged.		580	✓

29	1	Rear L/H Axle Shock Absorber	Best	390	✓
30	1	Rear L/H Axle Long Shaft	Dupd	950	✓
31	1	Rear L/H Axle Spring Assy	Best	1800	✓
32	2	Rear Axle Spring Bracket	Best	350 700	✓
33	1	Rear Axle	Not on	3200	X
34	1	Rear Center Long Shaft Assy	Not on	2850	X

24531 S.N: 450
 18398.25 Subtotal :- \$0.00

Labour charges

To remove & refit seat cushion & carpet		\$2,000.00	X
To remove & refit roof top lining, air-con air cover, air-con pipe		\$2,200.00	1000
To remove & refit air-con condenser & top up gas		\$480.00	X
To remove & refit rear L/H & R/H fender glass	\$150 x 7	\$1,050.00	✓
Gum	\$80 x 7	\$560.00	✓
To remove & refit rear axle, long shaft & spring assy		\$1,200.00	800
To check wheel alignment		\$200.00	120
To check wiring		\$200.00	100
Tuff kote		\$180.00	✓
Towing fee		\$200.00	✓
Panel beating		\$5,500.00	3500
Spray painting		\$3,800.00	2800

Subtotal :- \$17,570.00

Total:- \$17,570.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

total: 29158.25
 L/S: 84K (Nett Value)
 28 Days