

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19000624/R1SD3E2

Date: 11/11/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN1764201801
Claimant Vehicle No : PC595U **Insured Vehicle No :** YL3072M
Date of Loss: 24/12/2018 Nature of Claim: TP Claim No: SNM19D200119C02/2(CBS)

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC595U**
Make & Model: ISUZU LT434P 7.8 SMT, 7.8 D (M) Engine No: 6HK1674648
Reg. Date: 22/04/2016 (Man. Year: 2015) Chassis No: JALLT434PF7000150
Colour: Multi-colour Odometer: 244449 km
Engine Capacity: 7790 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 11R22.5 Rear Tyre Size: 11R22.5 (D)
Front Left Side: TAITONG 8 mm Rear Left Side: TAITONG 8/8 mm
Front Right Side: TAITONG 8 mm Rear Right Side: TAITONG 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,020.00	2,385.00	4,635.00	66.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,250.00	2,400.00	2,850.00	54.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,270.00	4,785.00	7,485.00	61.00
Approved Total (Overridden) (\$\$)		3,800.00		
(\$\$)	12,270.00	3,800.00	8,470.00	69.03
+ GST 7.00/7.00% (\$\$)	858.90	266.00	592.90	69.03
Nett Amount (\$\$)	13,128.90	4,066.00	9,062.90	69.03

INSPECTION

Date of Assignment: 10/01/2019
Date Inspected: 24/01/2019 Inspected At: Crown Asia Bus Builder Pte Ltd (sungei Kadut) (HQ)
44 Sungei Kadut Ave
Singapore 729667
Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 11 Nov 2021)	
Parts:	N/A	ISUZU LT434P 7.8 SMT 7.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC595U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RIGHT BOTTOM BUMPER	Not Necessary	1,500.00 FL	*- FL
2	1		*REAR RIGHT BUMPER STRUCTURAL FRAME ASSY	Not Necessary	1,000.00 FL	*- FL
3	1		*REAR RIGHT LID COVER ASSY	N/S Repair / O/S Bent	5,300.00 FL	*2,650.00 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	7,800.00 2,650.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	780.00 265.00
					Total Parts (S\$)	7,020.00 2,385.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY AND SPRAY PAINTING FOR REAR BUMPER,REAR STRUCTURE ASSY AND TWO REAR RIGHT LID COVER,RIGHT BODY STRUCTURE	New	2,800.00	1,400.00
2	TO SPRAY FOAM,KNOCK AND REPAIR ALL NECESSARY PARTS INCLUDING CHANGING OF ALL DAMAGED PARTS	New	2,450.00	1,000.00
Gross Labour Cost (\$\$)			5,250.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >