

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19000628/R1vd3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date: 13-03-2019 Code: FCI2		
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 818Y	Veh. Inspected	WC 1618Z	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	D19000307MFSH	Excess (\$)	0.00	
	Assign From	EILEEN LEE	Assign Date	10/01/2019	
2. Vehicle Particulars & Condition					
	Make & Model	NISSAN CGB45CLSMNB	c.c	13074	
	Engine No.	HIDDEN	Year of Reg.	2007	
	Chassis No.	CGB4CLS00085	Colour	MULTI COLOUR	
	Odometer	228367	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	295/80 R22.5	LING LONG	8 mm	
	L/H Front Tyre	295/80 R22.5	LING LONG	8 mm	
	R/H Rear Tyre	295/80 R22.5 (D)	LING LONG	8/8 mm	
	L/H Rear Tyre	295/80 R22.5 (D)	LING LONG	8/8 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	07/01/2019	Inspection Date	25/01/2019	
	Survey held at	MOVA AUTOMOTIVE PTE LTD			
		15 FAN YONG ROAD SINGAPORE 629792			
5a.	. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days				