

ASS. REC. B)	C321 C110012000 (C1D) secral lastruction:	~
From (Person	ASSIGNMENT (Office) Only Christyn Urg of MS [G Date/Time: 100	12019
OD (TP)W	WS/TP RES/OD RES/EVA/INV/MV/CS	
at Workshop	Vehicle No: SLG 4680G Insured: SMC 4177 pm/s Z-One Automotive Tel: 975821 1 Keyki Bkd Ave 6 #01-87	IS
Policy No:Sum Insured:	H29087626 AVW Claim No: 568673	
Make of Veh (Client's Record	Excess:	3/2018
CA / REV	10.50 m 930/8/18 Person Contacted: VUNK Vehicle IN OUT	
Date/Time	Action/Instruction (X) Estimate Do Not Finulize. SLG 4680G-X	
31/8/15	3M(4177C-X.	Az
7/0/14	Sund 45700 Bh	nmy
	cled: 4300; 38%)	1200

11/1 - File pass to typist

RECEIVED 1 4 JAN 2019

ASS. REC. BY: MORCUS	MSIL
,	SSIGNMENT
From	,
Estimated Cost:	Veh No: \$26 86806 Yr Regn: 9 116
OD TP/)WS/TP RES/OD RES/EVA/INV/MV	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
To Inspect Vehicle No: 5 4 4680 6	Truck / Trailer or (A)
	Make: - Joyola haimer c.c 1986
at Workshop m/s 2-one	Colour Black A/C: Insured / Std / NI / NA
	Sp.Reading 360/ T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: 254 6000 7.75 81'
Claims No.	Gen. Cond: South Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: norder Lammed / Leaked / Burnt or
Make of Veh:	Modi: Nil (S/Rim / STD A/Rim or
	Tyre Size: F:
(Policy Condition)	R: 235/5-6-21f
Remark: The veh had commenced its N/S O/S	
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
Bal. or Market Value:	
IDAC Accident Rport. Consistent? : Yes or No	R/Bal. R/Bal.
GA PR Seem. Consistent?: Yes or No	L/Bal. Mm R/Bal. mm
Est. Repairs: (days Res.: Yes or No	mm UBal. mm
Lum Sum: % 3 Val.: Yes or No	D.O.A. 26/8/18 D.O.I. 30/8/18
	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: Vehicle: IN / OUT	han
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
- The section of the	
No settle pass la	mye
7500	(
1/8/18 dolphit PRS Report	
te/Time, File Pass to? : Prelli. Report	
Time! B.	Days Of Repair:
te/Time, File Return to?	Resurvey No. of Trip: Survey Fee: 120
	Transportation:
Add Fee:)_5+R5,_SI
port Format :	: Interview (\$) Photos
	: Tech. Invs (\$) Others
mp Sum / I.B.I: (\$: Weekend (\$
	TOTAL

(08/11/13) wef ,

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Ri	pt	Adj Submitted	Ins Auth'ed	Auth'ed Status		
Main	29 Aug 2018		29 Aug 2018 16:12 Edit Adj Rpt	S\$0.0 Edit Estim		S\$0.00 View Rpt	INS NOTIFICE		for Survey Report	
	Main	F	Reference		Claim D	etails	Docu	ments	Show All	
CLAIM S	UBFOLDER DET	AILS								
Insured:		KART	HIK BALKRISHNA	AN NATARA	JAN. ID	· \$7887937H T		reated by ins		
Main Clain	nant:	TEO H	AN WEE, ID: S	7222167B	JAN, 10	. 37007937H, 1	ei. +0391082	721, Email: NO	DEMAIL	
Vehicle Re	g. No.:	SLG4	1680G		Date of	Loss:	[2	0/08/2018 16:00 2 Months and 2 2g Date (Man Yr	7 Days From LTA	
Claim Type	e:	TP/	568673	Policy/Cover Note No.:			Co	A29087620AVW (Comprehensive Coverage: 29/06/2018 - 28/06/2019		
/ehicle Re	g. No. (Insured):	SMC4	177C		Policy No. (Claimant):			/06/2019		
					Excess:					
Repairer:		Z-one Bukit -	Automotive Pte	Ltd - Kb (H	Q) 1 Kaki	Bukit Avenue 6, #	01-87/85 Aut	obay @ Kaki Bu	kit, 417883 Kaki	
landling I	nsurer:		Insurance (Singa	pore) Pte.	Ltd. (HQ) - Tel: +65 6827	7888 [Han	dled by Christin	na Wong - 6643	
Adjuster:		14/01	uto Consultants I	Pte Ltd (HQ) - Tel: 6	256-3561 [Han	dled by MARC	US CHUA] [Final Rpt due	
river/Cus	todian (Insured):		IK BALKRISHNAN I	NATARAJAN	(40 / Male	e), NRIC: S7887	937H. Tel: -	+6591082721		
dj Asg. R	emarks:	Liabilit	y is down due to Bo : Yvonne / 9755 21	OLA. TP disa	gree with	our SJE list. Proce	ed to appoint	LKK Auto Consu	Iltants. Contact	
SSOCIA	TED MAIL RECE	IVED					View	All I Com	pose Case Mail	
MSIG_S	G (10/01/2019):	Report Send Ba	ick Alerts - SLG46	580G (TP)				Zui Com	pose case Maii	
=										
	CIATED TASKS				v	iew All Search	Tasks	Create New Task	Complete	
Due Dat o results.		Type Task	Group Subjec	t Handle	er As	signed By	Completed O	n Create	d On Done?	



No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Invoice No 08-18028/AY

Billing Name & Address Teo Han Wee 94 Lorong G Telok Kurau Singapore 426286

Date

12 Sep 2018

Vehicle No : SLG 4680 G

Model: Toyota Harrier

Item	Descriptions	Amount S\$
1	Date of inspection: 27 Aug 2018 A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs139 copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection Total	\$ 889.00
	SDLS : EIGHT HUNDRED AND EIGHTY-NINE ONLY	

Notes:

- 1. All cheque payment should be "Crossed" and made payable to "Pai's Appraiser Pte. Ltd."
- 2. All cheque should have our "Invoice No." written on the reverse side of the cheque
- 3. For further enquiries on this invoice, please feel free to contact us

Official Stamp

E & O. E



No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference: TP / 08-18028/AY / 2018

Date of Report : 12 Sep 2018

Teo Han Wee 94 Lorong G Telok Kurau Singapore 426286

THIRD PARTY SURVEY ACCIDENT HAPPENED ON

26 Aug 2018

As per your instruction dated 27 Aug 2018 with regard carried out a physical inspection on the said vehicle our report and findings as follows:

with regard to the above matter. We have SLG 4680 G . We enclosed herewith

1. VEHICLE PARTICULARS

Registration No : SLG 4680 G

Model : Toyota Harrier Year / Capacity : 2016/1986

Chassis No : ZSU60-0077585 Engine No : 3ZRB778309

Mileage : 36018 Colour : Black

2. TYRES CONDITION

			Size	Made	Balance		Rim
FRONT	O/S	:	235/55 R18	Bridgestone	5.00	mm	Sport
REAR	O/S	:	235/55 R18	Bridgestone	5.00	mm	Sport
FRONT	N/S	:	235/55 R18	Bridgestone	5.00	mm	Sport
REAR	N/S	:	235/55 R18	Bridgestone	5.00	mm	Sport



No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Z-One Automotive Pte Ltd

No.1 Kaki Bukit Ave 6, Blk D #01-87 AutoBay@Kaki Bukit

Singapore 417883

Estimated normal period of repair : 8 working days to complete.

6. Enclosed number of photograph : 139 copies.

- 7. In accordance to your instruction, we have <u>Not Authorised</u> repair to the vehicle and the survey was done on a <u>"Without Prejudice"</u> basis. We hope that this report will be of assistance to you in dealing with the matter.
- 8. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No:

SLG 4680 G

Report No:

TP/ 08-18028/AY / 2018

SPARE PARTS

Qty	Parts Description	Condition	orkshop's stimation	Our Revised Estimation
	List Items			
1	Rear windscreen moulding	Necessary	\$ 172.40	\$ 172.40
1	Rear tailgate	Damage	\$ 1712.05%	/+
1	Rear tailgate inner board	Damage	\$ 781.90	\$ 200 781.90
2	Rear tailgate lamps	Intact	\$ 748.90	\$ 17 701.90
1	Rear tailgate lock	Damage	\$ 381.75	\$ 381.70
1	Rear tailgate lock garnish	Damage	\$ 42.00	\$200
1	Rear tailgate rubber	Necessary	\$ 289.10	
1	Rear tailgate 'HARRIER' emblem	Necessary	\$ 77.00	\$ ful 289.10 \$ m 77.00
2	Rear taillamps	Damage	\$ 1123.20	\$ CM 1123.20
1	Rear end panel	Damage	\$ 781.10	\$ 30 781.10
1	Rear end panel inner garnish	Damage	\$ 374.45	\$74.45
1	Rear humner / 3 04	Damage	\$ 1718.00	\$ 1718.00
1	Rear bumper lower	Damage	\$ 369.10	\$7.5 369.10
1	Rear bumper clip (1 set) 60	Necessary	\$ 129.00	\$ nel 129.00
1	Rear bumper inner sponge	Damage	\$ 185.25	\$700 185.20
2	Rear bumper reflectors	Damage	\$ 166.20	\$1 166.20 💢
1	Rear n/s spare tyre side tray	Damage	\$ 568.70	\$CM 568.70
1	Rear o/s spare tyre side tray	Damage	\$ 568.70	\$ cm 568.70
	The second second second	3-	\$ 10188.80	\$ 9439.80
	Discount	25.0%	\$ 2547.20	\$ 2359.95
			\$ 7641.60	\$ 7079.85
	Special Nett Items			
1	Rear windscreen sealant	Necessary	\$ 60.00	\$ rey 50.00 40
1	Rear reverse sensor (1 set)	Damage	\$ 280.00	\$600 200
3	Rear amplifier (1 set)	Damage	\$ 3900.00	\$84 3900.00 \
			\$ 4240.00	\$ 4230.00

Vehicle No:

SLG 4680 G

Report No:

TP/ 08-18028/AY / 2018

LABOUR COST

S/No	Job Descriptions	orkshop's stimation	1	ır Revised stimation
	Spare Parts Total c/f	\$ 11881.60	\$	11309.85
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 50.00	\$	40.0030
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 150.00	\$	100.00 fo
3	To remove and refit rear bumper sensor.	\$ 150.00	\$	€2 00.08
4	To remove and refit rear windscreen glass.	\$ 200.00	\$	120.00
5	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and wield body panels. To re-adjust to the original position using power tools.	\$ 1500.00	\$	1000.00
6	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1500.00	\$	1000.00 950
7	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 180.00	\$	90.00 60
8	To remove and refit rear amplifier.	\$ 600.00	\$	400.00300
	Total	\$ 16211.60	\$	14139.85
	The repairer has agreed to undertake the repair under a Lump Sum Basis.We have further adjusted the amount			

SDLS: ELEVEN THOUSAND THREE HUNDRED ONLY

to a Lump Sum Repair Contract of:

Qualified/Appraiser

Page 4

11300.00

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUBF	OLDER TRA	CKING									
Case N	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Sul	bmitted	Ins Auth'ed		Status	
Main 2	9 Aug 2018		29 Aug 2018 16:12 Edit Adj Rpt	S\$7,000 Edit Es	0.00 timates	S\$7,00 View	- 1			Pending for Survey Report Cancel Case	
М	lain	Re	eference	C	laim Det	ails	$\neg \cap$	Docume	ents		Show All
CLAIM SUB	FOLDER DE	TAILS				[0	Created	by insurer]			
Insured:		BALKRISHNAN	NATARAJAN, ID: S	S7887937H	H, Tel: +	659108	2721, Er	nail: NOEMAIL			
Main Claimant:	TEO HAN	WEE , ID: S722	2167B								
Vehicle Reg. No.:	SLG468	0G			Date of L	.oss: [2	22 Months	3 16:00 - :59 and 27 Days			(Man Yr)]
Claim Type:	TP / 568	673			Policy/Co Note No.			AVW (Compre 29/06/2018 -			
Vehicle Reg. No. (Insured):	SMC4177	SMC4177C). it):					
					Excess:						
Repairer:	Z-one Au	tomotive Pte Ltd	- Kb (HQ) 1 Kaki B	lukit Avenu	ie 6, #01-	87/85 A	utobay @	Kaki Bukit, 41	17883 K	aki Bukit - T	el:
Handling Insurer:			re) Pte. Ltd. (HQ)								
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 625	56-3561	. [Handled	by MAF	RCUS CHI	JA] [Final	I Rpt d	ue 14/01,	2019]
Driver/Custo dian (Insured):	KARTHIK I		TARAJAN (40 / Male)								
Adj Asg. Remarks:	Liability is 2115 / 62		A. TP disagree with o	ur SJE list	. Proceed	to appoi	nt LKK Au	to Consultants	. Contac	ct Person: Y	vonne / 9755
ASSOCIAT	ED MAIL RE	CEIVED							View All	Compo	se Case Mail
MSIG_SG	(10/01/2019	e): Report Send	Back Alerts - SLG4	680G (TP)						
ALL ASSO	CIATED TAS	SKS⊟				Vie	w All	Search Tasks	Create	e New Task	Complete
Due Date No results.	Priority	Type Task	Group Subject	t Hand	ller A	ssigned	і Ву	Completed (On	Created O	n Done?
- COLUMN A I				100 To 10	V G AND HE STREET		HI CHARLES V			Ortelia decon	

Claim Documents

*SLG4680G (568673)

[SMC4177C]

TP

TEO HAN WEE

Aug 26 2018 4:00PM

[KARTHIK BALKRISHNAN NATARAJAN]

Z-one Automotive Pte Ltd - Kb

Vid	eo		1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbna	ail Prin
1	29/08/18 15:09	Video - Accident From:SC - Reg. No: SMC4177C, Claimant: KARTHIK BALKRISHNAN NATARAJAN	1 Load MP	4
Pho	tos/Images		3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	ail Prin
1	31/08/18 12:23	General View	1 Load JPC	3 •
2	31/08/18 12:23	General View	1 Load JPC	3 V
3	31/08/18 12:23	General View	1 Load JPC	G 🗸
4	31/08/18 12:23	General View	1 Load JPC	G 🔽
5	31/08/18 12:23	General View	1 Load JPC	3
6	31/08/18 12:23	General View	1 Load JPC	3 4
7	31/08/18 12:23	General View	1 Load JPC	G 🗹
8	31/08/18 12:23	General View	1 Load JPC	3 •
9	31/08/18 12:23	General View	1 Load JPC	3
10	31/08/18 12:23	General View	1 Load JPC	3 V
11	31/08/18 12:23	General View	1 Load JPC	G 🗹
12	31/08/18 12:23	General View	1 Load JPG	G 🔽
13	31/08/18 12:23	General View	1 Load JPC	G 🗸
14	31/08/18 12:23	General View	1 Load JPG	3 V
15	31/08/18 12:23	General View	1 Load JPG	3 V
16	31/08/18 12:23	General View	1 Load JPG	G 🔽
17	31/08/18 12:23	General View	1 Load JPG	3 V
18	31/08/18 12:23	General View	1 Load JPG	3 4
19	31/08/18 12:23	General View	1 Load JPG	3 V
20	31/08/18 12:23	General View	1 Load JPG	
21	31/08/18 12:23	General View	1 Load JPG	
22	31/08/18 12:23	General View	1 Load JPG	
23	31/08/18 12:23	General View	1 Load JPG	
24	31/08/18 12:23	General View	1 Load JPG	
25	31/08/18 12:23	General View	■ Load JPG	
26	31/08/18 12:23	General View	⚠ Load JP0	
27	31/08/18 12:23	General View	■ Load JPG	
28	31/08/18 12:23	General View	1 Load JPG	
29	31/08/18 12:23	General View	1 Load JPG	
1000	Epide Allega, Salaro, Salaro, Salaro	General View	1 Load JPG	
30	31/08/18 12:23		1 Load JPG	
31	31/08/18 12:23	General View	1 Load JPG	
32	31/08/18 12:23	General View	1 Load JPG	

Vid	90		1 per page	~	√
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		umbnail oad JPG	
34	31/08/18 12:23	General View			V
35	31/08/18 12:23	General View		oad JPG	\sqrt{\sq}\ext{\sqrt{\sq}}}}}}}}}}}}} \sqit{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sq}}}}}}}}}}}} \sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sq}}}}}}}}}} \sqrt{\sqrt{\sqrt{\sq}}}}}}}} \sqite\septite\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\
36	31/08/18 12:23	General View		oad JPG	V
37	31/08/18 12:23	General View		oad JPG	✓
38	31/08/18 12:23	General View		oad JPG	✓
39	31/08/18 12:23	General View		oad JPG	✓
40	31/08/18 12:23	General View	1 Lo	oad JPG	V
41	31/08/18 12:23	General View	1 Lo	oad JPG	✓
42	31/08/18 12:23	General View	⑥ Lo	oad JPG	V
43	31/08/18 12:23	General View	1 Lo	oad JPG	✓
44	31/08/18 12:23	General View	1 Lo	oad JPG	✓
45	31/08/18 12:23	General View	1 Lo	oad JPG	V
46	31/08/18 12:23	General View	⑤ Lo	oad JPG	~
47	31/08/18 12:23	General View	€ Lo	oad JPG	V
48	31/08/18 12:23	General View	1 Lo	oad JPG	V
49	31/08/18 12:23	General View	1 Lo	oad JPG	V
50	31/08/18 12:23	General View	1 Lo	oad JPG	V
51	31/08/18 12:23	General View		oad JPG	~
52	31/08/18 12:23	General View		oad JPG	V
53	31/08/18 12:23	General View		oad JPG	V
54	31/08/18 12:23	General View		oad JPG	V
	Principles of the search result to see 2	General View		oad JPG	∀
55	31/08/18 12:23			- C. 1150-21	V
56	31/08/18 12:23	General View		oad JPG	
57	31/08/18 12:23	General View		oad JPG	V
58	31/08/18 12:23	General View		oad JPG	V
59	31/08/18 12:23	General View		oad JPG	<u>~</u>
60	31/08/18 12:23	General View		oad JPG	V
61	31/08/18 12:23	General View		oad JPG	✓
62	31/08/18 12:23	General View		oad JPG	Y
63	31/08/18 12:23	General View		oad JPG	✓
64	31/08/18 12:23	General View		oad JPG	✓
65	31/08/18 12:23	General View	■ Lo	oad JPG	✓
66	31/08/18 12:23	General View	O Lo	oad JPG	✓
67	31/08/18 12:23	General View	O Lo	oad JPG	✓
68	31/08/18 14:03	Reinspection Photo	₫ Lo	oad JPG	✓
69	31/08/18 14:03	Reinspection Photo	1 Lo	oad JPG	✓
70	31/08/18 14:03	Reinspection Photo	1 Lo	oad JPG	✓
71	31/08/18 14:03	Reinspection Photo	1 Lo	oad JPG	✓
72	31/08/18 14:03	Reinspection Photo	1 Lo	oad JPG	✓
73	31/08/18 14:03	Reinspection Photo	₫ Lo	oad JPG	V
74	31/08/18 14:03	Reinspection Photo	1 Lo	oad JPG	V
75	31/08/18 14:03	Reinspection Photo		oad JPG	~
76	31/08/18 14:03	Reinspection Photo		oad JPG	V
77	31/08/18 14:03	Reinspection Photo		oad JPG	V
78	31/08/18 14:03	Reinspection Photo		oad JPG	V
79	31/08/18 14:03	Reinspection Photo		oad JPG	V
80	31/08/18 14:03	Reinspection Photo	-	oad JPG	V
				oad JPG	V
81	31/08/18 14:03	Reinspection Photo		oad JPG	∀
82	31/08/18 14:03	Reinspection Photo			V
83	31/08/18 14:03	Reinspection Photo	- LC	oad JPG	V

Vide	90		1 per pa		✓
No 84	Finalized On 31/08/18 14:03	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Reinspection Photo	0	Thumbnail Load JPG	Prin
			0	Load JPG	V
85	31/08/18 14:03	Reinspection Photo	0	Load JPG	V
86	31/08/18 14:03	Reinspection Photo	0	Load JPG	✓
87	31/08/18 14:03	Reinspection Photo	6	Load JPG	<u>~</u>
88	31/08/18 14:03	Reinspection Photo	0	Load JPG	~
89	31/08/18 14:03	Reinspection Photo	6	Load JPG	∀
90	31/08/18 14:03	Reinspection Photo			-
91	31/08/18 14:04	Reinspection Photo	0	Load JPG	V
92	31/08/18 14:04	Reinspection Photo	0	Load JPG	V
93	31/08/18 14:04	Reinspection Photo	0	Load JPG	~
94	31/08/18 14:04	Reinspection Photo	0	Load JPG	~
95	31/08/18 14:04	Reinspection Photo	0	Load JPG	V
96	31/08/18 14:04	Reinspection Photo	0	Load JPG	~
97	31/08/18 14:04	Reinspection Photo	0	Load JPG	<u>~</u>
98	31/08/18 14:04	Reinspection Photo	0	Load JPG	~
99	31/08/18 14:04	Reinspection Photo	0	Load JPG	~
100	31/08/18 14:04	Reinspection Photo	0	Load JPG	~
101	31/08/18 14:04	Reinspection Photo	0	Load JPG	✓
102	31/08/18 14:04	Reinspection Photo	0	Load JPG	V
103	31/08/18 14:04	Reinspection Photo	0	Load JPG	₩.
104	31/08/18 14:04	Reinspection Photo	0	Load JPG	4
105	31/08/18 14:04	Reinspection Photo	0	Load JPG	V
106	31/08/18 14:04	Reinspection Photo	0	Load JPG	~
107	31/08/18 14:04	Reinspection Photo	0	Load JPG	V
108	31/08/18 14:04	Reinspection Photo	0	Load JPG	▼
109	31/08/18 14:04	Reinspection Photo	0	Load JPG	V
110	31/08/18 14:04	Reinspection Photo	0	Load JPG	V
111	31/08/18 14:04	Reinspection Photo	0	Load JPG	V
112	31/08/18 14:04	Reinspection Photo	0	Load JPG	V
113	31/08/18 14:04	Reinspection Photo	0	Load JPG	V
114	31/08/18 14:04	Reinspection Photo	0	Load JPG	V
115	31/08/18 14:04	Reinspection Photo	0	Load JPG	V
116	31/08/18 14:04	Reinspection Photo	0	Load JPG	V
117	31/08/18 14:04	Reinspection Photo	0	Load JPG	V
118	31/08/18 14:04	Reinspection Photo	0	Load JPG	V
	31/08/18 14:04	Reinspection Photo	0	Load JPG	V
120	07/09/18 07:37	Reinspection Photo	0	Load JPG	V
121	07/09/18 07:37	Reinspection Photo	0	Load JPG	V
	07/09/18 07:37	Reinspection Photo	0	Load JPG	-
123	07/09/18 07:37	Reinspection Photo	0	Load JPG	V
124	07/09/18 07:37	Reinspection Photo	0	Load JPG	-
125	07/09/18 07:37	Reinspection Photo	0	Load JPG	V
126	07/09/18 07:37	Reinspection Photo	0	Load JPG	V
127	07/09/18 07:37	Reinspection Photo	0	Load JPG	<u>-</u>
	07/09/18 07:37	Reinspection Photo	0	Load JPG	Z
		Reinspection Photo	0	Load JPG	<u>-</u>
III DIESS	07/09/18 07:37		0	Load JPG	2
130	07/09/18 07:37	Reinspection Photo	0		2
131	07/09/18 07:37	Reinspection Photo		Load JPG	
132	07/09/18 07:37	Reinspection Photo	0	Load JPG	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \

Vide	90		1 per	page 🗸	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
134	07/09/18 07:37	Reinspection Photo	0	Load JPG	✓
135	07/09/18 07:37	Reinspection Photo	0	Load JPG	✓
136	07/09/18 07:37	Reinspection Photo	0	Load JPG	✓
137	07/09/18 07:37	Reinspection Photo	0	Load JPG	✓
138	07/09/18 07:37	Reinspection Photo	Ð	Load JPG	✓
139	07/09/18 07:37	Reinspection Photo	0	Load JPG	✓
Doc	umentation		1 per	page 🔻	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	29/08/18 15:07	Email - PRI	0	Load PDF	
2	29/08/18 15:08	Notice to conduct PRI	0	Load PDF	
3	29/08/18 15:09	SKZ517J GIA Rpt From:SC - Reg. No: SMC4177C, Claimant: KARTHIK BALKRISHNAN NATARAJAN	0	Load PDF	
4	29/08/18 15:09	SLG4680G GIA Rpt From:SC - Reg. No: SMC4177C, Claimant: KARTHIK BALKRISHNAN NATARAJAN	Ð	Load PDF	
5	08/11/18 12:33	TP Survey Rpt part 1	0	Load PDF	
6	08/11/18 12:33	TP Survey Rpt part 2	0	Load PDF	
7	08/11/18 12:33	TP Survey Rpt part 3	0	Load PDF	
8	08/11/18 12:33	TP Survey Rpt part 4	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/01/19 11:00	Colour Photo1	0	Load PDF	
2	14/01/19 11:00	Colour Photo2	Ð	Load PDF	
3	14/01/19 11:01	PRS Invoice	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/MSG18015880/UTBE2-1

Date:

14/01/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

A29087620AVW

Claimant Vehicle SLG4680G

Insured Vehicle No:

SMC4177C

No: Date of Loss:

26/08/2018

Nature of Claim:

TP

Claim No: 568673

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLG4680G

Make & Model:

TOYOTA HARRIER, 2.0 Premium (A)

Engine No:

3ZRB778309

Reg. Date: Colour:

30/09/2016 (Man. Year: 2016)

Chassis No: Odometer:

ZSU600077585 36018 km

Engine Capacity:

1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

235/55 R18

Rear Tyre Size:

235/55 R18

Front Left Side:

Bridgestone 7 mm

Rear Left Side: Rear Right Side: Bridgestone 7 mm Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,881.60	6,610.01	5,271.59	44.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,330.00	2,190.00	2,140.00	49.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,211.60	8,800.01	7,411.59	45.72
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	16,211.60	7,000.00	9,211.60	56.82
+ GST 7.00/7.00% (S\$)	1,134.81	490.00	644.81	56.82
Nett Amount (S\$)	17,346.41	7,490.00	9,856.41	56.82

INSPECTION

Date of Assignment:

29/08/2018

Date Inspected:

30/08/2018 Inspected At:

Z-one Automotive Pte Ltd - Kb (HQ)

1 Kaki Bukit Avenue 6, #01-87/85 Autobay

@ Kaki Bukit Singapore 417883

Estimated Period of Repair:

6.0 days

Adjuster: MARCUS CHUA Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jan 2019)

Parts: M1-SUV TOYOTA HARRIER 2.0 Premium (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLG4680G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

Candition

Danairar'a

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	172.40 FL	*172.40 FL
2	1		*REAR TAILGATE	Bent / Dented	1,712.05 FL	*1,712.05 FL
3	1		*REAR TAILGATE INNER BOARD	Deformed / Torn	781.90 FL	*781.90 FL
4	2		*REAR TAILGATE LAMPS	Not Necessary	748.90 FL	*- FL
5	1		*REAR TAILGATE LOCK	Dented	381.75 FL	*381.70 FL
6	1		*REAR TAILGATE LOCK GARNISH	Damaged	42.00 FL	*42.00 FL
7	1		*REAR TAILGATE RUBBER	Twisted	289.10 FL	*289.10 FL
8	1		*REAR TAILGATE HARRIER EMBLEM	Necessary	77.00 FL	*77.00 FL
9	2		*REAR TAILLAMPS	Cracked	1,123.20 FL	*1,123.20 FL
10	1		*REAR END PANEL	Dented	781.10 FL	*781.10 FL
11	1		*REAR BUMPER	Dented	1,718.00 FL	*1,381.20 FL
12	1		*REAR BUMPER LOWER	Distorted	369.10 FL	*369.10 FL
13	1		*SET REAR BUMPER CLIP	Necessary	129.00 FL	*60.00 FL
14	1		*REAR BUMPER INNER SPONGE	Torn	185.25 FL	*185.20 FL
15	2		*REAR BUMPER REFLECTORS	Not Necessary	166.20 FL	*- FL
16	1		*REAR N/S SPARE TYRE SIDE TRAY	Cracked	568.70 FL	*568.70 FL
17	1		*REAR O/S SPARE TYRE SIDE TRAY	Cracked	568.70 FL	*568.70 FL
18	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
19	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
20	1		*SET REAR AMPLIFIER	Serviceable	3,900.00 FS	*-FS
21	1		*REAR END PANEL INNER GARNISH	Not Necessary	374.45 FL	*-FL
F=Fr	anchise	part. S=Spcf	Nett. L=ListItemDisc.	-		
				Sub Total (S\$)	14,428.80	8,733.35
			- List Item Discount on L	Items 25.00/25.00% (S\$)	2,547.20	2,123.34
				Total Parts (S\$)	11,881.60	6,610.01
				_		

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING	New	50.00	30.00
2	TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIRS.	New	150.00	80.00
3	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	150.00	50.00
4	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	200.00	120.00
5	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WIELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,500.00	600.00
6	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	1,500.00	950.00
7	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	180.00	60.00
8	TO REMOVE AND REFIT REAR AMPLIFIER	New	600.00	300.00
	Gross Labou	r Cost (S\$)	4,330.00	2,190.00

< END OF ESTIMATES >