

INS. CASE OWNER:

CC

F, ALH, 2014896, Kpa3-1

LKK:

IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

Normal Repair

TP Paper Summary

\$150.00

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: account@lkkauto.com;admin-c@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC7/AIG12024896/KG2T2W2
Date: 17/01/2013REFERENCE

Handling Insurer:	Chartis Singapore Insurance Pte Ltd	Policy No:	2100287732
Claimant Vehicle No :	SJZ592C	Insured Vehicle No :	SKE563K
Date of Loss:	20/12/2012	Nature of Claim:	TP
			Claim No: 800625735

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ592C	Engine No:	Z6327910
Make & Model:	MAZDA 3, 1.6 (A)	Chassis No:	JM6BK106100147232
Reg. Date:	20/04/2005 (Man. Year: 2005)	Odometer:	100194 km
Colour:	Metallic Black		
Engine Capacity:	1598 cc		
Market Value:	N/A		
Sum Insured (S\$):	Market Value		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	26/12/2012	
Date Inspected:	26/12/2012	Inspected At:
Est Repair Period:	4	Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721

Adjuster: KENNETH KONG

Manager: ASHLEY CHONG CHOO LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

LKK Auto Consultants Pte Ltd/SJZ592C/17/01/2013 13:23

< END OF ESTIMATES >

AUTO PERFORMANCE APPRAISAL

APA

VEHICLE SURVEY REPORTS																																
<p>Amir Iskandar Jaapar C/O Guan Motor Works 176 Sin Ming Drive Sin Ming AutoCare #02-03 Singapore 575721</p>																																
1	<p>Reference Job Reference No : 12/000106 Claim No : - Claim Type : Third Party Accident Date : 20/12/2012 Survey Date : 28/12/2012 Survey Report Date : 08/01/2013</p>																															
2	<p>Particulars Of Vehicle Vehicle Registration No : SJZ592C Make & Model : Mazda 3 Vehicle Registration Date : 20/04/2005 Chassis No : JM6BK106100147232 Engine No : Blocked Colour : Black</p>																															
3	<p>Condition Of Vehicle And Tyres</p> <table border="1"> <thead> <tr> <th><u>Mileage (KM)</u></th> <th><u>Brakes</u></th> <th><u>Steering</u></th> <th><u>Modification</u></th> </tr> </thead> <tbody> <tr> <td>100194</td> <td>Serviceable</td> <td>Serviceable</td> <td>None</td> </tr> </tbody> </table> <table border="1"> <thead> <tr> <th><u>Tyres</u></th> <th><u>Make</u></th> <th><u>Size</u></th> <th><u>Balance (MM)</u></th> </tr> </thead> <tbody> <tr> <td>Front RHS</td> <td>Michelin</td> <td>205/55R16</td> <td>5</td> </tr> <tr> <td>Front LHS</td> <td>Michelin</td> <td>205/55R16</td> <td>5</td> </tr> <tr> <td>Rear RHS</td> <td>Michelin</td> <td>205/55R16</td> <td>6</td> </tr> <tr> <td>Rear LHS</td> <td>Michelin</td> <td>205/55R16</td> <td>6</td> </tr> </tbody> </table>				<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>	100194	Serviceable	Serviceable	None	<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>	Front RHS	Michelin	205/55R16	5	Front LHS	Michelin	205/55R16	5	Rear RHS	Michelin	205/55R16	6	Rear LHS	Michelin	205/55R16	6
<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>																													
100194	Serviceable	Serviceable	None																													
<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>																													
Front RHS	Michelin	205/55R16	5																													
Front LHS	Michelin	205/55R16	5																													
Rear RHS	Michelin	205/55R16	6																													
Rear LHS	Michelin	205/55R16	6																													
4	<p>Description Of Damages The vehicle sustained damages at rear portion (For information of damages please refer to Parts/Labour/Photographs attached)</p>																															
5	<p>Instruction This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.</p>																															

AUTO PERFORMANCE APPRAISAL

Vehicle Assessment Reports

Annex A

Ref No : 12/000106

Damage And Repair Cost Adjustment

S/No	Qty	Parts Description	Comments/condition	Workshop Estimate (\$)	Our Assessment (\$)
			<u>List Items</u>		
1	1	Rear bumper	Deformed	832.00	832.00
2	2	Rear bumper reflector	Broken/cut <i>n/surx</i>	126.00	126.00 <i>o/s</i>
3	2	Rear bumper side retainer	Broken/necessary	108.00	108.00
4	1	Rear bumper reinforcement	Bent	397.60	397.60
5	1 set	Rear number plate lamp	Broken/cracked	234.60	234.60
6	1	Rear boot lid	Badly dented	972.00	972.00
7	2	Rear boot reflector	RH broken/LH reuse	377.60	188.80 <i>sn</i> X
8	1	Rear boot centre logo	Necessary	54.60	54.60
9	1	Rear boot "MAZDA" emblem	Necessary	25.20	25.20
10	1	Rear boot "3" emblem	Necessary	19.60	19.60
11	1	Rear boot inner trim	Reuse	133.30	-
12	1 set	Rear boot inner trim clips	Necessary	50.00	50.00
13	1	Rear boot top lock	Bent	221.60	221.60
14	1	Rear boot lower lock catch	Reuse	74.90	-
15	1	Rear boot weatherstrip	Cut	97.70	97.70 <i>50% 48.85</i>
16	2	Rear taillamp	Broken/cut	683.40	683.40
17	1	Rear end panel	Buckled	452.00	452.00
18	1	Rear end panel top garnish	Deformed	179.80	179.80
19	1	Rear spare tyre top cover	Reuse <i>n/v</i>	149.00	-
20	2	Rear fender under shield	RH deformed/LH reuse	132.00	66.00 <i>sn</i> X
21	1 set	Rear fender under shield clips	Broken/necessary	30.00	30.00
				5,350.90	4,738.90
Less discount 20%				1,070.18	947.78
Total :				4,280.72	3,791.12
			<u>Special Nett Items</u>		
22	1	Rear number plate	Bent/broken	50.00	50.00 <i>45% sn</i>
23	1 set	Reverse sensors	Malfunction <i>DM</i>	250.00	250.00 <i>20% sn</i>
Total :				300.00	300.00
Total Spare Parts :				4,580.72	4,091.12

AUTO PERFORMANCE APPRAISAL

Vehicle Assessment Reports

Annex B

Ref No : 12/000106

Damage And Repair Cost Adjustment

<u>Items</u>	<u>Job Description</u>	<u>Workshop Estimate (\$)</u>	<u>Adjusted Costs (\$)</u>
1	To remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	1,200.00	900.00 <i>600</i>
2	To putty and respray painting on affected areas.	1,000.00	900.00 <i>800</i>
3	To check lightings and wirings.	50.00	30.00 <i>20</i>
4	To remove, refix reverse sensor.	80.00	50.00
5	To remove, refix rear upholstery, garnish and attachments.	150.00	120.00 <i>60</i>
6	To remove, refix boot lid fittings to facilitate repair.	80.00	50.00
7	To remove, refix rear exhaust silencer for repair.	150.00	120.00 <i>60</i>
8	To apply undersealing.	120.00	90.00 <i>60</i>

Total Labour :	2,830.00	2,260.00
----------------	----------	----------

Total Spare Parts :	4,580.72	4,091.12
---------------------	----------	----------

Total Labour :	2,830.00	2,260.00
----------------	----------	----------

Total Repair Costs :	7,410.72	6,351.12
----------------------	----------	----------

Assessor's Recommendation

Repairer Estimate :	7,410.72
---------------------	----------

Our Adjustment :	6,351.12
------------------	----------

Remarks

The repairer has agreed to undertake the repair on a lump sum basis of \$5,100.00, with a repair period of 6 working days.

Surveyed By:



Lek Boon Hwee
Automobile Appraiser

Mei Kwan (LKKAuto)

From: Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>
Sent: Thursday, 10 January, 2019 5:36 PM
To: Mei Kwan (LKKAuto)
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: RE: Paper Adjustment for 800625735

Follow Up Flag: Follow up
Flag Status: Completed

Categories: HMK

Dear Mei Kwan,

I have requested the coloured photos from TP.

Will revert once they have given us the copy.

Thank you,

Best Regards,

Bernard Ler
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946

Bernard-JQ.Ler@aig.com | www.aig.com.sg

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: 10 January 2019 5:35 PM
To: Ler, Bernard-JQ
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: RE: Paper Adjustment for 800625735

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Bernard,

We refer to our tele-conversation a while ago.

Please forward us the LOD with colour copy to enable us to review the matter.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC7/AIG12024896/Kpa3q2-1	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 11-01-2019	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKE 563K	Veh. Inspected	SJZ 592C
Policy No.	2100287732	Coverage (\$)	0.00
Claim No.	800625735	Excess (\$)	0.00
Assign From		Assign Date	10/01/2019
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 3 1.6 (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	JM6BK106100147232	Colour	METALLIC BLACK
Odometer	100194	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16		mm
L/H Front Tyre	205/55 R16		mm
R/H Rear Tyre	205/55 R16		mm
L/H Rear Tyre	205/55 R16		mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/12/2012	Inspection Date	26/12/2012
Survey held at	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 592C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	832.00	832.00
2	REAR BUMPER REFLECTOR	O/S BROKEN / CUT / N/S SERVICEABLE	126.00	63.00
2	REAR BUMPER SIDE RETAINER	BROKEN / NECESSARY	108.00	108.00
1	REAR BUMPER REINFORCEMENT	BENT	397.60	397.60
1	SET REAR BUMPER PLATE LAMP	BROKEN / CRACKED	234.60	234.60
1	REAR BOOT LID	BADLY DENTED	972.00	972.00
2	REAR BOOT REFLECTOR	SERVICEABLE	377.60	-
1	REAR BOOT CENTRE LOGO	NECESSARY	54.60	54.60
1	REAR BOOT 'MAZDA' EMBLEM	NECESSARY	25.20	25.20
1	REAR BOOT '3' EMBLEM	NECESSARY	19.60	19.60
1	REAR BOOT INNER TRIM	NOT NECESSARY	133.30	-
1	SET REAR BOOT INNER TRIM CLIPS	NECESSARY	50.00	50.00
1	REAR BOOT TOP LOCK	BENT	221.60	221.60
1	REAR BOOT LOWER LOCK CATCH	NOT NECESSARY	74.90	-
2	REAR TAILLAMP	BROKEN / CUT	683.40	683.40
1	REAR END PANEL	BUCKLED	452.00	452.00
1	REAR EN DPANEL TOP GARNISH	DEFORMED	179.80	179.80
1	REAR SPARE TYRE TOP COVER	NOT NECESSARY	149.00	-
2	REAR FENDER UNDER SHIELD	SERVICEABLE	132.00	-
1	SET REAR FENDER UNDER SHIELD CLIPS	BROKEN / NECESSARY	30.00	30.00
	LESS 20% DISCOUNT		-1,050.64	-864.68
			4,202.56	3,458.72
1	REAR BOOT WEATHERSTRIP (50%) (SN)	CUT	97.70	48.85
	LESS 20% DISCOUNT		-19.54	-
			78.16	48.85

Report Ref No. CC7/AIG12024896/Kpa3q2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	BENT / BROKEN	50.00	45.00
1	SET REVERSE SENSORS (SN)	DAMAGED	250.00	200.00
			300.00	245.00
	<u>LABOUR</u>			
	TO REMOVE, CUT OUT DAMAGED PORTION ,JACK OUT ,STRAIGHTEN,PANEL BEATING ,WELDING ,ALIGN AND RENEW REPLACED PARTS.		1,200.00	600.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS.		1,000.00	600.00
	TO CHECK LIGHTINGS AND WIRINGS.		50.00	20.00
	TO REMOVE,REFIX REVERSE SENSOR .		80.00	50.00
	TO REMOVE,REFIX REAR UPHOLSTERY ,GARNISH AND ATTACHMENTS.		150.00	60.00
	TO REMOVE,REFIX BOOT LID FITTINGS TO FACILITATE REPAIR.		80.00	50.00
	TO REMOVE,REFIX REAR EXHAUST SILENCER FOR REPAIR.		150.00	60.00
	TO APPLY UNDERSEALING.		120.00	60.00
			2,830.00	1,500.00
GRAND TOTAL			7,410.72	5,252.57
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,200.00

Report Ref No. CC7/AIG12024896/Kpa3q2-1

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.