	o) thong Boarden of CT Detertime 11/1196 9-49 om
OD TP W	bst: Bill to: Bill to:
To Inspect V at Workshop	chicle No: Sta 68499 Insured: GY 17711  Tel: 6462 7018
	100 311 FILES (DIVE # 02-20)
Policy No:_	Claim No:
Sum Insured	
	Excess;
Make of Veh (Client's Recor	D.O.A. 08 01 2019
(Client's Recor CA / REV Date/Time:	D.O.A. OS OI 2019  / REP. / REV 24 HRS (WP)  10.30000011/11/19 Person Contacted: Shuman Vehicle IN OUT
(Client's Recor CÅ / REV	D.O.A. 08/01/2019  / REP. / REV 24 HRS (WP)  10.30000011/11/19 Person Contacted: Shuman Vehicle In Journ  Action/Instruction ( ) Estimate
(Client's Recor CA / REV Date/Time:	D.O.A. OS OI 2019  / REP. / REV 24 HRS (WP)  10.30000011/11/19 Person Contacted: Shuman Vehicle IN OUT

# ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING								
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	10 Jan 2019 15:23	10 Jan 2019 15:43	11 Jan 2019 09:49				New Assignment Cancel Case	
101000000	Sendback Est	5\$4,135.64	Assign				Cancer Case	

Ma	ain 📗	Reference		Claim Details		Document	5	Show All
CLAIM SUB	FOLDER DETAILS							
Insured:	NIL, Co. Reg. N	o.: 0						
Main Claimant:	BUKIT BATOK D	RIVING CENTRE L	TD, Co. Reg.	No.: 198801155R				
Vehicle Reg. No.:	SLA6849G			Date of Loss:		9 16:00 - :59 s and <b>28</b> Days Fr	om LTA Reg Date (	Man Yr)]
Claim Type:	ТР			Policy/Cover Note No.:				9 I IAVI
Vehicle Reg. No. (Insured):	GY1771L			Policy No. (Claimant):				
				Excess:	S\$0.00			
Repairer:	K Kim Hin Auto	Pte Ltd (HQ) 160 S	Sin Ming Drive #	02-20, Sin Ming Aut	oCity, 57572	22 Sin Ming - Tel:	64527018	
Handling Insurer:	China Taiping I	nsurance (Singapo	ore) Pte. Ltd. (	HQ) - Tel: 6389 611	1 [Handle	ed by Chong Boo	n Sen]	
Claimant's Insurer:		nsurance Co-opera		1000				
Adjuster:	LKK Auto Consu	Itants Pte Ltd (HQ	) - Tel: 6256-35	661 [Final Rpt	due 22/01	/2019]		
ASSOCIATE	D MAIL RECEIVE	D		40		v	iew All   Compose	Case M
There are no	mall for this case.					_		
ALL ASSOC	IATED TASKS				View All	Search Tasks	Create New Task	Comple
Due Date No results.	Priority Typ	e Task Group	Subject 1	Handler Assign	ned By	Completed On	Created On	Don

# ...CLAIM SUBFOLDER...(Pending for Approval)

Case	Notified	Estimates	Est Submitted	Adj Assigner	Ins Auth	ed	Status		
Main	10 Jan 2019 15:23		10 Jan 2019 15:43 <b>\$\$4,135.64</b>				Pending for Approval		
	Main		Reference	Clain	Details		Documents	Show All	
CLAIM S	BFOLDER DE	TAILS			CATTOR OF SHIPLE STATE	-			
Insured:	NIL, Co.	Reg. No.: 0							
Main Claimant:	BUKIT BA	TOK DRIVING	CENTRE LTD, Co.	Reg. No.: 198	301155R				
Vehide Re No.:	SLA684	9G		Da	te of Loss:	08/01/2019 16:00 - :59 [33 Months and 28 Days From LTA Reg Date (Man Yr)			
Claim Type	: TP			licy/Cover te No.:					
Vehicle Re No. (Insured):	GY1771L	GY1771L			licy No. laimant):	0073346186-15			
Repairer:	K Kim Hir	Auto Pte Ltd	(HQ) PROFILE 160	Sin Ming Driv	e #02-20, s	Sin Ming	AutoCity, 575722 Sin Ming -	Tel: 64527018	
Handling Insurer:	China Tai	ping Insuranc	e (Singapore) Pte. l	Ltd. (HQ) - Tel	: 6389 611	1			
Claimant's Insurer:	NTUC Inc	ome Insuranc	e Co-operative Ltd (	(HQ) - Tel:					
ASSOCIA	TED MAIL RE	CEIVED					View All	Compose Case Mai	
	no mail for this	6350							

### Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Tuesday, 9 April 2019 11:11 AM

To:

survey@kkimhin.com.sg; SUR

Subject:

RE: SLA6849G TP-CHINA FINALISATION

Dear Meng Huat,

WITHOUT PREJUDICE

Confirmed P/P=\$2,883.68

4 working days.

Kindly send Final invoice and all supporting documents to CHINA TAIPING

Best Regards, Veron Chen | Case Handler LKK Auto Consultants Pte Ltd Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

----Original Message-----

From: survey@kkimhin.com.sg <survey@kkimhin.com.sg>

Sent: Sunday, 7 April 2019 11:14 AM

To: Veron Chen (LKKAuto) < veronchen@lkkauto.com>

Subject: SLA6849G TP-CHINA FINALISATION

Hi Veron,

Enclosed your attention. P/P=\$2,883.68 4 working days. Please confirm. Thank you.

Regard Meng Huat K.kim Hin Auto

### > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: Vehicle Details	1155R
Vehicle No.:	SLA6849G
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 VTIR M/T ABS D/AIRBAG 2WD
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	L15B31010005
Chassis No.:	JHMGK5750GX202100
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$15,895.00
Original Registration Date:	11 Mar 2016
First Registration Date:	11 Mar 2016
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$15,895.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Mar 2026
PARF Rebate Amount: Intended COE Rebate Details	\$11,921.00
COE Expiry Date:	10 Mar 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,002.00
COE Rebate Amount:	\$32,263.00
Total Rebate Amount:	\$44,184.00

The information contained herein is correct as at 09 Jan 2019

CO. REG. NO: 199402370D GST NO: M2-0123250-3

# AUTO PTE LTD

# 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21, Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895 Email: service@kkimhin.com.sg

TP INSURER:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

NIL

Singapore

Claimant Insurer:

NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:

Policy No:

THIRD PARTY

Ref. No:

Rei. No.

Date of Loss:

Vehicle Reg. No.:

**SLA6849G** 

Driveable?

Party At Fault:

UNKNOWN

Driver (TP):

LIM SI YI

Make/Model:

HONDA JAZZ, 1.5 (M)

Vehicle Reg. Date:

11/03/2016

08/01/2019

Vehicle Colour:

SILVER L15B31010005

Chassis No:

JHMGK5750GX202100

Engine No: Odometer:

0 KM

Paint Type:

Total Loss?

Est. Duration of Repair

(day)

NO

& 4day

Not Notharked Resonry B4 paint

Description of

PLEASE REFER TO SKETCH PLAN.

Accident/Loss

Remarks:

VEHICLE IS IN, KINDLY ARRANGE FOR SURVEY AND ADVISE LIABILITY. THANK

YOU.

Present Location:

K KIM HIN AUTO PTE LTD (HQ)

COST OF CLAIMS		Amount
Parts		2,785.64
Miscellaneous Items		0.00
Labour		1,350.00
Paintwork Labour		0.00
Towing		0.00
	Gross Total (S\$)	4,135.64
	+ GST 7.00% (S\$)	289.49
	Nett Amount (S\$)	4,425.13

This claim is handled by: WONG SHU MAN

#### REPAIR DETAILS

#### Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 10 Jan 2019)

Parts:

HONDA JAZZ 1.5 (M) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Validity:

Print Code: (Unsubmitted, no print-code for SLA6849G)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%	Disc	%Dep	Amount
1	1		*REAR BUMPER	Bu	0.00	0.00	*492.70 F ~
2	10		*REAR BUMPER CLIPS	Ne	0.00	0.00	
3	1		*O/S REAR BUMPER SIDE RETAINER	DIT	0.00	0.00	
4	1		*O/S REAR BUMPER SIDE GARNISH	SVC	0.00	0.00	*32.90 F
5	1		*TAILGATE	R	0.00	0.00	*830.60F L
6	1		*TAILGATE WINDSCREEN MOULDING-TOP	na	0.00	0.00	*38.00 F ~
7	1		*TAILGATE WINDSCREEN MOULDING-LOWER	M	0.00	0.00	*48.00 F
8	2		*TAILGATE WINDSCREEN MOULDING-SIDE (LH/RH)	m	0.00	0.00	*76.00 F
9	1		*TAILGATE OUTER CHROME	SVC	0.00	0.00	200.90 F
10	1		*TAILGATE LOGO	na			*24.00 F
11	1		*TAILGATE JAZZ EMBLEM	M			*38.00 F
12	2		*TAILGATE LAMP (LH/RH)	su.	0.00	0.0	*280.60 F $\lambda$
13	1		*TAILGATE WEATHERSTRIP		0.00		
14	2		*TAILLAMP ASSY (LH/RH)	dising			*447.80 F 4
15	1		*O/S TAILLAMP PANEL	59	0.00	1 0.0	76 : ::::::::::::::::::::::::::::::::::
16	1		*REAR NUMBER PLATE	V.		0.0	
17	1		*REAR BUMPER L BRACKET	P		0.75	35.00 FS
18	1		*REAR BUMPER L PLATE		7 0		*80.00 FS
19	2		*TAILGATE 4 AND 5 STICKER	M	2 0	0.0	20.00 FS
20	1		*TAILGATE THANK YOU FOR YOUR PATIENCE STICKER	M		0.0	
21	1		*TAILGATE WINDSCREEN SEALANT	Ne		0.0	
22	1		*TAILGATE WINDSCREEN DAMPING SEAL	N	~ 0	0.0	0 *20.00 FS
F=Fr	anchise	part. S=SpcN	Nett.				5452727356
				ub Total (S\$)			3,385.80
			- Add. Disc. on L,N Items	20.00% (S\$)			600.16
			Tot	al Parts (S\$)			2,785.64

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary lam(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

	200				
-sti	mat	es	on	ar	our

Particulars	Lab.Type	,	Amount
our Items			400
TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New		500.00
TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	New		120.00
TO TRANSFER TAILGATES FITTINGS.	New		80.00 6
TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	5001	600.00
TO FOCUS TAILLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.	New	201	50.00
Gross Labou	ır Cost (S\$)		1,350.00
	TO RENEW AFFECTED PARTS.  TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.  TO TRANSFER TAILGATES FITTINGS.  TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.  TO FOCUS TAILLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND New TO RENEW AFFECTED PARTS.  TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST. New TO TRANSFER TAILGATES FITTINGS.  New TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND New TO RENEW AFFECTED PARTS.  TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST. New TO TRANSFER TAILGATES FITTINGS.  TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.  TO FOCUS TAILLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.  New 202

Report was unsubmitted during this print-out. Generated using **Merimen e-Claims IEAS** 

< END OF ESTIMATES >

CO. REG. NO: 199402370D GST NO: M2-0123250-3

# AUTO PTE LTD

# 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21, Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895 Email: service@kkimhin.com.sg

TP INSURER:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

NIL

Singapore

Claimant Insurer:

NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM Ref. No: THIRD PARTY Claim Type: Date of Loss: 08/01/2019 Policy No: Driveable? SLA6849G Vehicle Reg. No.: UNKNOWN Party At Fault: Driver (TP): LIM SI YI Vehicle Reg. Date: 11/03/2016 HONDA JAZZ, 1.5 (M) Make/Model: SILVER Vehicle Colour: JHMGK5750GX202100 Chassis No: L15B31010005 Engine No: Not Motorial Resoner B4 paint Odometer: 0 KM Paint Type: Total Loss? 8 4day Est. Duration of Repair (day) PLEASE REFER TO SKETCH PLAN. Description of Accident/Loss VEHICLE IS IN, KINDLY ARRANGE FOR SURVEY AND ADVISE LIABILITY. THANK

Remarks: YOU.

K KIM HIN AUTO PTE LTD (HQ) Present Location:

COST OF CLAIMS		Amount
Parts		2,785.64
Miscellaneous Items		0.00
Labour		1,350.00
Paintwork Labour		0.00
Towing	a call a succession and the succession of the su	0.00
10	Gross Total (S\$)	4,135.64
	+ GST 7.00% (S\$)	289.49
	Nett Amount (S\$)	4,425.13

This claim is handled by: WONG SHU MAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR D	ETAILS			
Reference	се			
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2019)		
Parts:	144	HONDA JAZZ 1.5 (M) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted,	no print-code for SLA6849G)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info:	The state of the s	not in reference catalogue are prefixed with an asterisk *.		

	imates on Qty Part No.	Particulars	%!	Disc	%Depr	Amount
140.	City Fair No.	Turious Company of the Company of th	Bu			
1	1	*REAR BUMPER		0.00	0.00	*492.70F
2	10	*REAR BUMPER CLIPS		0.00	0.00	*42.00 F
3	1	*O/S REAR BUMPER SIDE RETAINER		0.00	0.00	*28.90 F <u>~</u>
4	1	*O/S REAR BUMPER SIDE GARNISH	Sn		0.00	-32.90 F
5	1	*TAILGATE		0.00	0.00	*830.60 F
6	1	*TAILGATE WINDSCREEN MOULDING-TOP	na	0.00	0.00	*38.00F -
7	1	*TAILGATE WINDSCREEN MOULDING-LOWER	0.000 0.000	0.00	0.00	*48.00F ~
8	2	*TAILGATE WINDSCREEN MOULDING-SIDE (LH/RH)		0.00	0.00	*76.00F ~
9	1	*TAILGATE OUTER CHROME	m		0.00	*200.00 F -7
10	1	*TAILGATE LOGO		0.00	0.00	*24.00F -
11	1	*TAILGATE JAZZ EMBLEM	M		0.00	*38.00 F
12	2	*TAILGATE LAMP (LH/RH)	n	0.00	0.00	.±280:60 F →
13	1	*TAILGATE WEATHERSTRIP	h	0.00	0.00	*100.00F
14	2	*TAILLAMP ASSY (LH/RH)	dising			25.9647.80F-L
15	1	*O/S TAILLAMP PANEL		0.00	0.00	-320.40F X
16	1	*REAR NUMBER PLATE	υ	. 0	0.00	
17	1	*REAR BUMPER L BRACKET		70	0.00	35.00FS
18	1	*REAR BUMPER L PLATE		7 0	0.00	'80.00FS
19	2	*TAILGATE 4 AND 5 STICKER	M	. 0	0.00	*20.00FS
20	1	*TAILGATE THANK YOU FOR YOUR PATIENCE STICKER	M	0	0.00	*150.00 FS L
21	1	"TAILGATE WINDSCREEN SEALANT	M		0.00	*40.00 FS c
22	1	*TAILGATE WINDSCREEN DAMPING SEAL	Ne	. 0	0.00	*20.00 FS _
F=Fra	nchise part. S=Spc)					2 225 22
			tal (S\$)			3,385.80
		- Add. Disc. on L,N Items 20.0	0% (5\$)			600.16
		Total Pa	rts (S\$)			2,785.64

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

\$1,842-10-Put -202 \$1,473.68 \$ 310-00-S(1) \$1,100.00-Luh

# Estimates on Miscellaneous Items There are no new miscellaneous Items selected.

	timates on Labour Particulars	Lab.Type	89	Amount
			***************************************	400
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New		500.00
2	TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	New	70.000 I (100.0047479)	120.00
3 4	TO TRANSFER TAILGATES FITTINGS. TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New New	5001	80.00 6 600.00
5	TO FOCUS TAILLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.	New	204	50.00
	Gross Labor	ır Cost (S\$)	10	1,350.00
	Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS			
	< END OF ESTIMATES >		W. V. C.	

### LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI19000659/KVD3N2

Date:

12/04/2019

REFERENCE

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

Claimant

SLA6849G

GY1771L

Vehicle No: Date of Loss:

08/01/2019

Nature of Claim:

Insured Vehicle No:

TP

Claim No: N/A

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SLA6849G

Make & Model:

HONDA JAZZ, 1.5 (M)

Engine No:

L15B31010005

Reg. Date:

11/03/2016 (Man. Year: 2016)

Chassis No:

JHMGK5750GX202100

Colour:

Metallic Silver 1498 cc

Odometer:

100010 km

Engine Capacity:

Market Value/New Car

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

185/55R16

Rear Tyre Size:

185/55R16

Front Left Side:

Dunlop 7 mm

Rear Left Side:

Dunlop 7 mm

Dunlop 7 mm

Rear Right Side:

Front Right Side:

Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts	Repairer's 2,785.64	Adjuster's 1,783.68	1,001.96	Diff % 35.97
Miscellaneous Items	0.00	0.00	0.00 250.00	18.52
Labour Paintwork Labour	1,350.00 0.00	1,100.00 0.00	0.00	10.52
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,135.64	2,883.68	1,251.96	30.27
+ GST 7.00/7.00% (S\$)	289.49	201.86	87.63	30.27
Nett Amount (S\$)	4,425.13	3,085.54	1,339.59	30.27

INSPECTION

Date of Assignment:

11/01/2019 Present Location:

K Kim Hin Auto Pte Ltd (HQ)

Date Inspected:

11/01/2019 Inspected At:

K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming

AutoCity

Singapore 575722

Estimated Period of Repair:

4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

Referen	ce				
Part Source: MRM-SG		Version: 1.0 (Last Synchronised: 12 Apr 2019)			
Parts:	144	HONDA JAZZ 1.5 (M) (Catalogue:Merimen Singapore 1.0)			
Labour:	Repairer's	(Price-denominated Standard List)			
Print Code:	e: (Unsubmitted, no print-code for SLA6849G)				
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page				
Further Info	: Items/values n	ot in reference catalogue are prefixed with an asterisk *.			

# Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	492.70 F	*492.70 F
2	10		*REAR BUMPER CLIPS	Necessary	42.00 F	*42.00 F
3	1		*O/S REAR BUMPER SIDE RETAINER	Distorted	28.90 F	*28.90 F
4	1		*O/S REAR BUMPER SIDE GARNISH	Serviceable	32.90 F	*-F
5	1		*TAILGATE	Bent	830.60 F	*830.60 F
6	1		*TAILGATE WINDSCREEN MOULDING-TOP	Necessary	38.00 F	*38.00 F
7	1		*TAILGATE WINDSCREEN MOULDING-LOWER	Necessary	48.00 F	*48.00 F
8	2		*TAILGATE WINDSCREEN MOULDING-SIDE (LH/RH)	Necessary	76.00 F	*76.00 F
9	1		*TAILGATE OUTER CHROME	Serviceable	200.90 F	*- F
10	1		*TAILGATE LOGO	Necessary	24.00 F	*24.00 F
11	1		*TAILGATE JAZZ EMBLEM	Necessary	38.00 F	*38.00 F
12	2		*TAILGATE LAMP (LH/RH)	Serviceable	280.60 F	*-F
13	1		*TAILGATE WEATHERSTRIP	Serviceable	100.00 F	*-F
14	1		*TAILLAMP ASSY (LH/RH)	O/s Cracked	447.80 F	*223.90 F
15	1		*O/S TAILLAMP PANEL	Repair	320.40 F	*- F
16	1		*REAR NUMBER PLATE	Serviceable	40.00 FS	*- FS
17	1		*REAR BUMPER L BRACKET	Repair	35.00 FS	*-FS
18	1		*REAR BUMPER L PLATE	Missing	80.00 FS	*80.00 FS
19	2		*TAILGATE 4 AND 5 STICKER	Necessary	20.00 FS	*20.00 FS
20	1		*TAILGATE THANK YOU FOR YOUR PATIENCE STICKER	Necessary	150.00 FS	*150.00 FS
21	1		*TAILGATE WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
22	1		*TAILGATE WINDSCREEN DAMPING SEAL	Necessary	20.00 FS	*20.00 FS
F=Fr	anchise	part. S=S	SpcNett.	Sub Total (S\$	3,385.80	2,152.10
			- Add. Disc. on L,N Items 20		이 그 그는 그 없었다면 없어 없어졌다.	368.42
				Total Parts (S\$	) 2,785.64	1,783.68

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	500.00	400.00
2	TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	New	120.00	120.00
3	TO TRANSFER TAILGATES FITTINGS.	New	80.00	60.00
4	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	600.00	500.00
5	TO FOCUS TAILLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.	New	50.00	20.00
	Gross Labo	our Cost (S\$)	1,350.00	1,100.00
	Report was unsubmitted du	ring this print-out.		

< END OF ESTIMATES >