

ASS. REC. BY:

REF:

CS/MSG19000662/ Usd3 1/2

Instruction:

Survey of
Menmen

Marius

ASSIGNMENT (Office)

From (Person):

Chhia Nyuk Pui

of

MSG

Date/Time: 11/11/19 @ 9:43am

Estimated Cost:

Bill to:

CD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

PC 1893C

Insured:

SJS 9715T

at Workshop in/s

Think One

Tel:

91288488

of

No-18 De fu Ave 2

Policy No:

29032696TMC

Claim No:

581599

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 04/01/2019

CA / REV / REP. / REV 24 HRS

lup!

H.O.D. Endorsement:

Date/Time:

10:21am @ 11/11/19

Person Contacted:

Kern

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

PC1893C-X

SJS 9715T-X

15/01/19

@ 10:48 a.m. revised to IA, Chhia Nyuk Pui via memos.

(08/11/13) wef

ASS. REC. BY: MARIS

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: PC1893at Workshop m/s Thi one

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: L Consistent? : Yes or NoEst. Repairs: 6 days Res.: Yes or NoLum Sum: 70 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LIA 31391

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: PC1893CYr Regn: 813

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CMMake: Toyota Hiace c.c. 2800Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 340054 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KDM 2010 17498

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195-12.5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 4/1/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

25/2/19 2/5 \$5250 confirmed with Karen
(\$7,662.25 Rd - 55%)

RECEIVED 25 FEB 2019

26/2/2019

Date/Time, File Pass to?

26/02/19

1) Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 6Resurvey No. of Trip: 2Survey Fee: 200

Transportation: _____

S + RS: \$ _____

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) 5,250 / L/S

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 15 Jan 2019

Preliminary Advice

Insured Vehicle No	: SJS9715T	Accident Date	: 04/01/2019
TP Vehicle No	: PC1893C	Assignment Date	: 11/01/2019
Make	: TOYOTA HIACE	Est. Duration of Repair	: 6 days
Date of Inspection	: 11/01/2019		
Inspection At	: Think One Autocare Pte Ltd (HQ) No. 18 Defu Avenue 2 Singapore 539522		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,912.25
Revised Amount	:S\$	6,248.25
Check Items (Estimated)	:S\$	815.50
Total	:S\$	7,063.75

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/01/2019 11:17
Date Of Accident	04/01/2019 12:45
Exact Location Of Accident	BAYSHORE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC1893C
Insured/Policyholder	
Name Of Registered Owner	R&K ANG SERVICES PTE. LTD.
Co Reg No	201120669E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83142560
Alternative Phone No	OFFICE-83142560

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE-2.5 DX (M)
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102383312
Cover Note Number	

Driver

Name of Driver	MASMIKIRWAN BIN ABBAS
NRIC No	S1793797I
Date Of Birth	14/12/1967
Occupation	OUTDOOR
Date Of Driving Pass	15/07/1995
Driving Experience	23 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83142560
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	APT BLK 362B SEMBAWANG CRESENT #06-823
Postcode	752362
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT TIMAH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 1 DUKE ROAD , POSTCODE: 268914 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4629999 - FAX NO: 64628933
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJS9715T
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Pls refer to the Police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Think One Autocare Pte Ltd
18 Defu Lane Avenue 2
Singapore 539522
Tel: 6844 3800 Fax: 6842 4988

Reporting Centre Personnel's Signature
Name:
NRC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190107/2059

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

2 of 3

Report No. T/20190107/2059

CONTINUATION OF REPORT

Driver			
Name	MASMIWAN BIN ABBAS	ID No.	S1793797I
Related Vehicle	NIL	Contact No.	83142560
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	04	Degree of Injury	NIL
Driver			
Name	AL- AMINNUR BIN IBRAHIM	ID No.	S8316578B
Related Vehicle	NIL	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the above date, time and location, while I was driving my van (PC1893C) along ECP towards Changi direction before Bayshore road exit, I was driving along the third lane. As the car in front of me slowed down their speed, I also slowly decrease, suddenly a car (SJS9715T) slammed into the rear of my car and the impact was so huge that my car swerve forward. Thereafter, I was conveyed to Changi General Hospital and was prescribed with 2 days of medical leave from 4 January 19 to 5 January 19. However, I still feel unwell and went to Mount Alvernia Hospital for check, and was given 4 days of medical leave from 7 January 19 to 10 January 19. I wished to state that my neck, forearm arm, lower back hurt a lot. There was no visible injury. After being conveyed to Changi General Hospital, I believe my van had been towed off. Until now, I have yet to see and make a check on my van damage. But I saw the other vehicle was severely damaged.

There was no government property or foreign vehicle involved.

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

15/1/19
11/1/19
6 day
4/5 \$5250

PC1893C Toyota Hiace

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy <i>Ref</i> 432.80	\$ 1,260.00
2	2	Rear bumper bracket <i>Ref</i>	\$ 172.00
3	1	Rear bumper inner beam <i>Ref</i> 266.10	\$ 287.00
4	1	Rear tailgate assy <i>Ref</i> 1950.10	\$ 2,062.00
5	1	Rear tailgate lock mechanism <i>Ref</i>	\$ 266.00
6	1	Rear tailgate lock catch <i>Ref</i>	\$ 62.00
7	2	Rear tailgate hinges <i>Ref</i>	\$ 162.00
8	2	Rear tailgate damper <i>Ref</i>	\$ 375.00
9	1	Rear tailgate weatherstrip <i>Ref</i>	\$ 288.00
10	1	Rear tailgate inner board <i>Ref</i>	\$ 190.00
11	1	Rear tailgate centre logo <i>Ref</i>	\$ 68.00
12	1	Rear tailgate windscreen glass moulding <i>Ref</i>	\$ 295.00
13	1	Rear tailgate lock actuator <i>Ref</i>	\$ 189.00
14	1	Rear tailgate top garnish <i>Ref</i>	\$ 280.00
15	2	Rear tailgate side garnish <i>Ref</i>	\$ 220.00
16	1	Rear tailgate outer garnish <i>Ref</i>	\$ 176.00
17	1	Rear tailgate lock cylinder <i>Ref</i>	\$ 191.00
18	1	Rear left taillamp <i>Ref</i> 386.70	\$ 785.00
19	1	Rear right taillamp <i>Ref</i> 386.70	\$ 785.00
20	1	Rear left taillamp lower panel <i>Ref</i>	\$ 109.00
21	1	Rear right taillamp lower panel <i>Ref</i>	\$ 109.00
22	1	Rear end lower panel <i>Ref</i> 866.01	\$ 1,274.00
23	1	Rear exhaust muffler assy <i>Ref</i>	\$ 2,400.00
24	2	Rear exhaust muffler rubber mounting <i>Ref</i>	\$ 38.00
		Rear end panel top plate <i>Ref</i> 282.40	\$ 12,043.00
		Less 25%	\$ 3,010.75
			\$ 9,032.25

Warranty
1. This warranty is valid only for the original purchaser of the vehicle.
2. The warranty is void if the vehicle is used for commercial purposes.
3. The warranty is void if the vehicle is involved in an accident.
4. The warranty is void if the vehicle is modified without the approval of the manufacturer.
5. The warranty is void if the vehicle is not maintained according to the manufacturer's instructions.
6. The warranty is void if the vehicle is not registered with the relevant authorities.
7. The warranty is void if the vehicle is not insured.
8. The warranty is void if the vehicle is not driven on public roads.
9. The warranty is void if the vehicle is not driven in Singapore.
10. The warranty is void if the vehicle is not driven in the state of Singapore.

P-566281
257
P-4247110
S.W 190
Labor 2150
6587.1
8269

Think One Autocare Pte Ltd
 No.18 Defu Avenue 2
 Singapore 539522
 Tel: 6844 3300 Fax: 6842 4988

PC1893C Toyota Hiace

No	Qty	Parts Description	Estimated Parts Price
----	-----	-------------------	--------------------------

Special Nett Items

1	10	Rear bumper clips <i>nee</i>	\$ 50.00 ✓
2	12	Rear tailgate inner board clips <i>nee</i>	\$ 30.00 ✓
3	4	Rear tailgate outer garnish clips <i>11</i>	\$ 20.00 X
4	1	Rear tailgate '70km/h' sticker <i>nee</i>	\$ 30.00 10
5	1	Rear tailgate '>1230kg' sticker <i>nee</i>	\$ 30.00 ✓
6	1	Rear tailgate 'hiace' sticker <i>nee</i>	\$ 30.00 ✓
7	6	Rear tailgate top garnish clips <i>11</i>	\$ 30.00 X
8	6	Rear tailgate side garnish clips <i>11</i>	\$ 30.00 X
9	1	Rear windscreen glass sealant <i>nee</i>	\$ 80.00 40
10	2	Rear bumper reverse sensor <i>NZ</i>	\$ 250.00 X
11	1	Rear no plate <i>11</i>	\$ 60.00 X
			<hr/>
			\$ 640.00

Total Parts

\$ 9,672.25 *190*

Think One Autocare Pte Ltd
 No.18 Defu Avenue 2
 Singapore 539522
 Tel: 6844 3300 Fax: 6842 4988

PC1893C Toyota Hiace

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,200.00 1000
2	To putty and spray painting rear portion.	\$ 1,200.00 800
3	To check rear lighting and wiring.	\$ 50.00 30
4	To remove and install rear tailgate lock mechanism.	\$ 80.00 60
5	To remove and install rear inner garnish and trim to facilitate the repair.	^ ^ \$ 150.00 X
6	To apply anti rust proofing to rear affected area.	\$ 120.00 80
7	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 120
8	To remove and install rear bumper reverse sensor.	^ ^ \$ 80.00 X
9	To remove and install rear exhaust muffler assy.	\$ 120.00 60
10	Towing service.	^ ^ \$ 100.00 20
Total labour :		\$ 3,240.00 2150

Total parts : \$ 9,672.25

Total labour : \$ 3,240.00

Total repair cost : \$ 12,912.25




































...CLAIM SUBFOLDER...(Pending for Survey Report)

















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jan 2019		11 Jan 2019 09:43 Edit Adj Rpt	S\$5,250.00 Edit Estimates	S\$5,250.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	RIDE NOW PRIVATE LIMITED , Co. Reg. No.: 201626643D								
Main Claimant:	R&K ANG SERVICES PTE. LTD. , Co. Reg. No.: 201120669E								
Vehicle Reg. No.:	PC1893C	Date of Loss:	04/01/2019 12:00 - :59 [64 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 581599	Policy/Cover Note No.:	29032696TMC (Third Party Only) Coverage: 27/10/2018 - 26/10/2019						
Vehicle Reg. No. (Insured):	SJS9715T	Policy No. (Claimant):							
		Excess:	S\$3,000.00						
Repairer:	Think One Autocare Pte Ltd (HQ) No. 18 Defu Avenue 2, 539522 Ubi - Tel: 68443300								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 10/02/2019]								
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK. OI NOT REPORTED. CONTACT: KAREN TAN 9128 8488/ 6844 3300								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PC1893C (581599)
[SJS9715T]
TP
R&K ANG SERVICES PTE. LTD.
Jan 4 2019 12:00PM
[RIDE NOW PRIVATE LIMITED]
Think One Autocare Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	15/01/19 10:30	Adjuster Immediate Advice					Load HTM		
2	15/01/19 10:48	Adjuster Immediate Advice					Load HTM		
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	11/01/19 18:41	Odometer Reading					Load JPG	<input checked="" type="checkbox"/>	
2	11/01/19 18:41	Chassis Number					Load JPG	<input checked="" type="checkbox"/>	
3	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
4	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
5	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
6	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
7	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
8	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
9	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
10	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
11	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
12	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
13	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
14	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
15	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
16	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
17	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
18	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
19	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
20	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
21	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
22	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
23	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
24	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
25	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
26	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
27	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
28	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
29	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
30	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
31	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
32	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	
33	11/01/19 18:41	General View					Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
34	11/01/19 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
35	11/01/19 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
36	11/01/19 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
37	11/01/19 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
38	11/01/19 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
39	11/01/19 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
40	11/01/19 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
41	11/01/19 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
42	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	16/01/19 18:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	25/01/19 08:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	25/01/19 08:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	25/01/19 08:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	25/01/19 08:29	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/01/19 11:26	PC1893C TP E-FILE REPORT	 Load PDF	
2	10/01/19 11:26	EMAIL FROM TP TO ARRANGE SURVEY	 Load PDF	
3	11/01/19 08:45	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19000662/USD3Q2

Date: 27/02/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29032696TMC

Claimant Vehicle No : PC1893C

Insured Vehicle No : SJS9715T

Date of Loss: 04/01/2019

Nature of Claim: TP

Claim No: 581599

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PC1893C

Make & Model: TOYOTA HIACE, 3.0 D DX (M)

Engine No: 1KD2302562

Reg. Date: 21/08/2013 (Man. Year: 2013)

Chassis No: KDH2010117498

Colour: Silver

Odometer: 340054 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,884.05	4,437.11	5,446.94	55.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	2,150.00	1,090.00	33.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,124.05	6,587.11	6,536.94	49.81
Approved Total (Overridden) (S\$)		5,250.00		
(S\$)	13,124.05	5,250.00	7,874.05	60.00
+ GST 7.00/7.00% (S\$)	918.68	367.50	551.18	60.00
Nett Amount (S\$)	14,042.73	5,617.50	8,425.23	60.00

INSPECTION

Date of Assignment: 11/01/2019

Date Inspected: 11/01/2019 Inspected At:

Think One Autocare Pte Ltd (HQ)

No. 18 Defu Avenue 2

Singapore 539522

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Feb 2019)
Parts:	213	TOYOTA HIACE 3.0 D DX (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC1893C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Distorted	1,260.00 FL	*432.80 FL
2	2		*REAR BUMPER BRACKET	Bent	172.00 FL	*172.00 FL
3	1		*REAR BUMPER INNER BEAM	Bent	287.00 FL	*266.10 FL
4	1		*REAR TAILGATE ASSY	Badly Dented	2,062.00 FL	*1,950.10 FL
5	1		*REAR TAILGATE LOCK MECHANISM	Dented / Jammed	266.00 FL	*266.00 FL
6	1		*REAR TAILGATE LOCK CATCH	Not Necessary	62.00 FL	*- FL
7	2		*REAR TAILGATE HINGES	Not Necessary	162.00 FL	*- FL
8	2		*REAR TAILGATE DAMPER	Not Necessary	375.00 FL	*- FL
9	1		*REAR TAILGATE WEATHERSTRIP	Twisted	288.00 FL	*288.00 FL
10	1		*REAR TAILGATE INNER BOARD	Not Necessary	190.00 FL	*- FL
11	1		*REAR TAILGATE CENTRE LOGO	Necessary	68.00 FL	*68.00 FL
12	1		*REAR TAILGATE WINDSCREEN GLASS MOULDING	Not Necessary	295.00 FL	*- FL
13	1		*REAR TAILGATE LOCK ACTUATOR	Jammed	189.00 FL	*189.00 FL
14	1		*REAR TAILGATE TOP GARNISH	Not Necessary	280.00 FL	*- FL
15	2		*REAR TAILGATE SIDE GARNISH	Not Necessary	220.00 FL	*- FL
16	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	176.00 FL	*- FL
17	1		*REAR TAILGATE LOCK CYLINDER	Not Necessary	191.00 FL	*- FL
18	1		*REAR LEFT TAILLAMP	Cracked	785.00 FL	*386.70 FL
19	1		*REAR RIGHT TAILLAMP	Cracked	785.00 FL	*386.70 FL
20	1		*REAR LEFT TAILLAMP LOWER PANEL	Repair	109.00 FL	*- FL
21	1		*REAR RIGHT TAILLAMP LOWER PANEL	Cut	109.00 FL	*109.00 FL
22	1		*REAR END LOWER PANEL	Badly Dented	1,274.00 FL	*866.01 FL
23	1		*REAR EXHAUST MUFFLER ASSY	Repair	2,400.00 FL	*- FL
24	2		*REAR EXHAUST MUFFLER RUBBER MOUNTING	Not Necessary	38.00 FL	*- FL
25	1		*REAR END PANEL TOP PLATE	Bent	282.40 FL	*282.40 FL
26	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
27	12		*REAR TAILGATE INNER BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
28	4		*REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
29	1		*REAR TAILGATE 70KM/H STICKER	Necessary	30.00 FS	*10.00 FS
30	1		*REAR TAILGATE >1230KGSTICKER	Necessary	30.00 FS	*30.00 FS
31	1		*REAR TAILGATE HIACE STICKER	Necessary	30.00 FS	*30.00 FS
32	6		*REAR TAILGATE TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
33	6		*REAR TAILGATE SIDE GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
34	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
35	2		*REAR BUMPER REVERSE SENSOR	Not fitted	250.00 FS	*- FS
36	1		*REAR NO PLATE	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **12,965.40** **5,852.81**
 - List Item Discount on L Items 25.00/25.00% (\$\$) 3,081.35 1,415.70

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					9,884.05	4,437.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	1,200.00	1,000.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,200.00	800.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	30.00
4	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM	New	80.00	60.00
5	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	150.00	0.00
6	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	120.00	80.00
7	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	140.00	120.00
8	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	0.00
9	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY	New	120.00	60.00
10	TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (\$\$)			3,240.00	2,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >