

21/03/2002

ASS. REC. BY:

REF

FCI 19000704 / 719d3d

Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time: 4:44pm @ 10/01/2019

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 9392P

Insured:

SHB 3646L

at Workshop m/s

Success United

Tel:

9223 6288

of

2 kaki Bukit Ave 2 # 01-33 Autohub

Policy No:

Claim No:

D19000322 MFSH

Sum Insured:

Excess:

Make of Veh.

(Client's Record)

D.O.A.

04/01/2019

CA / REV / REP. / REV 24 HRS

lup1

H.O.D. Endorsement:

15/01/2019 @ 1:30pm ow

Date/Time:

4:30pm @ 11/1/19

Person Contacted:

Sirin

Vehicle IN ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	GBD 9392P-X
	SHB 3646L-CS / FCI 18015696 / 711d3e2

18/1/19 @ 5:13pm revised to Karen Tan by email.

14/3/19 @ 5:15pm checked with Sirin (worksp), the vehicle has not send in for repair due to awaiting liability issue.

15/3/19 Submit Prel. report

31/5/19 @ 2:27pm confirmed with Sirin LS @ 2950, 5 days. (Red @ 4197.54, 59%)

* reopen ref. for submit final report, Celine 4/6/19.

6/6/19 reopen ref only * 1st pot 18/3/19 * ↓

Tanji

REF: FCI

ASSIGNMENT

From

Date 15/01/2019

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No

GBD 9392P

at Workshop m/s

Success United

of

2 kaki Bukit Ave 2 #01-33 Autohub

Insured

Policy No.

Claims No.

Sum Insured

Excess:


(Client's Record)

Make of Veh.

1:30pm @ owner's cutting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

5 days Res.: Yes or No

Lump Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

GBD 9392P

in Regn 2015 Aug

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

1543M. NHR 85.

CC 2999

Colour

White

A/C Insured / Std / NI / NA

Sp. Reading

59477.

T/Radio Insured / Std / NI / NA

Eng/No.

C/No:

JWAN HR 85E F71.00005

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

195/90R15.

R:

145/R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

D.O.I

15/1/19

Survey held at

Success United

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 15 MAR 2019

Date/Time, File Pass to?

15/3/19 M/S

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$)

☒ Prel. Report
☐ Final Report

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation

3 + RS 31

Photos

Others

TOTAL

150

50

35

235

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 31 May 2019 2:27 PM
To: sirina@successunited.com.sg
Subject: RE: GBD 9392P After Paint. Finalisation

Dear Sirina,

WITHOUT PREJUDICE

Confirm Lump Sum \$2,950.00 and 5 repair days.

Kindly send the relevant documents to MS First Capital Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: sirina@successunited.com.sg <sirinassk@gmail.com>

Sent: Tuesday, 28 May 2019 5:09 PM

To: SUR <sur@lkkauto.com>

Subject: GBD 9392P After Paint. Finalisation

Hi

Attached herein the after paint photos and our finalisation for your action.

Awaits your confirmation.

Thank You.

Best Regards,

Sirina Soon

Senior Claims Executive

Mobile: +65 9223 6288

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2

#01-33 / #02-29

Kaki Bukit AutoHub

Singapore 417921

Tel: 6746 1515 Fax: 6748 5015

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub, Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67485015
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 200402570G

MS First Capital Insurance Limited
36 Robinson Road
#16-01 City House
Singapore 068877
Attention : Motor Claim Department
Contact : 65073848 Fax No. : 65073849

Estimate : TP19-008

Date : 10/01/2019
Vehicle Num. : GBD9392P
Make/Model : Isuzu Lorry-2015
Chassis/Eng# : JAANHR85EF7100105/4JJ11W7289
Accident Date : 04/01/2019
Claim No. : 319000322MFSH
Reference :
Policy No. : (31/07/2019)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	Frt Bumper Assy	725.85	
3.	1	Frt Bumper Bracket LH	281.34	
4.	1	Headlamp Assy LH	420.00	
5.	1	Headlamp Side Lamp LH	155.20	
6.	1	Frt Door LH	1,174.38	
7.	1	Frt Door Weatherstrip LH	195.80	
8.	2	Frt Door Hinge, Top/Lower LH	312.00	
9.	1	Frt Door Center Check LH	78.00	
10.	1	Side Step Garnish LH	148.17	
11.	1	Frt Wheel Arch Guard Garnish LH	98.10	
12.	1	Frt Door Pillar LH	1,358.70	

List Total S\$:

SPECIAL NETT ITEMS :

1. 1

Co's Sticker

Special Nett Total S\$:

LABOUR :

To remove, rearrange electrical wirings, check lighting

To remove, replace & transfer door components.

To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident

To putty and respray painting on affected area.

Labour Total S\$:

156.00

15%

2778.84

15% - 2362.01

725.85

281.34

420.00

155.20

1,174.38

195.80

312.00

78.00

148.17

98.10

1,358.70

4,947.54

40.00

40.00

30 60.00

60 200.00

600 1,000.00

600 900.00

1290 2,160.00

3692.01

4592950

18/1/19

62563561

Total S\$: 7,147.54

for SUCCESS UNITED PTE LTD

E. & O.E.
LKK Auto Consultancy
the Repairer of the fork
• To resurvey the repairer spray
• To display the repaired parts during resurvey
• Parts price are subject to information
• Third party survey on "without Prejudice" basis
• No illegal modification is allowed
• Supplementary cost must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Kah 97495749
- wr
15/1/19 @ 130pm
Lumpsum
Resurvey after repair
sure/ok autocon
05 days

SUCCESS UNITED PTE LTD


2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub, Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67485015
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 200402570G

MS First Capital Insurance Limited
36 Robinson Road
#16-01 City House
Singapore 068877
Attention : Motor Claim Department
Contact : 65073848 Fax No. : 65073849

Finalisation : TP19-008

Date : 28/05/2019
Vehicle Num. : GBD9392P
Make/Model : Isuzu Lorry-2015
Chassis/Eng# : JAANHR85EF7100105/4JJ11W7289
Accident Date : 04/01/2019
Claim No. : D19000322MFSH
Reference :
Policy No. : (31/07/2019)

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	Frt Bumper Assy		725.85
2.	1	Frt Bumper Bracket LH		281.34
3.	1	Headlamp Assy LH		
4.	1	Headlamp Side Lamp LH		155.20
5.	1	Frt Door LH		1,174.38
6.	1	Frt Door Weatherstrip LH		195.80
7.	REPAIR	Frt Door Hinge, Top/Lower LH		
8.	1	Frt Door Center Check LH		
9.	1	Side Step Garnish LH		148.17
10.	1	Frt Wheel Arch Guard Garnish LH		98.10
11.	REPAIR	Frt Door Pillar LH		1.00
List TotalS\$:				2,779.84
15.00% Discount S\$:				416.98
				2,362.86
SPECIAL NETT ITEMS :				
1.	1	Co's Sticker		40.00
Special Nett Total S\$:				40.00
LABOUR :				
To remove, rearrange electrical wirings, check lighting				30.00
To remove, replace & transfer door components.				60.00
To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident				600.00
To putty and respray painting on affected area.				600.00
Labour Total S\$:				1,290.00
Total S\$:				3,692.86


SUCCESS UNITED PTE LTD

LS @ 2,950.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19000704/T1qd3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 18-03-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3646L	Veh. Inspected	GBD 9392P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000322MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	10/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	ISUZU NHR85AUE4AA	c.c	2999	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JAANHR85EF7100105	Colour	WHITE	
Odometer	59477	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/90 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/90 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	145 R13	YOKOHAMA	6/6 mm	
L/H Rear Tyre	145 R13	YOKOHAMA	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/01/2019	Inspection Date	15/01/2019	
Survey held at	SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 9392P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT BUMPER ASSY	CRACKED	725.85	725.85
1	FRT BUMPER BRACKET LH	BENT	281.34	281.34
1	HEADLAMP ASSY LH	NOT NECESSARY	420.00	-
1	HEADLAMP SIDE LAMP LH	CRACKED	155.20	155.20
1	FRT DOOR LH	BENT	1,174.38	1,174.38
1	FRT DOOR WEATHERSTRIP LH	NECESSARY	195.80	195.80
2	FRT DOOR HINGE, TOP / LOWER LH @\$156.00	TO REPAIR SEE LABOUR	312.00	-
1	FRT DOOR CENTER CHECK LH	NOT NECESSARY	78.00	-
1	SIDE STEP GARNISH LH	CUT	148.17	148.17
1	FRT WHEEL ARCH GUARD GARNISH LH	CUT	98.10	98.10
1	FRT DOOR PILLAR LH	TO REPAIR SEE LABOUR	1,358.70	-
	LESS 15% DISCOUNT		-	-416.83
			4,947.54	2,362.01
SPECIAL NETT ITEMS				
1	CO'S STICKER (SN)	CUT	40.00	40.00
			40.00	40.00
LABOUR				
	TO REMOVE, REPAIR AND REPLACED DAMAGED BODYPARTS, REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRT DOOR HINGE, TOP / LOWER LH AND FRT DOOR PILLAR LH.		1,000.00	600.00
	TO REMOVE, REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTING.		60.00	30.00
	TO REMOVE, REPLACE & TRANSFER DOOR COMPONENTS.		200.00	60.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA.		900.00	600.00
			2,160.00	1,290.00
GRAND TOTAL			7,147.54	3,692.01

Report Ref No. CS/FCI19000704/T1qd3e2



RECOMMENDED COST OF LUMP SUM REPAIRS
(TO ITS PRE-ACCIDENT CONDITION)

Page No.:2 of 2

2,950.00

Report Ref No. CS/FCI19000704/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.