

Circulator *Howe Jie*

ASSIGNMENT

From: Date: *10/01/2019*

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No. *SHB1991C*

at Workshop m/s

of

Insured

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS *up*

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No *SHB1991C*Yt Regn *20/8/2014*Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make: *Toyota Prius*C.C. *1797*Colour *Maroon*

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: *JTDKN36U10S747759*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim orTyre Size: F: *195/65R15*R: *-*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal. *6* mmR/Bal. *6* mmL/Bal. *6* mmL/Bal. *6* mmD.O.A. *9/1/19*D.O.I. *10/1/19*

Survey held at

*Smt*Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*SHB1991C - 003 / Jtd 17015772 / Sub 302**JUA: 12/8/17**01/19/2040**GBG 9343R - X**Lump sum \$6050/- (Red: 11,618.95: 65%)**GBG 9343R*

RECEIVED 29 APR 2019

Date/Time, File Pass to?

☐ Preli. Report*29/4 Typist*☒ Final Report

Date/Time, File Return to?

Days Of Repair: *6*

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

*160**160*

Report Format:

Lump Sum / I.B.I. (\$)

*TP**6050/-*Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)**Policy Query**

Policy No.		Date of Accident	09/01/2019 12:30
Vehicle No.(For Motor)	GBG9343R	Certificate Number	
Search			

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5070244660-03		THINK ONE LEASING PTE.LTD.	201115609M	GFT	Comprehensive	GBG9343R	GBG9343R	28/02/2018	

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	MT/1027118-003	SMRT TAXIS	SHB 1991C	GBG 9343R
2	MT/1036966-002	SMRT TAXIS	SHC 4154C	FBL 3526T
3	MT/1034441-002	SMRT BUS	SG5757E	SJA 4511S
4	MT/1041502-002	COMFORT TRANSPORTATION PTE LTD	SHC 3387D	PA 786X
5	MT/1040396-002	COMFORT TRANSPORTATION PTE LTD	SH7087L	SGR 5464J
6	MT/1041321-002	COMFORT TRANSPORTATION PTE LTD	SHC 3540C	SLC 6469J
7	MT/1041433-002	COMFORT TRANSPORTATION PTE LTD	SHD 4981B	SJU 9496P
8	MT/1041156-002	COMFORT TRANSPORTATION PTE LTD	SHB 4050Z	SLU 2212P
9	MT/1041766-002	COMFORT TRANSPORTATION PTE LTD	SH 9151X	XE 499J
10	MT/1041821-002	COMFORT TRANSPORTATION PTE LTD	SHC 3607U	SLT 2910M

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/01/2019 16:03
Date Of Accident	09/01/2019 13:10
Exact Location Of Accident	ANG MO KIO AVE 8 TOWARDS ANG MO KIO CENTRAL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1991C
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	TOH CHIN KHOON
NRIC No	S1720457B
Date Of Birth	05/07/1965
Occupation	OUTDOOR
Date Of Driving Pass	27/09/1985
Driving Experience	33 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG ANG MO KIO AVE 8 TOWARDS ANG MO KIO CENTRAL. TRAFFIC LIGHT TURNED AMBER, AS SUCH I STOPPED. AFTER WHICH I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE GBG9343R HAD COLLIDED ONTO THE REAR LEFT PORTION OF MY TAXI.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG9343R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	UNKNOWN
NRIC/Passport Number	S9743847A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

1/9/2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

9/1/2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Case Details

Case Reference Number :

TAX/01/19/2040

Type of Repair : Accident Repair

Vehicle Registration Number :

SHB1991C

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-5288-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 09/01/2019 05:10 AM

Vehicle Age(In Months) : 53

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval		
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace ▾ DEF
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	1	154.27	Replace ▾ DD
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check ▾
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give ▾
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.68	Replace ▾ DEF
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	1	54.15	Replace ▾ DEF
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give ▾
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace ▾ CRA
Total Spare Part Cost									12,414.39	Surveyor Total			
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)			
Final Spare Part Cost									9,931.51	Final Sur Total			

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give ▾
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace ▾ Shorter
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾ NEL
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give ▾
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	1	451.58	Replace ▾ DP
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace ▾ NEL
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	0	0	Check ▾
One Time Key In	Main			MEMBER SUB-ASSY, RR LH	1	174.10	174.10	25.00	130.57	Replace	0	0	Not Give ▾
One Time Key In	Main			FLOOR PANEL RR/LH	1	102.00	102.00	25.00	76.50	Replace	0	0	Check ▾
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.92	Replace ▾ PD
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	0	0	Not Give ▾
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	0	0	Not Give ▾
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give ▾
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.80	60.80	25.00	45.60	Replace	0	0	Not Give ▾
Total Spare Part Cost									12,414.39		Surveyor Total	4,312.46	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost									9,931.51		Final Sur Total	3,449.97	

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give ▾
One Time Key In	Main			STICKER SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give ▾
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give ▾
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace ▾ NEL
One Time Key In	Main			TAILGATE LOWER WINDOW GLASS	1	721.30	721.30	25.00	540.97	Replace	1	540.97	Replace ▾ CRA
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace ▾ NEL
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace ▾ NEL
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace ▾ NEL
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	1	0	Repair ▾
One Time Key In	Main			3RD BRAKE LAMP	1	231.30	231.30	25.00	173.48	Replace	0	0	Not Give ▾
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	0	0	Not Give ▾
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	0	0	Not Give ▾
One Time Key In	Main			LICENSE PLATE LAMP	2	35.70	71.40	10.00	64.26	Replace	0	0	Not Give ▾
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Check ▾
Total Spare Part Cost									12,414.39		Surveyor Total	4,312.46	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost									9,931.51		Final Sur Total	3,449.97	

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0	Check
One Time Key In	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.77	Replace	0	0	Check
One Time Key In	Main			TAILGATE DOOR HINGE LH/RH	2	58.30	116.60	25.00	87.45	Replace	0	0	Check
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0	Check
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0	Not Give
One Time Key In	Main			TAILGATE, BOARD ASSY	1	246.90	246.90	25.00	185.18	Replace	0	0	Not Give
One Time Key In	Main			BOX, DECK FLOOR, COVER LH	1	230.10	230.10	25.00	172.57	Replace	0	0	Not Give
One Time Key In	Main			BOX, DECK FLOOR, LH	1	196.80	196.80	25.00	147.60	Replace	0	0	Not Give
One Time Key In	Main			BOX, DECK FLOOR, RR	1	649.70	649.70	25.00	487.28	Replace	0	0	Not Give
One Time Key In	Main			BOX RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	0	0	Not Give
One Time Key In	Main			BOARD ASSY, RR RH	1	379.20	379.20	25.00	284.40	Replace	0	0	Not Give
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	1	575.10	Replace
One Time Key In	Main			QUARTER GLASS RR/LH	1	168.10	168.10	25.00	126.07	Replace	1	126.07	Replace
Total Spare Part Cost									12,414.39		Surveyor Total	4,312.46	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost									9,931.51		Final Sur Total	3,449.97	

BUC

NEC

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	NEC
One Time Key In	Main			STICKER SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	NEC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	NEC
One Time Key In	Main			DUCT ASSY, QUARTER	1	70.40	70.40	25.00	52.80	Replace	1	52.80	Replace	NEC
One Time Key In	Main			FENDER LINER RR/LH	1	141.30	141.30	25.00	105.98	Replace	0	0	Check	
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Check	
One Time Key In	Main			SILL MEMBER PLATE RR/LH	1	57.50	57.50	25.00	43.13	Replace	0	0	Not Give	
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	
One Time Key In	Main			WHEEL DISC	1	1,484.20	1,484.20	25.00	1,113.15	Replace	0	0	Not Give	
One Time Key In	Main			LID ASSY, FUEL	1	102.00	102.00	25.00	76.50	Replace	0	0	Not Give	
One Time Key In	Main			DOOR RR/LH	1	954.50	954.50	25.00	715.88	Replace	0	0	Not Give	
One Time Key In	Main			TROUGH, BACK DOOR LH	1	110.90	110.90	25.00	83.18	Replace	0	0	Check	
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	25.00	411.30	Replace	1	411.30	Replace	CRA
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	30.70	30.70	25.00	23.02	Replace	1	23.02	Replace	MIS
Total Spare Part Cost									12,414.39		Surveyor Total	4,312.46		
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20		
Final Spare Part Cost									9,931.51		Final Sur Total	3,449.97		

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR REAR PORTION	1,690.00	800	
Total:		1,690.00	800.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY FRONT BUMPER	378.00	0	
2	TO RESPRAY REAR PANEL	180.00	100	
3	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	
4	TO RESPRAY REAR MEMBER,LH	180.00	0	
5	TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0	
6	TO RESPRAY TAIL GATE	378.00	200	
7	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0	
8	TO RESPRAY SPOILER	180.00	100	
9	TO RESPRAY REAR FENDER LH	378.00	200	
10	TO RESPRAY RIM	180.00	0	
11	TO REPSRAY REAR DOOR LH	378.00	0	
12	TO RESPRAY TROUGH BACK DOOR LH	180.00	0	
13	TO REPSRAY REAR BUMPER	0.00	200	
Total:		2,952.00	800.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO APPLY RUST-PROOFING ON AFFECTED AREA	250.00	100	
Total:		2,050.00	720.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
4	TO ALIGN CHASSIS	350.00	0	
5	TO TRANSFER REAR TAILGATE MECHANISM	120.00	50	
6	TO REMOVE / REFIT WINDSCREEN	120.00	100	
7	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	250.00	250	
8	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50	
9	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30	
10	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
11	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	
12	TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	30	
13	TO WASH AND VACUUM	60.00	0	
14	TO REPLACE SUNDRY PARTS	100.00	0	
Total:		2,050.00	720.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	9,931.51	3,449.97
Total Labour Cost	1,690.00	800.00
Total Spray Painting	2,952.00	800.00
Other:	2,050.00	720.00
Overall Total	16,623.51	5,769.97
Lump Sum Repair Option	✓	✓
Lump Sum Total	16,600.00	5,750.00
Surveyor Approved Amount		5,750.00

Estimator Assessment(\$)

Surveyor Assessment(\$)

No of Repair Days*

10

6


Remarks

L/S repair, photo after paint.

Surveyor Name

Hwee jie

Signature


14/1/19

Save

Clear

Survey Date

10/01/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company



Acknowledged by Repairer

Signature:

Date:

Section A - Accident Details

Registration Number	SHB1991C
Case Reference Number	TAX/01/19/2040
Registration Date	20/8/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TOH CHIN KHOON
Type of Accident	Head to Rear
Accident Date and Time	9/1/2019 1:10 PM
Accident Reported Date and Time	9/1/2019 3:37 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24099610
Special Instruction to ARC, if any	TP
Prepared Date and Time	10/1/2019 10:57 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



L/S repair. photo after paint.

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,890.00	\$900.00
Total Spray Cost	\$3,312.00	\$950.00
Total Spare Part Cost	\$10,416.96	\$4,964.48
Total Other Cost	\$2,050.00	(\$764.49)
TOTAL COST	\$17,668.96	\$6,050.00 (L/S)
Lump Sum Total	\$17,108.96	\$0.00
Number of Repair Days	10.0	6.0
Prepared / Adjusted By	Zhi Yang Phua	Hwee Jie (LKK) / NTUC
ARC / Surveyor Sign Off Date	10/01/2019 3:43 PM	10/01/2019 3:22 PM
Signature		
Remarks		L/S repair. photo after paint.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1904-0334	Invoice Number	
Quotation Date	25.04.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR APRON PANEL LH	\$200.00	\$100.00
TO REPAIR REAR PORTION	\$1,690.00	\$800.00
Total Labour	\$1,890.00	\$900.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO SPRAY PAINT LOWER PANEL	\$180.00	\$50.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	\$180.00	\$100.00
TO REPSRAY FRONT BUMPER	\$378.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY REAR MEMBER, LH	\$180.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
TO RESPRAY SPOILER	\$180.00	\$100.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
TO REPSRAY REAR DOOR LH	\$378.00	\$0.00
TO RESPRAY TROUGH BACK DOOR LH	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$0.00	\$200.00
Total Spray Painting & Panel Beating	\$3,312.00	\$950.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$250.00	\$100.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO ALIGN CHASSIS	\$350.00	\$0.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$50.00
TO REMOVE / REFIT WINDSCREEN	\$120.00	\$100.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$250.00	\$250.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$50.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$30.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park EA, Singapore 757705
FAX Number : 63685502
Estimator Telephone Number : 68682523
Accident Reporting Number : 98582672

Date Generated : 23/04/2019

User ID : PohSuan

TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE & REFIT REAR QUARTER GLASS LH	\$120.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$2,050.00	\$720.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
		76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace
		76088-47020	BUMPER LIP COVER RR/LH	1.00	\$72.20	25.00	\$54.15	Replace	Replace
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given
		52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given
		58307-47060	END PANEL	1.00	\$602.10	25.00	\$451.58	Replace	Replace
			SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace
		58311-47071	SPARE TYRE PANEL	0.00	\$667.70	0.00	\$0.00	Replace	Check
		57604-47030	MEMBER SUB-ASSY, RR LH	0.00	\$174.10	0.00	\$0.00	Replace	Not Given
		58303-47301	FLOOR PANEL RR/LH	0.00	\$102.00	0.00	\$0.00	Replace	Check
		67005-47241	TAILGATE ASY	1.00	\$1,007.90	25.00	\$755.93	Replace	Replace
		76801-47070-B0	TAILGATE OUTSIDE GARNISH	0.00	\$504.90	0.00	\$0.00	Replace	Not Given
		75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given
		75442-47030	NAME PLATE (PRIUS)	0.00	\$60.80	0.00	\$0.00	Replace	Not Given
		75443-47030	NAME PLATE (TOYOTA)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given
			STICKER SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given
			STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given
		75575-47030	MOULDING BACK WINDOW, LOWER NO.1	1.00	\$29.40	25.00	\$22.05	Replace	Replace
		64821-47030	TAILGATE LOWER WINDOW GLASS	1.00	\$721.30	25.00	\$540.98	Replace	Replace
		75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace
		75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace
			SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace
		76085-47910	SPOILER REAR	1.00	\$953.70	100.00	\$0.00	Replace	Repair
		81006-47011	3RD BRAKE LAMP	0.00	\$231.30	0.00	\$0.00	Replace	Not Given
			NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given
			NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 6862623
Accident Reporting Number : 6862672

Date Generated : 25/04/2018

User ID : PuhBuan

	81271-53011	LICENSE PLATE LAMP	0.00	\$35.70	0.00	\$0.00	Replace	Not Given	X
	89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Check	X
	69350-47030	TAILGATE DOOR LOCK	0.00	\$444.10	0.00	\$0.00	Replace	Check	X
	69415-47020	TAILGATE LOCK, COVER	0.00	\$15.70	0.00	\$0.00	Replace	Check	X
	68810-47010	TAILGATE DOOR HINGE LH/RH	0.00	\$58.30	0.00	\$0.00	Replace	Check	X
	67881-47022	TAILGATE DOOR WEATHER STRIP	0.00	\$353.40	0.00	\$0.00	Replace	Check	X
	64718-47031B0	END PANEL COVER, DECK TRIM HOLE	0.00	\$46.10	0.00	\$0.00	Replace	Not Given	X
	64716-47031B0	END PANEL COVER, DECK TRIM, RR	0.00	\$121.10	0.00	\$0.00	Replace	Not Given	X
	67750-47071C0	TAILGATE, BOARD ASSY	0.00	\$246.90	0.00	\$0.00	Replace	Not Given	X
	58418-47070B0	BOX, DECK FLOOR, COVER LH	0.00	\$230.10	0.00	\$0.00	Replace	Not Given	X
	64997-47020	BOX, DECK FLOOR, LH	0.00	\$196.80	0.00	\$0.00	Replace	Not Given	X
	64993-47020	BOX, DECK FLOOR, RR	0.00	\$649.70	0.00	\$0.00	Replace	Not Given	X
	58416-47030B3	BOX RR FLOOR, BOARD	0.00	\$679.60	0.00	\$0.00	Replace	Not Given	X
	58490-47140B0	BOARD ASSY, RR RH	0.00	\$379.20	0.00	\$0.00	Replace	Not Given	X
	61602-47091	FENDER RR/LH	1.00	\$766.80	25.00	\$575.10	Replace	Replace	X
	62720-47031	QUARTER GLASS RR/LH	1.00	\$168.10	25.00	\$126.08	Replace	Replace	X
		SEALANT W/SCREEN	1.00	\$37.00	0.00	\$37.00	Replace	Replace	X
		STICKER SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	X
		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	X
	62940-16060	DUCT ASSY, QUARTER	1.00	\$70.40	25.00	\$52.80	Replace	Replace	X
	65638-47021	FENDER LINER RR/LH	0.00	\$141.30	0.00	\$0.00	Replace	Check	X
	52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Check	X
	65632-47041	SILL MEMBER PLATE RR/LH	0.00	\$57.50	0.00	\$0.00	Replace	Not Given	X
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
	42611-47140	WHEEL DISC	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given	X
	77350-47030	LID ASSY, FUEL	0.00	\$102.00	0.00	\$0.00	Replace	Not Given	X
	67004-47080	DOOR RR/LH	0.00	\$954.50	0.00	\$0.00	Replace	Not Given	X
	61622-47030	TROUGH, BACK DOOR LH	0.00	\$110.90	0.00	\$0.00	Replace	Check	X
	81561-47170	TAIL LAMP LH	1.00	\$548.40	25.00	\$411.30	Replace	Replace	X
	52563-47010	TAIL LAMP BRACKET, LH	1.00	\$30.70	25.00	\$23.03	Replace	Replace	X
Total				\$15,985.94		\$4,312.51			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace
		75442-47030	NAME PLATE (PRIUS)	1.00	\$60.80	25.00	\$45.60	Replace	Replace
		75443-47030	NAME PLATE (TOYOTA)	1.00	\$51.90	25.00	\$38.93	Replace	Replace
		76801-47070-B0	TAILGATE OUTSIDE GARNISH	1.00	\$504.90	25.00	\$378.68	Replace	Replace
		75310-47020	EMBLEM REAR	1.00	\$60.30	25.00	\$45.23	Replace	Replace
Total					\$669.40		\$512.07		

REQUEST FOR SUPPLYMENT PARTS

Contractor:			
Accident Case Number	TAX/01/19/2040	Date of Collection	1 / 1
Vehicle No	SHB 1991 C	Date of Request	12/01/2019
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (if any)	2

S/N	Part Number	Part Description	Quantity	Unit Price
		ARM SUB ASSY/REAR BUMPER RH	1pc	DD ✓
		EMBLEM REAR	1pc	NEC ✓
		NAME PLATE (HYBRID)	1pc	NEC ✓
		NAME PLATE (PRIUS)	1pc	NEC ✓
		NAME PLATE (TOYOTA)	1pc	NEC ✓
		TAILGATE OUTSIDE GARNISH	1pc	CRA ✓

<<<Please submit photographs for damaged parts>>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
 Signature of person making this declaration
 (to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

REQUEST FOR SUPPLEMENT PARTS

Contractor:			
Accident Case Number	TAX/01/19/2040	Date of Collection	1 / 1
Vehicle No	SUB 1991 C	Date of Request	12 01/2019
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	2

S/N	Part Number	Part Description	Quantity	Unit Price
		REAR BUMPER SEAL IN	1m	CUT ✓
		labour to REPAIR REAR FLOOR PANEL LH		\$200 \$100
		labour to SPRAY REAR FLOOR PANEL LH		\$180 \$100
		labour to SPRAY TAIL GATE OUTER BARNISH		\$180 \$50

<<Please submit photographs for damaged parts>>

14/1/19

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

P5 1/2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19000762/Jtd3e2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 10-05-2019

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 9343R	Veh. Inspected	SHB 1991C
Policy No.	5070244660-03	Coverage (\$)	0.00
Claim No.	MT/1027118-003	Excess (\$)	0.00
Assign From		Assign Date	10/01/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U105747759	Colour	MAROON
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	09/01/2019	Inspection Date	10/01/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1991C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER REAR (DISC 25%)	DEFORMED	458.60	343.95
1	BUMPER REINFORCEMENT REAR (DISC 25%)	DENTED	205.70	154.28
1	BUMPER LIP COVER RR/LH (DISC 25%)	DEFORMED	72.20	54.15
1	BUMPER SIDE RETAINER RR/LH (DISC 25%)	CRACKED	94.80	71.10
1	END PANEL (DISC 25%)	DENTED	602.10	451.58
1	TAILGATE ASY (DISC 25%)	DENTED	1,007.90	755.93
1	MOULDING BACK WINDOW, LOWER NO.1 (DISC 25%)	NECESSARY	29.40	22.05
1	TAILGATE LOWER WINDOW GLASS (DISC 25%)	CRACKED	721.30	540.98
1	TAIL GATE DOOR GLASS MOULDING, LH (DISC 25%)	NECESSARY	29.40	22.05
1	TAIL GATE DOOR GLASS MOULDING, RH (DISC 25%)	NECESSARY	29.40	22.05
1	FENDER RR/LH (DISC 25%)	BUCKLED	766.80	575.10
1	QUARTER GLASS RR/LH (DISC 25%)	NECESSARY	168.10	126.08
1	TAIL LAMP LH (DISC 25%)	CRACKED	548.40	411.30
1	TAIL LAMP BRACKET, LH (DISC 25%)	MISSING	30.70	23.03
1	ARM SUB-ASSY, RR BUMPER RH (DISC 25%)	DENTED	139.60	104.70
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	NAME PLATE (PRIUS) (DISC 25%)	NECESSARY	60.80	45.60
1	NAME PLATE (TOYOTA) (DISC 25%)	NECESSARY	51.90	38.93
1	TAILGATE OUTSIDE GARNISH (DISC 25%)	NECESSARY	504.90	378.68
1	EMBLEM REAR (DISC 25%)	CRACKED	60.30	45.23
1	SENSOR REVERSE (SN)	SHORTED	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SEALANT SIKAFLEX (SN)	NECESSARY	37.00	37.00
3	SEALANT W/SCREEN @\$37.00 (SN)	NECESSARY	111.00	111.00
1	SEALANT W/SCREEN (SN)	NECESSARY	37.00	37.00
1	STICKER SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	BUMPER LIP REAR (DISC 25%)	DEFORMED	228.90	171.68
1	DUCT ASSY, QUARTER (DISC 25%)	NECESSARY	70.40	52.80
1	ARM SUB-ASSY, RR BUMPER LH	NOT NECESSARY	139.60	-

Report Ref No. NS/INC19000762/Jtd3e2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ARM SUB-ASSY, RR BUMPER RH	NOT NECESSARY	139.60	-
1	BUMPER LIP COVER RR/RH	NOT NECESSARY	118.10	-
1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	94.80	-
1	UNDER COVER SUB-ASSY, RR FLOOR	NOT NECESSARY	514.50	-
1	SPARE TYRE PANEL	NOT NECESSARY	667.70	-
1	MEMBER SUB-ASSY, RR LH	NOT NECESSARY	174.10	-
1	FLOOR PANEL RR/LH	NOT NECESSARY	102.00	-
1	TAILGATE OUTSIDE GARNISH	NOT NECESSARY	504.90	-
1	NAME PLATE (HYBRID)	NOT NECESSARY	51.90	-
1	NAME PLATE (PRIUS)	NOT NECESSARY	60.80	-
1	NAME PLATE (TOYOTA)	NOT NECESSARY	51.90	-
1	STICKER SMRT LOGO	NOT NECESSARY	7.80	-
1	STICKER DECAL 6555 8888	NOT NECESSARY	21.60	-
1	3RD BRAKE LAMP	NOT NECESSARY	231.30	-
1	NUMBER PLATE FRAME	NOT NECESSARY	12.00	-
1	NUMBER PLATE	NOT NECESSARY	15.00	-
1	LICENSE PLATE LAMP	NOT NECESSARY	35.70	-
1	ANTENNA ELECTRICAL LOWER REAR	NOT NECESSARY	157.40	-
1	TAILGATE DOOR LOCK	NOT NECESSARY	444.10	-
1	TAILGATE LOCK, COVER	NOT NECESSARY	15.70	-
2	TAILGATE DOOR HINGE LH/RH	NOT NECESSARY	58.30	-
1	TAILGATE DOOR WEATHER STRIP	NOT NECESSARY	353.40	-
1	END PANEL COVER, DECK TRIM HOLE	NOT NECESSARY	46.10	-
1	END PANEL COVER, DECK TRIM, RR	NOT NECESSARY	121.10	-
1	TAILGATE, BOARD ASSY	NOT NECESSARY	246.90	-
1	BOX, DECK FLOOR, COVER LH	NOT NECESSARY	230.10	-
1	BOX, DECK FLOOR, LH	NOT NECESSARY	196.80	-
1	BOX, DECK FLOOR, RR	NOT NECESSARY	649.70	-
1	BOX RR FLOOR, BOARD	NOT NECESSARY	679.60	-
1	BOARD ASSY, RR RH	NOT NECESSARY	379.20	-
1	FENDER LINER RR/LH	NOT NECESSARY	141.30	-
1	BUMPER SEAL, RR LH	NOT NECESSARY	88.90	-
1	SILL MEMBER PLATE RR/LH	NOT NECESSARY	57.50	-

Report Ref No. NS/INC19000762/Jtd3e2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TYRE	NOT NECESSARY	126.74	-
1	WHEEL DISC	NOT NECESSARY	1,484.20	-
1	LID ASSY, FUEL	NOT NECESSARY	102.00	-
1	DOOR RR/LH	NOT NECESSARY	954.50	-
1	TROUGH, BACK DOOR LH	NOT NECESSARY	110.90	-
1	SPOILER REAR	TO REPAIR SEE LABOUR	953.70	-
			16,989.34	4,964.58
	LABOUR			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF SPOILER REAR.		1,890.00	900.00
	SPRAY PAINT.		3,312.00	950.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		250.00	100.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	30.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	20.00
	TO ALIGN CHASSIS.	NOT NECESSARY	350.00	-
	TO TRANSFER REAR TAILGATE MECHANISM.		120.00	50.00
	TO REMOVE & REFIT WINDSCREEN.		120.00	100.00
	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM.		250.00	250.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	50.00
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	30.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	NOT NECESSARY	120.00	-
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.		120.00	60.00
	TO REMOVE & REFIT REAR QUARTER GLASS LH.		120.00	30.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			7,252.00	2,570.00
GRAND TOTAL			24,241.34	7,534.58
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				6,050.00

Report Ref No. NS/INC19000762/Jtd3e2

ONG HWEE JIE
Automotive Assessor

A handwritten signature in black ink, appearing to be 'K.K. LAU'.

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.