

ASS. REC. BY:

REF: CS/FCI19000766/Asd3 n2

Special Instruction:

Surveyor: Adnan
CWS

ASSIGNMENT (Office)

From (Person): Joanne Yong of FCI

Date/Time: 11/11/19 @ 7:09pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLM1737R Insured: SHC 0647Z

at Workshop m/s: N-SI Automotive Tel: 68420051

of: 2 kuti Bukit Ave 2 # 01-18

Policy No: Claim No: D19000367MFS4

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 10/01/2019

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time: 10:04am @ 11/11/19 Person Contacted: melody

Vehicle: IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLM1737R-X
	SHC647Z-CS/FCI-16009687/h3 JUA: 22/5/16
15/11/19	@ 14:44 p.m. revert pending estimate from repairs to Joanne Yong via email.

REF: FCI

ASSIGNMENT

From: Date: 14/01/2019

Veh No: SLM1737R Yr Regn: 2017 March

Estimated Cost

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No: SLM1737R
at Workshop n/s: N-51 Automotive
of: 2 kaki Bukit Ave 2 #01-17/18

Make: Honda Vezel Hybrid c.c: 1496
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 173300 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No: Ru 31230380

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 215/60R16

R: 215/60R16

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Halilead

Bal. or Market Value:

Front

Rear

IDAC Accident Rport: Consistent? : Yes or No

R/Bal. 06 mm

R/Bal. 06 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 06 mm

L/Bal. 06 mm

Est. Repairs: days Res.: Yes or No

D.O.A.

D.O.I. 14/01/19

Lum Sum: % 3 Val: Yes or No

Survey held at NSI

CA / REV / REP. / 24 HRS 'DS'

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP 1st Cap.
24/05/19	Confirmed LIS \$ 15k @ 14 days with Advise. (\$ 10,532.68 Red - 41%)

RECEIVED 24 MAY 2019

Date/Time: File Pass to? : Preli. Report

Days Of Repair: 14

1) 24/05/19 Typ'st : Final Report

Resurvey No. of Trip: 2

Date/Time: File Return to?

Survey Fee:

2)

Add Fee: Site Insp (\$

Transportation

Interview (\$

3) 50

Tech Trivs (\$

4) Photos

Weekend (\$

5) Other

Report Format:

Lump Sum / I.B.I: (\$ 15k LIS

6) 50

7) 27/5/19

TOTAL

15x15 = 225
170 + 225
50
50 + 50
239
784

MOTOR SURVEY ASSIGNMENT

Date	11-01-2019	Our Ref No. D19000367MFSH
Accident Date	10-01-2019	Claim Type. Third Party
Insured Vehicle	SHC0647Z	Third Party Vehicle. SLM1737R
Survey Location	2 KAKI BUKIT AVENUE 2 #01-18 KAKI BUKIT AUTOHUB	
Contact Person.	MELODY CHIN	
Contact No.	68420051/ 0	Fax No. 67410510
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	N-51 AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 15 January 2019 2:44 PM
To: 'Joanne Yong Lai fong'; 'CWS Motor Claims'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D19000367MFSH/1

Dear Joanne,

Please be informed that we have inspected the vehicle SLM 1737R on 14/01/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 14 January 2019 10:06 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <JoanneYong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000367MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 11 January 2019 7:09 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <JoanneYong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000367MFSH/1


Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005 93865479

*TP 1st Cap.
 Shirley.*

ESTIMATE

Repair Code : CLM14996

Date in : 10/01/2019

Vehicle Num. : SLM1737R

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31230380/LEB5930392

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON CONDENSER <i>But</i>	1	568.10	✓ 568.10
AIRCON CONDENSER AIR GUIDE L/R <i>2 not see</i>	2	32.00	+ 64.00
FRONT BONNET MECHANISM LOCK	1	95.00	+ 95.00
FRONT BUMPER <i>Reformed</i>	1	810.70	✓ 810.70
FRONT BUMPER FOGLAMP BRACKET L/R <i>could</i>	2	22.00	✓ 44.00
FRONT BUMPER FOGLAMP GARNISH L/R <i>could</i>	2	45.00	✓ 90.00
FRONT BUMPER FOGLAMP L/R <i>could</i>	2	327.70	✓ 655.40
FRONT BUMPER LOWER GRILLE <i>Never</i>	1	77.50	+ 77.50
FRONT BUMPER LOWER LID <i>could</i>	1	381.00	✓ 381.00
FRONT BUMPER REINFORCEMENT <i>But</i>	1	321.00	✓ 321.00
FRONT BUMPER REINFORCEMENT MOULDING GARNISH L/R <i>Reformed</i>	2	50.40	✓ 100.80
FRONT BUMPER SIDE RETAINER L/R <i>Not</i>	2	20.60	✓ 41.20
FRONT GRILLE <i>could</i>	1	351.80	✓ 351.80
FRONT GRILLE 'LOGO' EMBLEM <i>Not</i>	1	23.40	✓ 23.40
FRONT GRILLE CENTER BRACKET <i>could</i>	1	76.00	✓ 76.00
FRONT GRILLE CHROME MOULDING <i>could</i>	1	58.80	✓ 58.80
FRONT GRILLE OUTER COVER <i>could</i>	1	421.00	242 421.00
FRONT GRILLE TOP GARNISH <i>Not</i>	1	85.00	+ 85.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005 93865479

ESTIMATE

Repair Code : CLM14996

Date in : 10/01/2019

Vehicle Num. : SLM1737R

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31230380/LEB5930392

FRONT HEADLAMP L/R <i>cracked</i>	2	1784.50	✓ 3,569.00
FRONT HEADLAMP LOWER BRACKET L/R <i>cracked</i>	2	35.00	✓ 70.00
FRONT HEADLAMP SIDE BRACKET L/R <i>cracked</i>	2	35.00	✓ 70.00
FRONT NUMBER PLATE <i>cracked</i>	1	25.00	✓ 25.00
REAR BUMPER <i>deformed</i>	1	762.70	✓ 762.70
REAR BUMPER LOWER COVER <i>deformed</i>	1	250.00	✓ 250.00
REAR BUMPER REFLECTOR L/R <i>cracked</i>	2	141.10	✓ 282.20
REAR BUMPER SIDE L/R <i>deformed</i>	2	195.00	✓ 390.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	23.00	✓ 46.00
REAR END PANEL <i>Deformed</i>	1	415.60	✓ 415.60
REAR END PANEL ANTENNA SENSOR <i>cracked.</i>	1	60.10	✓ 60.10
REAR END PANEL BUZZLE SENSOR <i>cracked</i>	1	85.20	✓ 85.20
REAR END PANEL INNER TOP GARNISH <i>deformed</i>	1	98.00	✓ 98.00
REAR EXHAUST ALUMINIUM HEAT SHIELD <i>cracked.</i>	1	55.00	✓ 55.00
REAR EXHAUST CHROME TAIL PIPE <i>Best</i>	1	135.00	✓ 135.00
REAR EXHAUST RUBBER MOUNTING <i>new</i>	2	16.50	✗ 33.00
REAR EXHAUST SILENCER BOX <i>Best</i>	1	517.70	✗ 517.70
REAR EXHAUST SILENCER BOX GASKET <i>new</i>	1	48.30	✗ 48.30

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005 93865479

ESTIMATE

Repair Code : CLM14996
 Date in : 10/01/2019
 Vehicle Num. : SLM1737R
 Model : HONDA VEZEL HYBRID 1.5X AUTO
 Chassis/Eng# : RU31230380/LEB5930392

REAR FENDER ARCH GARNISH L/R	LH Cambd	2	195.00	185	390.00
REAR FENDER INNER TRIM GARNISH L/R	reband	2	295.00	✓	590.00
REAR FLOOR JACK PANEL	Bent	1	95.00	✓	95.00
REAR FLOOR PANEL	Distorted	1	662.20	✓	662.20
REAR FLOOR PANEL COMPARTMENT TRAY GARNISH	reband	1	485.30	285	485.30
REAR FLOOR PANEL CROSS MEMBER (NO:1)	} new	1	180.00	+	180.00
REAR FLOOR PANEL CROSS MEMBER (NO:2)		1	250.00	+	250.00
REAR FLOOR PANEL INNER TOP BOARD COVER	reband	1	430.30	255	430.30
REAR HYBRID UNIT AIR DUCT	reband	1	98.00	✓	98.00
REAR HYBRID UNIT BLOWER MOTOR	crushed	1	540.00	✓	540.00
REAR HYBRID UNIT BLOWER MOTOR AIR DUCT	new	1	75.00	X	75.00
REAR HYBRID UNIT TOP PANEL COVER	Bent	1	315.00	✓	315.00
REAR HYBRID UNIT TRAY GARNISH	reband	1	285.40	✓	285.40
REAR TAILGATE	Distorted	1	953.30	✓	953.30
REAR TAILGATE 'HYBRID' EMBLEM	} new	1	75.50	✓	75.50
REAR TAILGATE 'VEZEL' EMBLEM		1	56.20	✓	56.20
REAR TAILGATE HINGES L/R	new	2	50.00	X	100.00
REAR TAILGATE INNER PULL GARNISH	new	1	27.50	X	27.50

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 93865479

ESTIMATE

Repair Code : CLM14996

Date in : 10/01/2019

Vehicle Num. : SLM1737R

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31230380/LEB5930392

REAR TAILGATE INNER TRIM GARNISH <i>cracked</i>	1	153.40	✓ 153.40
REAR TAILGATE MECHANISM LOCK <i>Damaged</i>	1	180.00	✓ 180.00
REAR TAILGATE MECHANISM LOCK STRIKER <i>Best here</i>	1	27.50	✓ 27.50
REAR TAILGATE OPENER BUTTON SENSOR	1	175.50	X 175.50
REAR TAILGATE OUTER GARNISH <i>cracked</i>	1	220.00	✓ 220.00
REAR TAILGATE OUTER GARNISH 'H' LOGO EMBLEM <i>new</i>	1	25.00	✓ 25.00
REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R <i>new</i>	2	38.50	40 77.00
REAR TAILGATE REFLECTOR L/R <i>wt</i>	2	413.20	✓ 826.40
REAR TAILGATE RUBBER GUIDE STOPPER L/R <i>new</i>	2	18.50	X 37.00
REAR TAILGATE WEATHER STRIP <i>wt</i>	1	96.80	✓ 96.80
REAR TAILGATE WINDSCREEN INNER SEAL <i>new</i>	2	65.30	✓ 130.60
REAR TAILGATE WINDSCREEN MOULDING <i>new</i>	2	50.00	✓ 100.00
REAR TAILLAMP L/R <i>cracked</i>	2	474.60	✓ 949.20
Subtotal before discount			19,784.60
Percentage discount 20%			3,956.92
Sub-total 1			15,827.68
FRONT BUMPER CLIPS - SET <i>new</i>	1	50.00	30 50.00
FRONT GRILLE CLIPS - SET <i>new</i>	1	50.00	20 50.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005 93865479

ESTIMATE

Repair Code : CLM14996
 Date in : 10/01/2019
 Vehicle Num. : SLM1737R
 Model : HONDA VEZEL HYBRID 1.5X AUTO
 Chassis/Eng# : RU31230380/LEB5930392

FRONT NUMBER PLATE HOLDER <i>ok hand</i>	1		50.00	30.50.00
REAR BUMPER CLIPS - SET <i>new</i>	1		50.00	30.50.00
REAR BUMPER REVERSE SENSOR <i>ok hand</i>	1		250.00	20.250.00
REAR FENDER ARCH GARNISH CLIPS L/R - SET <i>new</i>	2		40.00	20.80.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET <i>new</i>	2		50.00	60.100.00
REAR FLOOR PANEL INSULATOR MAT <i>new</i>	1		250.00	200.250.00
REAR NUMBER PLATE <i>3 new</i>	1		25.00	X 25.00
REAR NUMBER PLATE HOLDER <i>3 new</i>	1		50.00	X 50.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET <i>new</i>	1		100.00	30.100.00
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>new</i>	1	710	40.00	10.40.00
REAR TAILGATE REVERSE CAMERA <i>new new</i>	1		800.00	X 800.00
REAR TAILGATE SPOILER CLIPS - SET <i>new new</i>	1		50.00	X 50.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1		60.00	✓ 60.00
REAR TAILLAMP CLIPS L/R - SET <i>new</i>	2		30.00	20.60.00
			Subtotal before discount	2,065.00
Percentage discount 0%				0.00
			Sub-total 2	2,065.00
			Parts-total	17,892.68

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005 93865479

ESTIMATE

Repair Code : CLM14996
 Date in : 10/01/2019
 Vehicle Num. : SLM1737R
 Model : HONDA VEZEL HYBRID 1.5X AUTO
 Chassis/Eng# : RU31230380/LEB5930392

LABOUR

To remove, change air con parts, vacuums, refill air con gas.	X	120.00
To reset system after repair works	X	400.00
To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	✓	100.00
To remove, reinstall tailgate windscreen	120	150.00
To remove, reinstall rear suspension and undercarriage part. (to FR)	X	250.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	100	150.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	800	2,000.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	X	120.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1800	2,300.00
To mount vehicle on to Car 'O' Liner.	X	350.00
To apply anti-rust chemical on repaired and replaced panel.	60	120.00
To remove, reinstall tailgate mechanism and check for function	✓	80.00
To remove and reinstall hybrid converter unit, hose bracket and other attachment parts. Diagnosis, repair and check for function.	300	1,500.00
		<hr/>
Labour Total		7,640.00
Parts & Labour Total		25,532.68

3860

total 18808.80
 L/S: 15K

14 Days

15K

LKK Auto Consultants hence notify the Repairer of the following: *** This is a computer-generated document which requires no signature.***

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19000766/Asd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 03-06-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 647Z	Veh. Inspected	SLM 1737R
Policy No.		Coverage (\$)	0.00
Claim No.	D19000367MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	11/01/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU31230380	Colour	BLACK
Odometer	173300	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	HABILEAD	6 mm
L/H Front Tyre	215/60 R16	HABILEAD	6 mm
R/H Rear Tyre	215/60 R16	HABILEAD	6 mm
L/H Rear Tyre	215/60 R16	HABILEAD	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	10/01/2019	Inspection Date	14/01/2019
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 1737R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	AIRCON CONDENSER	BENT	568.10	568.10
2	AIRCON CONDENSER AIR GUIDE L/R @\$32.00	NOT NECESSARY	64.00	-
1	FRONT BONNET MECHANISM LOCK	NOT NECESSARY	95.00	-
1	FRONT BUMPER	DEFORMED	810.70	810.70
2	FRONT BUMPER FOGLAMP BRACKET L/R @\$22.00	CRACKED	44.00	44.00
2	FRONT BUMPER FOGLAMP GARNISH L/R @\$45.00	CRACKED	90.00	90.00
2	FRONT BUMPER FOGLAMP L/R @\$327.70	CRACKED	655.40	655.40
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	77.50	-
1	FRONT BUMPER LOWER LID	CRACKED	381.00	381.00
1	FRONT BUMPER REINFORCEMENT	BENT	321.00	321.00
2	FRONT BUMPER REINFORCEMENT MOULDING GARNISH L/R @\$50.40	DEFORMED	100.80	100.80
2	FRONT BUMPER SIDE RETAINER L/R @\$20.60	NECESSARY	41.20	41.20
1	FRONT GRILLE	CRACKED	351.80	351.80
1	FRONT GRILLE "LOGO" EMBLEM	NECESSARY	23.40	23.40
1	FRONT GRILLE CENTER BRACKET	CRACKED	76.00	76.00
1	FRONT GRILLE CHROME MOULDING	CRACKED	58.80	58.80
1	FRONT GRILLE OUTER COVER	CRACKED	421.00	242.00
1	FRONT GRILLE TOP GARNISH	NOT NECESSARY	85.00	-
2	FRONT HEADLAMP L/R @\$1784.50	CRACKED	3,569.00	3,569.00
2	FRONT HEADLAMP LOWER BRACKET L/R @\$35.00	CRACKED	70.00	70.00
2	FRONT HEADLAMP SIDE BRACKET L/R @\$35.00	CRACKED	70.00	70.00
1	FRONT NUMBER PLATE	CRACKED	25.00	25.00
1	REAR BUMPER	DEFORMED	762.70	762.70
1	REAR BUMPER LOWER COVER	DEFORMED	250.00	250.00
2	REAR BUMPER REFLECTOR L/R @\$141.10	CRACKED	282.20	282.20
2	REAR BUMPER SIDE L/R @\$195.00	DEFORMED	390.00	390.00
2	REAR BUMPER SIDE RETAINER L/R @\$23.00	NECESSARY	46.00	46.00
1	REAR END PANEL	DENTED	415.60	415.60
1	REAR END PANEL ANTENNA SENSOR	CRACKED	60.10	60.10
1	REAR END PANEL BUZZLE SENSOR	CRACKED	85.20	85.20

Report Ref No. CS/FCI19000766/Asd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	98.00	98.00
1	REAR EXHAUST ALUMINIUM HEAT SHIELD	CRUMPLED	55.00	55.00
1	REAR EXHAUST CHROME TAIL PIPE	BENT	135.00	135.00
2	REAR EXHAUST RUBBER MOUNTING @\$16.50	NOT NECESSARY	33.00	-
1	REAR EXHAUST SILENCER BOX	BENT	517.70	517.70
1	REAR EXHAUST SILENCER BOX GASKET	NECESSARY	48.30	48.30
2	REAR FENDER ARCH GARNISH L/R @\$195.00	N/S CRACKED	390.00	195.00
2	REAR FENDER INNER TRIM GARNISH L/R @\$295.00	DEFORMED	590.00	590.00
1	REAR FLOOR JACK PANEL	BENT	95.00	95.00
1	REAR FLOOR PANEL	DISTORTED	662.20	662.20
1	REAR FLOOR PANEL COMPARTMENT TRAY GARNISH	DEFORMED	485.30	285.00
1	REAR FLOOR PANEL CROSS MEMBER (NO:1)	NOT NECESSARY	180.00	-
1	REAR FLOOR PANEL CROSS MEMBER (NO:2)	NOT NECESSARY	250.00	-
1	REAR FLOOR PANEL INNER TOP BOARD COVER	DEFORMED	430.30	255.00
1	REAR HYBRID UNIT AIR DUCT	DEFORMED	98.00	98.00
1	REAR HYBRID UNIT BLOWER MOTOR	CRACKED	540.00	540.00
1	REAR HYBRID UNIT BLOWER MOTOR AIR DUCT	NOT NECESSARY	75.00	-
1	REAR HYBRID UNIT TOP PANEL COVER	BENT	315.00	315.00
1	REAR HYBRID UNIT TRAY GARNISH	DEFORMED	285.40	285.40
1	REAR TAILGATE	DISTORTED	953.30	953.30
1	REAR TAILGATE "HYBRID" EMBLEM	NECESSARY	75.50	75.50
1	REAR TAILGATE "VEZEL" EMBLEM	NECESSARY	56.20	56.20
2	REAR TAILGATE HINGES L/R @\$50.00	NOT NECESSARY	100.00	-
1	REAR TAILGATE INNER PULL GARNISH	NOT NECESSARY	27.50	-
1	REAR TAILGATE INNER TRIM GARNISH	CRACKED	153.40	153.40
1	REAR TAILGATE MECHANISM LOCK	DAMAGED	180.00	180.00
1	REAR TAILGATE MECHANISM LOCK STRIKER	BENT	27.50	27.50
1	REAR TAILGATE OPENER BUTTON SENSOR	NOT NECESSARY	175.50	-
1	REAR TAILGATE OUTER GARNISH	CRACKED	220.00	220.00
1	REAR TAILGATE OUTER GARNISH "H" LOGO EMBLEM	NECESSARY	25.00	25.00
2	REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R @\$38.50	NECESSARY	77.00	40.00
2	REAR TAILGATE REFLECTOR L/R @\$413.20	CUT	826.40	826.40

Report Ref No. CS/FCI19000766/Asd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR TAILGATE RUBBER GUISE STOPPER L/R @\$18.50	NOT NECESSARY	37.00	-
1	REAR TAILGATE WEATHER STRIP	CUT	96.80	96.80
2	REAR TAILGATE WINDSCREEN INNER SEAL @\$65.30	NECESSARY	130.60	130.60
2	REAR TAILGATE WINDSCREEN MOULDING @\$50.00	NECESSARY	100.00	100.00
2	REAR TAILLAMP L/R @\$474.60	CRACKED	949.20	949.20
	LESS 20% DISCOUNT		-3,956.92	-3,559.70
			15,827.68	14,238.80
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	50.00	20.00
1	FRONT NUMBER PLATE HOLDER (SN)	DEFORMED	50.00	30.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
2	SET REAR FENDER ARCH GARNISH CLIPS L/R @\$40.00 (SN)	NECESSARY	80.00	20.00
2	SET REAR FENDER INNER TRIM GARNISH CLIPS L/R @\$50.00 (SN)	NECESSARY	100.00	60.00
1	REAR FLOOR PANEL INSULATOR MAT (SN)	NECESSARY	250.00	200.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	REAR NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
1	SET REAR TAILGATE INNER TRIM GARNISH CLIPS (SN)	NECESSARY	100.00	30.00
1	SET REAR TAILGATE OUTER GARNISH CLIPS (SN)	NECESSARY	40.00	10.00
1	REAR TAILGATE REVERSE CAMERA (SN)	NOT NECESSARY	800.00	-
1	SET REAR TAILGATE SPOILER CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
2	SET REAR TAILLAMP CLIPS L/R @\$30.00 (SN)	NECESSARY	60.00	20.00
			2,065.00	710.00
	<u>LABOUR</u>			
	TO REMOVE,CHANGE AIR CON PARTS,VACUUMS,REFILL AIR CON GAS.	NOT NECESSARY	120.00	-
	TO RESET SYSTEM AFTER REPAIR WORKS.	NOT NECESSARY	400.00	-
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR.		100.00	100.00

Report Ref No. CS/FCI19000766/Asd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE,REINSTALL TAILGATE WINDSCREEN.		150.00	120.00
	TO REMOVE,REINSTALL REAR SUSPENSION AND UNDERCARRIAGE PART (TO FR).	NOT NECESSARY	250.00	-
	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR).		150.00	100.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT.		2,000.00	1,300.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	NOT NECESSARY	120.00	-
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		2,300.00	1,800.00
	TO MOUNT VEHICLE ON TO CAR "O" LINER.	NOT NECESSARY	350.00	-
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	60.00
	TO REMOVE,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION.		80.00	80.00
	TO REMOVE AND REINSTALL HYBRID CONVERTER UNIT,HOSE BRACKET AND OTHER ATTACHMENT PARTS,DIAGNOSIS,REPAIR AND CHECK FOR FUNCTION.		1,500.00	300.00
			7,640.00	3,860.00
GRAND TOTAL			25,532.68	18,808.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				15,000.00

Report Ref No. CS/FCI19000766/Asd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.