

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG19000782/JEB3S2**Date:** 03/10/2019REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100418857
Claimant Vehicle No :	SHB5063E	Insured Vehicle No :	SJM7017U
Date of Loss:	08/01/2019	Nature of Claim:	TP
		Claim No:	8619165073SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5063E	Engine No:	2ZRS098462
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKB3FU803573001
Reg. Date:	12/10/2017 (Man. Year: 2017)	Odometer:	165598 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,542.90	2,209.10	5,333.80	70.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,768.00	1,380.00	2,388.00	63.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	11,310.90	3,589.10	7,721.80	68.27
+ Loss of Use (6.5 x S\$50.00/day) (S\$)		325.00		
+ Car Rental (6.5 x S\$117.17/day) (S\$)		761.61		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		4,682.71		
Global Sum Settlement (S\$)		4,680.00		

INSPECTION

Date of Assignment:	10/01/2019	
Date Inspected:	10/01/2019	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	5.0 days	

Adjuster: ONG HWEE JIE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, RR BUMPER ASSY (DISC 25%)	Dented	423.90 F	*317.93 F
2	1		*CLIPS PIECE, FRT & RR BUMPER (DISC 25%) 10pcs	Necessary	15.00 F	*11.25 F
3	2		*PAD, RR BUMPER, RH & LH, 1 (DISC 25%)	Necessary	7.60 F	*5.70 F
4	2		*PAD, RR BUMPER, RH & LH, 2 (DISC 25%)	Necessary	7.60 F	*5.70 F
5	2		*PAD, RR BUMPER, RH & LH, 3 (DISC 25%)	Necessary	7.60 F	*5.70 F
6	2		*SEAL, RR BUMPER ARM, RH & LH (DISC 25%)	Necessary	22.00 F	*16.50 F
7	1		*SEAL, RR BUMPER, LH (DISC 25%)	Missing	85.20 F	*63.90 F
8	1		*FILLER, RR BUMPER, LH (DISC 25%)	Deformed	119.90 F	*89.93 F
9	1		*RETAINER, RR BUMPER, LH (DISC 25%)	Cracked	111.50 F	*83.63 F
10	1		*REAR BUMPER REINFORCEMENT (DISC 25%)	Dented	318.80 F	*239.10 F
11	1		*GUARD, RR BUMPER, LOWER (DISC 25%)	Deformed	558.30 F	*418.73 F
12	1		*COVER, GUARD RR BUMPER LOWER (DISC 25%)	Necessary	14.80 F	*11.10 F
13	3		*PAD, RR BUMPER, CTR (DISC 25%)	Necessary	6.60 F	*4.95 F
14	1		*EMBLEM SUB-ASSY REAR (DISC 25%)	Necessary	46.30 F	*34.73 F
15	1		*NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR (DISC 25%)	Necessary	52.30 F	*39.23 F
16	1		*NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR (DISC 25%)	Necessary	52.30 F	*39.23 F
17	1		*LENS & BODY ASSY, RR BUMPER, LH (DISC 10%)	Cracked	486.80 F	*438.12 F
18	1		*ANTENNA, ELECTRICAL KEY (DISC 10%)	Shorted	60.30 F	*54.27 F
19	1		*SENSOR REVERSE (SN)	Shorted	180.00 F	*180.00 F
20	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
21	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
22	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
23	1		*FILLER, RR BUMPER, RH	Not Necessary	119.90 F	*- F
24	1		*RETAINER, RR BUMPER, RH	Not Necessary	112.70 F	*- F
25	1		*COVER, REAR FLOOR UNDER, LH	Not Necessary	234.30 F	*- F
26	1		*COVER, REAR FLOOR UNDER, RH	Not Necessary	169.50 F	*- F
27	1		*WIRE LUGGAGE ROOM	Not Necessary	143.50 F	*- F
28	1		*TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	Not Necessary	27.90 F	*- F
29	1		*TAIL GATE MOULDING GLASS, BACK DOOR	Not Necessary	29.70 F	*- F
30	1		*TAIL GATE LOCK ASSY, BACK DOOR	Not Necessary	452.10 F	*- F
31	1		*TAIL GATE LOCK COVER, BACK DOOR	Not Necessary	25.30 F	*- F
32	1		*TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH	Not Necessary	29.90 F	*- F
33	1		*TAIL GATE MOULDING LOWER GLASS BACK DOOR, RH	Not Necessary	29.90 F	*- F
34	1		*TAIL GATE MOULDING LOWER GLASS, BACK DOOR	Not Necessary	19.70 F	*- F
35	1		*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	Not Necessary	891.20 F	*- F
36	3		*SEALANT W/SCREEN	Not Necessary	111.00 F	*- F
37	1		*TAIL GATE STRIKER ASSY, BACK DOOR	Not Necessary	24.90 F	*- F
38	1		*TAIL GATE WEATHERSTRIP, BACK DOOR	Not Necessary	360.70 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*END PANEL, SUBASSY, BODY LOWER BACK	Not Necessary	629.80 F	*- F
40	1		*SEALANT SIKAFLEX	Not Necessary	37.00 F	*- F
41	1		*LENS & BODY, REAR COBINATION LAMP, LH	Not Necessary	438.10 F	*- F
42	1		*TAIL GATE PANEL SUB-ASSY, BACK DOOR	Repair	929.60 F	*- F

F=Franchise part.

Total Parts (\$)	7,542.90	2,209.10
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	1,014.00	600.00
2	SPRAY PAINT.	New	1,656.00	650.00
3	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	20.00
4	TO TRANSFER REAR TAILGATE MECHANISM.	New	120.00	0.00
5	TO REMOVE AND REFIX REAR WINDSCREEN.	New	240.00	0.00
6	TO REMOVE AND REFIT WIRE HARDESS.	New	200.00	0.00
7	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	New	120.00	20.00
8	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	New	120.00	50.00
9	TO REPLACE SUNDRY PARTS.	New	100.00	0.00
10	TO WASH AND VACUUM.	New	60.00	0.00
11	TOWING CHARGE.	New	58.00	40.00
Gross Labour Cost (\$\$)			3,768.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >