

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG19000809/KVD3E2

**Date:** 27/03/2019

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700053075
<b>Claimant Vehicle No :</b> SJT6679D	<b>Insured Vehicle No :</b>	SLS2550Z
Date of Loss: 04/01/2019	Nature of Claim:	TP Claim No: 8842709626SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJT6679D</b>		
Make & Model:	MAZDA 3, 1.6 L (A)	Engine No:	Z6808910
Reg. Date:	26/10/2009 (Man. Year: 2009)	Chassis No:	JM6BL10Z1A0114535
Colour:	Metallic Grey	Odometer:	176635 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Michelin 3 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Michelin 3 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,736.76	3,350.88	5,385.88	61.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	1,400.00	2,500.00	64.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,636.76</b>	<b>4,750.88</b>	<b>7,885.88</b>	<b>62.40</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,636.76</b>	<b>3,800.00</b>	<b>8,836.76</b>	<b>69.93</b>

#### INSPECTION

Date of Assignment:	14/01/2019	
Date Inspected:	16/01/2019 Inspected At:	Auburn Auto Pte Ltd (HQ) 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE Singapore 575721
Estimated Period of Repair:	5.0 days	

**Adjuster:** KENNETH KONG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT BUT NOT AGREED WITH OUR RECOMMENDATION.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	949.30 FL	*949.30 FL
2	1		*REAR BOOT LOCK	Dented	148.80 FL	*148.80 FL
3	1		*REAR BOOT RUBBER	Serviceable	118.80 FL	*- FL
4	2		*REAR BOOT HINGES	Repair	216.40 FL	*- FL
5	1		*REAR BOOT 3 EMBLEM	Necessary	40.50 FL	*40.50 FL
6	1		*REAR BOOT MAZDA EMBLEM	Necessary	48.60 FL	*48.60 FL
7	1		*REAR BOOT LOGO	Necessary	56.90 FL	*56.90 FL
8	2		*REAR BOOT LAMPS	Serviceable	522.90 FL	*- FL
9	2		*REAR TAILLAMPS	Serviceable	2,076.80 FL	*- FL
10	1		*REAR END PANEL	Repair	321.80 FL	*- FL
11	1		*REAR END PANEL INNER GARNISH	Serviceable	162.80 FL	*- FL
12	1		*REAR BUMPER	Buckled	1,026.70 FL	*1,026.70 FL
13	2		*REAR BUMPER BRACKETS	Cracked	30.00 FL	*30.00 FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	454.50 FL	*454.50 FL
15	2		*REAR BUMPER SIDE RETAINERS	Serviceable	77.00 FL	*- FL
16	2		*REAR BUMPER REFLECTORS	Cracked	117.00 FL	*117.00 FL
17	1		*REAR SPARE TYRE BOARD	Serviceable	411.10 FL	*- FL
18	1		*REAR EXHAUST SILENCER	Bent	953.80 FL	*953.80 FL
19	2		*REAR EXHAUST MOUNTINGS	Serviceable	91.00 FL	*- FL
20	2		*REAR FENDER INNER TRIMS	Serviceable	319.00 FL	*- FL
21	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
22	1		*REAR NUMBER PLATE WITH HOLDER	Cracked	50.00 FS	*45.00 FS
23	1		*SET REAR REVERSE SENSOR	Dented	350.00 FS	*200.00 FS
24	1		*REAR SPARE TYRE PANEL	Repair	2,221.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>10,809.70</b>	<b>4,116.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	2,072.94	765.22
<b>Total Parts (\$)</b>	<b>8,736.76</b>	<b>3,350.88</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY	New	120.00	50.00
5	TO REMOVE, REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	60.00
6	TO APPLY TUFF KOTE	New	150.00	0.00
7	PANEL BEATING	New	1,600.00	500.00
8	TO RESPRAY PAINTING	New	1,500.00	660.00
<b>Gross Labour Cost (S\$)</b>			<b>3,900.00</b>	<b>1,400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >