

INS. CASE OWNER:

CC 3, 071 1900

0890, Jka3 sr

LKK:
IDAC:

Su

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

23/1

nc

4/4/19

16/8/19

2/12/19

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

15/1

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 24/4/19-JL

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

Repair Cost:

SS 2942.20

Loss of Rental (LOR):

SS 886.00

(

8

days) x

\$110.75

Loss of Use (LOU):

SS

-

(\$

x

days)

Loss of Income (LOI):

SS 911.60

(\$

113.75 x

8

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS 7.00

Medical:

SS

-

Disbursement:

SS

-

Legal Cost

SS

-

Total:

SS 4746.80

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 4746.80

Name 1:

SMART Taxis Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400

COPY SENT

REP: CIT

Huse Jc

ASSIGNMENT

From: Date: 14/1/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHB5248P

at Workshop n/s

of

SMRT
woodlands Depot

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{hup}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SHB5248P

Yr Regn: 19/2/16

Type: M/Car / M/Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make: Toyota Prius

cc: 1798

Colour: Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKN36UX05767458

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 11/1/19

D.O.I. 14/1/19

Survey held at

Smrd

Des. of Damages: Front / Seat / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/P - \$2942.20 (Red \$ 9699.44 / 772)

01/19/2052

SJB6393Y

SHD3182Y

SHB4967D

Date/Time: File Pass to?



: Preli. Report

1)



: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1) S + RS \$

2) Photos

3) Other

4) ...

TOTAL

Report Format:

Lump Sum / I.B.I. (\$)

Add Fee:



Site Insp. (\$)



Interview (\$)





Tech. Invs (\$)



Weekend (\$)

Section A - Accident Details

Registration Number	SHB6248P
Case Reference Number	TAX/01/19/2052
Registration Date	19/2/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	NG BEE TIAM
Type of Accident	Head to Rear
Accident Date and Time	11/1/2019 8:15 PM
Accident Reported Date and Time	12/1/2019 9:50 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	11/1/2019 8:57 PM
Replacement Vehicle Issued?	No
Job Card Number	24099653
Special Instruction to ARC, if any	TOWED \$40 / CHINA - LKK
Prepared Date and Time	14/1/2019 10:38 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,552.00	\$750.00
Total Spray Cost	\$2,034.00	\$700.00
Total Spare Part Cost	\$7,839.64	\$1,352.20
Total Other Cost	\$1,216.00	\$140.00
TOTAL COST	\$12,641.64	\$2,942.20 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	11.0	6.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / China TaiPing
ARC / Surveyor Sign Off Date	14/01/2019 1:13 PM	14/01/2019 4:08 PM
Signature		
Remarks		P/P repair, photo before paint.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0144	Invoice Number	
Quotation Date	13.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RR END PANEL	\$200.00	\$100.00
TO REPAIR FRONT PORTION	\$338.00	\$200.00
TO REPAIR REAR PORTION	\$1,014.00	\$450.00
Total Labour	\$1,552.00	\$750.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$2,034.00	\$700.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$40.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$30.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$30.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,216.00	\$140.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given
		76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
55 Woodlands Industrial Park EA, Singapore
FAX Number: 63685522
Estimator Telephone Number: 88882823
Accident Reporting Number: 08002072

Date Generated: 15/08/2019

User ID: P08000

52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X
58308-47011	UNDER COVER SUBASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given	X
67005-47241	TAILGATE ASY	1.00	\$1,007.90	100.00	\$0.00	Replace	Repair	X
75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	0.00	\$29.40	0.00	\$0.00	Replace	Not Given	X
75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	0.00	\$29.40	0.00	\$0.00	Replace	Not Given	X
75575-47030	MOULDING BACK WINDOW, LOWER NO.1	0.00	\$29.40	0.00	\$0.00	Replace	Not Given	X
	SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
69350-47030	TAILGATE DOOR LOCK	0.00	\$444.10	0.00	\$0.00	Replace	Not Given	X
67881-47022	TAILGATE DOOR WEATHER STRIP	0.00	\$353.40	0.00	\$0.00	Replace	Not Given	X
69415-47020	TAILGATE LOCK, COVER	0.00	\$15.70	0.00	\$0.00	Replace	Not Given	X
69431-47010	STRIKER, BACK DOOR	0.00	\$48.90	0.00	\$0.00	Replace	Not Given	X
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	X
58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check	X
64718-47031B0	END PANEL COVER, DECK TRIM HOLE	0.00	\$46.10	0.00	\$0.00	Replace	Not Given	X
64716-47031B0	END PANEL COVER, DECK TRIM, RR	0.00	\$121.10	0.00	\$0.00	Replace	Not Given	X
56338-12090	REINFORCEMENT, RR	0.00	\$34.60	0.00	\$0.00	Replace	Check	X
	SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Check	X
58311-47071	SPARE TYRE PANEL	0.00	\$667.70	0.00	\$0.00	Replace	Check	X
64993-47020	BOX, DECK FLOOR, RR	0.00	\$649.70	0.00	\$0.00	Replace	Not Given	X
58416-47030B3	BOX, RR FLOOR, BOARD	0.00	\$679.60	0.00	\$0.00	Replace	Not Given	X
52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair	X
52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace	X
52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given	X
52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Not Given	X
57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X
57013-47030	ARM SUB-ASSY, FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X
52114-47140	BRACKET, FR BUMPER	1.00	\$110.40	25.00	\$82.80	Replace	Replace	X
	NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace	X
	NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace	X
53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given	X
53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Not Given	X
75310-47010	EMBLEM FRONT	0.00	\$86.50	0.00	\$0.00	Replace	Not Given	X
52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given	X
52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given	X
52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace	X
52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace	X
89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Check	X
	SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	X
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	X
Total			\$9,580.52		\$988.52			

1352.20
+ 750.00
+ 840.00
2942.20

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52015-47050	ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
		52016-47030	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace
Total					484.90		363.68		



Case Details

Case Reference Number : TAX/01/19/2052
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5248P

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5329-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd
 Accident Date and Time : 11/01/2019 12:15 PM
 Vehicle Age(In Months) : 35

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give * X N/A
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give * X N/A
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.68	Replace * DE
One Time Key In	Main			BUMPER SEAL RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give * X N/A
One Time Key In	Main			BUMPER SEAL RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give * X N/A
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give * X N/A
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give * X N/A
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give * X N/A
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	0	Repair * X R
									Total Spare Part Cost	7,839.64	Surveyor Total	988.51	
									Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0	
									Final Spare Part Cost	7,839.64	Final Sur Total	988.51	

SMRT Recommendation												Surveyor Approval	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give * X N/A
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give * X N/A
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give * X N/A
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	0	0	Not Give * X N/A
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0	Not Give * X N/A
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0	Not Give * X N/A
One Time Key In	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.77	Replace	0	0	Not Give * X N/A
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0	Not Give * X N/A
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace * HEC
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check * X N/A
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give * X N/A
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0	Not Give * X N/A
One Time Key In	Main			REINFORCEMENT, RR	2	34.60	69.20	25.00	51.90	Replace	0	0	Check * X N/A
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check * X N/A
Total Spare Part Cost											Surveyor Total	988.51	
Lump Sum Discount (%)										0.00	Lump Sum Dis (%)	0	
Final Spare Part Cost										7,839.64	Final Sur Total	988.51	

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	0	0	Check * X N/A
One Time Key In	Main			BOX, DECK FLOOR, RR	1	649.70	649.70	25.00	487.28	Replace	0	0	Not Givt * X N/A
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	0	0	Not Givt * X N/A
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	0	Repair * R
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace * NEC /
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Givt * X N/A
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Not Givt * X N/A
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Givt * X N/A
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Givt * X N/A
One Time Key In	Main			BRACKET, FR BUMPER	1	110.40	110.40	25.00	82.80	Replace	1	82.80	Replace * CPA /
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace * BUC
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	12.00	Replace * BUC
One Time Key In	Main			BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0	Not Givt * X N/A
One Time Key In	Main			GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	Not Givt * X N/A
Total Spare Part Cost											Surveyor Total	988.51	
Lump Sum Discount (%)											Lump Sum Dis (%)	0	
Final Spare Part Cost											Final Sur Total	988.51	

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			EMBLEM FRONT	1	86.50	86.50	25.00	64.88	Replace	0	0	Not Give * X N/A
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give * X N/A
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give * X N/A
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace / DEF
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace / NEI
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check * X N/A
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check * X N/A
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check * X N/A
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Check * X N/A
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace / Stuart
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace / NEI
Total Spare Part Cost									7,839.64		Surveyor Total	988.51	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost									7,839.64		Final Sur Total	988.51	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR FRONT PORTION	336.00	200	
2	TO REPAIR REAR PORTION	1,014.00	450	
Total:		1,352.00	650.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY FRONT BUMPER	378.00	200	
2	TO REPSRAY REAR BUMPER	378.00	200	
3	TO RESPRAY BUMPER BEAM	180.00	0	
4	TO RESPRAY TAIL GATE	378.00	200	
5	TO RESPRAY REAR PANEL	180.00	0	
6	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	
7	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0	
Total:		1,854.00	600.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TOWING CHARGE	56.00	40	
2	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	N/C
3	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0	
4	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	N/C
5	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0	
6	TO REMOVE AND REFIT WIRE HARDESS	200.00	0	
7	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	30	N/C
8	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30	N/C
9	TO REPLACE SUNDRY PARTS	100.00	0	
10	TO WASH AND VACUUM	60.00	0	
Total:		1,216.00	140	

15,350.10

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	7,839.64	988.51
Total Labour Cost	1,352.00	650.00
Total Spray Painting	1,854.00	600.00
Other	1,216.00	100.00
Overall Total	12,261.64	2,338.51
Lump Sum Repair Option		
Lump Sum Total	0.00	2,338.51
Surveyor Approved Amount		2,338.51
No of Repair Days*	10	5
Remarks		P/P repair, photo before paint.
Surveyor Name		Hwee Jie
Signature		

Save Clear

Survey Date 14/01/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	TAX/01/19/2952	Date of Collection	15/1/19
Vehicle No	SH13 5248P	Date of Request	18/1/19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	12 DAYS

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price	
1	6217,18,19,20,21	Bumper Reinforcement Rear		\$1205.70	DN ✓ \$154.28
2	6224,25	Arm Sub Assy RR Bumper LH		\$139.60	BT ✓ \$104.70
3	6222,23	Arm Sub Assy RR Bumper RH		\$139.60	BT ✓ \$104.70
4	6227,28,29	To Repair End Panel		\$200.00 \$100	✓
5		To Respray End Panel		\$180.00 \$100	✓
6					
7					
8					

I, (Name) CHIA

(Position) ADVISOR

<<<Please submit photographs for damaged parts>>>

21/1/19

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Charles

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff



Case Details

Case Reference Number : TAX/01/19/2052
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5248P

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5329-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd
 Accident Date and Time : 11/01/2019 12:15 PM
 Vehicle Age(In Months) : 35

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval		
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.68	Replace
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	0	Repair
									Total Spare Part Cost	7,839.64	Surveyor Total	988.51	
									Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0	
									Final Spare Part Cost	7,839.64	Final Sur Total	988.51	

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give *
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give *
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give *
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	0	0	Not Give *
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0	Not Give *
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0	Not Give *
One Time Key In	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.77	Replace	0	0	Not Give *
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0	Not Give *
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace * NE
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check *
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give *
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0	Not Give *
One Time Key In	Main			REINFORCEMENT, RR	2	34.60	69.20	25.00	51.90	Replace	0	0	Check *
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check *
Total Spare Part Cost									7,839.64		Surveyor Total	988.51	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost									7,839.64		Final Sur Total	988.51	

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	0	0	Check	▼
One Time Key In	Main			BOX, DECK FLOOR, RR	1	649.70	649.70	25.00	487.28	Replace	0	0	Not Give	▼
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	0	0	Not Give	▼
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	0	Repair	▼
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	▼ NGC
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Give	▼
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Not Give	▼
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give	▼
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give	▼
One Time Key In	Main			BRACKET, FR BUMPER	1	110.40	110.40	25.00	82.80	Replace	1	82.80	Replace	▼ CPA
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace	▼ BK
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	12.00	Replace	▼ BK
One Time Key In	Main			BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0	Not Give	▼
One Time Key In	Main			GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	Not Give	▼
Total Spare Part Cost									7,839.64		Surveyor Total	988.51		
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	0		
Final Spare Part Cost									7,839.64		Final Sur Total	988.51		

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			EMBLEM FRONT	1	86.50	86.50	25.00	64.88	Replace	0	0	Not Give
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Check
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace
Total Spare Part Cost									7,839.64		Surveyor Total	988.51	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost									7,839.64		Final Sur Total	988.51	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR FRONT PORTION	338.00	200	
2	TO REPAIR REAR PORTION	1,014.00	450	
Total:		1,352.00	650.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY FRONT BUMPER	378.00	200	
2	TO REPSRAY REAR BUMPER	378.00	200	
3	TO RESPRAY BUMPER BEAM	180.00	0	
4	TO RESPRAY TAIL GATE	378.00	200	
5	TO RESPRAY REAR PANEL	180.00	0	
6	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	
7	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0	
Total:		1,854.00	600.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TOWING CHARGE	56.00	0	
2	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
3	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0	
4	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
5	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0	
6	TO REMOVE AND REFIT WIRE HARDESS	200.00	0	
7	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	30	
8	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30	
9	TO REPLACE SUNDRY PARTS	100.00	0	
10	TO WASH AND VACUUM	60.00	0	
Total:		1,216.00	100.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	7,839.64	988.51
Total Labour Cost	1,352.00	650.00
Total Spray Painting	1,854.00	600.00
Other	1,216.00	100.00
Overall Total	12,261.64	2,338.51
Lump Sum Repair Option		
Lump Sum Total	0.00	2,338.51
Surveyor Approved Amount		2,338.51
No of Repair Days*	10	5
Remarks		P/P repair, photo before paint.
Surveyor Name		Hwee jie
Signature		
Survey Date	14/01/2019	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI19000890/Jha3

Date: 15.01.2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB 5248P


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14.01.2019 at the premises of M/s SMRT Automotive Services Pte Ltd (Woodlands) and have the following to report:-

Workshop Estimate Amount	: S\$	12,261.64
Revised Estimate Amount	: S\$	2,338.51
"Check" Items Amount	: S\$	1,546.59
Total (Including Check Items)	: S\$	3,885.10
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5.0 days

Yours faithfully,

ONG HWEE JIE
Licensed Appraiser

Mei Kwan (LKKAUTO)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Thursday, 17 January, 2019 12:23 PM
To: Mei Kwan (LKKAUTO)
Cc: Mei Kwan (LKKAUTO); Ong Chin Kiat
Subject: CTP REF NO. SNM19D200250C02 LKK REF NO. CC3/CTI19000890/JHA3 - ACCIDENT INVOLVING SJB6393Y AND SHB5248P ON 11 JANUARY 2019
Attachments: GIA REPORT SJB6393Y.pdf
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear MeiKwan,

We refer to the above matter and your email dated 15 January 2019.

Enclosed herewith our insured GIA Report as requested by you.

Thank you.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road # 16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI19000890/Jda3s2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 04-12-2019	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJB 6393Y	Veh. Inspected	SHB 5248P	
Policy No.	DMPCSN3093121802	Coverage (\$)	0.00	
Claim No.	SNM19D200250C02	Excess (\$)	0.00	
Assign From		Assign Date	14/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTDKN36UX05767458	Colour	MAROON	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	6 mm	
L/H Front Tyre	195/65 R15	FALKEN	6 mm	
R/H Rear Tyre	195/65 R15	FALKEN	6 mm	
L/H Rear Tyre	195/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/01/2019	Inspection Date	14/01/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5248P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER LIP REAR (DISC 25%)	DEFORMED	228.90	171.68
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
10	BUMPER CLIPS @ \$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BRACKET, FR BUMPER (DISC 25%)	CRACKED	110.40	82.80
1	BUMPER REAR (DISC 25%)	DEFORMED	458.80	343.95
10	BUMPER CLIPS @ \$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	NUMBER PLATE (SN)	BUCKLED	15.00	15.00
1	NUMBER PLATE FRAME (SN)	BUCKLED	12.00	12.00
1	SENSOR REVERSE (SN)	SHORTED	180.00	180.00
2	PIXEL STICKER @ \$60.00 (SN)	NECESSARY	120.00	120.00
1	BUMPER LIP COVER RR/LH	NOT NECESSARY	72.20	-
1	BUMPER LIP COVER RR/RH	NOT NECESSARY	118.10	-
1	BUMPER SEAL, RR LH	NOT NECESSARY	88.90	-
1	BUMPER SEAL, RR RH	NOT NECESSARY	65.70	-
1	BUMPER SIDE RETAINER RR/LH	NOT NECESSARY	94.80	-
1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	94.80	-
1	UNDER COVER SUBASSY, RR FLOOR	NOT NECESSARY	514.50	-
1	TAIL GATE DOOR GLASS MOULDING, LH	NOT NECESSARY	29.40	-
1	TAIL GATE DOOR GLASS MOULDING, RH	NOT NECESSARY	29.40	-
1	MOULDING BACK WINDOW, LOWER NO.1	NOT NECESSARY	29.40	-
3	SEALANT W/SCREEN @ \$37.00	NOT NECESSARY	111.00	-
1	TAILGATE DOOR LOCK	NOT NECESSARY	444.10	-
1	TAILGATE DOOR WEATHERSTRIP	NOT NECESSARY	353.40	-
1	TAILGATE LOCK, COVER	NOT NECESSARY	15.70	-
1	STRIKER, BACK DOOR	NOT NECESSARY	48.90	-
1	END PANEL	NOT NECESSARY	602.10	-
1	END PANEL COVER, DECK TRIM HOLE	NOT NECESSARY	46.10	-
1	END PANEL COVER, DECK TRIM, RR	NOT NECESSARY	121.10	-
2	REINFORCEMENT, RR @ \$34.60	NOT NECESSARY	69.20	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	SPARE TYRE PANEL	NOT NECESSARY	667.70	-

Report Ref No. CC3/CTI19000890/Jda3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOX, DECK FLOOR, RR	NOT NECESSARY	649.70	-
1	BOX RR FLOOR, BOARD	NOT NECESSARY	679.60	-
1	BUMPER ENERGY ABSORBER FRT	NOT NECESSARY	78.80	-
1	BUMPER REINFORCEMENT FRT	NOT NECESSARY	498.40	-
1	ARM SUB-ASSY FR BUMPER LH	NOT NECESSARY	250.40	-
1	ARM SUB-ASSY, FR BUMPER RH	NOT NECESSARY	250.40	-
1	BUMPER GRILLE SUB-ASSY, LOWER	NOT NECESSARY	311.10	-
1	GRILLE, RADIATOR	NOT NECESSARY	310.60	-
1	EMBLEM FRONT	NOT NECESSARY	86.50	-
1	BUMPER SUPPORT F/LH	NOT NECESSARY	76.40	-
1	BUMPER SUPPORT F/RH	NOT NECESSARY	76.40	-
1	BUMPER REINFORCEMENT REAR	NOT NECESSARY	205.70	-
1	ARM SUB-ASSY, RR BUMPER LH	NOT NECESSARY	139.60	-
1	ARM SUB-ASSY RR BUMPER RH	NOT NECESSARY	139.60	-
1	ANTENNA, ELECTRICAL LOWER REAR	NOT NECESSARY	157.40	-
1	TAILGATE ASY	TO REPAIR SEE LABOUR	1,007.90	-
1	BUMPER FRT	TO REPAIR SEE LABOUR	482.00	-
1	BUMPER REINFORCEMENT REAR (DISC 25%) (ADDITIONAL)	DENTED	205.70	154.28
1	ARM SUB ASSY RR BUMPER LH (DISC 25%) (ADDITIONAL)	BENT	139.60	104.70
1	ARM SUB ASSY RR BUMPER RH (DISC 25%) (ADDITIONAL)	BENT	139.60	104.70
			10,748.10	1,352.20
LABOUR				
PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF TAILGATE ASY AND BUMPER FRT.			1,352.00	650.00
SPRAY PAINT.			1,854.00	600.00
TOWING CHARGE.			56.00	40.00
TO CHECK WIRING AND SYSTEM FUNCTION.			80.00	20.00
TO TRANSFER TAILGATE MECHANISM.			120.00	-
TO TEST AND REFIX REVERSE SENSOR SYSTEM.			120.00	20.00
TO REMOVE AND REFIX REAR WINDSCREEN.			240.00	-

Report Ref No. CC3/CTI19000890/Jda3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT WIRE HARNESS.	NOT NECESSARY	200.00	-
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	30.00
	TO INSSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	30.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPAIR END PANEL. (ADDITIONAL)		200.00	100.00
	TO RESPRAY END PANEL. (ADDITIONAL)		180.00	100.00
			4,802.00	1,590.00
GRAND TOTAL			15,550.10	2,942.20
RECOMMENDED COST OF REPAIRS				2,942.20

Report Ref No. CC3/CT119000890/Jda3s2

ONG HWEЕ JIE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.