

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19000894/KDA3Q2

Date: 24/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100460852-03

Claimant

Vehicle No : SJJ4767Z

Insured Vehicle No : SLB6224D

Date of Loss: 04/12/2018

Nature of Claim: TP

Claim No: 8922590662SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJJ4767Z**

Make & Model: TOYOTA ESTIMA, 2.4 AERAS (A)

Engine No: 2AZC459229

Reg. Date: 15/09/2008 (Man. Year: 2008)

Chassis No: ACR507069267

Colour: Metallic Pearl White

Odometer: 230018 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40 R18

Rear Tyre Size: 245/40 R18

Front Left Side: Continental 5 mm

Rear Left Side: Continental 7 mm

Front Right Side: Continental 5 mm

Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,210.10	2,377.70	832.40	25.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,840.00	1,530.00	310.00	16.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,050.10	3,907.70	1,142.40	22.62
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	5,050.10	3,100.00	1,950.10	38.62
+ GST 7.00/7.00% (S\$)	353.51	217.00	136.51	38.62
Nett Amount (S\$)	5,403.61	3,317.00	2,086.61	38.62
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,924.45		
Global Sum Settlement (S\$)		3,900.00		

INSPECTION

Date of Assignment: 14/01/2019

Date Inspected: 15/01/2019 Inspected At:

Tai Cheng Motor Vehicle Spray

Painting (HQ)

Block 10 Ang Mo Kio Industrial Park

2A, #01-03 AMK Autopoint

Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE TOTOYA CENTRE EMBLEM	Necessary	88.20 FL	*88.20 FL
2	1		*REAR TAILGATE ESTIMA EMBLEM	Necessary	76.70 FL	*76.70 FL
3	1		*REAR TAILGATE AREAS EMBLEM	Necessary	82.40 FL	*82.40 FL
4	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	80.30 FL	*80.30 FL
5	1		*REAR TAILGATE INNER LOCK	Repair	468.20 FL	*- FL
6	1		*REAR BUMPER	Buckled	576.30 FL	*576.30 FL
7	1		*REAR TAILGATE RUBBER (50%)	Dented / Distorted	290.03 FS	*193.35 FS
8	1		*REAR BUMPER SIDE RETAINER	O/S Distorted	144.80 FL	*72.40 FL
9	1		*REAR TAILGATE LOWER LOCK STRIKER	Repair	42.10 FL	*- FL
10	1		*REAR END PANEL	Necessary	680.70 FL	*680.70 FL
11	1		*REAR END PANEL LOWER COVER GARNISH	Dented	210.40 FL	*210.40 FL
12	1		*REAR END PANEL OUTER CENTRE SENSOR	Service item	171.60 FL	*- FL
13	1		*SUPPLY OF CLIPS	Necessary	30.00 FS	*30.00 FS
14	1		*REAR BUMPER TOP LED LAMP	Necessary	280.00 FS	*150.00 FS
15	1		*REAR BUMPER REVERSE SENSOR	Shorted	240.00 FS	*200.00 FS
16	1		*REAR BUMPER INNER TV ANTENNA	Necessary	180.00 FS	*180.00 FS
17	1		*REAR END PANEL TOP GARNISH	Mtg Cracked	298.40 FL	*298.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,940.13	2,919.15
- List Item Discount on L Items 25.00/25.00% (\$\$)	730.03	541.45
Total Parts (\$\$)	3,210.10	2,377.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL ACCIDENT AFFECTED WIRING TO FACILITATE REPAIR	New	40.00	20.00
2	TO REINSTALL OF REAR REVERSE SENSOR	New	50.00	50.00
3	TO ANTI RUST REAR ACCIDENT PORTION	New	80.00	60.00
4	TO REMOVE REAR COMPARTMENT CARPET ,TRIMS ETC TO FACILITATE REPAIR	New	120.00	60.00
5	TO REMOVE DAMAGED PANELS ,JACKING ,STRAIGHTEN ,KNOCKING FLATTENING OF FLOOR PANEL ,FIXING AND ALIGN OF PARTS	New	800.00	700.00
6	TO RESPAY OF ACCIDENT AFFECTED PORTION	New	750.00	640.00
Gross Labour Cost (S\$)			1,840.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >