

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19000898/AGA3Q2  
**Date:** 12/04/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800063602
<b>Claimant Vehicle No :</b>	GBF9556Z	<b>Insured Vehicle No :</b>	SLM76X
Date of Loss:	10/01/2019	Nature of Claim:	TP
		Claim No:	7536171139SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBF9556Z</b>	Engine No:	1KD2683186
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Chassis No:	JTFHT02P200215617
Reg. Date:	24/04/2017 (Man. Year: 2016)	Odometer:	55536 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	OHTSU 6 mm	Rear Left Side:	OHTSU 6 mm
Front Right Side:	OHTSU 6 mm	Rear Right Side:	OHTSU 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,556.90	3,487.95	3,068.95	46.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,450.00	1,950.00	1,500.00	43.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,006.90</b>	<b>5,437.95</b>	<b>4,568.95</b>	<b>45.66</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,350.00</b>		
(S\$)	10,006.90	4,350.00	5,656.90	56.53
<b>+ GST 7.00/7.00% (S\$)</b>	700.48	304.50	395.98	56.53
<b>Nett Amount (S\$)</b>	<b>10,707.38</b>	<b>4,654.50</b>	<b>6,052.88</b>	<b>56.53</b>
	<b>+ Medical Costs (S\$)</b>	139.20		
	<b>+ Car Rental (10.0 x S\$64.30/day) (S\$)</b>	643.00		
	<b>+ Doc/Search Fee (S\$)</b>	2.00		
	<b>Nett Liability (S\$)</b>	<b>5,438.70</b>		

### INSPECTION

Date of Assignment:	14/01/2019	
Date Inspected:	14/01/2019 Inspected At:	Lee Sheng Auto Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-58/60 AutoBay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	7.0 days	

---

**Adjuster:** ADRIAN LING

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	475.00 FL	*475.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	260.00 FL	*- FL
3	1		*REAR BUMPER BRACKET LH	Bent	30.00 FL	*30.00 FL
4	1		*REAR BUMPER BRACKET RH	Bent	30.00 FL	*30.00 FL
5	1		*REAR TRUNKLID OUTER GARNISH	Not Necessary	155.00 FL	*- FL
6	1		*BOOTLID LOCK	Damaged	275.00 FL	*275.00 FL
7	1		*FLOOR PANEL	Repair	850.00 FL	*- FL
8	1		*BOOTLID	Distorted	2,150.00 FL	*1,792.00 FL
9	1		*BOOTLID HINGED LH	Not Necessary	105.00 FL	*- FL
10	1		*BOOTLID HINGED RH	Not Necessary	105.00 FL	*- FL
11	1		*TRUNKLID EMBLEM	Necessary	75.00 FL	*75.00 FL
12	6		*TRUNKLID CLIPS	Not Necessary	24.00 FL	*- FL
13	1		*TRUNKLID INNER BOARD	Not Necessary	195.00 FL	*- FL
14	1		*TRUNKLID WEATHERSTRIP	Cut	395.00 FL	*395.00 FL
15	1		*SPARE TYRE BRACKET	Not Necessary	23.50 FL	*- FL
16	1		*EXHAUST ASSY	Not Necessary	285.00 FL	*- FL
17	2		*TRUNKLID DAMPER RH/LH	Not Necessary	710.00 FL	*- FL
18	1		*REAR END PANEL (INNER)	Dented	1,155.00 FL	*781.90 FL
19	1		*REAR END PANEL (OUTER)	Dented	331.70 FL	*331.70 FL
20	1		*REAR LAMPS	Not Necessary	301.00 FL	*- FL
21	1		*REAR END PANEL TOP MOULDING	Not Necessary	175.00 FL	*- FL
22	1		*TOYOTA STICKER	Necessary	15.00 FL	*15.00 FL
23	1		*HIACE STICKER	Necessary	15.00 FL	*15.00 FL
24	1		*70KM/H STICKER	Necessary	15.00 FL	*15.00 FL
25	6		*BOOTLID CLIPS	Not Necessary	24.00 FL	*- FL
26	1		*REAR NUMBER PLATE LAMP	Not Necessary	115.00 FL	*- FL
27	2		*REAR BUMPER RETAINER RH/LH	Necessary	100.00 FL	*100.00 FL
28	1		*REAR WINDSCREEN GLUM	Necessary	60.00 FS	*60.00 FS
29	1		*REVERSE SENSOR	Damaged	180.00 FS	*180.00 FS
30	1		*NO PLATE	Not Necessary	25.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>8,654.20</b>	<b>4,570.60</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	2,097.30	1,082.65
<b>Total Parts (\$)</b>	<b>6,556.90</b>	<b>3,487.95</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCKING ,JACKING ,CUTTING OUT REAR END PANEL REMOVE & REFIX	New	1,600.00	1,000.00
2	WIRING	New	50.00	30.00
3	REMOVE & REFIX EXHAUST	New	150.00	0.00
4	SPRAY PAINTING ON BOOTLID/FENDER RH REAR END PANEL	New	1,500.00	800.00
5	REMOVE & REFIX REAR WINDSCREEN	New	150.00	120.00
<b>Gross Labour Cost (S\$)</b>			<b>3,450.00</b>	<b>1,950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >