

15/02/19

INS. CASE OWNER:

Peter

CC 4/AXA1900

09/11

G 0352

LKK:

IDAC:

Surveyor:

x62

DOI:

ASSIGNMENT

16/1/19

Date / Time:

15/1/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKS 7573L

Name of Insured:

TAN HIAN TAN

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

SANDALWOOD 97780

Policy No.:

0410860

Make / Model:

MITSUBISHI

Place of Accident:

KYE TMS WY.

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SGG 127C



INSRS:

WSP:

Tel:

Liability:

RMKS:

TTS



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

16/1/19
TTS

SGG 127C-X

SKS 7573L-X

* SANDALWOOD

5VC; 014TH

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

DATE / PIC

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS

Loss of Rental (LOR):

SS

days) 120

Loss of Use (LOU):

SS

(S x days)

Loss of Income (LOI):

SS

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIL/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost:

SS

Total:

SS

Global Sum SS:

31,275.37

Email

Call

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

TTS EUROCARS PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

X

Payee 3: (Strike if N.A.)

SS

Name 3:

X

COPY SENT
16/1/19

104

REF: ASM 7747i

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV
 To: Inspect Vehicle No: SGG 1221G
 at Workshop n/s: TTS Eurocare
 of 383 Sin Ming Drive 82927422
 Insured: Kavi
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
16/1/2019 before 5pm.
 (Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: \$165k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 12 days Res: Yes or No
 Lump Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SGG 1221G Yr Regn: 09 Dec 2016
 Type: ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Merce E200 CC: 1991
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 45247 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WDD 2130 422 A 072395
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Insured / Jammed / Leaked / Burnt or
 Brake: Insured / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/55 R17
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental
 Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: 12/1/2019 D.O.I: 16-01-19
 Survey held at: W/S 3:25pm
 Des. of Damages: ☒ Frt ☒ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction	
07/3	COE \$82265	21m
	Finalized \$27433.06 with shabir	22
		23
		24
		25
		26
		27
		28
		29
		30

R(\$2,872.61/09/1)

Date/Time, File Pass to? ☐ : Prel. Report
☐ : Final Report
 Date/Time, File Return to? _____
 Days Of Repair: _____
 Resurvey No. of Trip: _____
 Survey Fee: _____
 Transportation: _____
 Add Fee: ☐ Site Insp \$
☐ Interview \$
☐ Tech. Invs \$
☐ Weekend \$
 Report Format : _____
 Lump Sum / L.B.I. : \$
 TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM19000911/jb3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 15-01-2019		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKS 7573L	Veh. Inspected	SGG 1221C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	15/01/2019	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/01/2019	Inspection Date		
Survey held at	TTS EUROCARS PTE LTD 383 SIN MING DRIVE TTS CENTRE SINGAPORE 575717			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



TTS EUROCARS pte ltd

A member of the TTS Motor Group

383 Sin Ming Drive, TTS Centre, S'pore 575717

Tel : 67572622 Fax : 67411626

TO	AXA Insurance Pte Ltd	DATE	14.12.2018
ATTN	MOTOR CLAIM DEPT	PAGE	1
MODEL	Mercedes benz E200	VEH NO	SGG1221C
YEAR	2017	C/N0	
		D.O.A	12/1/2019

S/NO	PARTS	Qty	
1	BONNET Repair X	1	X
2	BONNET HINGE RH X	1	X
3	BONNET HINGE LH X	1	X
4	BONNET INSULATOR X	1	X
5	BONNET INSULATOR CLIPS / MC	1	31.7
6	BONNET LOGO / MC	1	80.9
7	BONNET LOCK X	1	X
8	BONNET CATCH X	1	X
9	BONNET RUBBER STOPPER X	4	X
10	BONNET ABSORBER X	2	X
11	FRONT BUMPER / MC	1	1155.85
12	FRONT BUMPER CLIPS / MC	10	80
13	FRONT BUMPER GRILLE /	1	239.33
14	FRONT BUMPER GRILLE BASE /	1	168.62
15	FRONT BUMPER GRILLE CHROME /	1	280
16	FRONT GRILLE LOGO /	1	131.5
17	FRONT BUMPER LOWER GRILLE /	1	105.5
18	FRONT BUMPER LOWER GRILLE RH /	1	67.5
19	FRONT BUMPER LOWER GRILLE LH X	1	X
20	FRONT BUMPER NUMBER PLATE BASE X	1	X
21	FRONT BUMPER SENSORS 2PCS / DM @180	4	360
22	WIRE HARNESS FOR FRONT BUMPER SENSOR X	1	X
23	FRONT BUMPER TOW HOOK cover / cut	1	64.5
24	FRONT BUMPER REINFORCEMENT / BT	1	190
25	FRONT BUMPER SPONGE 2PCS / CFA	1	152
26	FRONT BUMPER SIDE RETAINER RH /	1	22.5
27	FRONT BUMPER SIDE RETAINER LH /	1	22.5
28	FRONT BUMPER BRACKET RH X	1	X
29	FRONT BUMPER BRACKET LH X	1	X
30	FRONT BUMPER STIFFENER RH X	1	X
31	FRONT BUMPER STIFFENER LH X	1	X
32	FRONT BUMPER LOWER COVER X	1	X

1-
2-
3-
4-
5-
6-
7-
8-
9-
10-
11-
12-
13-
14-

15 -	33	FRONT BUMPER LOWER GARNISH	X NN	1	X
16 -	34	FRONT FENDER RH	/ Bmc	1	961
	35	FRONT FENDER LH	/ Bmc	1	961
	36	FRONT LH DOOR	Repair X	1	X
	37	FRONT FENDER TOP GARNISH RH	X	1	X
	38	FRONT FENDER TOP GARNISH LH	X	1	X
	39	FRONT FENDER INNER SHIELD RH	X	1	X
	40	FRONT FENDER INNER SHIELD LH	X	1	X
	41	FRONT FENDER INNER SHIELD CLIPS	X NN	20	X
18 -	42	HEADLAMP RH	/ C/A	1	3160
19 -	43	HEADLAMP LH	/ C/A	1	3160
	44	HEADLAMP BALLAST ASSY	X NN	2	X
	45	HEADLAMP CONTROL MODULE	X NN	2	X
	46	HEADLAMP LOWER BRACKET RH	X	1	X
	47	HEADLAMP LOWER BRACKET LH	X NN	1	X
20 -	48	FRONT SUPPORT PANEL	/ BT	1	780
	49	RADIATOR	X NN	1	X
21 -	50	A/C CONDENSER	/ Cut.	1	1490
	51	GEAR OIL COOLER	X NN	1	X
	52	TURBO INTER COOLER	X NN	1	X
	53	FRONT CENTRE BRACE PANEL	X NN	1	X
	54	RADIATOR FAN MOTOR	X	1	X
	55	RADIATOR FAN BLADE	X	1	X
	56	RADIATOR FAN HOUSING	X	1	X
	57	HORN	X	1	X
22 -	58	REAR BOOT	/ BT	1	2240
23 -	59	REAR BOOT CHROME MOULDING	/ Cut	1	145
24 -	60	REAR BOOT LOGO	/ MC	1	86
25 -	61	REAR BOOT EMBLEM	/ MC	1	48
	62	REAR BOOT HINGE RH	X NN	1	X
	63	REAR BOOT HINGE LH	X NN	1	X
photo - 23 -	64	REAR BOOT SWITCH	/ BT	1	210
	65	REAR BOOT LOCK	X NN	1	X
38 -	66	REAR BOOT STOPPER/ ADJUSTOR	2 PCS / BT	4	40
	67	REAR NUMBER PLATE LAMP	X NN	2	X
26 -	68	REAR BUMPER	/ TV	1	1880
27 -	69	REAR BUMPER REFLECTOR RH	/ Cut.	1	28
	70	REAR BUMPER REFLECTOR LH	X NN	1	X
49 -	71	REAR BUMPER REINFORCEMENT	X / BT	1	760
	72	REAR BUMPER SPONGE	X NN	1	X
	73	REAR BUMPER SENSOR	3 PCS / 1M @ 180	4	540
	74	WIRE HARNESS FOR REAR BUMPER SENSOR	X NN	1	X
47 -	75	REAR BUMPER LOWER TRIM/ GARNISH	/ Cut.	1	260
28 -	76	EXHAUST SLEEVE RH	/ Cut.	1	390
	77	EXHAUST SLEEVE LH	X NN	1	X

	front lh fender inner panel, front rh chassis member, front lh chassis member and all other affected areas		
14	To check and adjust frontal chassis alignment, align and pull to specifications	\$	1,500.00
16	Sundries	\$	150.00
17	electrical wiring check for proper functioning	\$	150.00
18	Tuff kote - body cavity preservation (rear boot, rear end panel, spare tyre panel, rear rh and lh fender, tail panel rh, tail lamp panel lh and all other affected areas	\$	350.00
19	Sealant for body panel - rear boot, rear end panel, spare tyre panel, tail lamp panel, rear rh fender	\$	350.00
20	To remove and refix rear windscreen to facilitate repair, conduct water leak test	\$	450.00
21	Sealant for rear windscreen	\$	60.00
22	Inner seal for rear windscreen	\$	50.00
23	To supply and install rear solar film for rear windscreen	\$	350.00
24	To supply and install rear number plate with holder	\$	70.00
25	To remove and refix rear spare tyre board, fender inner trims, spare tyre compartments, tools, and equipment to facilitate repair	\$	450.00
26	To remove and refix rear passenger seats, seat belts, buckles and trims to facilitate repairs	\$	450.00
27	To remove and refix fuel tank, conduct leak test, calibrate fuel pump to facilitate repair	\$	450.00
28	To remove and refix rear exhaust tail pipe, check for leaks, to facilitate repair	\$	450.00
29	To repair, replace rear boot lid, rear bumper, rear end panel, spare tyre panel, rear tail rh panel, rear tail lamp lh panel rear rh fender, rear lh fender, and all other affected parts and areas	\$	3,000.00
30	To putty, sand, spray paint and polish rear boot, rear bumper, rear end panel, rear spare tyre panel, rear fender rh, rear fender lh, rear rh door, rh rocker panel, tail lamp panel rh, tail lamp panel lh and all other affected areas	\$	2,800.00
31	To conduct ecu programming, check and clear fault codes, restore programme modules	\$	550.00
32	CLEARING AND REMOVAL OF DEBRIS	\$	380.00
	Total	\$	21,280.00
	Grand Total	\$	21,280.00

27433.06

42218.86

Remarks

THIS QUOTE IS ONLY AN ESTIMATE FOR REPAIR, SHOULD ANY ADDITIONAL PARTS OR LABOUR INCURRED WE WILL INFORM YOU ACCORDINGLY PRIOR BEFORE WE PROCEED.

12 Days.
part by part.
before paint photos.
Gino Qiang - 82880282
16/1/2019.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

45457.46



TTS EUROCARS pte ltd

A member of the TTS Motor Group

383 Sin Ming Drive, TTS Centre, S'pore 575717

Tel : 67572622 Fax : 67411626

TO	AXA Insurance Pte Ltd	DATE	14.12.2018
ATTN	MOTOR CLAIM DEPT	PAGE	1
MODEL	Mercedes benz E200	VEH NO	SGG1221C
YEAR	2017	C/N0	
		D.O.A	12.12.2018

S/NO	SUPPLEMENTARY PARTS	Qty	
	<u>PARTS</u>		
1	BOOT MOULDING X NN	1	S 145.00 X
2	IMPACT ABSORBER (FRONT BUMPER SPONGE) X repeat	1	S 152.00 X
3	CROSS MEMBER (FRONT REINFORCEMENT) X repeat	1	S 490.00 X
4	ABSORBER (CHASSIS MEMBER EXTENSION) / BT	1	S 200.00 /
5	ABSORBER (CHASSIS MEMBER EXTENSION) / BT	1	S 230.00 /
6	STRIKER (RADIATOR BRACKET) / BT	1	S 90.00 /
7	ORNAMENTAL (FRONT BUMPER LOWER TRIM) / re	1	S 120.00 /
8	TRIM BUMPER (LOWER TRIM CHROME) / cut	1	S 120.00 /
9	ORNAMENTAL MOULDING (OUTER CHROME GRILLE) X NN	1	S 280.00 X
10	BASIC MOUNTING (LOWER GRILLE BASE) / mc	1	S 80.00 /
11	TRIM BUMPER REAR LOWER (REAR BUMPER LOWER EXTEND) X NN	1	S 260.00 X
12	BEAM (front bumper logo base) X NN	1	S 74.00 X
13	REAR CROSS MEMBER (REAR BUMPER REINFORCEMENT) X AA	1	S 760.00 X
14	CONSOLE (FRONT BUMPER CENTRE BEAM) / BT repeat	1	S 200.00 /
	Total	S	3,201.00
	LESS 10%	S	320.10
		S	2,880.90
	<u>LABOUR</u>		
		S	-
	Total	S	2,880.90

REMARK

LABOUR INCURRED WE WILL INFORM YOU ACCORDINGLY PRIOR BEFORE WE PROCEED.

Front lower radiator Air Duct - CRA \$122

Parking sensor Seal Ring - mc \$40

Bumper Trim clips - mc. \$162

Left Boot Lid Badge (star) - re \$74.

PRE INVOICE

AXA INSURANCE PTE LTD
08 Shenton Way
#24-01 AXA Tower
SINGAPORE 068811

DOCUMENT NO : IN19-000006
DATE : 12/02/2019

Vehicle No: SGG1221C
MERC E200
Mileage: 45247

Staff ID : KAVIDHA
Account No : AXA INSUR
JOB NO : TN19-000006

No	Description	quantity U	List Price	Disc %	Amount
----	-------------	------------	------------	--------	--------

5	1	Bonnet Insulator Clip	1	\$31.70	\$31.70	NEC
6	2	Bonnet Logo	1	\$80.90	\$80.90	NEC
11	3	Front Bumper	1	\$1,155.85	\$1,155.85	DE
14	4	Rivet	10	\$80.00	\$80.00	NEC
13	5	Front Bumper Grille	1	\$239.33	\$239.33	CRA
14	6	Front Bumper Grille Base	1	\$168.62	\$168.62	CRA
(A) 7	7	Frt lower Radiator Air Duct - (A) - CRA (WA 0004)	1	\$122.00	\$122.00	(A)
16	8	Mercedes Benz Ambler	1	\$131.50	\$131.50	CRA
17	9	Frt Bumper Lower Grille	1	\$105.50	\$105.50	NEC
18	10	Lower Bumper Grille	1	\$67.50	\$67.50	NEC
21	11	E class parking sensor	5	\$900.00	\$900.00	150
(A) 12	12	Parking sensor Seal Ring - (A) - NEC	5	\$40.00	\$40.00	(A)
23	13	Towing Eye Cover	1	\$64.50	\$64.50	CRA
26+27	14	Mounting Bracket Bumper	2	\$45.00	\$45.00	NEC
34	15	Front LH Fender	1	\$961.00	\$961.00	NEC
35	16	Front RH Fender	1	\$961.00	\$961.00	NEC
(A) 17	17	Bumper Trim Clips - (A) - NEC	20	\$162.00	\$162.00	(A)
42	18	Headlamp RH Unit	1	\$3,160.00	\$3,160.00	CRA
43	19	Headlamp LH Unit	1	\$3,160.00	\$3,160.00	CRA
48	20	Front Panel Cross member	1	\$780.00	\$780.00	BT
50	21	Condenser	1	\$1,440.00	\$1,440.00	CUT
58	22	Trunk Lid Cover	1	\$2,240.00	\$2,240.00	BT
64	23	Rear Tailgate Boot Lock Cover	1	\$210.00	\$210.00	NEC
60	24	E 200 LOGO	1	\$86.00	\$86.00	NEC
61	25	Rear Boot Lid Badge (star)	1	\$48.00	\$48.00	NEC
68	26	Rear Trim Bumper	1	\$1,880.00	\$1,880.00	NEC
69	27	Reflector rear Bumper	1	\$28.00	\$28.00	CUT
76	28	Rear Tail Pipe	1	\$390.00	\$390.00	CUT
59	29	Boot Moulding	1	\$145.00	\$145.00	CUT
25	30	Impact Absorber - (It)	1	\$152.00	\$152.00	CUT
79	31	Rear Bumper Centre Chrome	1	\$320.00	\$320.00	CUT
82	32	Rear Bumper Mounting LH	1	\$66.00	\$66.00	NEC
87	33	Rear Bumper Mounting RH	1	\$66.00	\$66.00	NEC
87	34	Rear Body Panel	1	\$1,360.00	\$1,360.00	NEC
89	35	Rear Hatch Strip	1	\$190.00	\$190.00	NEC
93	36	Interior Panel Clips	4	\$32.00	\$32.00	NEC
95	37	Rear Lamp	1	\$690.00	\$690.00	CRA
66	38	Front Fender Spring	1	\$40.00	\$40.00	2 pieces

supplement

- 248 - 39 Front Bumper Support ~~BT~~ (TA) 1
 S 4 - 40 Reinforcement Absorber BT 103818 1
 S 5 - 41 Frt bumper Absorber BT 103946 1
 S 6 - 42 Radiator Bracket BT 104536 1
 S 7 - 43 Frt Bumper Lower Trim BT 104536 1
 S 8 - 44 Frt Bumper Trim BT 1 1
 S 15 - 45 Frt Chrome Grille 1 1
 S 10 - 46 Frt Bumper Mounting NEC 1
 75 - 47 Lower Rear Bumper Trim 1
 71 - 48 Frt Boot Lid Badge(Star) 22 1
 71 - 49 Reinforcement Rear Cross Member (Rear) 1
 S 14 - 50 Radiator Support Console BT 1

\$490.00
 \$200.00
 \$230.00
 \$90.00
 \$120.00
 \$120.00
 \$120.00
 \$280.00
 \$80.00
 \$260.00
 \$74.00
 \$760.00
 \$200.00

\$490.00 (TA)
 \$200.00 (TA) (A)
 \$230.00 (TA)
 \$90.00 (A)
 \$120.00 (A)
 \$120.00 (A)
 \$120.00 (A)
 \$280.00
 \$80.00 (A)
 \$260.00 (A)
 \$74.00 (A)
 \$760.00 (A)
 \$200.00 (A)

Total Parts \$24,703.40
 10% parts Discount \$2,470.34
 Total Parts \$22,233.06

Labour

1	Sundries	1	\$40.00	\$40.00
2	Electrical wiring check for proper Functioning	1	\$30.00	\$30.00
3	Remove/replace Frt Headlamp Adjust/align headlamp focus	1	\$250.00	\$250.00
4	Tuff kote body cavity preserv.	1	\$20.00	\$20.00
5	Remove/refix/replace radiator cooling system conduct pressure test	1	\$60.00	\$60.00
6	Remove/refix/replace a/c condenser Vacuum refill condct pressure test check for leaks	1	\$60.00	\$60.00
7	Towing Charges	1	\$180.00	\$180.00
8	Repair/replace Frt Bonnet Frt bumper Frt support panel headlamp, Frt RH Fender/Frt LH Fender Frt RH chassis memberfit LH chassis member/frt LH door and all other affected parts	1	\$880.00	\$880.00
9	E class Number Plate (special)	1	\$360.00	\$360.00
10	Putty,sand,spray paint polish wax frt bonnet, frt RH fender frt LH fender frt bumperfrt rh dr, frt rh fender inner panel	1	\$1,500.00	\$1,500.00
11	Sundries	1	\$20.00	\$20.00
12	Tuff kote body cavity preserv. rear boot rear end panel, spare tyre panel, rear RH and LH fender tail panel LH and all other affected parts	1	\$40.00	\$40.00
13	Sealant for body panel-rear boot rear end panelspare tyre paneltail lamp panel rear RH fender	1	\$40.00	\$40.00
14	Remove/refix rear spare tyre board fender inner trims spare tyre compartment tools and equipment for repairs	1	\$80.00	\$80.00
15	Repair, replace rear boot lid, rear bumper	1	\$1,000.00	\$1,000.00

	rear end panel spare tyre panel			
	rear tail rh panel rear tail lamp lh panel			
	rear rh fender rear lh fender and all			
	other affected parts			
16	Putty,sand,spray paint polish rear boot	1	\$1,000.00	\$1,000.00
	rear bumper rear end panel rear spare			
	tyre panel rear fender rh rear fender lh			
	rear rh door rh rocker panel tail lamp			
	panel rh tail lamp panel lh and all			
	affected parts			
17	conduct ECU programming check and		\$150.00	\$150.00
	clear fault codes restore programming			
	modules			
18	clearing and removal of debris	1	\$380.00	\$380.00

Total Labour	\$6,090.00
Total Parts	\$22,233.06
Subtotal	\$28,323.06
Add 7% GST	\$1,982.61
Total	\$30,305.67

*** Acknowledgement by Customer ***

I confirm that the goods stated in this invoice have been received by me in good working order and condition.

I further confirm that all services and /or repair jobs

Stated in this invoice are completed and done to my Satisfaction.

TTS EUROCARS PTE LTD



Name/Signature/NRIC No/Co Stamp (where applicable)

Authorised Signature



TTS EUROCARS pte ltd

Company Reg. No: 200413930H

3930-H

383 Sin Ming Drive, TTS Centre, Singapore 575717 Ssles: +65 6842 2222 Admin: +65 6757 0122 Aftersales: +65 6757 2622 Fax: +65 6741 1626

Branch : No.15, Commonwealth Lane, Lot A1, Commonwealth Car Mall, Singapore 149554 Tel : +65 6462 1111 Fax : +65 6252 4834

For corporate, fleet & leasing enquiries, please contact +65 6462 1111 24-Hour Emergency Assistance: +65 6475 2722

Website: www.tts.com.sg



Service Request Details

Claim

S9M01ADF

Reference

None

Loss Date

January 12, 2019

Request Date

January 15, 2019

Due Date

January 22, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Incident Only

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration #

SGG1221C

Make

TPVD MERCEDES-BENZ

Model

E200 (R17)-2.0 (A,

Service Address

15/1 ms for i
- Vehicle in
- arranged 16/1 - 645 pm.

TAN HIAN THIN
BLK 873 #10-159, YISHUN STREET 81, 760873, Singapore
98637778
DANVXTAN@GMAIL.COM

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

New Message



Revision on quantum:

Type

🔗 Question

Message

COR: \$29353.37; LOR: \$2240 (\$140/day for 16 days). LTA Fee: \$2. Total: \$31595.37.

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564313

Remarks:

5 VEH CHAIN ; OI 4TH IN LINE-BOLA 28.

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	29,353.37
Loss of rental	\$	2,400.00 \$150 x 16days
2 LTA search fees	\$	2.00
Proposed Total	\$	31,755.37

Kavi

From: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Sent: 7 March, 2019 5:21 PM
To: shabir@tts.com.sg
Cc: kavi@tts.com.sg
Subject: RE: SGG1221C - BEFORE PAINT PHOTOS

Follow Up Flag: Follow up
Flag Status: Flagged

Dear Shabir,

Finalize COR \$27433.06 before GST @ 12 working days.

Regards,
Guo Qiang

-----Original Message-----

From: Shabir [mailto:shabir@tts.com.sg]
Sent: Thursday, 7 March, 2019 2:29 PM
To: Guo Qiang (LKKAUTO)
Cc: kavi@tts.com.sg
Subject: SGG1221C - BEFORE PAINT PHOTOS

Dear Guo Qiang,

Attached before paint photos.

Best Regards
Mohamed Shabir
After Sales Manager

We are committed to the preservation of the environment. Please print this email only if it is absolutely necessary.
TTS Motor Group Pte Ltd (Co Reg No: 198702999Z) TTS Eurocars Pte Ltd (Co Reg No: 200413930H)
383 Sin Ming Drive TTS Centre Singapore 575717
Tel: (65) 6462 1111 Ext123 Fax: (65) 6741 1626
Email: shabir@tts.com.sg Website: www.tts.com.sg
Disclaimer: The information contained in this email, including any attachments, may contain confidential information of TTS Motor Group Pte Ltd / TTS Eurocars Pte Ltd. This email is intended only for the use of the addressee(s) listed above. Unauthorized review, dissemination or any other use of the information contained in this email is strictly prohibited. If you have received this email in error or have reason to believe that you are not authorized to receive it, please notify the sender by return email and promptly delete this email .****

Kavi

From: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
Sent: 18 January, 2019 4:31 PM
To: kavi@tts.com.sg
Cc: Admin A; CS A Team
Subject: TTS EUROCARS PTE LTD ACCIDENT BETWEEN SGG1221G AND SKS7573L ON 12.01.2019

WITHOUT PREJUDICE

Dear Kavi,

With reference to the subject.

Please be informed that basing on the accident statements submitted by parties involved, the liability is clear.

The final repair cost is subject to the consistency of the damages according to the nature of the accident and approval of the insurer.

The days for losses(use and/or rental) will be based on the number of days of repair recommended by our surveyor.

Please note that this e-mail is on without prejudice basis and does not amount to an authorisation of repair to your client's vehicle. Contents herein should not be construed as an admission of any liability, confirmation of damages whatsoever to the insured/insurer's part.

Furthermore, this e-mail should not be regarded as a waiver by AXA of their rights to repudiate the claim should there be future discovery of any breach of policy terms and conditions committed by their driver or insured.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

DISCHARGE VOUCHER

30TH JANUARY 2019

AXA Insurance Pte Ltd

NAME : MR. LIM CHOONG KIAT (LIN JUNJIE)
NRIC NO : 57927747I
CAR PLATE NO : SGG1221C
CLAIM TYPE : THIRD PARTY
POLICY NO : _____
INSURANCE EXCESS : NIL
REPAIR COST : _____
DATE OF ACCIDENT : 12/1/2019

I Hereby acknowledge having received from TTS MOTOR GROUP PTE LTD, 383 Sin Ming Drive, TTS CENTRE Singapore 575717, my vehicle, which had been repaired to my satisfaction and acceptance.

I Admit that payment of SGD account for such repairs is in full discharge of reference claim number GA375196 in respect of the damage caused to the said vehicle.

Dated this day of : 30TH JAN 2019



Signed by Policy holder/Insured





Signed by Workshop
TTS EUROCARS
A member of the TTS Motor Group

Company Reg. No: 200413930H
GST No: 20-0413930-H

383 Sin Ming Drive, TTS Centre, Singapore 575717 Sales: +65 6842 2222 Admin: +65 6757 0122 Aftersales: +65 6757 2622 Fax: +65 6741 1626
Branch : No.15, Commonwealth Lane, Lot A1, Commonwealth Car Mall, Singapore 149554 Tel : +65 6462 1111 Fax : +65 6252 4834

For corporate, fleet & leasing enquiries, please contact +65 6462 1111
24-Hour Emergency Assistance: +65 6475 2722

Website : www.tts.com.sg



TTS EUROCARS pte ltd

A member of the TTS Motor Group

Company Reg No: 200413930H

LETTER OF AUTHORIZATION- THIRD PARTY CLAIM

I, LIM CHOON KAT (LIN JUNJIE) THE OWNER OF THE VEHICLE NUMBER: SGG1D21C

Hereby do authorize TTS Eurocars Pte Ltd/TTS Motor Group Pte Ltd to proceed with repairs of my vehicle as per the 3rd party insurer and the surveyor's recommendation which I file against the 3rd party insurer and shall pay the amount of car rental (if any including GST) to TTS Eurocars Pte Ltd/TTS Motor Group Pte Ltd upon collection of my vehicle and duly complete and sign the Discharge Voucher.

I am further aware that TTS Eurocars Pte Ltd/TTS Motor Group Pte Ltd is assisting me in the claim against the third party insurer. I shall release TTS Eurocars Pte Ltd/TTS Motor Group Pte Ltd against liability.

Regardless of all circumstances or reasons causing the delay or unsuccessful claim(s), I agreed that TTS Eurocars Pte Ltd/TTS Motor Group Pte Ltd will not be held responsible or liable in any event if the claim is either partially successful and or unsuccessful.

Dated the Day of 2019

Owners Name/Signature

Witness (name/Signature)

57927747I

NRIC No

58171135F

NRIC No



TTS EUROCARS pte ltd

A member of the TTS Motor Group

Company Reg No: 200413530H

Acknowledgment

Accident Involving SAG1221C and SKS7573L on 12/1/19

I, LIM CHOONG KAT (LIN JUNTIE) the owner of Vehicle Registration Number SAG1221C, have

been advised by Customer Service Adviser and understand the content of my motor claim as specify herein:

1. Type of Claim: ☐ Claiming own-policy only.
☐ Claiming own-policy and uninjured losses.
☒ Direct settlement with 3rd-Party Insurer [Any reversion to own-policy claim shall be submitted to my insurer within 14 days from date of accident as required by the policy]
2. TTS Eurocars Pte Ltd/ TTS Motor group Pte Ltd being an appointed Approved Reporting Centre is bound by GIA not to induce, instigate, encourage or procure any owner or driver of any motor vehicle to engage the services of any solicitors to make any third party claims.
3. The estimated repair costs shall be subjected to insurer surveyors' finalisation on completion of job and after considering additional parts and/or labours discovered in the course of repair.
4. A compulsory policy excess _____, stated in the Motor Policy taken up by you, is applicable for own- damage claim.
5. Loss of Use and Cost of Rental shall be computed in accordance to the number of days as recommended by the surveyor and the Benchmark Rates published in State Courts Practice Directions for Non-injury of Motor Accident (NIMA).Claims.
6. I am fully aware that TTS Eurocars Pte Ltd/ TTS Motor group Pte Ltd is assisting me in my claim against the third-party insurer. I shall release TTS Eurocars Pte Ltd/ TTS Motor group Pte Ltd against any liability, loss claim or ~~proceedings~~ which may arise out of, in the course of, or by reasons of execution of the services.
7. In the event that my insurer or third party insurer is not prepared to settle the claim due to breach of policy or other reasons, I shall pay TTS Eurocars Pte Ltd/ TTS Motor group Pte Ltd the full repair bill.
8. A towing charge of \$120.00, administration fee of \$300.00 and storage fee \$50.00 per day is chargeable to me if my vehicle is not repaired by TTS Eurocars Pte Ltd/ TTS Motor group Pte Ltd
9. The average time span to settle a claim is 6 months or longer for complex cases. Any correspondence or stairs enquiry of the mentioned claim shall be directed to the under-mentioned personnel:

Name: Ms. Kavi
Tel: 82927422
Email: kavi@tts.com.sg

10. Special Instructions:

Signed by:


Name: Lim choong kat
NRIC No: S79277471
Date:

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKS 7573L (Insd veh)	Model:	MERCEDES BENZ E200
	SGG 1221C (TP veh)		
Date of Accident:	12/01/2019		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	48,640.02
Final Repair Cost	:	\$	29,353.37
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,920.00 16 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$
---------	---	----

	:	\$
Final Settlement Sum (GLOBAL SUM)	:	\$ 31,275.00

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: ____		
BOLA Liability: ____ (%)		Assessed Liability (*): ____ 0 ____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____ _____				

Payment Instruction: Payee's Breakdown			
1)	TTS EUROCARS PTE LTD	:	\$ 31,275.00

NUR SHAQILAH BTE ABDOL
WAHAB

07/05/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19000911/Gjb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: PETER WANG

Date : 07-05-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKS 7573L	Veh. Inspected	SGG 1221C
Policy No.	GA102860	Coverage (\$)	0.00
Claim No.	S9M01ADF	Excess (\$)	0.00
Assign From	PETER WANG	Assign Date	15/01/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E200	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD2130422A072395	Colour	SILVER
Odometer	45247	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55R17	CONTINENTAL	6 mm
L/H Front Tyre	225/55R17	CONTINENTAL	6 mm
R/H Rear Tyre	225/55R17	CONTINENTAL	6 mm
L/H Rear Tyre	225/55R17	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	12/01/2019	Inspection Date	16/01/2019
Survey held at	TTS EUROCARS PTE LTD 383 SIN MING DRIVE TTS CENTRE SINGAPORE 575717		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 7

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGG 1221C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	BONNET HINGE RH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	BONNET HINGE LH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	BONNET INSULATOR (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	BONNET INSULATOR CLIPS (CONSISTENT)	NECESSARY	31.70	31.70
1	BONNET LOGO (CONSISTENT)	NECESSARY	80.90	80.90
1	BONNET LOCK (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	BONNET CATCH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
4	BONNET RUBBER STOPPER (NPA) (CONSISTENT)	NOT NECESSARY	-	-
2	BONNET ABSORBER (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	FRONT BUMPER (CONSISTENT)	DEFORMED	1,155.85	1,155.85
10	FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	80.00	80.00
1	FRONT BUMPER GRILLE (CONSISTENT)	CRACKED	239.33	239.33
1	FRONT BUMPER GRILLE BASE (CONSISTENT)	CRACKED	168.62	168.62
1	FRONT BUMPER GRILLE CHROME (CONSISTENT)	CRACKED	280.00	280.00
1	FRONT GRILLE LOGO (CONSISTENT)	CRACKED	131.50	131.50
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	DEFORMED	105.50	105.50
1	FRONT BUMPER LOWER GRILLE RH (CONSISTENT)	DEFORMED	67.50	67.50
1	FRONT BUMPER LOWER GRILLE LH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	FRONT BUMPER NUMBER PLATE BASE (NPA) (CONSISTENT)	NOT NECESSARY	-	-
4	FRONT BUMPER SENSORS (CONSISTENT)	DAMAGED 2PCS ONLY	360.00	360.00
1	WIRE HARNESS FOR FRONT BUMPER SENSOR (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	FRONT BUMPER TOW HOOK COVER (CONSISTENT)	CUT	64.50	64.50
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	490.00	490.00
1	FRONT BUMPER SPONGE (CONSISTENT)	CRACKED	152.00	152.00
1	FRONT BUMPER SIDE RETAINER RH (CONSISTENT)	DEFORMED	22.50	22.50
1	FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	DEFORMED	22.50	22.50

Report Ref No. CC4/ASM19000911/Gjb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER BRACKET RH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	FRONT BUMPER BRACKET LH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	FRONT BUMPER STIFFENER RH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	FRONT BUMPER STIFFENER LH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	FRONT BUMPER LOWER COVER (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	FRONT BUMPER LOWER GARNISH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	FRONT FENDER RH (CONSISTENT)	BUCKLED	961.00	961.00
1	FRONT FENDER LH (CONSISTENT)	BUCKLED	961.00	961.00
1	FRONT LH DOOR (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	FRONT FENDER TOP GARNISH RH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	FRONT FENDER TOP GARNISH LH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	FRONT FENDER INNER SHIELD RH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	FRONT FENDER INNER SHIELD LH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
20	FRONT FENDER INNER SHIELD CLIPS (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	HEADLAMP RH (CONSISTENT)	CRACKED	3,160.00	3,160.00
1	HEADLAMP LH (CONSISTENT)	CRACKED	3,160.00	3,160.00
2	HEADLAMP BALLAST ASSY (NPA) (CONSISTENT)	NOT NECESSARY	-	-
2	HEADLAMP CONTROL MODULE (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	HEADLAMP LOWER BRACKET RH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	HEADLAMP LOWER BRACKET LH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	FRONT SUPPORT PANEL (CONSISTENT)	BENT	780.00	780.00
1	RADIATOR (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	A/C CONDENSER (CONSISTENT)	CUT	1,440.00	1,440.00
1	GEAR OIL COOLER (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	TURBER INTER COOLER (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	FRONT CENTRE BRACE PANEL (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	RADIATOR FAN MOTOR (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	RADIATOR FAN BLADE (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	RADIATOR FAN HOUSING (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	HORN (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR BOOT (CONSISTENT)	BENT	2,240.00	2,240.00
1	REAR BOOT CHROME MOULDING (CONSISTENT)	CUT	145.00	145.00

Report Ref No. CC4/ASM19000911/Gjb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOT LOGO (CONSISTENT)	NECESSARY	86.00	86.00
1	REAR BOOT EMBLEM (CONSISTENT)	NECESSARY	48.00	48.00
1	REAR BOOT HINGE RH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR BOOT HINGE LH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR BOOT SWITCH (CONSISTENT)	DEFORMED	210.00	210.00
1	REAR BOOT LOCK (NPA) (CONSISTENT)	NOT NECESSARY	-	-
4	REAR BOOT STOPPER / ADJUSTOR (CONSISTENT)	BENT	40.00	40.00
2	REAR NUMBER PLATE LAMP (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR BUMPER (CONSISTENT)	TORN	1,880.00	1,880.00
1	REAR BUMPER REFLECTOR RH (CONSISTENT)	CUT	28.00	28.00
1	REAR BUMPER REFLECTOR LH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	760.00	760.00
1	REAR BUMPER SPONGE (NPA) (CONSISTENT)	NOT NECESSARY	-	-
4	REAR BUMPER SENSOR (CONSISTENT)	DAMAGED 3PCS ONLY	540.00	540.00
1	WIRE HARNESS FOR REAR BUMPER SENSOR (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR BUMPER LOWER TRIM / GARNISH (CONSISTENT)	CUT	260.00	260.00
1	EXHAUST SLEEVE RH (CONSISTENT)	CUT	390.00	390.00
1	EXHAUST SEELVE LH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR BUMPER TOWING COVER (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR BUMPER LOWER CHROME MOULDING (CONSISTENT)	CUT	320.00	320.00
1	REAR BUMPER BRACKET RH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR BUMPER BRACKET LH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR BUMPER SIDE RETAINER RH (CONSISTENT)	NECESSARY	66.00	66.00
1	REAR BUMPER SIDE RETAINER LH (CONSISTENT)	NECESSARY	66.00	66.00
1	REAR BUMPER STIFFENER RH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR BUMPER STIFFENER LH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR BUMPER SENSOR BRACKET (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR END PANEL (CONSISTENT)	BUCKLED	1,360.00	1,360.00
1	REAR END PANEL TOP GARNISH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR BOOT LID WEATHERSTRIP (CONSISTENT)	NECESSARY	190.00	190.00
1	REAR BOOT LID LOCK CATCH (NPA) (CONSISTENT)	NOT NECESSARY	-	-

Report Ref No. CC4/ASM19000911/Gjb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE TYRE PANEL (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	SPARE TYRE BOARD (NPA) (CONSISTENT)	NOT NECESSARY	-	-
4	END PANEL TOP GARNISH CLIPS (CONSISTENT)	NECESSARY	32.00	32.00
1	REAR RH FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	TAIL LAMP RH (CONSISTENT)	CRACKED	690.00	690.00
1	TAIL LAMP LH (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR WINDSCREEN (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR WINDSCREEN MOULDING (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR RH DOOR WEATHERSTRIP (INNER) (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	BOOT MOULDING (CONSISTENT) (ADDITIONAL)	NOT NECESSARY	145.00	-
1	IMPACT ABSORBER (FRONT BUMPER SPONGE) (CONSISTENT) (ADDITIONAL)	REPEATED	152.00	-
1	CROSS MEMBER (FRONT REINFORCEMENT) (CONSISTENT) (ADDITIONAL)	REPEATED	490.00	-
1	ABSORBER (CHASSIS MEMBER EXTENSION) (CONSISTENT) (ADDITIONAL)	BENT	200.00	200.00
1	ABSORBER (CHASSIS MEMBER EXTENSION) (CONSISTENT) (ADDITIONAL)	BENT	230.00	230.00
1	STRIKER (RADIATOR BRACKET) (CONSISTENT) (ADDITIONAL)	BENT	90.00	90.00
1	ORNAMENTAL (FRONT BUMPER LOWER TRIM) (CONSISTENT) (ADDITIONAL)	DEFORMED	120.00	120.00
1	TRIM BUMPER (LOWER TRIM CHROME) (CONSISTENT) (ADDITIONAL)	CUT	120.00	120.00
1	ORNAMENTAL MOULDING (OUTER CHROME GRILLE) (CONSISTENT) (ADDITIONAL)	NOT NECESSARY	280.00	-
1	BASIC MOUNTING (LOWER GRILLE BASE) (CONSISTENT) (ADDITIONAL)	NECESSARY	80.00	80.00
1	TRIM BUMPER REAR LOWER (REAR BUMPER LOWER EXTENDED) (CONSISTENT) (ADDITIONAL)	NOT NECESSARY	260.00	-
1	BEAM (FRONT BUMPER LOGO BASE) (CONSISTENT) (ADDITIONAL)	NOT NECESSARY	74.00	-
1	REAR CROSS MEMBER (REAR BUMPER REINFORCEMENT) (CONSISTENT) (ADDITIONAL)	REPEATED	760.00	-
1	CONSOLE (FRONT BUMPER CENTRE BEAM) (CONSISTENT) (ADDITIONAL)	BENT	200.00	200.00

Report Ref No. CC4/ASM19000911/Gjb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT LOWER RADIATOR AIT DUCT (CONSISTENT) (ADDITIONAL)	CRACKED	122.00	122.00
1	PARKING SENSOR SEAL RING (CONSISTENT) (ADDITIONAL)	NECESSARY	40.00	40.00
1	BUMPER TRIM CLIPS (CONSISTENT) (ADDITIONAL)	NECESSARY	162.00	162.00
1	FRT BOOT LID BADGE (STAR) (CONSISTENT) (ADDITIONAL)	DEFORMED	74.00	74.00
	LESS 10% DISCOUNT		-2,686.44	-2,470.34
			24,177.96	22,233.06
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	300.00	40.00
1	FRONT NUMBER PLATE WITH HOLDER (SN) (NPA) (CONSISTENT)	NOT NECESSARY	70.00	-
1	SEALANT FOR REAR WINDSCREEN (SN) (CONSISTENT)	NOT NECESSARY	60.00	-
1	INNER SEAL FOR REAR WINDSCREEN (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR SOLAR FILM FOR REAR WINDSCREEN (SN) (CONSISTENT)	NOT NECESSARY	350.00	-
1	REAR NUMBER PLATE WITH HOLDER (SN) (CONSISTENT)	BENT	70.00	50.00
			900.00	90.00
	LABOUR			
	ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING.		150.00	30.00
	TO REMOVE AND REPLACE FRONT HEADLAMP, ADJUST AND ALIGN HEADLAMP FOCUS.		250.00	50.00
	TUFF KOTE - BODY CAVITY PRESERVATION (FRONT BONNET, FRONT RH FENDER, FRONT LH FENDER, FRONT SUPPORT PANEL)		350.00	40.00
	SEALANT FOR BODY PANEL - BONNET, FRONT RH FENDER, FRONT LH FENDER.	NOT NECESSARY	250.00	-
	TO REMOVE AND REFIX / REPLACE RADIATOR COOLING SYSTEM, CONDUCT PRESSURE TEST, CHECK FOR LEAKS.		550.00	60.00
	TO REMOVE AND REFIX / REPLACE A/C CONDENSER. VACUUM REFILL, CONDUCT PRESSURE TEST CHECK FOR LEAKS.		550.00	60.00

Report Ref No. CC4/ASM19000911/Gjb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REPLACE TURBO INTERCOOLER, CONDUCT PRESSURE TEST, CHECK FOR LEAKS.	NOT NECESSARY	550.00	-
	TOWING CHARGES.		250.00	180.00
	TO REMOVE AND REPLACE FRONT HEADLAMP WIPER WASHER SYSTEM.	NOT NECESSARY	350.00	-
	TO REPAIR, REPLACE FRONT BONNET, FRONT BUMPER, FRONT SUPPORT PANEL, HEADLAMPS, FRONT RH FENDER, FRONT LH FENDER, FRONT RH CHASSIS MEMBER, FRONT LH CHASSIS MEMBER CHASSIS MEMBER, FRONT LH DOOR AND ALL OTHER AFFECTED PARTS AND AREAS. INCLUSIVE OF THE REPAIR OF BONNET AND FRONT LH DOOR.		3,000.00	880.00
	TO PUTTY, SAND, SPRAY PAINT, POLISH AND WAX FRONT BONNET, FRONT RH FENDER FRONT LH FENDER, FRONT BUMPER, FRONT RH DOOR, FRONT RH FENDER INNER PANEL FRONT LH FENDER INNER PANEL, FRONT RH CHASSIS MEMBER, FRONT LH CHASSIS MEMBER AND ALL OTHER AFFECTED AREAS.		2,800.00	1,500.00
	TO CHECK AND ADJUST FRONTAL CHASSIS ALIGNMENT, ALIGN AND PULL TO SPECIFICATIONS.	NOT NECESSARY	1,500.00	-
	ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING.	NOT NECESSARY	150.00	-
	TUFF KOTE - BODY CAVITY PRESERVATION (REAR BOOT, REAR END PANEL, SPARE TYRE PANEL, REAR RH AND LH FENDER, TAIL PANEL RH, TAIL LAMP PANEL LH AND ALL OTHER AFFECTED AREAS.		350.00	40.00
	SEALANT FOR BODY PANEL - REAR BOOT, REAR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL, REAR RH FENDER.		350.00	40.00
	TO REMOVE AND REFIX REAR WINDSCREEN TO FACILITATE REPAIR, CONDUCT WATER LEAK TEST.	NOT NECESSARY	450.00	-
	TO REMOVE AND REFIX REAR SPARE TYRE BOARD, FENDER INNER TRIMS, SPARE TYRE COMPARTMENTS, TOOLS, AND EQUIPMENT TO FACILITATE REPAIR.		450.00	80.00
	TO REMOVE AND REFIX REAR PASSENGER SEATS, SEAT BELTS, BUCKLES AND TRIM TO FACILITATE REPAIRS.	NOT NECESSARY	450.00	-
	TO REMOVE AND REFIX FUEL TANK, CONDUCT LEAK TEST, CALIBRATE FUEL PUMP TO FACILITATE REPAIR.	NOT NECESSARY	450.00	-
	TO REMOVE AND REFIX REAR EXHAUST TAIL PIPE, CHECK FOR LEAKS, TO FACILITATE REPAIR.	NOT NECESSARY	450.00	-

Report Ref No. CC4/ASM19000911/Gjb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPAIR, REPLACE REAR BOOT LID, REAR BUMPER, REAR END PANEL, SPARE TYRE PANEL, REAR TAIL RH PANEL, REAR TAIL LAMP LH PANEL REAR RH FENDER, REAR LH FENDER, AND ALL OTHER AFFECTED PARTS AND AREAS. INCLUSIVE OF THE REPAIR OF REAR RH FENDER.		3,000.00	1,000.00
	TO PUTTY, SAND, SPRAY PAINT AND POLISH REAR BOOT, REAR BUMPER, REAR END PANEL REAR SPARE TYRE PANEL, REAR FENDER RH, REAR FENDER LH, REAR RH DOOR, RH ROCKER PANEL, TAIL LAMP PANEL RH, TAIL PANEL LH AND ALL AFFECTED AREAS.		2,800.00	1,000.00
	TO CONDUCT ECU PROGRAMMING, CHECK AND CLEAR FAULT CODES, RESTORE PROGRAMME MODULES.		550.00	150.00
	CLEARING AND REMOVAL OF DEBRIS.	NOT NECESSARY	380.00	-
			20,380.00	5,110.00
GRAND TOTAL			45,457.96	27,433.06
RECOMMENDED COST OF REPAIRS				27,433.06

Report Ref No. CC4/ASM19000911/Gjb3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.