| Garrinur XM | SMO | | | | . 4 |
|--|-------------------|--|-----------------|----------------------------|-------------------------|
| Marian March | | IGNMENT | | 1 | |
| rom Date 6 | 91.01.2019 | Veh No. | SKBr | | May 11 |
| stimated Cost. | | | | / Van / Lorry / Taxi / Pri | me Mover / |
| (TP) WS/TP RES/OD RES/EVA/INV/M | / I∨ | | Trailer or | 1101- 2 | 7 0260 |
| Inspect Vehicle No: SKB 2729C | | | Hyund | | 6.0 275/ |
| Workshop m/s Ace Chrome | .1 | Golour | Silver | | ured / Std / NI / NA |
| 2 Kaki Bubit AVE 2 #02-2 | 4 | Sp.Reading | 15645 | L T/Radio: In: | sured / Std / NI / NA |
| sured | | Eng/No: | 1 | - 101 - 10 | a 1 a 422 |
| licy No. | | Č/No: | KMH | EC 41 CM | 042755 |
| aims No. | | | od / Fair / Poo | or / Burnt | |
| im Insured: Excess: | | | _ | Leaked / Burnt or | |
| (Client's Record) | | | , | Leaked / Burnt or | |
| ake of Veh: | | Modi: Nil / | S/Rim / STO | A'Rim or | |
| 21/1/2019 | | Tyre Size: | F: (| 25/\$ 55 R | () |
| (Policy Condition) | | | R: | . // | |
| emark: The veh had commenced its repair at the time of inspection. | N/S O/S | BS / DUN / EX | | S/LIZA/MIG/OHTSU | / PIR / SUMI / |
| al, or Market Value: | | Front | | Rear | , |
| AC Accident Rport: Consistent?: | Yes or No | R/Bal. | 6 m | m R/Bal. | b mm |
| IA / PR Seen: Consistent?: | Yes or No | L/Bal. | 6 m | m L/Bal. | 6 mm |
| st. Repairs: 6 days Res.: ` | Yes or No | D.O.A. | | D,O.I. | 21-01-19 |
| um Sum: 20 % 3 Val.: Y | es or No | Survey held a | t | WS | 4:45 m |
| A / REV / REP. / 24 HRS | | Des. of Dama | ges Frt / Rea | ar / qis Nis / U/C / | |
| | Vehicle: IN / OUT | | | | |
| ate. Person Contacted: | | The U/C | Chassis fram | e / Body Structure at | fected due to collision |
| Date / Time Action / Instruction | \$600 | & You | · - \$8 | 000 | |
| ate/Time. File Pass to?: Preli. Repor | t | Days Of Rep | air: | 6 | |
| : Final Report | t | Resurvey No | o. of Trip: | Survey Fe | e: 100 |
| ate/Time. File Return to? | | | | Transportation | 1011 |
| | Add Fe | Personal Control of the Control of t | nsp (\$ |)S+RS | SI |
| | | y-more or | iew (\$ |) Photos | |
| eport Format : PRQ | v | Tech | Invs (\$ |) Others | 10 |
| ump Sum / I.B.I: (\$ |) | . West | end (\$ | 2 1 - | - |
| | | | | TOTAL | 230 |

...CLAIM SUBFOLDER...(New Assignment)

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status | |
|---|--------------------|--------------------|--------------------------------|----------------------|------------------------|---------------------------------------|---------------------------------------|------------------|
| Main | 14 Jan 2019 | | 15 Jan 2019 14:15 Assign | | | THIS HALL CO | New Assign | |
| | Main | R | eference | | Claim Details | Do | cuments | Show All |
| CLAIM S | UBFOLDER DET | TAILS | | Market State Control | | The second second | [Created by i | nsurer1 |
| Insured: | | ETHO | Z GROUP LTD, | Co. Reg. No. | : 198104531H | | | |
| Main Clair | nant: | | KENG KIM HERB | | | | | |
| Vehicle Re | g. No.: | SKB2 | 729C | | Date of Loss: | | 11/01/2019 19 | :00 - :59 |
| Claim Typ | e: | TP/ | TP / CMTD1900328 | | Policy/Cover Note No.: | | D19MTRENT000061 (Third Party Only) | |
| Vehicle Re | g. No. (Insured): | SLB99 | SLB9960S | | Policy No. (Claimant): | | | |
| | | | | | Excess: | | | |
| Repairer: Ace Chrome & Restoration Pte Ltd (HQ) 2 KAKI BUKIT AVENUE 2, #02-24 Kaki Bukit - Tel: | | | | 24 KAKI BUKIT A | AUTOHUB, 417921 | | | |
| Handling I | nsurer: | Somp 6329 5 | Insurance Sing [202] | japore Pte. | Ltd. (HQ) - Tel: 6461 | 6555 [Handle | ed by NGO SAU | WEI SHAWN - |
| Adjuster: | | LKK A | uto Consultants | Pte Ltd (HC | 2) - Tel: 6256-3561 | Final Rpt du | ue 24/01/201 | 91 |
| Adj Asg. R | emarks: | -PLEAS | E BE INFORMED | THAT OUR IN | ISURED HAS NOT REPO | RTED THE ACCI | DENT -NO TP SA | S SUBMITTED |
| ASSOCIA | TED MAIL REC | EIVED | | | , | \ | /iew All Co | ompose Case Mail |
| There are | no mail for this c | ase. | | | | | | |
| E ALL ASS | OCIATED TASK | c | | | 7 | · · · · · · · · · · · · · · · · · · · | | |
| ALL ASS | OCIATED TASK | .5 | | | View All S | Search Tasks | Create New T | ask Complete |
| Due Da No results | | Type Task (| Group Subje | ct Hand | ler Assigned By | Complete | d On Crea | ated On Done? |

Arrange on 21/1/2019

Catherine Chong (LKK Auto)

From:

Teo, Grace <grace.teo@sompo.com.sg>

Sent:

Tuesday, 15 January, 2019 2:12 PM

To:

ct-admin@visionlawllc.com; jactan@visionlawllc.com; admin-d@lkkauto.com;

assignments@lkkauto.com

Cc:

Ngo, Sau Wei Shawn; Ye, Yong Kang Melvin; Henry, Irene James

Subject:

CMTD1900328/NSW - SUV(LKK)/ SLB9960S & SKB2729C ACC ON 11.01.19

Our Reference: CMTD1900328/NSW

Your Reference: AM.jt.Ins.Y55.SKB2729C.19 (sj)

Date: 15/01/2019

Without Prejudice EMAIL ONLY

Attention:

M/S VISION LAW LLC

Dear Anjalli,

ACCIDENT INVOLVING SLB9960S & SKB2729C ON 11.01.2019

We refer to your email reply of today.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

Kindly provide us the address of location and contact for our motor surveyor to conduct the pre-repair survey.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards
Grace Teo
Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|--|-------------------------------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: Vehicle Details | 9183C |
| Vehicle No.: | SKB2729C |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 23 Jan 2019 |
| Vehicle Make: | HYUNDAI |
| Vehicle Model: | 145 2.4 AT ABS AIRBAG 2WD 4DR GAS/D |
| Primary Colour: | Silver |
| Manufacturing Year: | 2010 |
| Engine No.: | G4KEAU190536 |
| Chassis No.: | KMHEC41CMBA243326 |
| Maximum Power Output: | 131.0 kW (175 bhp) |
| Open Market Value: | \$19,414.00 |
| Original Registration Date: | 12 May 2011 |
| First Registration Date: | 12 May 2011 |
| Transfer Count: | 0 |
| Actual ARF Paid: Intended PARF Rebate Details | \$19,414.00 |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 11 May 2021 |
| PARF Rebate Amount: Intended COE Rebate Details | \$11,648.00 |
| COE Expiry Date: | 11 May 2021 |
| COE Category: | E - Open Category |
| COE Period(Years): | 10 |
| QP Paid: | \$62,001.00 |
| COE Rebate Amount: | \$14,253.00 |
| Total Rebate Amount: | \$25,901.00 |

The information contained herein is correct as at 23 Jan 2019

ОК

...CLAIM SUBFOLDER...(Pending for Survey Report)

| LAIM SUBF | OLDER TRA | CKING | | | | | | | | | |
|----------------------------------|-----------------|------------------------|--------------------------------------|---------------------|-----------------------|-------|-------------|---------------------------------------|------------|---|-------------|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | | Adj S | Submitted | Ins Auth'ed | St | tatus | |
| Main | 14 Jan 2019 | | 15 Jan 2019 14:15 Edit Adj Rpt | S\$0.00 Edit Est | imates | S\$0. | 00 w Rpt | | R | Pending for Surver Report Cancel Case | |
| 1 | Main | R | eference | C | laim Det | ails | | Docume | ents | | Show All |
| CLAIM SU | BFOLDER DI | TAILS | | | | | [Created | by insurer] | | | |
| Insured: | ETHOZ G | ROUP LTD, Co. I | Reg. No.: 19810453 | 1H | | | | | | | |
| Main Claimant: | SEET KEN | IG KIM HERBERT | , ID: S1089183C | | | | | | | | |
| Vehicle Reg No.: | SKB272 | 9C | | | Date of I | oss: | | 9 19:00 - :59 s and 30 Days | From LTA | Reg Date (| Man Yr)] |
| Claim Type: | TP / CM | TD1900328 | | | Policy/Co Note No. | | D19MTREN | T000061 (Thir | d Party O | nly) | |
| Vehicle Reg No. (Insured): | SLB9960 | s | | | Policy No (Claiman | | : | | | | |
| | | | | | Excess: | | | | | | |
| Repairer: | Ace Chro | me & Restoratio | n Pte Ltd (HQ) 2 K | AKI BUKIT | AVENUE 2 | , #02 | -24 KAKI BI | JKIT AUTOHUB | , 417921 | Kaki Bukit | - Tel: |
| Handling Insurer: | | | ore Pte. Ltd. (HQ) | | | | | | | | |
| Adjuster: | LKK Auto | Consultants Pte | Ltd (HQ) - Tel: 62 | 56-3561 | [Handled | by X | ING GUO Q | IANG] [Fir | nal Rpt | due 24/0 | 1/2019] |
| Adj Asg. Remarks: | -PLEASE E | E INFORMED THA | T OUR INSURED HA | S NOT REPO | ORTED TH | E ACC | IDENT -NO | TP SAS SUBMI | TTED | | |
| ASSOCIAT | ED MAIL RE | CEIVED | | | | | | | View All | Compose | e Case Mail |
| There are n | o mail for this | case. | | | | | | _ | | | |
| ALL ASSO | CIATED TAS | SKS⊡ | | | | V | iew All S | Search Tasks | Create | New Task | Complete |
| Due Date No results. | Priority | Type Task | Group Subjec | ct Hand | ler A | ssign | ed By | Completed C | On (| Created On | Done? |
| | | | | | | | | | 59664 5515 | | |

Claim Documents

*SKB2729C (CMTD1900328)

[SLB9960S]

TP

SEET KENG KIM HERBERT

Jan 11 2019 7:00PM

[ETHOZ GROUP LTD]

Ace Chrome & Restoration Pte Ltd

| Phot | tos/Images | | 3 per page ✓ | V |
|------|-----------------|-----------------------------------|----------------|----------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnai | Print |
| 1 | 23/01/19 10:27 | General View | Load JPG | ✓ |
| 2 | 23/01/19 10:27 | General View | Load JPG | ✓ |
| 3 | 23/01/19 10:27 | General View | Load JPG | ✓ |
| 4 | 23/01/19 10:27 | General View | 1 Load JPG | ✓ |
| 5 | 23/01/19 10:27 | General View | Load JPG | ✓ |
| 6 | 23/01/19 10:27 | General View | Load JPG | ✓ |
| 7 | 23/01/19 10:27 | General View | Load JPG | ✓ |
| 8 | 23/01/19 10:27 | General View | Load JPG | ✓ |
| 9 | 23/01/19 10:27 | General View | Load JPG | ✓ |
| 10 | 23/01/19 10:27 | General View | Load JPG | ✓ |
| 11 | 23/01/19 10:27 | General View | ■ Load JPG | V |
| 12 | 23/01/19 10:27 | General View | ■ Load JPG | ✓ |
| 13 | 23/01/19 10:27 | General View | Load JPG | ✓ |
| 14 | 23/01/19 10:27 | General View | Load JPG | ✓ |
| 15 | 23/01/19 10:27 | General View | Load JPG | ✓ |
| 16 | 23/01/19 10:27 | General View | Load JPG | ✓ |
| 17 | 23/01/19 10:27 | General View | Load JPG | ✓ |
| 18 | 23/01/19 10:27 | General View | Load JPG | ✓ |
| 19 | 23/01/19 10:27 | General View | 1 Load JPG | ✓ |
| 20 | 23/01/19 10:27 | General View | Load JPG | ✓ |
| 21 | 23/01/19 10:27 | General View | Load JPG | ✓ |
| 22 | 23/01/19 10:27 | General View | 1 Load JPG | ✓ |
| 23 | 23/01/19 10:27 | General View | 1 Load JPG | ✓ |
| 24 | 23/01/19 10:27 | General View | Load JPG | ✓ |
| 25 | 23/01/19 10:27 | General View | Load JPG | ✓ |
| 26 | 23/01/19 10:27 | General View | 1 Load JPG | ✓ |
| 27 | 23/01/19 10:27 | General View | Load JPG | V |
| 28 | 23/01/19 10:27 | General View | 1 Load JPG | ✓ |
| 29 | 23/01/19 10:27 | General View | 1 Load JPG | V |
| 30 | 23/01/19 10:27 | General View | 1 Load JPG | ✓ |
| 31 | 28/01/19 14:36 | Photographs of Damaged Parts | 1 Load JPG | ✓ |
| 32 | 28/01/19 14:36 | Photographs of Damaged Parts | 1 Load JPG | ✓ |
| 33 | 28/01/19 14:36 | Photographs of Damaged Parts | 1 Load JPG | ~ |
| 34 | 28/01/19 14:36 | Photographs of Damaged Parts | 1 Load JPG | V |
| 35 | 28/01/19 14:36 | Photographs of Damaged Parts | 1 Load JPG | ✓ |
| 36 | 28/01/19 14:36 | Photographs of Damaged Parts | 1 Load JPG | ~ |
| 37 | 28/01/19 14:36 | Photographs of Damaged Parts | ♠ Load JPG | ~ |

| Pho | otos/Images | | 3 per p | oage 🔻 | V |
|-----|-----------------|--|---------|-----------|----------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 38 | 28/01/19 14:36 | Photographs of Damaged Parts | 0 | Load JPG | ✓ |
| 39 | 28/01/19 14:36 | Photographs of Damaged Parts | 0 | Load JPG | ✓ |
| 40 | 28/01/19 14:36 | Photographs of Damaged Parts | 6 | Load JPG | ✓ |
| 41 | 28/01/19 14:36 | Photographs of Damaged Parts | 0 | Load JPG | ✓ |
| 42 | 28/01/19 14:36 | Photographs of Damaged Parts | 0 | Load JPG | ☑ |
| 43 | 28/01/19 14:37 | Photo After Spray | 0 | Load JPG | ✓ |
| 44 | 28/01/19 14:37 | Photo After Spray | 0 | Load JPG | V |
| 45 | 28/01/19 14:37 | Photo After Spray | 0 | Load JPG | V |
| 46 | 28/01/19 14:37 | Photo After Spray | 0 | Load JPG | V |
| 47 | 28/01/19 14:37 | Photo After Spray | 0 | Load JPG | ✓ |
| 48 | 28/01/19 14:37 | Photo After Spray | 0 | Load JPG | ✓ |
| 49 | 28/01/19 14:37 | Photo After Spray | 0 | Load JPG | ✓ |
| 50 | 28/01/19 14:37 | Photo After Spray | 0 | Load JPG | ✓ |
| 51 | 28/01/19 14:37 | Photo After Spray | 0 | Load JPG | V |
| 52 | 28/01/19 14:37 | Photo After Spray | 0 | Load JPG | ✓ |
| 53 | 28/01/19 14:37 | Photo After Spray | 0 | Load JPG | ✓ |
| 54 | 28/01/19 14:37 | Photo After Spray | 0 | Load JPG | ✓ |
| Dod | cumentation | | 1 per | page 🔻 | V |
| No | Finalized On | Sompo Insurance Singapore Pte. Ltd. (HQ) | | Thumbnail | Print |
| 1 | 15/01/19 10:03 | Pre-Repair Survey - VISION LAW LLC | 0 | Load PDF | |
| 2 | 15/01/19 14:13 | Pre-Repair Survey - ASSIGN LKK | 0 | Load PDF | |
| 3 | 15/01/19 15:16 | Pre-Repair Survey - ACE CHROME & RESTORATION | 0 | Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) | | | |
| | | | ^ |
| | | | ~ |
| Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties. | | | |

LKK Auto Consultants Pte Ltd (Co. Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/SMO19000929/GCD3E2

Date:

30/01/2019

REFERENCE

Handling Insurer:

Sompo Insurance Singapore Pte.

Policy No:

D19MTRENT000061

Claimant Vehicle

No:

SKB2729C

Insured Vehicle No:

SLB9960S

Date of Loss:

11/01/2019

Nature of Claim:

TP

Claim No:

CMTD1900328

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKB2729C

Make & Model:

HYUNDAI 145, 2.4 ABS AIRBAG 2WD 4DR GAS/D

Engine No:

G4KEAU190536

156452 km

Reg. Date:

(A)

12/05/2011 (Man. Year: 2010)

Chassis No: Odometer:

KMHEC41CMBA243326

Colour: Engine Capacity:

Silver 2359 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Footbrake (Serviceable): Yes

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES Front Tyre Size:

215/55 R17

Rear Tyre Size:

No

215/55 R17

Front Left Side:

Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side:

Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------|------------|------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment:

15/01/2019

Date Inspected:

21/01/2019 Inspected At:

Ace Chrome & Restoration Pte Ltd (HQ)

2 KAKI BUKIT AVENUE 2, #02-24 KAKI

BUKIT AUTOHUB Singapore 417921

Estimated Period of Repair:

6.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen ... 30/1/2019



A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

Adjuster Report Page 4 of 5

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last S

Version: 1.0 (Last Synchronised: 30 Jan 2019)

Parts: 143

HYUNDAI I45 2.4 ABS AIRBAG 2WD 4DR GAS/D (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Fillit Cot

Print Code: (Unsubmitted, no print-code for SKB2729C)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >