

ASS. REC. BY:

REF:

CS/SMD19000930/Asd3n2

Special Instruction:

SUN/JOY

## ASSIGNMENT (Office)

From (Person): Phelmo Choo of SMD Date/Time: 15/1/2019Estimated Cost: \$17,620.25 Bill to: \_\_\_\_\_OD TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SMF 5823Z Insured: YP7003Rat Workshop m/s Abwin Service Tel: 67139417 Linda Liaoof No. 8 Kaki Bukit Ave 4 #07-48Policy No: D18MTPCVE002574 Claim No: CMTD1900334

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 13/1/2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 15/1 Person Contacted: Linda Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SMF 5823Z - X</u>
	<u>YP7003R - X</u>
<u>18/01/19</u>	<u>@ 17:44 p.m. revert pending estimate from repairer to Thelma via merimer.</u>

REF:

SMO

## ASSIGNMENT

From:

Date:

16/1

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMFS823Z

at Workshop m/s Abwin Service

at No. 8 Kaki Bukit Ave 4

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days:

Res: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh Hg:

SMFS823Z

Yr Regn:

2018 Nov

Type ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Fit. Hybrid c.c. 1496

Colour:

Black

A/C

Insured / Std / NI / NA

Sp Reading

1774.

T/Ratio: Insured / Std / NI / NA

Eng/No:

C/No:

6PS3414832

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

185/60R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

19/1/2019

D.O.I.

16/01/19.

Survey held at

Abwin.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Sampo.

08/03/19 Continued p/p \$3,296.68 @ 4 days with Adrian.  
( \$13,170.84 Red - 80% )

RECEIVED 08 MAR 2019

Date/Time, File Pass to?

08/03/19  
Typ. 4

: Preli. Report



: Final Report

Date/Time, File Return to?

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation

1. S + R. 3

2. Photos

3. Others

4. TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$ 3,296.68 p/p

450  
10

460

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Jan 2019		15 Jan 2019 14:39 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All																				
<b>CLAIM SUBFOLDER DETAILS</b>			<b>[Created by insurer]</b>																					
Insured:	<b>SOHO LIVING GROUP PTE LTD,</b> Co. Reg. No.: 201009617G																							
Main Claimant:	<b>CHEN JUN JIE MATTHIAS,</b> ID: S8703426G																							
Vehicle Reg. No.:	<b>SMF5823Z</b>	Date of Loss:	13/01/2019 00:00 - :59																					
Claim Type:	<b>TP / CMTD1900334</b>	Policy/Cover Note No.:	<b>D18MTPCVE002574</b> (Comprehensive)																					
Vehicle Reg. No. (Insured):	<b>YP7003R</b>	Policy No. (Claimant):																						
		Excess:																						
Repairer:	<b>Abwin Service Pte Ltd (HQ) No. 8 Kaki Bukit Avenue 4, #07-48 Premier@Kaki Bukit Gate 2, 415875 Kaki Bukit - Tel: 6713 9400</b>																							
Handling Insurer:	<b>Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]</b>																							
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/01/2019]</b>																							
Adj Asg. Remarks:	<b>-PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT</b>																							
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>																				
There are no mail for this case.																								
<div> <b>ALL ASSOCIATED TASKS</b> </div> <div> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </div> <table border="1"> <thead> <tr> <th>Due Date</th><th>Priority</th><th>Type</th><th>Task Group</th><th>Subject</th><th>Handler</th><th>Assigned By</th><th>Completed On</th><th>Created On</th><th>Done?</th></tr> </thead> <tbody> <tr> <td colspan="10">No results.</td></tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Veh lu  
16/1 morning

## View Sent Message

This mail is associated with :

**\*SMF5823Z (CMTD1900334)  
[YP7003R]**

TP  
CHEN JUN JIE MATTHIAS  
Jan 13 2019 12:00AM  
[SOHO LIVING GROUP PTE LTD]  
Abwin Service Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 18/01/2019 17:44 PM.  
**To** thelma.choo@sompo.com.sg  
**CC** sur@lkkauto.com  
**Subject** SMF5823Z (CMTD1900334) [YP7003R] TP

Dear Thelma,

Please be informed that we have inspected the vehicle SMF 5823Z on 16/01/2019.

We are pending estimate from repairer.

Thank you.  
Best Regards,  
Shirley Hiew | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### DOCUMENTS SUMMARY

There are no documents.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/01/2019 15:44
Date Of Accident	13/01/2019 13:00
Exact Location Of Accident	YISHUN AVENUE 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMF5823Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHEN JUN JIE MATTHIAS
NRIC No	S8703426G
Email Address	AKIOSHUN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94764831
Alternative Phone No	OTHERS-94764831

### Vehicle Particulars

Manufacturer	HONDA
Model	FIT-1.5 HYBRID (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA418489
Cover Note Number	

### Driver

Name of Driver	CHEN JUN JIE MATTHIAS
NRIC No	S8703426G
Date Of Birth	17/02/1987
Occupation	INDOOR
Date Of Driving Pass	30/08/2017
Driving Experience	1 YEAR AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94764831
Fax Number	
Contact Number	OTHERS-94764831
Email Address	AKIOSHUN@GMAIL.COM

Address	BLK 310 CANBERRA ROAD #06-131 SINGAPORE
Postcode	750310
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TAN ZHI XIAN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH OWNER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP7003R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

14/1/19

2:28pm

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Power



### Sketch Plan #2

### SKETCH PLAN

Vehicle  
A-SMF 5823R  
B-YP 7003R

Legend  
 Vehicle  
 Motorcycle

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Xishun Ave 1 towards Sembawang Rd, my car was in the right turn lane with the traffic light right arrow turning yellow. Prior to this, my car was already slowing down, coming to a stop before the Stop line. The lorry, ~~that~~ was at least two cars distance away from me, and yet did not seem to brake early or in time. The collision sent the car, at least a bike distance beyond the stop line. Contacts were exchanged, and the lorry's P.O.C. apologised for the rear-end collision.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against own policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature \_\_\_\_\_

Date & Time:

2:28pm  
14/11/19

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Names:

NRIC/FIN No.:

perman

Please arrange to survey vehicle at  
8 KAKI BUKIT AVENUE 4 - GATE 2  
#07-48 PREMIER @ KAKI BUKIT  
SINGAPORE 415875

**ABWIN** 諭輝

Date : 15/01/2019  
TP Vehicle No. : YP -7003-R  
To : **SOMPO INSURANCE SINGAPORE PTE. LTD.**  
Attn : **Motor Claim Department**

LINDA LIAO  
ABWIN SERVICE PTE LTD  
DID: 67139417  
Fax: 67139415  
HP: 97519596

Owner : CHEN JUN JIE MATTHIAS  
AXA INSURANCE SINGAPORE PTE LTD  
Certificate No. : GA418489  
Vehicle No. : SMF-5823-Z  
Make & Model : HONDA FIT HYBRID 1.5 AUTO

Accident Date: 13/01/2019

6153414832

### ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
<u>List Item</u>			
1	TAILGATE <i>Dented</i>	\$2,180.50	1150
1	TAILGATE CHROME GARNISH <i>new</i>	\$580.60	x
1	TAILGATE MOULDING <i>new</i>	\$385.60	+
1	TAILGATE LOGO <i>new</i>	\$95.60	x
1	TAILGATE EMBLEM "HYBRID" <i>new</i>	\$75.60	✓
1	TAILGATE EMBLEM "FIT" <i>new</i>	\$68.50	✓
10	TAILGATE CHROME GARNISH CLIPS <i>new</i>	\$50.00	x
1	TAILGATE REFLECTOR LH <i>new</i>	\$695.80	+
1	TAILGATE REFLECTOR RH <i>new</i>	\$695.80	+
1	TAILGATE INNER TRIM BOARD <i>new</i>	\$480.50	x
10	TAILGATE INNER TRIMBOARD CLIPS <i>new</i>	\$50.00	x
1	TAILGATE LOCK <i>new</i>	\$380.60	+
1	TAILGATE LOCK CATCH <i>new</i>	\$150.60	+
1	REAR WINDSCREEN WEATHERSTRIP <i>new</i>	\$195.60	✓
1	TAILLAMP RH <i>new</i>	\$850.90	+
1	TAILLAMP LH <i>new</i>	\$850.90	+
1	REAR END PANEL <i>Repis</i>	\$780.90	x
1	REAR END PANEL TOP GARNISH <i>new</i>	\$215.80	x
1	REAR BUMPER REINFORCEMENT <i>new</i>	\$195.00	x
1	REAR BUMPER BRACKET LH <i>new</i>	\$98.50	x
1	REAR BUMPER BRACKET RH <i>new</i>	\$98.50	x
1	REAR BUMPER <i>Debond</i>	\$1,850.60	774.50
1	REAR BUMPER RETAINER LH <i>new</i>	\$95.60	x
1	REAR BUMPER RETAINER RH <i>new</i>	\$95.60	x
1	REAR BUMPER REFLECTOR RH <i>new</i>	\$125.60	+
1	REAR BUMPER RELECTOR LH <i>new</i>	\$125.60	x
1	REAR BUMPER LOWER GARNISH <i>new</i>	\$315.60	x
<b>Sub Total</b>		<b>\$11,784.40</b>	
<b>Discount 20% on Parts</b>		<b>(\$2,356.88)</b>	

22646

1811.68

Date : 15/01/2019  
 TP Vehicle No. : YP -7003-R  
 To : SOMPO INSURANCE SINGAPORE PTE. LTD.  
 Attn : Motor Claim Department

LINDA LIAO  
 ABWIN SERVICE PTE LTD  
 DID: 67139417  
 Fax: 67139415  
 HP: 97519596

Owner : CHEN JUN JIE MATTHIAS  
 AXA INSURANCE SINGAPORE PTE LTD  
 Certificate No. : GA418489  
 Vehicle No. : SMF-5823-Z  
 Make & Model : HONDA FIT HYBRID 1.5 AUTO

Accident Date: 13/01/2019

## ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
		\$9,427.52	

### Special Nett

10	REAR BUMPER CLIPS <i>neu</i>	\$50.00	30
10	REAR END PANEL TOP GARNISH CLIPS <i>neu</i>	\$50.00	10
1	REAR NUMBER PLATE & CASEING <i>neu</i>	\$95.00	105
1	TAILGATE REVERSE CAMERA <i>neu</i>	\$450.00	+
1	REAR WINDSCREEN SEALANT <i>neu</i>	\$65.00	✓
1	TAILGATE SEALANT <i>neu</i>	\$65.00	+
1	REAR END PANEL SEALANT <i>neu</i>	\$65.00	+
1	REAR BUMPER REVERSE SENSOR <i>neu</i>	\$550.00	+
	<b>Sub Total</b>	<b>\$1,390.00</b>	

### Labour & Misc

TO STAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$2,500.00	500
TO SPRAY PAINT ON AFFECTED AREAS	\$2,000.00	600
TO CHECK LIGHTING AND FOCUS TAILLAMP	\$350.00	30
TO INSTALL REVERSE SENSOR & CHECK FUNCTIONALITY	\$250.00	50
TO TRANSFER TAILGATE COMPOENTS	\$250.00	80
TO TRANSFER REAR WINDSCREEN FITTING	\$150.00	120
TO APPLY TUFF KOTE ON AFFECTED AREA.	\$150.00	+
<b>Sub Total</b>	<b>\$5,650.00</b>	

Sub Total \$16,467.52  
 GST 7% \$1,152.73  
 Total \$17,620.25

total: 3296.68 (P/P)

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19000930/ASD3N2

Date: 13/03/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE002574		
Claimant Vehicle No :	SMF5823Z	Insured Vehicle No :	YP7003R		
Date of Loss:	13/01/2019	Nature of Claim:	TP	Claim No:	CMTD1900334

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SMF5823Z	Engine No:	LEB6069317
Make & Model:	HONDA FIT, 1.5 HYBRID (A)	Chassis No:	GP53414832
Reg. Date:	16/11/2018 (Man. Year: 2018)	Odometer:	1774 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,817.52	1,916.68	8,900.84	82.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,650.00	1,380.00	4,270.00	75.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>16,467.52</b>	<b>3,296.68</b>	<b>13,170.84</b>	<b>79.98</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,152.73</b>	<b>230.77</b>	<b>921.96</b>	<b>79.98</b>
<b>Nett Amount (S\$)</b>	<b>17,620.25</b>	<b>3,527.45</b>	<b>14,092.80</b>	<b>79.98</b>

## INSPECTION

Date of Assignment:	15/01/2019	
Date Inspected:	16/01/2019	Inspected At: Abwin Service Pte Ltd (HQ) No. 8 Kaki Bukit Avenue 4, #07-48 Premier@Kaki Bukit Gate 2 Singapore 415875
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 Mar 2019)
<b>Parts:</b> 144	HONDA FIT 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SMF5823Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,180.50 FL	*1,150.00 FL
2	1		*TAILGATE CHROME GARNISH	Not Necessary	580.60 FL	*- FL
3	1		*TAILGATE MOULDING	Not Necessary	385.60 FL	*- FL
4	1		*TAILGATE LOGO	Not Necessary	95.60 FL	*- FL
5	1		*TAILGATE EMBLEM HYBRID	Necessary	75.60 FL	*75.60 FL
6	1		*TAILGATE EMBLEM FIT	Necessary	68.50 FL	*68.50 FL
7	10		*TAILGATE CHROME GARNISH CLIPS	Not Necessary	50.00 FL	*- FL
8	1		*TAILGATE REFLECTOR LH	Not Necessary	695.80 FL	*- FL
9	1		*TAILGATE REFLECTOR RH	Not Necessary	695.80 FL	*- FL
10	1		*TAILGATE INNER TRIM BOARD	Not Necessary	480.50 FL	*- FL
11	10		*TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FL	*- FL
12	1		*TAILGATE LOCK	Not Necessary	380.60 FL	*- FL
13	1		*TAILGATE LOCK CATCH	Not Necessary	150.60 FL	*- FL
14	1		*REAR WINDSCREEN WEATHERSTRIP	Necessary	195.60 FL	*195.60 FL
15	1		*TAILLAMP RH	Not Necessary	850.90 FL	*- FL
16	1		*TAILLAMP LH	Not Necessary	850.90 FL	*- FL
17	1		*REAR END PANEL	Repair	780.90 FL	*- FL
18	1		*REAR END PANEL TOP GARNISH	Not Necessary	215.80 FL	*- FL
19	1		*REAR BUMPER REINFORCEMENT	Not Necessary	195.00 FL	*- FL
20	1		*REAR BUMPER BRACKET LH	Not Necessary	98.50 FL	*- FL
21	1		*REAR BUMPER BRACKET RH	Not Necessary	98.50 FL	*- FL
22	1		*REAR BUMPER	Deformed	1,850.60 FL	*774.90 FL
23	1		*REAR BUMPER RETAINER LH	Not Necessary	95.60 FL	*- FL
24	1		*REAR BUMPER RETAINER RH	Not Necessary	95.60 FL	*- FL
25	1		*REAR BUMPER REFLECTOR RH	Not Necessary	125.60 FL	*- FL
26	1		*REAR BUMPER REFLECTOR LH	Not Necessary	125.60 FL	*- FL
27	1		*REAR BUMPER LOWER GARNISH	Not Necessary	315.60 FL	*- FL
28	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
29	10		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*10.00 FS
30	1		*REAR NUMBER PLATE & CASING	Not Necessary	95.00 FS	*- FS
31	1		*TAILGATE REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
32	1		*REAR WINDSCREEN SEALANT	Necessary	65.00 FS	*65.00 FS
33	1		*TAILGATE SEALANT	Not Necessary	65.00 FS	*- FS
34	1		*REAR END PANEL SEALANT	Not Necessary	65.00 FS	*- FS
35	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>13,174.40</b>	<b>2,369.60</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>2,356.88</b>	<b>452.92</b>
<b>Total Parts (\$\$)</b>	<b>10,817.52</b>	<b>1,916.68</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	New	2,500.00	500.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	2,000.00	600.00
3	TO CHECK LIGHTING AND FOCUS TAILLAMP	New	350.00	30.00
4	TO INSTALL REVERSE SENSOR & CHECK FUNCTIONALITY	New	250.00	50.00
5	TO TRANSFER TAILGATE COMPONENTS	New	250.00	80.00
6	TO TRANSFER REAR WINDSCREEN FITTING	New	150.00	120.00
7	TO APPLY TUFF KOTE ON AFFECTED AREA	New	150.00	0.00
Gross Labour Cost (S\$)			5,650.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >