

Surveyor

Tanaka

REF:

MS14-

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. B29062113MCY
 Claims No. 585420
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S
<input checked="" type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB 822P Yr Regn: 2014 Sep.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Pro C.C. 1798
 Colour: Maroon A/C: Insured / Std / NI / NA
 Sp. Reading: 378793 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 5T DKN364205748919
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/25R15
 R: 27

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or was there

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 11/1/19
 Survey held at SMKT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SHB 822P- NA/INC11018052/S2

SKX 9217B-X

16/11/19 @ 5.59pm Email GIA, Estimate revised to Christina Wong & Hasvanah.

18/6/19 Confirm L/S \$4300, 6 days with Polt Sean thru e-mail
(Red \$9609.65, 69%)

01/19/2045
SKX 9217B

17/6/2019

RECEIVED 1-8 JUN 2019

Date/Time. File Pass to?

☐

: Preli. Report

1) 18/6/19 Final

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Survey Fee:

Transportation

) S + RS \$

) Photos

) Others

)

TOTAL

Report Format: MER-TP

Lump Sum / I.B.I. (\$) 4300

200

11

211

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 16 January 2019 5:59 PM
To: Christina Wong; Hasrianah Binte Hassan
Cc: KKLau; SUR; Accounts (LKKAuto)
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICES PTE LTD (TP VEHICLE: SHB 822P, INSURED VEHICLE: SSKX 9217B, DOA: 10-01-2019)
Attachments: CC3MSG19000935T1qd3.pdf; SHB822 GIA.pdf; SHB822 EST.pdf

Dear Christina and Hasrianah,

Please be informed that we had inspected the vehicle **SHB 822P** at M/s: **SMRT AUTOMOTIVE SERVICES PTE LTD**, 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705.

Enclosed herewith a copy of TP's GIA report and estimate.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: Please advise

Date: 16 January 2019

Our Ref: CC3/MSG19000935/T1qd3

The Motor Claims Department
MSIG Insurance Singapore Pte Ltd

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SHB 822P

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/01/2019 at the premises of M/s SMRT and have the following to report:-

Workshop Estimate Amount	: S\$ 11,860.64 .
Revised Estimate Amount	: S\$ 4,932.13 .
"Check" Items Amount	: S\$ 246.68 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages consistent.

We have not authorized repair.

Yours faithfully

Taufikh
Automotive Assessor

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB822P
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR6127475
Chassis No.:	JTDKN36U205748919
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	10 Sep 2014
First Registration Date:	10 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Sep 2022
PARF Rebate Amount:	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date:	09 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$23,125.00
Total Rebate Amount:	\$29,191.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 16 Jan 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/01/2019 15:16
Date Of Accident	10/01/2019 04:05
Exact Location Of Accident	MARINE PARADE ROAD TOWARDS PARKWAY PARADE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB822P
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	LIM TECK WEE
NRIC No	S7770684D
Date Of Birth	18/07/1977
Occupation	OUTDOOR
Date Of Driving Pass	23/01/2004
Driving Experience	14 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG MARINE PARADE TOWARDS PARKWAY PARADE WITH ONE PASSENGER (FEMALE CHINESE) ON BOARD. MY PASSENGER WANTED TO ALIGHT AS SUCH I SLOWED DOWN TO A STOP. AFTER WHICH I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SKX9217B HAD COLLIDED ONTO THE REAR LEFT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKX9217B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHO NAMUNG
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

MRT CONSTRUCTION SITE
THOMSON EAST COAST
LINE

STOP LINE

TAXI

YELLOW BOX

10/01/2019
D. M. L.

[illegible]

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature] 10/01/2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature] 10/1/2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Case Details

Case Reference Number :

TAX/01/19/2045

Company Type : SMRT Taxis Pte Ltd

Insurance Company Name : MSIG Insurance (S) Pte Ltd

Type of Repair : Accident Repair

Estimation ID : EST-5308-ID

Accident Date and Time : 09/01/2019 08:09 PM

Vehicle Registration Number : SHB822P

Assigned By : Taxi Claims Manager Team

Vehicle Age(In Months) : 52

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	30.00	343.95	Replace	1	343.95	Replace ✓
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	30.00	12.08	Replace	10	12.08	Replace ✓
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	30.00	154.27	Replace	1	154.27	Replace ✓
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	30.00	104.70	Replace	1	104.70	Replace ✓
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	30.00	104.70	Replace	0	0	Not Give ✓
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check ✓
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ✓
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	30.00	54.15	Replace	1	54.15	Replace ✓
Total Spare Part Cost									7,223.64		Surveyor Total	3,171.56	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost									5,778.91		Final Sur Total	2,537.25	

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	30.00	171.68	Replace	0	0 <i>ny</i>	Not Give <i>X</i>
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	30.00	66.68	Replace	0	0 <i>ny</i>	Check <i>X</i>
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	30.00	71.10	Replace	1	71.10	Replace <i>ny</i>
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	30.00	71.10	Replace	0	0	Not Give <i>X ny</i>
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	30.00	385.88	Replace	0	0	Not Give <i>ny</i>
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	30.00	755.92	Replace	1	755.92	Replace <i>Ry</i>
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	30.00	38.92	Replace	1	38.92	Replace <i>ny</i>
One Time Key In	Main			END PANEL	1	602.10	602.10	30.00	451.58	Replace	1	0	Repair <i>Ry</i>
One Time Key In	Main			REINFORCEMENT, RR	1	34.60	34.60	30.00	25.95	Replace	1	25.95	Replace <i>Bl</i>
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace <i>ny</i>
One Time Key In	Main			FLOOR PANEL RR/LH	1	102.00	102.00	30.00	76.50	Replace	1	76.50	Replace <i>bl</i>
One Time Key In	Main			BOARD, RR FLOOR	1	392.30	392.30	30.00	294.23	Replace	0	0	Not Give <i>ny</i>
One Time Key In	Main			BOARD ASSY, RR RH	1	379.20	379.20	30.00	284.40	Replace	0	0	Not Give <i>ny</i>
One Time Key In	Main			PANEL ASSY, DECK RH	1	307.00	307.00	30.00	230.25	Replace	0	0	Not Give <i>ny</i>
Total Spare Part Cost									7,223.64		Surveyor Total	3,171.56	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost									5,778.91		Final Sur Total	2,537.25	

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			PANEL SUB-ASSY, QTR WHEEL HOUSE	1	588.40	588.40	30.00	441.30	Replace	1	0 <i>R</i>	Repair
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	30.70	30.70	30.00	21.49	Replace	1	0.00 <i>del</i>	Replace
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	1	493.56 <i>one</i>	Replace
One Time Key In	Main			TROUGH, BACK DOOR LH	1	110.90	110.90	30.00	83.18	Replace	1	83.18 <i>new</i>	Replace
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	30.00	575.10	Replace	1	575.10 <i>new</i>	Replace
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80 <i>new</i>	Replace
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60 <i>new</i>	Replace
One Time Key In	Main			FENDER LINER RR/LH	1	141.30	141.30	30.00	105.98	Replace	1	105.98 <i>del</i>	Replace
One Time Key In	Main			LID ASSY, FUEL	1	102.00	102.00	30.00	76.50	Replace	1	0 <i>R</i>	Repair
One Time Key In	Main			CABLE SUB-ASSY, FUEL LID	1	63.90	63.90	30.00	47.92	Replace	0	0 <i>Xun</i>	Not Give
One Time Key In	Main			RETAINER, FUEL LID CABLE	1	5.90	5.90	30.00	4.43	Replace	0	0 <i>Xun</i>	Not Give
One Time Key In	Main			CAP ASSY, FUEL TANK	1	68.10	68.10	30.00	51.07	Replace	0	0 <i>Xun</i>	Not Give
One Time Key In	Main			PIPE SUB-ASSY, FUEL NECK	1	230.80	230.80	30.00	173.10	Replace	0	0 <i>Xun</i>	Not Give
One Time Key In	Main			TUBE, FUEL TANK	1	36.10	36.10	30.00	27.08	Replace	0	0 <i>Xun</i>	Not Give
Total Spare Part Cost									7,223.64		Surveyor Total	3,171.56	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost									5,778.91		Final Sur Total	2,537.25	

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			QUARTER GLASS RR/LH	1	168.10	168.10	30.00	126.07	Replace	0 <i>Xun</i>	0	Not Give ▾
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	1 <i>Xun</i>	37.00	Replace ▾
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0 <i>Xun</i>	0	Not Give ▾
One Time Key In	Main			DUCT ASSY, QUARTER	1	70.40	70.40	30.00	52.80	Replace	1 <i>de</i>	52.80	Replace ▾
One Time Key In	Main			DOOR RR/LH	1	954.50	954.50	30.00	715.88	Replace	1 <i>Ry</i>	0	Repair ▾
Total Spare Part Cost									7,223.64		Surveyor Total	3,171.56	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost									5,778.91		Final Sur Total	2,537.25	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR LEFT REAR PORTION	1,014.00	800	
Total:		1,014.00	800.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200	
2	TO RESPRAY BUMPER BEAM	180.00	100	
3	TO RESPRAY TAIL GATE	378.00	200	
4	TO RESPRAY REAR PANEL	180.00	100	
5	TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	100	
Total:		2,412.00	1,200.00	



S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
6	TO RESPRAY TROUGH BACK DOOR LH	180.00	0	
7	TO RESPRAY REAR FENDER LH	378.00	200	
8	TO RESRAY REAR DOOR LH	378.00	200	
9	TO RESPRAY REAR LH WHEEL HOUSE	180.00	100	
Total:		2,412.00	1,200.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TOWING CHARGE	126.00	0	Provide tow receipt
2	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
3	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
4	TO REMOVE & REFIT FUEL TANK	120.00	80	
5	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	125.00	
6	TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	80	
7	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	
8	TO REMOVE AND REFIT WIRE HARDESS	0.00	0.00	
9	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	60	
10	TO REPLACE SUNDRY PARTS	120.00	30	
11	TO WASH AND VACUUM	60.00	0	
12	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30	
Total:		1,211.00	495.00	



Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	5,778.91	2,537.25

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Labour Cost	1,014.00	800.00
Total Spray Painting	2,412.00	1,200.00
Other	1,211.00	495.00
Overall Total	10,415.91	5,032.25
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	10,400.00	5,050.00
Surveyor Approved Amount		5,050.00
No of Repair Days*	7	6
Remarks	-	Resurvey after repair
Surveyor Name		Taufikh
Signature		
Survey Date	11/01/2019	<div>Save Clear</div>

Section A - Accident Details

Registration Number	SHB822P
Case Reference Number	TAX/01/19/2045
Registration Date	10/9/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	LIM TECK WEE
Type of Accident	Head to Rear
Accident Date and Time	10/1/2019 4:09 AM
Accident Reported Date and Time	10/1/2019 3:01 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24099628
Special Instruction to ARC, if any	TP/MSIG - LKK
Prepared Date and Time	11/1/2019 10:28 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Toyota Prius

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$800.00
Total Spray Cost	\$2,412.00	\$1,200.00
Total Spare Part Cost	\$5,778.91	\$2,423.53
Total Other Cost	\$1,211.00	\$585.00
TOTAL COST	\$10,415.91	\$5,008.53
Lump Sum Total	\$10,400.00	\$5,000.00 (L/S)
Number of Repair Days	7.0	6.0
Prepared / Adjusted By	Tuck Foo Kok	Taufikh (LKK) / MSIG
ARC / Surveyor Sign Off Date	11/01/2019 5:29 PM	11/01/2019 4:37 PM
Signature		
Remarks		Resurvey after repair

13909.5665

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1902-0365	Invoice Number	
Quotation Date	25.02.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LEFT REAR PORTION	\$1,014.00	\$800.00
Total Labour	\$1,014.00	\$800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY BUMPER BEAM	\$180.00	\$100.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	\$180.00	\$100.00
TO RESPRAY REAR LH WHEEL HOUSE	\$180.00	\$100.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TROUGH BACK DOOR LH	\$180.00	\$0.00
TO RESRAY REAR DOOR LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$2,412.00	\$1,200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$30.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$125.00 X
TO REMOVE & REFIT FUEL TANK	\$120.00	\$80.00
TO REMOVE & REFIT REAR QUARTER GLASS LH	\$120.00	\$80.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$60.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$120.00	\$30.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$125.00	\$90.00
Total Other Costs	\$1,211.00	\$585.00

460

1411

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
	X		SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check	X nn
	✓	52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	30.00	\$66.36	Replace	Replace	✓ nec
	✓	58336-12090	REINFORCEMENT, RR	1.00	\$34.60	30.00	\$24.22	Replace	Replace	✓ br
	RX	61608-47061	PANEL SUB-ASSY, QTR WHEEL HOUSE	1.00	\$588.40	100.00	\$0.00	Replace	Repair	✓ R
	✓	52016-47030	ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	30.00	\$97.72	Replace	Replace	✓ dt
	X	77035-47090	CABLE SUB-ASSY, FUEL LID	0.00	\$63.90	0.00	\$0.00	Replace	Not Given	X nn
	✓		SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace	✓ nec
	X	76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given	X nn
	X	62720-47031	QUARTER GLASS RR/LH	0.00	\$168.10	0.00	\$0.00	Replace	Not Given	X nn
	✓	61622-47030	TROUGH, BACK DOOR LH	1.00	\$110.90	30.00	\$77.63	Replace	Replace	✓ nec
	✓	65638-47021	FENDER LINER RR/LH	1.00	\$141.30	30.00	\$98.91	Replace	Replace	✓ de
	RX	67005-47241	TAILGATE ASY	1.00	\$1,007.90	30.00	\$705.53	Replace	Replace	X R
	X	58308-47011	UNDER COVER SUBASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given	X nn
	X	77300-52030	CAP ASSY, FUEL TANK	0.00	\$68.10	0.00	\$0.00	Replace	Not Given	X nn
	X	52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Check	X in
	✓	62940-16060	DUCT ASSY, QUARTER	1.00	\$70.40	30.00	\$49.28	Replace	Replace	✓ de
	X	64730-47031B2	PANEL ASSY, DECK RH	0.00	\$307.00	0.00	\$0.00	Replace	Not Given	X nn
	X	58490-47140B0	BOARD ASSY, RR RH	0.00	\$379.20	0.00	\$0.00	Replace	Not Given	X nn
	X	77226-47040	TUBE, FUEL TANK	0.00	\$35.10	0.00	\$0.00	Replace	Not Given	X nn
	✓		PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	✓ nec
	✓	75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	30.00	\$36.33	Replace	Replace	✓ nec
	✓	52563-47010	TAIL LAMP BRACKET, LH	1.00	\$30.70	30.00	\$21.49	Replace	Replace	✓ de
	✓		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓ nec
	X	77377-75010	RETAINER, FUEL LID CABLE	0.00	\$5.90	0.00	\$0.00	Replace	Not Given	X nn
	✓	61602-47091	FENDER RR/LH	1.00	\$766.80	30.00	\$536.76	Replace	Replace	✓ nec
	X		SEALANT W/SCREEN	1.00	\$37.00	0.00	\$37.00	Replace	Replace	X nec
	✓	52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	30.00	\$143.99	Replace	Replace	✓ br
	✓	52159-47905	BUMPER REAR	1.00	\$458.60	30.00	\$321.02	Replace	Replace	✓ de
	RX	77350-47030	LID ASSY, FUEL	1.00	\$102.00	100.00	\$0.00	Replace	Repair	✓ R
	✓		SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓ nec
	✓	52161-16010	BUMPER CLIPS	10.00	\$1.61	30.00	\$11.27	Replace	Replace	✓ nec
	X	77201-47250	PIPE SUB-ASSY, FUEL NECK	0.00	\$230.80	0.00	\$0.00	Replace	Not Given	X nn
	X	58415-47030	BOARD, RR FLOOR	0.00	\$392.30	0.00	\$0.00	Replace	Not Given	X nn
	X		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X nn
	RX	58307-47060	END PANEL	1.00	\$602.10	100.00	\$0.00	Replace	Repair	✓ R
	✓	76088-47020	BUMPER LIP COVER RR/LH	1.00	\$72.20	30.00	\$50.54	Replace	Replace	✓ cut
	✓	58303-47301	FLOOR PANEL RR/LH	1.00	\$102.00	30.00	\$71.40	Replace	Replace	✓ br
	RX	67004-47080	DOOR RR/LH	1.00	\$954.50	100.00	\$0.00	Replace	Repair	✓ R
	✓	81561-47170	TAIL LAMP LH	1.00	\$548.40	10.00	\$493.56	Replace	Replace	✓ cft

	X	52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X
	X	52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X
Total					\$9,272.65		\$3,029.41			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

3029.41 2286.88
 -207 1829.50
 + 2423.53 800
 + 800.00 1660
 + 1785.00 4289.50
 5008.53 4594300
 415 \$5000/-
 14180.14

...CLAIM SUBFOLDER...(Pending for Survey Report)




CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Feb 2019		12 Mar 2019 10:03 Edit Adj Rpt	S\$4,300.00 Edit Estimates	S\$4,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SAMSUNG C&T CORPORATION , Co. Reg. No.: NA								
Main Claimant:	SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHB822P	Date of Loss:	10/01/2019 04:00 - :59 [52 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 585420	Policy/Cover Note No.:	B29062113MCY (Comprehensive) Coverage: 01/01/2019 - 31/12/2019						
Vehicle Reg. No. (Insured):	SKX9217B	Policy No. (Claimant):							
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 13/03/2019]								
Driver/Custodian (Insured):	CHO NAMUNG (), NRIC: G0863696L, Tel: +6596664556 Email:								
Adj Asg. Remarks:	Direct Survey done								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHB822P (585420)
[SKX9217B]
TP
SMRT TAXIS PTE LTD
Jan 10 2019 4:00AM
[SAMSUNG C&T CORPORATION]
SMRT Automotive Services Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
2	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
3	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
4	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
5	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
6	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
7	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
8	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
9	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
10	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
11	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
12	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
13	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
14	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
15	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
16	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
17	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
18	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
19	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
20	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
21	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
22	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
23	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
24	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
25	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
26	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
27	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
28	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
29	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
30	14/06/19 14:31	Chassis Number		Load JPG	<input checked="" type="checkbox"/>					
31	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
32	14/06/19 14:31	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>					
33	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
34	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
35	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
36	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					
37	14/06/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
38	14/06/19 14:31	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
39	14/06/19 14:31	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
40	14/06/19 14:31	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19000935/T1QD3E2

Date: 26/06/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B29062113MCY

Claimant Vehicle No : SHB822P

Insured Vehicle No : SKX9217B

Date of Loss: 10/01/2019

Nature of Claim: TP

Claim No: 585420

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB822P

Make & Model: TOYOTA PRIUS TAXI, 1.8 (A)

Engine No: 2ZR6127475

Reg. Date: 10/09/2014 (Man. Year: 2014)

Chassis No: JTDKN36U205748919

Colour: Maroon

Odometer: 378793 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,347.14	2,286.88	7,060.26	75.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,837.00	2,460.00	2,377.00	49.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,184.14	4,746.88	9,437.26	66.53
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	14,184.14	4,300.00	9,884.14	69.68

INSPECTION

Date of Assignment: 12/03/2019

Date Inspected: 11/01/2019 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jun 2019)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB822P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER SIDE RETAINER RR/LH (DISC 30%)	Necessary	94.80 F	*66.36 F
2	1		*REINFORCEMENT, RR (DISC 30%)	Bent	34.60 F	*24.22 F
3	1		*ARM SUB-ASSY, RR BUMPER LH (DISC 30%)	Bent	139.60 F	*97.72 F
4	1		*TROUGH, BACK DOOR LH (DISC 30%)	Necessary	110.90 F	*77.63 F
5	1		*FENDER LINER RR/LH (DISC 30%)	Deformed	141.30 F	*98.91 F
6	1		*DUCT ASSY, QUARTER (DISC 30%)	Deformed	70.40 F	*49.28 F
7	1		*NAME PLATE (HYBRID) (DISC 30%)	Necessary	51.90 F	*36.33 F
8	1		*TAIL LAMP BRACKET, LH (DISC 30%)	Deformed	30.70 F	*21.49 F
9	1		*FENDER RR/LH (DISC 30%)	Buckled	766.80 F	*536.76 F
10	1		*BUMPER REINFORCEMENT REAR (DISC 30%)	Bent	205.70 F	*143.99 F
11	1		*BUMPER REAR (DISC 30%)	Defaced	458.60 F	*321.02 F
12	1		*BUMPER CLIPS (DISC 30%) (10PCS)	Necessary	16.10 F	*11.27 F
13	1		*BUMPER LIP COVER RR/LH (DISC 30%)	Cut	72.20 F	*50.54 F
14	1		*FLOOR PANEL RR/LH (DISC 30%)	Bent	102.00 F	*71.40 F
15	1		*TAIL LAMP LH (DISC 10%)	Cracked	548.40 F	*493.56 F
16	1		*SEALANT SIKAFLEX (SN)	Necessary	37.00 F	*37.00 F
17	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
18	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
19	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
20	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
21	1		*CABLE SUB-ASSY, FUEL LID	Not Necessary	63.90 F	*- F
22	1		*BUMPER LIP REAR	Not Necessary	228.90 F	*- F
23	1		*QUARTER GLASS RR/LH	Not Necessary	168.10 F	*- F
24	1		*UNDER COVER SUBASSY, RR FLOOR	Not Necessary	514.50 F	*- F
25	1		*CAP ASSY, FUEL TANK	Not Necessary	68.10 F	*- F
26	1		*BUMPER SEAL, RR LH	Not Necessary	88.90 F	*- F
27	1		*PANEL ASSY, DECK RH	Not Necessary	307.00 F	*- F
28	1		*BOARD ASSY, RR RH	Not Necessary	379.20 F	*- F
29	1		*TUBE, FUEL TANK	Not Necessary	36.10 F	*- F
30	1		*RETAINER, FUEL LID CABLE	Not Necessary	5.90 F	*- F
31	1		*SEALANT W/SCREEN	Not Necessary	37.00 F	*- F
32	1		*PIPE SUB-ASSY, FUEL NECK	Not Necessary	230.80 F	*- F
33	1		*BOARD, RR FLOOR	Not Necessary	392.30 F	*- F
34	1		*TYRE	Not Necessary	126.74 F	*- F
35	1		*BUMPER SIDE RETAINER RR/RH	Not Necessary	94.80 F	*- F
36	1		*ARM SUB-ASSY, RR BUMPER RH	Not Necessary	139.60 F	*- F
37	1		*PANEL SUB-ASSY, QTR WHEEL HOUSE	Repair	588.40 F	*- F
38	1		*TAILGATE ASY	Repair	1,007.90 F	*- F
39	1		*LID ASSY, FUEL	Repair	102.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*END PANEL	Repair	602.10 F	*- F
41	1		*DOOR RR/LH	Repair	954.50 F	*- F
				Total Parts (S\$)	9,347.14	2,286.88

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,014.00	800.00
2	SPRAY PAINT	New	2,412.00	1,200.00
3	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	30.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	30.00
5	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	New	120.00	30.00
6	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM	New	125.00	0.00
7	TO REMOVE & REFIT FUEL TANK	New	120.00	80.00
8	TO REMOVE & REFIT REAR QUARTER GLASS LH	New	120.00	80.00
9	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	60.00
10	TO REMOVE AND REFIT WIRE HARNESS	New	200.00	0.00
11	TO REPLACE SUNDRY PARTS	New	120.00	30.00
12	TO TEST REFIX REVERSE SENSOR SYSTEM	New	120.00	30.00
13	TO WASH AND VACUUM	New	60.00	0.00
14	TOWING CHARGE	New	126.00	90.00
Gross Labour Cost (\$\$)			4,837.00	2,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >